



# Volkswagen

VIN: WV1ZZZ7HZKH050653

Diesel

2019

Generat pe 2025-01-14 15:41



## Scop

⚠ Necesită atenție



## Odometru

✓ Arată bine



## Statut legal

✓ Arată bine



## Daune

⚠ Necesită atenție



+31

## Surse de date

Am verificat 900+ de surse de date în 35 de țări

## Fotografii

2023-02

23 de fotografii











## Scop

A fost folosit vehiculul drept taxi, pentru închiriere sau alt vehicul de serviciu? Notă: acest gen de vehicule pot fi într-o stare mai proastă decât ar fi normal!

### ⚠ Ai grijă!

Vehiculul a fost folosit ca mașină utilitară!


### Iată ce am verificat:

-  **Utilitar** ⚠ Înregistrare găsită 2025-01  **România** A fost folosit ca vehicul utilitar
-  **Taxi** ✓ Nu s-a găsit nici o înregistrare Nici o dovadă că a fost folosit pe post de taxi
-  **Transport** ✓ Nu s-a găsit nici o înregistrare Nici o dovadă că a fost folosit ca vehicul de transport
-  **Închiriere** ✓ Nu s-a găsit nici o înregistrare Nici o dovadă că a fost folosit ca vehicul de închiriat
-  **Poliție** ✓ Nu s-a găsit nici o înregistrare Nici o dovadă că a fost folosit de poliție
-  **Demo** ✓ Nu s-a găsit nici o înregistrare Nu există dovezi că a fost folosit pe post de vehicul demonstrativ




## Furt

Vehiculul este în prezent marcat ca furat? A fost furat în trecut? A fost recuperat?

- ✓ **Nu s-au găsit probleme**  
Nu am găsit nicio înregistrare că vehiculul a fost furat.

- i **Notă**  
Verificarea bazei de date a poliției privind vehiculele furate finalizată în **8 țări**:  +2

### Iată ce am verificat:

-  **Căutat drept furat** ✓ Nu s-a găsit nici o înregistrare
-  **Furat în trecut** ✓ Nu s-a găsit nici o înregistrare Starea actuală necunoscută
-  **Furat în trecut** ✓ Nu s-a găsit nici o înregistrare Vehiculul a fost recuperat

Baza de date aparținând poliției cu vehicule furate, **verificare finalizată în:**




România



Statele Unite ale Americii




Danemarca



Slovacia



Suedia



Slovenia



Lituania




Cehia

## Odometru

Există semne conform cărora kilometrajul a fost dat înapoi sau discrepanțe ale kilometrajului?

### Notă

Ultimul kilometraj cunoscut: 167.306 km



**Disclaimer (declinarea responsabilității):** acest grafic reprezintă o tendință estimată a kilometrajului. Deși se bazează pe înregistrări reale de kilometraj disponibile pentru acest vehicul, există lacune având în vedere că evoluția kilometrajului nu este înregistrată în mod constant. Pentru a lua în considerare aceste date lipsă, aplicăm un model patentat de analiză a datelor care prezice modul în care probabil s-a schimbat kilometrajul între evenimentele înregistrate. Acest lucru ajută la furnizarea unei imagini mai complete a utilizării vehiculului în timp.

## Statut legal

A trecut vehiculul inspecțiile tehnice? A fost notat drept casat?

### Notă

## Legal


✓= Inspekție tehnică periodică (ITP) **A trecut** 2024-04  România


A trecut cu succes inspekția tehnică Valabil până la 2025-04

↺↻ **Casat** ✓ Nu s-a găsit nici o înregistrare Nu există nici o înregistrare că vehiculul a fost marcat drept casat


## Daune

Acest vehicul a fost avariat în trecut ? Care a fost valoarea daunelor?

 **Ai grijă!**  
Vehiculul a fost avariat de 2 ori!

 **Notă**  
Daunele minore nu vor afecta în mod normal siguranța vehiculului și nu vor cauza probleme structurale

## Înregistrări de daune




Spate

Partea stângă

Partea dreaptă

Față

1

2022-01  România

### Daune

Părți afectate

**Față**

Costul estimativ al reparațiilor

**2.001 RON – 6.000 RON**

Cauza posibilă

**Necunoscut**

Categorii de daune

**Sticlă**



Daune pe partea dreaptă:

Spate / Bară de protecție

Spate stânga / Bară de protecție

Spate dreapta / Bară de protecție

2022-07

România

## Daune

Părți afectate

Spate

Costul estimativ al reparațiilor

**2.001 RON – 6.000 RON**

Cauza posibilă

**Necunoscut**

Categoriile de daune

Părți exterioare ale caroseriei

**Disclaimer (declinarea responsabilității):** Majoritatea înregistrărilor de daune sunt legate de accidente, dar uneori nu este acesta cazul. Unele înregistrări provin din alte surse cum ar fi serviciile specializate pe lucrări de caroserie, cereri de daune, licitații sau inspecții ale vehiculelor. Aceste înregistrări arată că starea vehiculului a fost evaluată, chiar dacă nu a fost din cauza unui accident.

## Dezastre naturale

Locația vehiculului a fost înregistrată în zona unui dezastru natural?

✓ Nu s-au găsit probleme

Locația vehiculului nu a fost înregistrată în zona unui dezastru natural

## Emisii

Câte emisii de CO2 produc vehiculele din acest model/an?

i Notă

Emisii CO2: D (166 g/km)

## Emisii CO<sub>2</sub>

Emisiile CO<sub>2</sub> ale

Emisii CO<sub>2</sub> ale  
vehiculului tău

**166 g/km** Clasă **D**

Până la 120

120 - 140

140 - 155

155 - 165

165 - 190

190 - 225

225 și peste

Emisii CO<sub>2</sub> g/km

## Specificații și echipare

Ce specificații și echipamente sunt înregistrate pentru acest vehicul?

### Notă

Verificați dacă specificațiile și echipamentul acestui vehicul se potrivesc cu datele furnizate de vânzător.

## Identificare și specificații tehnice



Producător

**Volkswagen**



Tip caroserie

**Dubă**



An de fabricație

**2019**



An model

**2019**



Capacitate cilindrică

**2 l**



Putere motor

**110 kW (148 cp)**



Tip combustibil

**Diesel**



Cutie de viteze

**Automată**



Tip transmisie

**Tracțiune față (FWD)**



Culoare

**Gri**



Nr. uși

**4**



Amplasarea volanului

**Volan pe stânga**



Nr. cilindri

**4**



Nr. locuri

**5**



Cod motor

**CXHA**

---

## Echipare

Cum a fost primit de la producător

---

**0E2**

LONG WHEELBASE

**0FA**

STANDARD MANUFACTURING SEQUENCE

**0G7**

TIPTRONIC

**0JF**

WEIGHT CATEGORY FRONT AXLE WEIGHT RANGE 6

**0KT**

SPECIAL LABEL

**0SA**

WITHOUT SPECIAL LABELS/PLATES

**0TA**

WITHOUT FLOOR MATS

**0WR**

GROSS VEHICLE WEIGHT RATING

**0XH**

INFORMATION KIT IN ROMANIAN

**0Y1**



## STANDARD CLIMATIC ZONES

0YD

WEIGHT RANGE 4 INSTALLATION CONTROL ONLY, NO REQUIREMENT FORECAST

1AK

ELECTRONIC STABILITY CONTROL (ESC) WITH BRAKE ASSIST SYSTEM

1BH

SUSPENSION/SHOCK ABSORPTION, STANDARD 2

1CP

VEHICLE CLASS DIFFERENTIATION 7E0

1D1

TRAILER HITCH

1EV

SPECIAL IDENTIFICATION PLATE EC FOR COMMERCIAL VEHICLES

1G2

STEEL SPARE WHEEL WITH ORIGINAL EQUIPMENT TIRE

1HZ

LABELS WITHOUT COUNTRY GROUP

1LO

STANDARD AIR CLEANER

1MM

STEERING WHEEL

1N1

POWER STEERING

1NE

WHEEL CENTER TRIM

1PA

STANDARD WHEEL BOLTS

1S6

HEAVY-DUTY TOOL KIT AND JACK

1T0

WITHOUT FIRST AID KIT AND WARNING TRIANGLE

1U0

WITHOUT TABLE

1W0

WITHOUT REFRIGERATOR/GLOVE COMPARTMENT COOLING SYSTEM

1Y0

WITHOUT DIFFERENTIAL LOCK

1Z0

INITIAL STANDARD FUEL FILLING

2A0

WITHOUT DELIVERY EQUIPMENT

2E3

16-INCH CHASSIS

2G0

WITHOUT INSERT FOR THE FILLING UP OF FUEL

2JB

STANDARD BUMPERS

2N1

STANDARD ANTI-DRUM MEASURES

2P1

PLASTIC LOADING EDGE PROTECTION

2Q0

WITHOUT MODULAR SEAT MOUNTING

2QA

NAMEPLATE SET TRANSPORTER

2V1

DUST AND POLLEN FILTER

2WA

WITHOUT ADDITIONAL TIRES

3B0

WITHOUT ADDITIONAL CHILD SEAT ANCHOR

3CA

WITHOUT PARTITION

3HA

WITHOUT LEATHER PARTS SCOPE

3J6

NARROW HEAD RESTRAINTS, HEIGHT-ADJUST.

3JA

WITHOUT ROOF INSERT IN LOAD AND PASSENGER COMPARTMENT

3L1

MANUAL HEIGHT ADJUSTMENT FOR LEFT FRONT SEAT

3LN

UNPAINTED DOOR TRIM PANEL

3M6

LIGHT COMMERCIAL VEHICLE VERSION WITH UPTO 6 SEATS

3R0

STANDARD ROOF

3RB

TAILGATE WITHOUT WINDOW APERTURE

3S0

WITHOUT ROOF RAILS/ROOF LOAD RACK

3SH

SEAT IN CAB, RIGHT

3TH

SEAT IN CAB, LEFT

3U0

WITHOUT LUGGAGE COMPARTMENT COVER

3UI

SEAT PREPARATION SCS

3VA

WITHOUT SEATS

3W0

WITHOUT ADDITIONAL NOISE SUPPRESSION MEASURES FOR PASSENGER COMPARTMENT

3WA

WITHOUT BENCH

3Y0

WITHOUT ROLL-UP SUNSHADE

4A0

WITHOUT SEAT HEATER

4E0

TAILGATE/TRUNK LID UNLOCKING FROM OUTSIDE

4FT

FIXED SIDE WINDOW FRONT CLOSED IN REAR IN LOAD/PASSENGER COMPARTMENT, LEFT

4GF

WINDSHIELD IN HEAT-INSULATING GLASS

4H0

WITHOUT CHILD SAFETY LOCK IN PASSENGER COMPARTMENT

4HA

WITHOUT REAR WINDOW

4I1

CENTRAL LOCKING SYSTEM WITHOUT SAFELOCK

4JT

FIXED SIDE WINDOW FRONT CLOSED IN REAR IN LOAD/PASSENGER COMPARTMENT, RIGHT

4L3

WITHOUT BREAKAWAY INTERIOR REARVIEW MIRROR

4N2

STANDARD DASHBOARD

4R1

POWER WINDOWS

4S2

ARMREST FOR LEFT FRONT SEAT

4UF

DRIVER AND FRONT PASSENGER AIRBAG WITH FRONT PASSENGER AIRBAG DEACTIVATION

4X0

WITHOUT SIDE AIRBAG

4Y0

WITHOUT STORAGE COMPARTMENT/SAFE BOX

5AC

RUBBER FLOOR COVERING IN CAB

5BA

WITHOUT FLOOR COVERING IN PASSENGER/LOADCOMPARTMENT

5C0

WITHOUT SPECIAL BODY MEASURES

5CL

ROOF TRIM IN CAB AS COMFORT MOLDED HEADLINER, IN LOAD/PASSENGER COMPARTMENT WITH HARDBOARD

5D1

CARRIER FREQUENCY 433.92 MHZ-434.42 MHZ

5DV

SIDE TRIM PANEL FOR BASIC EQUIPMENT (EXTENDED)

5FA

WITHOUT ADDITIONAL STORAGE COMPARTMENTS IN CAB

5G0

WITHOUT CURTAINS

5K0

WITHOUT SURFACE PROTECTION, WITH ADDITIONAL TRANSPORT PROTECTION MEASURES

5N2

FOLDING GRAB HANDLES AT ROOF FRAME

5Q0

WITHOUT DOOR IN LOAD/PASSENGER COMPARTMENT LEFT (CLOSED SIDE PANEL)

5R2

SLIDING DOOR RIGHT IN LOAD/PASSENGER COMPARTMENT

5RQ

RIGHT EXTERIOR MIRROR, CONVEX

5SJ

LEFT EXTERIOR MIRROR, CONVEX

5TC

WITHOUT DECORATIVE INSERTS

5V3

HINGES FOR TAILGATES/TRUNK LID (STANDARD DESIGN)

6B1

LASHING RINGS FOR LOAD RESTRAINT SYSTEM

6CA

WITHOUT REAR HEATING/VENTILATION DUCT

6DE

SUN VISORS WITHOUT MIRROR, WITH TICKET POCKET ON DRIVER SIDE AND AIRBAG LABEL ON SUN VISOR

6FA

COMPONENTS WITHOUT SPECIAL SURFACE APPEARANCE

6K0

WITHOUT AREA MONITORING SYSTEM/WITHOUT AUTONOMOUS EMERGENCY BRAKING SYSTEM

6KL

RADIATOR GRILLE

6L0

WITHOUT C-RAILS

6N2

MUD FLAP IN FRONT AND REAR

6U0

WITHOUT ADDITIONAL SEALS OUTSIDE

6X0

WITHOUT ENTRY GRAB HANDLE

6XN

EXTERIOR MIRRORS: POWER-ADJUSTABLE, SEPARATELY HEATED

7AA

ELECTRONIC ENGINE IMMOBILIZER

7B0

WITHOUT SOCKET

7H0

WITHOUT SPEED LIMITER

7K0

WITHOUT DIRECT TIRE PRESSURE MONITORING SYSTEM

7L6

START/STOP SYSTEM WITH REGENERATIVE BRAKING

7MM

EMISSION STANDARD EU6 PLUS

7P5

MANUALLY ADJUSTABLE LUMBAR SUPPORT FOR LEFT FRONT SEAT

7Q0

WITHOUT NAVIGATION DEVICE

7QA

WITHOUT CD/DVD FOR NAVIGATION

7V2

DASHBOARD ILLUMINATION, NOT DIMMABLE

7X8

PARK DISTANCE CONTROL IN FRONT AND REAR, AND REAR VIEW CAMERA SYSTEM

7Y0

WITHOUT LANE CHANGE ASSIST

8FA

WITHOUT SECOND BATTERY

8G0

WITHOUT LIGHT CONTROL

8GU

ALTERNATOR 140 A

8IA

HALOGEN HEADLAMPS

8K1

SEPARATE DAYTIME RUNNING LIGHTS

8N1

WINDSHIELD WIPER INTERMITTENT CONTROL

8Q1

HEADLIGHT RANGE ADJUSTMENT

8QJ

KEY FOR LOCKING SYSTEM WITH REMOTE CONTROL

8RE

4 SPEAKERS (PASSIVE)

8SA

TAIL LAMP ASSEMBLIES, STANDARD DESIGN

8T2

CRUISE CONTROL SYSTEM (CCS) ELECTRONIC

8TB

REAR FOG LAMP

8WH

FRONT FOG LAMP AND CORNERING LAMP

8X0

WITHOUT HEADLAMP WASHER SYSTEM

8Y0

SINGLE-TONE HORN

8Z5

NOT HOT COUNTRY



9AP

CLIMATIC AIR-CONDITIONING SYSTEM (SEMI-AUTOMATIC)

9CU

STANDARD INTERIOR LIGHT CONCEPT IN PASSENGER/LOAD COMPARTMENT

9H0

WITHOUT ROOF TURN SIGNALS

9JA

NON-SMOKER'S PACKAGE

9KA

WITHOUT IDENTIFICATION LIGHTS

9LA

WITHOUT ROTATING BEACON

9M0

WITHOUT AUXILIARY HEATER/FUEL-FIRED PARKING HEATER

9N0

WITHOUT STEP ILLUMINATION

9NA

WITHOUT TACHOGRAPH

9P1

SEAT BELT REMINDER, ELECTRIC CONTACT IN BUCKLE

9Q0

WITHOUT MULTI-FUNCTION DISPLAY/ ON-BOARD COMPUTER

9WT

MIRRORLINK

9Z0

OPERATING VOLTAGE 12 V

9ZX

MOBILE PHONE INTERFACE

A65

CATEGORY 5

A8B

BASIC EQUIPMENT

AF0

WITHOUT STOWAGE COMPARTMENT

AV1

DRIVING ON THE RIGHT

B0A

COMPONENT PARTS SET WITHOUT COUNTRY-SPECIFIC BUILDING REGULATION

B43

TYPE APPROVAL COUNTRY ROMANIA

C53

OPERATING PERMIT, ALTERATION

C9D

STEEL WHEELS 6.5J X 16

DN4

4-CYL. TURBO DIESEL ENGINE 2.0 L/110 KW (4V) TDI COMMON RAIL; B.ENGINE T37/T6F  
TS1/TR1/T0P/T0N/T13/T29/TM4/TD1/TI9/T1I

E0A

NO SPECIAL EDITION

EA0

WITHOUT FOLLOW-ON WARRANTY

ELO

WITHOUT ONLINE SERVICE

EM0

WITHOUT DRIVER ALERT SYSTEM

EU0

WITHOUT SOCKET IN FRONT

EW0

WITHOUT MAINTENANCE CONTRACT

F0A

NO SPECIAL PURPOSE VEHICLE, STANDARD EQUIPMENT

FM0

BASIC EQUIPMENT VARIANT

G1C

SEVEN-SPEED AUTOMATIC TRANSMISSION

GX0

MANUALLY OPERATED DOORS

GY0

WITHOUT POWER LATCHING FOR TAILGATE

GZ0

MANUALLY OPERATED DOORS

I7A

MIB2 STANDARD PQ RADIO PLUS EU/ROW

IG2

CURB WEIGHT RANGE 2

II0

WITHOUT BUILT-IN CUPBOARD

IM0

FRONT AXLE WEIGHT, STANDARD

IN0

REAR AXLE WEIGHT, STANDARD

IS0

WITHOUT INTERFACE FOR EXTERNAL USE

J1N

BATTERY 420 A (75 AH)

K4A

PANEL VAN

KK1

REFRIGERANT R134A

L0L

LEFT-HAND DRIVE

N1L

SEAT TRIM COVERS IN WOVEN FABRIC

NF0

WITHOUT AWNING

NR0

WITHOUT INSERT/BADGES (INTERIOR)

NY0

STANDARD BATTERY/ALTERNATOR CAPACITY

NZ0

WITHOUT CALL FEATURE

Q30

TIRES 205/65 R16 C 107/105T LOW ROLLING RESISTANCE

QA0

WITHOUT CHILD SEAT

QE0

WITHOUT STORAGE COMPARTMENT PACKAGE/BOX

QG1

SERVICE INTERVAL PROLONGATION

QH0

WITHOUT VOICE CONTROL

QI8

SERVICE INDICATOR 40 000 KM OR 2 YEARS ( VARIABLE )

QJ0

WITHOUT ALUMINUM/CHROME PACKAGE

QL3

HEAT-INSULATING GLASS (GREEN)

QV0

WITHOUT TV RECEPTION/DIGITAL RADIO RECEPTION

S27

EXPORT VEHICLES WITH BUILT-IN PARTS BY SERVICE CENTER FOR SPECIAL EQUIPMENT (PRICING CONTROL)

S5X

COMPLETION OF OPTIONAL EQUIPMENT

T29

4-CYLINDER DIESEL ENGINE 2.0 L UNIT 04L.G

U5A

INSTRUMENT CLUSTER, KM/H SPEEDOMETER

UG1

HILL START ASSIST

UI4

ELECTRIC INTERFACE FOR EXTERNAL USE, AUX-IN JACK, USB (IPOD-CAPABLE)

V0A

TIRES WITHOUT SPECIFICATION OF TIRE BRAND

X7Y

EQUIPMENT OPTIONS SUBSET FOR EXPORT (OTHERS)

## Cronologie

Cronologia înregistrărilor pentru acest vehicul

S-au găsit 9 înregistrări

### Ultimele înregistrări

2019-01  Țară necunoscută



**A fost fabricat**

Țara (sau statul) indică fie locația centrului de producție, uzina de asamblare sau adresa de înregistrare a producătorului. Data poate fi aproximativă.

2019-04  România



**A fost înmatriculat**

Înregistrarea reprezintă un eveniment administrativ. Acest lucru ar putea fi legat de o schimbare de proprietar, documente etc

2021-04  România

 = **A fost verificat**

A fost înregistrat un eveniment de inspecție tehnică (cunoscut și sub denumirea de ITP, test tehnic sau test de control al emisiilor). Pot fi incluse atât instanțe reușite, cât și eșuate.

2022-01  România

 **Daună detectată** 

Avem indicii potrivit cărora acest vehicul a fost recunoscut ca avariat în această țară (sau stat). Pentru detalii, vă rugăm să consultați secțiunea „Daune”.

2022-04  România

 = **A fost verificat**

A fost înregistrat un eveniment de inspecție tehnică (cunoscut și sub denumirea de ITP, test tehnic sau test de control al emisiilor). Pot fi incluse atât instanțe reușite, cât și eșuate.

2022-07  România

 **Daună detectată** 

Avem indicii potrivit cărora acest vehicul a fost recunoscut ca avariat în această țară (sau stat). Pentru detalii, vă rugăm să consultați secțiunea „Daune”.

2023-02  România

 **A fost la vânzare**

Această înregistrare a fost creată deoarece vehiculul a fost listat pentru vânzare pe o anumită piață. Uneori, țara (sau statul) vânzătorului suprascrie locația reală a vehiculului.

2023-04  România

 = **A fost verificat**

A fost înregistrat un eveniment de inspecție tehnică (cunoscut și sub denumirea de ITP, test tehnic sau test de control al emisiilor). Pot fi incluse atât instanțe reușite, cât și eșuate.

2024-04  România

 **A fost verificat**

A fost înregistrat un eveniment de inspecție tehnică (cunoscut și sub denumirea de ITP, test tehnic sau test de control al emisiilor). Pot fi incluse atât instanțe reușite, cât și eșuate.



+31

**Surse de date**

Am verificat 900+ de surse de date în **35 de țări**