



Volkswagen Polo

VIN: WVWZZZAWZLU074787

Benzină

2020

Generat pe 20.03.2025, 09:19



Odometru

✓ Arată bine



Statut legal

✓ Arată bine



Daune

⚠ Necesită atenție



+31

Surse de date

Am verificat 900+ de surse de date în 35 de țări

Furt

Vehiculul este declarat furat în prezent? A fost furat în trecut? A fost recuperat?




Nu s-au găsit probleme

Nu am găsit nicio înregistrare că vehiculul a fost furat.



Notă

Am încheiat verificarea bazelor de date ale poliției privind vehiculele furate din 9 țări:  +3

Iată ce am verificat:



Căutat drept furat

✓ Nu s-a găsit nicio înregistrare



Furat în trecut

✓ Nu s-a găsit nicio înregistrare Starea actuală necunoscută



Furat în trecut


✓ Nu s-a găsit nicio înregistrare Vehiculul a fost recuperat

Bazele de date ale poliției cu vehicule furate verificare finalizată în:

 România

 Slovenia

 Cehia

 Slovacia

 Italia

 Ungaria

 Canada

 Danemarca


 Suedia

Odometru

Există semne conform cărora kilometrajul a fost dat înapoi sau sunt discrepanțe de kilometraj?

i Notă

- Ultimul kilometraj cunoscut: 50.000 km
- Kilometraj mediu pentru modele similare: 56.309 km



Disclaimer (declinarea responsabilității): acest grafic reprezintă o tendință estimată a kilometrajului. Deși se bazează pe înregistrări reale de kilometraj disponibile pentru acest vehicul, există lacune având în vedere că evoluția kilometrajului nu este înregistrată în mod constant. Pentru a lua în considerare aceste date lipsă, aplicăm un model patentat de analiză a datelor care prezice modul în care probabil s-a schimbat kilometrajul între evenimentele înregistrate. Acest lucru ajută la furnizarea unei imagini mai complete a utilizării vehiculului în timp.

Statut legal

A trecut vehiculul inspecțiile tehnice? A fost marcat drept casat?

i Notă

Inspecția tehnică a fost transmisă pe 05.2023 în România

Legal

= Inspecție tehnică periodică (ITP) **A trecut** 05.2023 România A trecut cu succes inspecția tehnică
 = Valabil până la 05.2025

= Casat Nu s-a găsit nicio înregistrare Nu există nicio înregistrare că vehiculul a fost marcat drept casat

Daune

Acest vehicul a fost avariat în trecut ? Care a fost valoarea daunelor?

Ai grijă!
Am găsit 1 înregistrare pentru acest vehicul

Notă
Daunele minore nu vor afecta în mod normal siguranța vehiculului și nu vor cauza probleme structurale

Înregistrări de daune



05.2024 România

Evaluare

Părți afectate

Față

Costul estimativ al reparațiilor

6.001 RON – 14.000 RON

Cauza posibilă

Necunoscut

Categorii de daune

Părți exterioare ale caroseriei

Daune frontale:

- Față / Bară de protecție
- Față stânga / Bară de protecție
- Față dreapta / Bară de protecție

Disclaimer (declinarea responsabilității): Majoritatea înregistrărilor de daune sunt legate de accidente, dar uneori nu este acesta cazul. Unele înregistrări provin din alte surse cum ar fi serviciile specializate pe lucrări de caroserie, cereri de daune, licitații sau inspecții ale vehiculelor. Aceste înregistrări arată că starea vehiculului a fost evaluată, chiar dacă nu a fost din cauza unui accident.

Termeni secțiunea Daune

Evaluare
Evaluarea este procesul prin care se determină gradul de deteriorare al unui vehicul. Aceasta implică inspectarea vehiculului pentru a determina ce reparații sunt necesare, pentru a estima costurile și pentru a decide dacă vehiculul este reparabil sau poate fi considerat daună totală.

Costul estimativ al reparațiilor
Odată ce un incident în care a fost implicat un vehicul este evaluat, furnizorii de date referitoare la daune calculează costul reparației și îl prezintă în moneda țării în care a fost evaluată dauna. Prin urmare, este posibil ca această estimare să nu coincidă cu așteptările tale. Motivele pot include:

- Țara în care au fost evaluate daunele vehiculului poate avea costuri de reparație mai mari/mai mici în comparație cu țara ta. (prețurile pieselor de schimb și costul forței de muncă diferă de la o țară la alta)
- Costul reparațiilor este calculat ca și cum reparațiile au fost făcute la un service oficial (care este de obicei ceva mai scump)

Dezastre naturale

Locația vehiculului a fost înregistrată în zona unui dezastru natural?



Nu s-au găsit probleme

Locația vehiculului nu a fost înregistrată în zona unui dezastru natural

Valoare de piață

Cu cât s-a vândut vehiculul în trecut? Care este prețul mediu pentru un vehicul din același model și an?



Notă

- Prețul mediu de pe piață pentru un astfel de vehicul: 57.722 RON
- Atenție la problemele ascunse dacă vehiculul a fost la vânzare la un preț semnificativ mai mic decât prețul actual!

Valoarea actuală de piață pentru Volkswagen Polo 2020

Valoarea de piață este determinată prin examinarea prețului unui anumit model de mașină (fabricat în același an) în țara în care a fost generat raportul. Analizăm datele din ultimele 6 luni.

Cel mai mic preț

54.825 RON

Prețul mediu

57.722 RON

Cel mai mare preț

62.998 RON

Emisii

Care este nivelul de emisii de CO₂ al vehiculele din acest model/an?



Notă

Emisii CO₂: B (127 g/km)

Emisii CO₂

Emisiile de CO₂ ale
vehiculului tău

127 g/km Clasă **B**

Până la 120

120 - 140

140 - 155

155 - 165

165 - 190

190 - 225

225 și peste

Emisii CO₂ g/km

Specificații și echipare

Ce specificații și echipamente sunt înregistrate pentru acest vehicul?



Notă

Verifică dacă specificațiile și echipamentul acestui vehicul se potrivesc cu datele furnizate de vânzător.

Identificare și specificații tehnice



Producător
Volkswagen



Model
Polo



Tip caroserie
Hatchback



An de fabricație
2020



Capacitate cilindrică
11



Putere motor
70 kW (94 cp)



Tip combustibil
Benzină



Cutie de viteze
Manuală



Tip transmisie
Tracțiune față (FWD)



Culoare
Alb



Nr. uși
4



Amplasarea volanului
Volan pe stânga



Nr. locuri
5



Cod motor
DKLA



Categorie
m1

Echipare

Cum a fost primit de la producător

REAR OVERHANG, SHORT

0AR

FRONT STABILIZER

0EM

INSTALLATION DIFFERENTIATION FOR TRANSMISSION
MQ 200 -- VEHICLE COMPONENTS --

0K0

WITHOUT ALTERNATIVE DRIVE SYSTEM

0N1

STANDARD REAR AXLE

0P0

REAR EXHAUST TAILPIPE (STANDARD)

0TA

WITHOUT FLOOR MATS

0Y1

STANDARD CLIMATIC ZONES

1A5

FUEL SYSTEM FOR SI ENGINE

1D0

WITHOUT TRAILER HITCH

1EX

SPECIAL IDENTIFICATION PLATE FOR EC FOR M1
PASSENGER VEHICLE

1JP

REAR SHOCK ABSORPTION

1N1

POWER STEERING

1PA

STANDARD WHEEL BOLTS

1SA

WITHOUT ADDITIONAL FRONT UNDERBODY GUARD

1TB

VEHICLE CLASS DIFFERENTIATION -2G0- FOR BUILD
STATUS EUROPE

1Y0

WITHOUT DIFFERENTIAL LOCK

1ZG

4 DOORS

0B1

WHEELBASE

0FV

SOUTH AFRICA MANUFACTURING SEQUENCE

0KA

WITHOUT DECALS AND EMBLEMS

0NB

NAMEPLATE SET IN BASIC STYLE

0SS

LABELS/PLATES IN ENGLISH AND FRENCH

0XH

INFORMATION KIT IN ROMANIAN

0YJ

WEIGHT RANGE 9 INSTALLATION CONTROL ONLY, NO
REQUIREMENT FORECAST

1AS

ELECTRONIC STABILITY CONTROL (ESC)

1E5

ACTIVATED CARBON CANISTER FOR INTENSIFIED
EVAPORATION SYSTEM WITH ON-BOARD
DIAGNOSTIC SYSTEM 2

1G2

STEEL SPARE WHEEL WITH ORIGINAL EQUIPMENT
TIRE

1KA

DRUM BRAKES IN REAR

1NJ

WHEEL TRIMS

1S1

TOOL KIT AND JACK

1T2

WARNING TRIANGLE

1X0

FRONT WHEEL DRIVE

1Z0

INITIAL STANDARD FUEL FILLING

2A8

DISK BRAKES IN FRONT (GEOMET D)

2C5

AXIAL AND VERTICAL ADJUSTABLE STEERING COLUMN

2JG

BODY-COLORED BUMPERS

2WA

WITHOUT ADDITIONAL TIRES

31K

FRONT AND REAR LICENSE PLATE CARRIER (ECE)

3C7

3-POINT SEAT BELT FOR CENTER REAR SEAT

3GD

PLANE REAR CARGO AREA

3L1

MANUAL HEIGHT ADJUSTMENT FOR LEFT FRONT SEAT

3Q6

THREE REAR HEAD RESTRAINTS

3U1

FOLDING TRUNK COVER

40I

STEEL WHEELS 5.5J X 15

4AP

DOOR AND SIDE TRIM PANEL

4I2

CENTRAL LOCKING WITH RADIO REMOTE CONTROL, INTERIOR RELEASE MECHANISM WITHOUT SAFELOCK

4L2

DIMMING BREAKAWAY INTERIOR REARVIEW MIRROR

4P0

REAR FLOOR PANEL MODULE, TYPE 1

4U5

LUGGAGE POCKETS ON BACKREST

4X3

DELIVERY EQUIPMENT FOR SHIPMENT

2H0

WITHOUT "DRIVE SELECT"

2V1

DUST AND POLLEN FILTER

2ZA

MULTIFUNCTION STEERING WHEEL

3A0

CHILD SEAT ANCHOR FOR CHILD SEAT SYSTEM I-SIZE, 2X TOP TETHER

3FA

WITHOUT ROOF INSERT (STANDARD ROOF)

3H0

WITHOUT BACKREST RELEASE FOR FRONT SEATS

3NZ

UNSPLIT REAR SEAT BENCH UNSPLIT, SPLIT FOLDING BACKREST

3QT

3-POINT SEAT BELTS IN FRONT, WITH PRETENSIONER AND HEIGHT ADJUSTMENT

3ZU

3-POINT SEAT BELTS, OUTER REAR WITH ECE LABEL

4A3

SEAT HEATER FOR FRONT SEATS SEPARATELY CONTROLLED

4GF

WINDSHIELD IN HEAT-INSULATING GLASS

4KC

SIDE AND REAR WINDOWS IN HEAT-INSULATING GLASS

4N1

PADDED DASHBOARD

4R4

POWER WINDOWS WITH COMFORT OPERATION AND CIRCUIT BREAKER

4UF

DRIVER AND FRONT PASSENGER AIRBAG WITH FRONT PASSENGER AIRBAG DEACTIVATION

51A

SIDE AIRBAG IN FRONT, WITH CURTAIN AIRBAG

5C0

WITHOUT SPECIAL BODY MEASURES

5K7

TRANSPORT PROTECTION FILM (MINIMUM PROTECTION) WITH ADDITIONAL TRANSPORT PROTECTION MEASURES

5RQ

RIGHT EXTERIOR MIRROR, CONVEX

5XJ

SUN VISORS WITH MIRROR, ILLUMINATED, WITH AIRBAG LABEL ON SUN VISOR AND B-PILLAR

6E3

CENTER ARMREST IN FRONT

6K2

FORWARD COLLISION WARNING INCL. AUTONOMOUS EMERGENCY BRAKING, WITHOUT ADAPTIVE CRUISE CONTROL

6PA

PLASTIC HAND BRAKE LEVER HANDLE

6T0

WITHOUT INTERIOR LIGHT IN FOOTWELL

6XD

EXTERIOR MIRRORS, POWER-ADJUSTABLE/ HEATED

7E0

WITHOUT HEAT ACCUMULATOR/AUXILIARY HEATER

7L6

START/STOP SYSTEM WITH REGENERATIVE BRAKING

7P0

WITHOUT LUMBAR SUPPORT IN SEAT BACKRESTS

7W0

WITHOUT EXTENDED SAFETY SYSTEM

7Y0

WITHOUT LANE CHANGE ASSIST

8G0

WITHOUT LIGHT CONTROL

8ID

HALOGEN TWIN HEADLAMPS

WITHOUT ADHESIVE FILM

5D1

CARRIER FREQUENCY 433.92 MHZ-434.42 MHZ

5MB

DECORATIVE INSERTS

5SL

LEFT EXTERIOR MIRROR: ASPHERICAL

5ZF

FRONT HEAD RESTRAINTS

6FF

BODY-COLORED EXTERIOR MIRROR HOUSINGS AND VARIOUS ADD-ON PARTS

6NA

UNSPLIT MOLDED HEADLINER

6Q1

PLASTIC GEARSHIFT KNOB/HANDLE

6U0

WITHOUT ADDITIONAL SEALS OUTSIDE

7AA

ELECTRONIC ENGINE IMMOBILIZER

7K1

DIRECT TIRE PRESSURE MONITORING SYSTEM

7M5

WITHOUT PROTECTIVE FILM FOR SCUFF PLATE

7Q0

WITHOUT NAVIGATION DEVICE

7X2

PARK DISTANCE CONTROL IN FRONT AND REAR

8FA

WITHOUT SECOND BATTERY

8GU

ALTERNATOR 140 A

8K3

SEPARATE DAYTIME RUNNING LIGHTS WITH AUTOMATIC HEADLAMP ACTIVATION AND COMING

8M1

REAR WINDOW WIPER AND WASHER SYSTEM WITH INTERMITTENT CONTROL

8Q1

HEADLIGHT RANGE ADJUSTMENT

8S3

ADDITIONAL READING LIGHTS IN REAR

8T9

SPEED LIMITER WITHOUT CRUISE CONTROL SYSTEM AND WITHOUT ADAPTIVE CRUISE CONTROL

8W1

WASHER FLUID LEVEL INDICATOR

8X0

WITHOUT HEADLAMP WASHER SYSTEM

8Z5

NOT HOT COUNTRY

9AB

MANUALLY CONTROLLED AIR CONDITIONING SYSTEM

9JB

SMOKER'S PACKAGE, ASHTRAY IN FRONT AND REAR

9P9

SEAT BELT REMINDER, ELECTRIC CONTACT IN THE BUCKLE, ADVANCED SAFETY EQUIPMENT

9T0

WITHOUT HEATED WASHER NOZZLES

9ZX

MOBILE PHONE INTERFACE

A8M

EXECUTIVE COMFORT EQUIPMENT

AW5

STANDARD VERSION

B43

TYPE APPROVAL COUNTRY ROMANIA

DI6

3-CYLINDER SI ENGINE 1.0 L/70 KW TSI BASE ENGINE IS TJ4

HOME FEATURE

8N8

WINDSHIELD WIPER INTERMITTENT CONTROL WITH PHOTOSENSOR

8RL

6 SPEAKERS (PASSIVE)

8SA

TAIL LAMP ASSEMBLIES, STANDARD DESIGN

8TC

REAR FOG LAMP FOR DRIVING ON THE RIGHT

8WH

FRONT FOG LAMP AND CORNERING LAMP

8Y0

SINGLE-TONE HORN

8ZQ

ANTENNA FOR FM RECEPTION ONLY, DIVERSITY

9E1

LUGGAGE COMPARTMENT LIGHTING

9M0

WITHOUT AUXILIARY HEATER/FUEL-FIRED PARKING HEATER

9S5

MULTI-FUNCTION DISPLAY/ON-BOARD COMPUTER"MEDIUM"

9WT

MIRRORLINK

A60

CATEGORY 0

AV1

DRIVING ON THE RIGHT

B0A

COMPONENT PARTS SET WITHOUT COUNTRY-SPECIFIC BUILDING REGULATION

C18

OPERATING PERMIT, ALTERATION

EOA

NO SPECIAL EDITION

EA0

WITHOUT FOLLOW-ON WARRANTY

ELO

WITHOUT ONLINE SERVICE

ER1

REGIONAL CODE " ECE " FOR RADIO

FC0

WITHOUT CUSTOMIZED INSTALLATION

G0C

5-SPEED MANUAL TRANSMISSION

I08

TIRES 185/65 R15 88H LOW ROLLING RESISTANCE

K8G

HATCHBACK

KK3

REFRIGERANT R1234YF

L0L

LEFT-HAND DRIVE

NY0

STANDARD BATTERY/ALTERNATOR CAPACITY

QG1

SERVICE INTERVAL PROLONGATION

QI6

SERVICE INDICATOR 30 000 KM OR 2 YEARS (VARIABLE)

QK0

WITHOUT MULTIFUNCTION CAMERA

QQ0

WITHOUT ADD. LIGHTS (INTERIOR LIGHTING)

QV0

WITHOUT TV RECEPTION/DIGITAL RADIO RECEPTION

U5A

INSTRUMENT CLUSTER, KM/H SPEEDOMETER

UQ5

ELECTRIC INTERFACE FOR EXTERNAL USE, 2 X USB

VF0

STANDARD PEDAL CLUSTER

EFO

WITHOUT ECO FUNCTION

EM0

WITHOUT DRIVER ALERT SYSTEM

F0A

NO SPECIAL PURPOSE VEHICLE, STANDARD EQUIPMENT

G01

SHOCK ABSORPTION IN FRONT

GP0

VEHICLES WITHOUT SPECIAL UPGRADE MEASURES

I8F

STANDARD RADIO (GEN2 GP)

KA0

WITHOUT CAMERA SYSTEMS/ACCIDENT SENSORS

L04

SUSPENSION RANGE 04 INSTALLATION CONTROL ONLY, NO REQUIREMENT FORECAST

N2H

SEAT TRIM COVERS IN FABRIC

Q1A

STANDARD SEATS IN FRONT

QH0

WITHOUT VOICE CONTROL

QJ1

CHROME PACKAGE

QN4

STORAGE COMPARTMENT UNDER FRONT SEAT(S)

QR8

WITHOUT DYNAMIC ROAD SIGN DISPLAY

TJ4

3-CYLINDER SI ENGINE 1.0 L UNIT 04C.D

UG1

HILL START ASSIST

VOA

TIRES WITHOUT SPECIFICATION OF TIRE BRAND

VL3

X4N

EQUIPMENT OPTIONS SUBSET FOR ROMANIA

Cronologie

S-au găsit 4 înregistrări

Cronologia înregistrărilor pentru acest vehicul

Ultimele înregistrări

01.2020 🌐 Țară necunoscută



A fost fabricat

Țara (sau statul) indică fie locația centrului de producție, uzina de asamblare sau adresa de înregistrare a producătorului. Data poate fi aproximativă.

05.2020 🇷🇴 România



Prima înmatriculare

Înregistrarea reprezintă un eveniment administrativ. Acest lucru ar putea fi legat de o schimbare de proprietar, documente etc

05.2023 🇷🇴 România



A fost verificat

A fost înregistrat un eveniment de inspecție tehnică (cunoscut și sub denumirea de ITP, test tehnic sau test de control al emisiilor). Pot fi incluse atât instanțe reușite, cât și eșuate.

05.2024 🇷🇴 România



Evaluare de daune detectată



Avem indicii că acest vehicul a fost supus unei evaluări de daune în această țară (sau stat). Pentru informații detaliate, te rugăm să consulți secțiunea "Daune" .



+31

Surse de date

Am verificat 900+ de surse de date în **35 de țări**