



Toyota Corolla

VIN: NMTBZ3BE50R039607

Generat pe 2024-04-03 12:35



Contor de parcurs

✓ Arată bine



Situație financiară și juridică

✓ Arată bine



Daune

⚠ Necesită atenție



+31

Surse de date

Am verificat 900+ de surse de date în **35 de țări**

Furt

Vehiculul este în prezent marcat ca furat? A fost furat în trecut? A fost recuperat?



Nu am găsit nicio înregistrare că vehiculul a fost furat.



Verificarea bazei de date a poliției privind vehiculele furate finalizată în **11 țări**:



+5

Iată ce am verificat:



Căutat drept furat

✓ Nu s-a găsit nici o înregistrare



Furat în trecut

✓ Nu s-a găsit nici o înregistrare

Starea actuală
necunoscută



Furat în trecut

✓ Nu s-a găsit nici o înregistrare

Vehiculul a fost recuperat

Baza de date aparținând poliției cu vehicule furate, **verificare finalizată în:**

 România

 Italia

 Slovenia

 Slovacia

 Ucraina

 Statele Unite ale Americii

 Lituania

 Suedia

 Cehia

 Finlanda


 Canada

Contor de parcurs

Există semne conform cărora kilometrajul a fost dat înapoi sau discrepanțe ale kilometrajului?

 Ultimul kilometraj cunoscut: 60.387 km

 4 înregistrări ale kilometrajului



Înregistrări ale contorului de parcurs

2021-04 **14.587 km**

2022-04 **30.215 km**

2023-01 **45.676 km**

2023-10 **60.387 km**

Situație financiară și juridică

Vehiculul a trecut inspecțiile tehnice? Are restricții asupra drepturilor de proprietate sau împrumuturi restante?



Nu s-au găsit restricții financiare pentru acest vehicul

Restricții financiare



Lease

✓ Nu s-a găsit nici o înregistrare

Nu există date disponibile despre împrumuturi restante sau acorduri de finanțare



Leasing operațional

✓ Nu s-a găsit nici o înregistrare

Nu există nici o înregistrare a vehiculului ca fiind în leasing operațional



Unitate de stocare

✓ Nu s-a găsit nici o înregistrare

Nu există nicio înregistrare că vehiculul ar fi sub finanțare pentru stocuri

Legal



Inspecție tehnică

✓ Nu s-a găsit nici o înregistrare

Nu au fost găsite înregistrări ale inspecției tehnice



Casat

✓ Nu s-a găsit nici o înregistrare

Nu există nici o înregistrare că vehiculul a fost marcat drept casat

Daune

Acest vehicul a fost avariat în trecut ? Care a fost valoarea daunelor?




Vehiculul a fost avariat de 3 ori!



Daunele minore nu vor afecta în mod normal siguranța vehiculului și nu vor cauza probleme structurale

Înregistrări de daune



2022-01

România

Daune

Costul estimativ al reparațiilor

**2.001 RON -
6.000 RON**

Cauza posibilă a daunelor

Necunoscut

Categoriile de daune

Sticlă



2023-02

 România

Daune

Costul estimativ al reparațiilor

**6.001 RON -
14.000 RON**


Cauza posibilă a daunelor

Necunoscut

Categorii de daune

Părți exterioare ale caroseriei

Elemente structurale ale caroseriei



2024-01

 România

Daune

Costul estimativ al reparațiilor

**2.001 RON -
6.000 RON**

Cauza posibilă a daunelor

Necunoscut

Categorii de daune

Părți exterioare ale caroseriei

Sticlă

Dezastru natural

Locația vehiculului a fost înregistrată în zona unui dezastru natural?




Locația vehiculului nu a fost înregistrată în zona unui dezastru natural

! Cu toate acestea, pot apărea inexactități ocazionale, mai ales la verificarea vehiculelor mai vechi. Mecanicii din garajele neautorizate deghizează adesea ilegal defecte sau daune ale vehiculului, neînregistrându-le nicăieri. Uneori chiar înlocuiesc plăcuțele VIN ale vehiculului sau efectuează alte acte ilegale. Avem o varietate de metode pentru a detecta chiar și astfel de infracțiuni, dar este imposibil de garantat 100%.

Specificații și echipare

Ce specificații și echipamente sunt înregistrate pentru acest vehicul?

 Verificați dacă specificațiile și echipamentul acestui vehicul se potrivesc cu datele furnizate de vânzător.

Identificare și specificații tehnice



Producător
Toyota



Model
Corolla



Tip caroserie
Sedan



Capacitate cilindrică
1,8 l



Cutie de viteze
Automată



Amplasarea volanului
Volan pe stânga



Descriere motor
1.8L (HEV SPECIAL)



Cod motor
2ZR-FXE

Echipare

CUP HOLDER

FR:2 RR:2

STARTER HOLDING CONTROL

WITHOUT

REAR ARM REST

WITH CUP HOLDER

SUN ROOF & MOON ROOF

WITHOUT

OWNER'S MANUAL

CLEAN AIR FILTER

POLLEN FILTER

ABS

WITH

BACK GLASS

GREEN 70%

OUTSIDE REAR VIEW MIRROR

ELECTRIC, HEATER

SPARE TYRE

WITHOUT

BACK MONITOR

CAMERA + W/H

FRONT FOG LAMPS

WITH (LED + MAT BLK + SILVER)

HEADLAMPS

BI PES HALOGEN + AHB

FENDER LINER

FR (WITH SILENCER) & RR

LIGHT CONTROL SYSTEM

ALC + FMH 3 POSITION

CHILD SEAT

WITHOUT

SEAT BELT WARNING

FR & RR (BUZZER + LAMP)

REAR FOG LAMP

WITH

GLOVE BOX

BIN TYPE W/O LOCK

TOOL (PLANT INSTALL)

H/N WRENCH + JACK HANDLE

SHIFT LEVER & KNOB

LEATHER (CVT)

GRADE PACKAGE

WITHOUT

FRONT SEAT SLIDE

260MM D&P MANUAL

CIGARETTE LIGHTER

WITHOUT

ENGINE MARK

HV

TEMP 125/70D17

DOOR TRIM

FR&RR: HARD WITH NV FELT

AUDIO JACK

W/ USB

FRONT SEAT BELT

D,P: 3ELR + PT + F/L*2

REAR BUMPER

PP PAINT COLOR

DRIVE MODE

TOGGLE DMS 3

REAR COMBINATION LAMP

LED (TAIL/STOP) + BULB (TURN)

SPEEDOMETER

KM/H + RESIN

PAINT PROTECTION WAX/FILM

WITH WRAP TYPE

ACCESSORY CONNECTOR (NO 2)

CONSOLE BOX1

ASSIST GRIP

FR2, RR2

JACK

WITH

GLOVE BOX LAMP

WITH

ASHTRAY

WITHOUT

SAFETY SENSE

TSS2

HIGH MOUNT STOP LAMP

WITH (LED TYPE/CABIN)

DOOR ARM REST

FABRIC

LIGHT REMIND WARNING

WITH (AUTOCUT)

SEAT HEATER

WITH (D+P CUSHION & BACK)

EMERGENCY BRAKE LIGHTS

WITH

RADIATOR LOWER GRILLE

MATERIAL BLACK

BLACK OUT

RADIATOR SP + ID PLATE + SASH

WINDSHIELD DEICER

WITHOUT

FRONT HEADRESTS

VERTICAL X2

SEAT LUMBAR SUPPORT

WITH D (POWER)

DOOR TRIM ORNAMENT

RESIN + SATIN PLATING

STABILIZER

FR & RR

REGULATION COMPLIANCY

WVTA LABEL

INSTRUMENT PANEL

SOFT W/ STITCH (P-PAD)

HOOD SILENCER

WITHOUT

REAR SEAT

6:4 SPLIT FOLD

LUGGAGE AND BACK DOOR RELEASE

CABLE + ELEC LOCK

STEERING COLUMN

TILT & TELESCOPIC

REAR HEADRESTS

VERTICAL*2 + FIXED*1

PARKING BRAKE

EPB

STARTING SYSTEM

PUSH (WITH SMART)

HEADLAMP CLEANER

WITHOUT

TIRE & DISC WHEEL

205/55R16 AL-1

LANE KEEP ASSIST (LKA)

WITH (LTA)

POWER WINDOWS

FR & RR 4 ONE TOUCH UP/DOWN HI

WINDSHIELD WIPER CONTROL

AUTO (RAIN SENSOR)

FRONT SEAT VERTICAL ADJUSTER

D: 2WAY MANUAL

ADDITIONAL HEATER

WITHOUT

BRAKE CONT VALVE- EDB CONTROL

EBD

WINDSHIELD GLASS

LAMINATED GREEN 70% AC

PACKAGE OPTION 3

MID

FRONT WHEEL BRAKE

15" DISC (B)

WIRELESS DOOR LOCK

SMART ENTRY LESS

OVERHEAD CONSOLE

WITH (WITH SOS SW, WITHOUT HOLDER)

TRUNK & DECK CARPET & MAT

NEEDLE PUNCH

RADIATOR GRILLE

BLACK PAINT + PLATING

SWITCH TRONICS

STRAIGHT W/O PADDLE

DESTINATION PACKAGE (EXC/ ERP)

WITHOUT

SPEED WARNING

WITH ASL

CONSOLE BOX

RESIN

DOOR BELT MOULDING

BLACK

SRS AIRBAG

D&P SNGL HI+SD (FR) + CSA + KN

SUN VISOR

PVC (D&P MIRROR + LIGHT)

WHEEL CAP

CENTRE ORNAMENT (FOR ALUMI)

REGISTER

FR & RR: SATIN

DOOR OUTSIDE HANDLE

BODYCOLOUR D: W/ KEY P:W/O

COOLER REAR DUCT

WITH

STEERING WHEEL

3-SPOKE LEATHER

WASHER FLUID LEVEL WARNING

WIRELESS CHARGER

WITHOUT

CLOCK

AUDIO + METER

DOOR INSIDE HANDLE

PLATING

LUGGAGE ROOM LAMP

WITH

BRAKE M/CYLIND & BOOSTER

AHB-R

ACCESSORY CONNECTOR (NO 1)

CONSOLE BOX

COAT HOOK

WITH

CHILD PROTECTOR

WITH (REAR DOOR ONLY)

PACKAGE TRAY TRIM & TONNEAU COVER

GLASS FIBER WITH FELT LO

POWER STEERING

EPS

MIKE & MIKE AMP

WITH (OHC)

FUEL CAUTION LABEL

E5, E10 REG.

DOOR WINDOW FRAME

PLATING

ANTENNA

RR WINDOW + SFIN

EXHAUST EMISSION CONTROL

EURO6D TEMP WITH OBD

COLD AREA PACKAGE

WITHOUT

LUGGAGE TRAY

WITH

BUMPER

PP COLOUR

INSTRUMENT FINISH PANEL

AUDIO PANEL & METER CLUSTER SATIN
(PLATING)

MUD GUARDS

WITHOUT

SHIFT POSITION INDICATOR

WITH (METER)

STEERING WHEEL SWITCHES

DISP (H) + TEL + VOICE + AUDIO + ACC + ASL +
LDA

REAR SEAT BELT

3ELR-PT-FL*2 3ELR*1

I/P UNDER COVER

WITH (D, P)

ACCELERATOR PEDAL

ELECTRIC TYPE

GRADE MARK

WITHOUT

EXHAUST TAIL PIPE & DIFFUSER

SINGLE WITHOUT DIFFUSER

DESTINATION PACKAGE

WITHOUT

DOOR SCUFF PLATE

WITH

CLEARANCE & BACK SONAR

WITHOUT

AIR BAG MANUAL ON-OFF SW

SUB-COLD AREA SPEC

FRONT SEAT

NORMAL

SEAT MATERIAL

FABRIC B MID

KEY PLATE

SMART-MASTER 2

A/C

AUTO (DUAL MODE)

INSIDE REAR VIEW MIRROR

EC MIRROR

HEAD UP DISPLAY

WITHOUT

LANE CHANGE ASSIST

WITHOUT

HILL ASSIST CONTROL (HAC)

WITH (HAC3)

SIDE TURN SIGNAL LAMP

WITH OUTER MIRROR

SHIFT LEVER BOOT

WITH SATIN PLATING + P-BLK BEZEL

ANTI-THEFT LABEL

WITHOUT

FRONT PERSONAL LAMP

WITH (BULB)

LUGGAGE ROOM & DECK TRIM

SIDE (WITH FELT) + RR + 1CON FK

LOWER BACK AND BACK DOOR GARNISH

WITH (PLATING)

POWER DOOR LOCK

P SEAT WITH INDICATOR

DAYTIME RUNNING LIGHT SYSTEM

WITH (LED TYPE)

ENGINE UNDER COVER & PROTECTION

WITH (WITHOUT ACOUSTIC MAT)

FRONT FLOOR CARPET AND MAT

DILOUR (WITH HEEL PAD)

REAR WINDOW DEFOGGER

WITH TIMER

MULTI INFO DISPLAY

WITH (7")

DOOR POCKET

FR&RR

BATTERY

LN1 36AH

CHILD RESTRAINT SYSTEM

ISIZE + TOP TETHER*2

DATA COMMUNICATION MODULE

WITH E-CALL

FLOOR MAT

TEX FM 520G HYBRID

REAR SIDE GLASS

GREEN 70%

CRUISE CONTROL

WITH (FULL RANGE ACC)

ROOM LAMP

PERSONAL TYPE

AUDIO

T1 (8") WITOUT CD WITH BT, USB 6SP

HEATER CONTROL PANEL

AUTO DUAL + SATIN

WITH

TRAFFIC SIGN RECOGNITION

WITH CAMERA

HEADLAMP LEVELLING

MANUAL

VSC

WITH (AHB-R)

ANTI-THEFT SYSTEM

IMMOBILIZER

SEAT BACK POCKET

WITH (PASSENGER ONLY)

I/P CENTER CLUSTER

SATIN PLATING/PIANO BLACK

WASHER FLUID

ETHANOL (FULL)

FRONT SIDE GLASS

GREEN 70%

REAR CONSOLE BOX

FAB W/O STITCH W/ SLIDE P-BLK

ROUGH ROAD PACKAGE

WITHOUT

NCAP

EURO

HEADLAMP AIMING

RH AIMING (FOR LHD CAR)

TYRE INFLATION PRESSURE WARNING

WITH (433MHZ) DIRECT

ILLUMINATED ENTRY SYSTEM

WITH (ROOM + MAP LAMP)

Cronologie

S-au găsit 3 înregistrări

Cronologia înregistrărilor pentru acest vehicul

Ultimele înregistrări

2022-01

 România



Daună detectată 

Avem indicii potrivit cărora acest vehicul a fost recunoscut ca avariat în această țară (sau stat). Pentru detalii, vă rugăm să consultați secțiunea „Daune”.

2023-02

 România



Daună detectată 

Avem indicii potrivit cărora acest vehicul a fost recunoscut ca avariat în această țară (sau stat). Pentru detalii, vă rugăm să consultați secțiunea „Daune”.

2024-01

 România



Daună detectată 

Avem indicii potrivit cărora acest vehicul a fost recunoscut ca avariat în această țară (sau stat). Pentru detalii, vă rugăm să consultați secțiunea „Daune”.



+31

Surse de date

Am verificat 900+ de surse de date în **35 de țări**