



Toyota Corolla

VIN: NMTBZ3BE70R118888

2021

Generat pe 2024-09-10 11:22



Contor de parcurs

✓ Arată bine



Statut legal

✓ Arată bine



Daune

⚠ Necesită atenție



+31

Surse de date

Am verificat 900+ de surse de date în **35 de țări**

Furt

Vehiculul este în prezent marcat ca furat? A fost furat în trecut? A fost recuperat?

✓ Nu s-au găsit probleme

Nu am găsit nicio înregistrare că vehiculul a fost furat.

i Notă

Verificarea bazei de date a poliției privind vehiculele furate finalizată în **10 țări**:



+4

Iată ce am verificat:



Căutat drept furat

✓ Nu s-a găsit nici o înregistrare



Furat în trecut

✓ Nu s-a găsit nici o înregistrare

Starea actuală
necunoscută



Furat în trecut

✓ Nu s-a găsit nici o înregistrare

Vehiculul a fost recuperat

Baza de date aparținând poliției cu vehicule furate, **verificare finalizată în:**

 România

 Statele Unite ale Americii

 Lituania

 Italia

 Slovacia

 Suedia

 Finlanda

 Slovenia

 Canada


 Cehia

Contor de parcurs

Există semne conform cărora kilometrajul a fost dat înapoi sau discrepanțe ale kilometrajului?

Notă

- Ultimul kilometraj cunoscut: 24.000 km
- 2 înregistrări ale kilometrajului



Înregistrări ale contorului de parcurs

2021-01 **13 km**

2022-10 **24.000 km**

Statut legal

A trecut vehiculul inspecțiile tehnice? A fost notat drept casat?



Nu s-au găsit probleme

Nu s-au găsit înregistrări despre statutul legal al acestui vehicul

Legal



Inspecție tehnică

✓ Nu s-a găsit nici o înregistrare

Nu au fost găsite înregistrări ale inspecției tehnice



Casat

✓ Nu s-a găsit nici o înregistrare

Nu există nici o înregistrare că vehiculul a fost marcat drept casat

Daune

Acest vehicul a fost avariat în trecut ? Care a fost valoarea daunelor?

Ai grijă!

Acest vehicul a fost avariat

Notă

Daunele minore nu vor afecta în mod normal siguranța vehiculului și nu vor cauza probleme structurale

Înregistrări de daune



2022-10

 România

Daune

Costul estimativ al reparațiilor

**0 RON -
2.000 RON**

Cauza posibilă a daunelor

Necunoscut

Categoriile de daune

Sticlă

Dezastru natural

Locația vehiculului a fost înregistrată în zona unui dezastru natural?

✓ Nu s-au găsit probleme

Locația vehiculului nu a fost înregistrată în zona unui dezastru natural

Valoarea de piață

Cu cât s-a vândut vehiculul în trecut? Care este în medie prețul vehiculelor din acest model și an?

i Notă

- Prețul mediu de pe piață pentru un astfel de vehicul: 122.005 RON
- Atenție la problemele ascunse dacă vehiculul a fost la vânzare la un preț semnificativ mai mic decât prețul actual!

Valoarea de piață azi pentru Toyota Corolla 2021

Valoarea de piață este determinată prin examinarea prețului unui anumit model de mașină (fabricat în același an) în țara în care a fost generat raportul. Analizăm datele din ultimele 6 luni.

Cel mai mic preț

104.460 RON

Prețul mediu

122.005 RON

Cel mai mare preț

139.430 RON

Emisii

Câte emisii de CO2 produc vehiculele din acest model/an?

i Notă

Emisii CO2: A (102 g/km)

Emisii CO₂

Emisiile CO2 ale
vehiculului tău

102 g/km Clasă **A**

Până la 120

120 - 140

140 - 155

155 - 165

165 - 190

190 - 225

225 și peste

Emisii CO₂ g/km

Specificații și echipare

Ce specificații și echipamente sunt înregistrate pentru acest vehicul?

i Notă

Verificați dacă specificațiile și echipamentul acestui vehicul se potrivesc cu datele furnizate de vânzător.

Identificare și specificații tehnice



Producător
Toyota



Model
Corolla



Tip caroserie
Sedan



An de fabricație
2021



Capacitate cilindrică
1,8 l



Putere motor
72 kW (97 cp)



Cutie de viteze
Automată



Tip transmisie
**Tracțiune față
(FWD)**



Culoare
Gri



Amplasarea volanului
Volan pe stânga



Descriere motor
1.8L (HEV SPECIAL)



Nr. locuri
5



Cod motor
2ZR-FXE

Echipare

Cum a fost primit de la producător

CUP HOLDER

FR:2 RR:2

CLEAN AIR FILTER

POLLEN FILTER

HIGH MOUNT STOP LAMP

WITH (LED/CABIN), PRIVACY

STARTER HOLDING CONTROL

WITHOUT

ABS

WITH

REAR ARM REST

WITH CUP HOLDER

ROCKER & DOOR LOWER MOULDING

WITHOUT

SUN ROOF & MOON ROOF

WITHOUT

OUTSIDE REAR VIEW MIRROR

ELECTRIC, HEATER

OWNER'S MANUAL

WITHOUT

SPARE TYRE

TEMP 125/70D17

BACK MONITOR

CAMERA + W/H

AUDIO

T1 (8") DAB 6SP

DOOR TRIM

FR&RR: HARD WITH NV FELT

FRONT FOG LAMPS

WITH (LED + MAT BLK + SILVER)

AUDIO JACK

W/ USB

REMOTE SERVICE PACKAGE

NOTIFICATION PACKAGE

FRONT SEAT BELT

D,P: 3ELR + PT + F/L*2

PACKAGE OPTION 5

WITHOUT

REAR BUMPER

PP PAINT COLOR

LIGHT CONTROL SYSTEM

ALC + FMH 3 POSITION

DRIVE MODE

TOGGLE DMS 3

VEHICLE APPROACH NOTICE

WITH

CHILD SEAT

WITHOUT

SEAT BELT WARNING

FR & RR (BUZZER + LAMP)

SPEEDOMETER

KM/H + RESIN

REAR FOG LAMP

WITH

PAINT PROTECTION WAX/FILM

WITH WRAP TYPE

GLOVE BOX

BIN TYPE W/O LOCK

ACCESSORY CONNECTOR (NO 2)

CONSOLE BOX1

TOOL (PLANT INSTALL)

H/N WRENCH + JACK HANDLE

PACKAGE OPTION 6

WITHOUT

ASSIST GRIP

FR2, RR2

SHIFT LEVER & KNOB

LEATHER (CVT)

JACK

WITH

GRADE PACKAGE

WITHOUT

GLOVE BOX LAMP

WITH

FRONT SEAT SLIDE

260MM D&P MANUAL

ASHTRAY

WITHOUT

CIGARETTE LIGHTER

WITHOUT

SAFETY SENSE

TSS2

FENDER LINER

FR (WITH FAB) & RR

ENGINE MARK

HV

DOOR ARM REST

FABRIC

STEERING COLUMN

TILT & TELESCOPIC

LIGHT REMIND WARNING

WITH (AUTOCUT)

REAR HEADRESTS

VERTICAL*2 + FIXED*1

SEAT HEATER

WITH (D+P CUSHION & BACK)

PACKAGE OPTION 4

WITHOUT

PARKING BRAKE

EPB

EMERGENCY BRAKE LIGHTS

WITH

STARTING SYSTEM

PUSH (WITH SMART)

RADIATOR LOWER GRILLE

MATERIAL BLACK

HEADLAMP CLEANER

WITHOUT

POWER STEERING

EPS (BRUSHLESS)

BLACK OUT

RADIATOR SP + ID PLATE + SASH

TIRE & DISC WHEEL

205/55R16 AL-1

WINDSHIELD DEICER

WITHOUT

LANE KEEP ASSIST (LKA)

WITH (LTA)

FRONT HEADRESTS

VERTICAL X2

POWER WINDOWS

FR & RR 4 ONE TOUCH UP/DOWN HI

SEAT LUMBAR SUPPORT

WITH D (POWER)

FRONT UNDER PROTECTOR

FR + TANK SIDE + RR

WINDSHIELD WIPER CONTROL

AUTO (RAIN SENSOR)

DOOR TRIM ORNAMENT

RESIN + SATIN PLATING

FRONT SEAT VERTICAL ADJUSTER

D: 2WAY MANUAL

MODEL NAME MARK

COROLLA (RR1)

STEERING WHEEL

3-SPOKE,LEATHER,HEATER

STABILIZER

FR & RR

ADDITIONAL HEATER

WITHOUT

REGULATION COMPLIANCY

WVTA LABEL

BRAKE CONT VALVE- EDB CONTROL

EBD

INSTRUMENT PANEL

SOFT W/ STITCH (P-PAD)

WIRELESS CHARGER

WITH

WINDSHIELD GLASS

LAMINATED GREEN 70% AC

FRONT FLOOR CARPET AND MAT

DILOUR (W/O HEEL PAD)

HOOD SILENCER

WITHOUT

PACKAGE OPTION 3

MID

REAR SEAT

6:4 SPLIT FOLD

FRONT WHEEL BRAKE

15" DISC (B)

LUGGAGE AND BACK DOOR RELEASE

CABLE + ELEC LOCK

WIRELESS DOOR LOCK

SMART ENTRY LESS

OVERHEAD CONSOLE

WITH (WITH SOS SW, WITHOUT HOLDER)

TRUNK & DECK CARPET & MAT

NEEDLE PUNCH

CLOCK

AUDIO + METER

RADIATOR GRILLE

BLACK PAINT + PLATING

DOOR INSIDE HANDLE

PLATING

EXHAUST EMISSION CONTROL (SECOND SPEC IN COSMOS)

EURO 6D RDE#2

SWITCH TRONICS

STRAIGHT W/O PADDLE

LUGGAGE ROOM LAMP

WITH

DESTINATION PACKAGE (EXC/ ERP)

WITHOUT

BRAKE M/CYLIND & BOOSTER

AHB-R

SPEED WARNING

WITH ASL

ACCESSORY CONNECTOR (NO 1)

CONSOLE BOX

CONSOLE BOX

RESIN

COAT HOOK

WITH

DOOR BELT MOULDING

BLACK

CHILD PROTECTOR

WITH (REAR DOOR ONLY)

SRS AIRBAG

D&P SNGL HI+SD (FR) + CSA + KN

PACKAGE TRAY TRIM & TONNEAU COVER

GLASS FIBER WITH FELT LO

SUN VISOR

PVC (D&P MIRROR + LIGHT)

WHEEL CAP

CENTRE ORNAMENT (FOR ALUMI)

MIKE & MIKE AMP

WITH (OHC)

REGISTER

FR & RR: SATIN

FUEL CAUTION LABEL

E5, E10 REG.

DOOR OUTSIDE HANDLE

BODYCOLOUR D: W/ KEY P:W/O

COOLER REAR DUCT

WITH

ANTENNA

RR WINDOW + SFIN

REAR COMBINATION LAMP

LED (STOP/TURN) + MULTI LED (TAIL)

WASHER FLUID LEVEL WARNING

WITHOUT

COLD AREA PACKAGE

SUB-COLD AREA SPEC

LUGGAGE TRAY

WITH

MALTA SPEC

WITHOUT

FRONT SEAT

NORMAL

REAR SIDE GLASS

PRIVACY 20%

BUMPER

PP COLOUR

SEAT MATERIAL

FABRIC B MID

INSTRUMENT FINISH PANEL

AUDIO PANEL & METER CLUSTER SATIN (PLATING)

KEY PLATE

SMART-MASTER 2

HEADLAMPS

BI PES LED + AHB

MUD GUARDS

WITHOUT

A/C

AUTO (DUAL MODE)

SHIFT POSITION INDICATOR

WITH (METER)

INSIDE REAR VIEW MIRROR

EC MIRROR

STEERING WHEEL SWITCHES

DISP (H) + TEL + VOICE + AUDIO + ACC + ASL + LDA

HEAD UP DISPLAY

WITHOUT

REAR SEAT BELT

3ELR-PT-FL*2 3ELR*1

LANE CHANGE ASSIST

WITHOUT

I/P UNDER COVER

WITH (D, P)

HILL ASSIST CONTROL (HAC)

WITH (HAC3)

REAR SPOILER

WITHOUT

ACCELERATOR PEDAL

ELECTRIC TYPE

SIDE TURN SIGNAL LAMP

WITH OUTER MIRROR

GRADE MARK

WITHOUT

SHIFT LEVER BOOT

WITH SATIN PLATING + P-BLK BEZEL

EXHAUST TAIL PIPE & DIFFUSER

SINGLE WITHOUT DIFFUSER

ANTI-THEFT LABEL

WITHOUT

CLEARANCE & BACK SONAR

FRONT+BACK SONAR

DESTINATION PACKAGE

WITHOUT

FRONT PERSONAL LAMP

WITH (BULB)

DOOR SCUFF PLATE

WITH

DOOR WINDOW FRAME

PLATING + RESIN

LUGGAGE ROOM & DECK TRIM

SIDE (WITH FELT) + RR + 1CON FK

BRAND SYMBOL MARK

TOYOTA HV SYMBOL (FR1, RR1)

LOWER BACK AND BACK DOOR GARNISH

WITH (PLATING)

AIR BAG MANUAL ON-OFF SW

P SEAT WITH INDICATOR

POWER DOOR LOCK

WITH

DAYTIME RUNNING LIGHT SYSTEM

WITH (LED TYPE)

TRAFFIC SIGN RECOGNITION

WITH CAMERA

ENGINE UNDER COVER & PROTECTION

WITH (WITHOUT ACOUSTIC MAT)

HEADLAMP LEVELLING

MANUAL

VSC

WITH (AHB-R)

REAR WINDOW DEFOGGER

WITH TIMER

ANTI-THEFT SYSTEM

IMMOBILIZER

MULTI INFO DISPLAY

WITH (7")

SEAT BACK POCKET

WITH (PASSENGER ONLY)

DOOR POCKET

FR&RR

I/P CENTER CLUSTER

SATIN PLATING/PIANO BLACK

BATTERY

LN1 36AH

WASHER FLUID

ETHANOL (FULL)

CHILD RESTRAINT SYSTEM

ISIZE + TOP TETHER*2

FRONT SIDE GLASS

GREEN 70%

DATA COMMUNICATION MODULE

WITH E-CALL

REAR CONSOLE BOX

FAB W/O STITCH W/ SLIDE P-BLK

FLOOR MAT

TEX FM 520G HYBRID

ROUGH ROAD PACKAGE

WITHOUT

BACK GLASS

PRIVACY 20%

NCAP

EURO

CRUISE CONTROL

WITH (FULL RANGE ACC)

HEADLAMP AIMING

RH AIMING (FOR LHD CAR)

ROOM LAMP

PERSONAL TYPE

TYRE INFLATION PRESSURE WARNING

WITH (433MHZ) DIRECT

ILLUMINATED ENTRY SYSTEM

WITH (ROOM + MAP LAMP)

HEATER CONTROL PANEL

AUTO DUAL + SATIN

Cronologie

S-au găsit 3 înregistrări

Cronologia înregistrărilor pentru acest vehicul

Ultimele înregistrări

2021-01

 **Țară necunoscută**



A fost fabricat

Țara (sau statul) indică fie locația centrului de producție, uzina de asamblare sau adresa de înregistrare a producătorului. Data poate fi aproximativă.

2021-12

 **România**



A fost înmatriculat

Înregistrarea reprezintă un eveniment administrativ. Acest lucru ar putea fi legat de o schimbare de proprietar, documente etc

2022-10

 România



Daună detectată

Avem indicii potrivit cărora acest vehicul a fost recunoscut ca avariat în această țară (sau stat). Pentru detalii, vă rugăm să consultați secțiunea „Daune”.



+31

Surse de date

Am verificat 900+ de surse de date în **35 de țări**