



Toyota C-HR

VIN:
NMTLY3FX30R011484

Generat pe 2024-07-04 07:49



Contor de parcurs

✓ Arată bine



Statut legal

✓ Arată bine



Daune

✓ Arată bine



+31


Surse de date

Am verificat 900+ de surse de date în **35 de țări**

Fotografii

2020-09

16 fotografii





Furt

Vehiculul este în prezent marcat ca furat? A fost furat în trecut? A fost recuperat?

✓ Nu s-au găsit probleme

Nu am găsit nicio înregistrare că vehiculul a fost furat.

i Notă

Verificarea bazei de date a poliției privind vehiculele furate finalizată în **11 țări**:



+5

Iată ce am verificat:



Căutat drept furat

✓ Nu s-a găsit nici o înregistrare



Furat în trecut

✓ Nu s-a găsit nici o înregistrare

Starea actuală
necunoscută



Furat în trecut

✓ Nu s-a găsit nici o înregistrare

Vehiculul a fost recuperat

Baza de date aparținând poliției cu vehicule furate, **verificare finalizată în:**

 România

 Lituania

 Italia

 Danemarca

 Statele Unite ale Americii

 Slovacia

 Finlanda

 Suedia

 Canada

 Slovenia


 Cehia

Contor de parcurs

Există semne conform cărora kilometrajul a fost dat înapoi sau discrepanțe ale kilometrajului?

Notă

- Ultimul kilometraj cunoscut: 110.970 km
- 11 înregistrări ale kilometrajului



Înregistrări ale contorului de parcurs

2018-06	13 km
2019-02	16.052 km
2019-03	16.936 km
2019-11	32.527 km
2020-05	44.317 km
2020-09	50.318 km

Înregistrări ale contorului de parcurs

2021-04	50.458 km
2021-11	65.541 km
2022-08	80.668 km
2023-03	98.001 km
2023-11	110.970 km

Statut legal

A trecut vehiculul inspecțiile tehnice? A fost notat drept casat?



Nu s-au găsit probleme

Nu s-au găsit înregistrări despre statutul legal al acestui vehicul

Legal



Inspecție tehnică

✓ Nu s-a găsit nici o înregistrare

Nu au fost găsite înregistrări ale inspecției tehnice



Casat

✓ Nu s-a găsit nici o înregistrare

Nu există nici o înregistrare că vehiculul a fost marcat drept casat

Daune

Acest vehicul a fost avariat în trecut ? Care a fost valoarea daunelor?

✓ Nu s-au găsit probleme

Înregistrări de daune



Ocazional pot apărea inexactități, mai ales la verificarea vehiculelor vechi. Atelierele clandestine de reparații pot deghiza ilegal defectele sau daunele vehiculelor, fără să declare nicăieri existența lor. Uneori până și plăcuțele VIN ale vehiculului pot fi înlocuite. Avem o varietate de metode de a detecta chiar și astfel de infracțiuni, dar este imposibil de oferit o garanție de 100%.

Dezastru natural

Locația vehiculului a fost înregistrată în zona unui dezastru natural?

✓ **Nu s-au găsit probleme**
Locația vehiculului nu a fost înregistrată în zona unui dezastru natural

Specificații și echipare

Ce specificații și echipamente sunt înregistrate pentru acest vehicul?

i Notă
Verificați dacă specificațiile și echipamentul acestui vehicul se potrivesc cu datele furnizate de vânzător.

Identificare și specificații tehnice

 Producător Toyota	 Model C-HR	 Tip caroserie SUV
 Capacitate cilindrică 1,2 l	 Cutie de viteze Automată	 Tip transmisie Tracțiune integrală (AWD)
 Nr. uși 5	 Amplasarea volanului Volan pe stânga	 Descriere motor 1.2L TURBO
 Nr. locuri 5	 Cod motor 8NR-FTS	

Echipare

Cum a fost primit de la producător

A/C

AUTO (DUAL MODE)

ACCELERATOR PEDAL

ELECTRIC TYPE

ACCESSORY CONNECTOR (NO 1)

12V

AIR BAG MANUAL ON-OFF SW

WITH

ANTENNA

AM+FM (SHARK FIN)

ANTI-THEFT LABEL

WITHOUT

ANTI-THEFT SYSTEM

IMMOBILIZER

ASSIST GRIP

FR 2

AUDIO

DA+DAB+USB AUX 6SP

BACK GLASS

PRIVACY

BACK MONITOR

BACK CAMERA

BATTERY

EN LN2 (H5)

BODY COLOUR

SOLID TWO-TONE

BRAKE CONT VALVE- EDB CONTROL

EBD

BUMPER

STANDARD

CHILD PROTECTOR

WITH (REAR DOOR ONLY)

CHILD RESTRAINT SYSTEM

ISO-FIX + TOP TETHER*2

CLEAN AIR FILTER

POLLEN FILTER

CLEARANCE & BACK SONAR

IPA

COLD AREA PACKAGE

SUB-COLD AREA SPEC

CONSOLE BOX

WITH LID

CRUISE CONTROL

WITH ACC, ALL SPEED

CUP HOLDER

WITH (FR:2)

DAYTIME RUNNING LIGHT SYSTEM

LED TYPE (WITHOUT OFF SWITCH)

DECK HOOK

WITH

DESTINATION PACKAGE

WITHOUT

DESTINATION PACKAGE (EXC/ ERP)

WITHOUT

DOOR BELT MOULDING

HIGH

DOOR INNER GARNISH

FR COLOUR B

DOOR INSIDE HANDLE

CHROME

DOOR OUTSIDE HANDLE

COLOURED

DOOR POCKET

FR&RR

DOOR TRIM

WITH ILLUMINATION

DOOR WINDOW FRAME

HIGH

DUMMY SPEC

WITHOUT

ECO PACKAGE

WITHOUT

EMV AND NAVIGATION SYSTEM

EXT BOX (HIGH WEST)

EXHAUST EMISSION LABEL

WITHOUT

FLOOR MAT

NEEDLE PUNCH (WITH HEEL PAD)

FRONT FOG LAMPS

WITH FOG LAMP (LED)

FRONT HEADRESTS

VERTICAL X2

FRONT PERSONAL LAMP

WITH

FRONT SEAT

SPORTY

FRONT SEAT SLIDE

D&P: 260MM MANUAL

FRONT SEAT VERTICAL ADJUSTER

D: 2WAY MANUAL

FRONT SIDE GLASS

GREEN

FRONT WHEEL BRAKE

16" DISC LS

FUEL CAUTION LABEL

ENGLISH

GLOVE BOX

WITH

GLOVE BOX LAMP

WITH

GRADE PACKAGE

WITHOUT

HEADLAMP AIMING

RH AIMING (FOR LHD CAR)

HEADLAMP CLEANER

WITHOUT

HEADLAMP LEVELLING

AUTO

HEADLAMPS

LED W/ AHB

HIGH MOUNT STOP LAMP

LED

HILL ASSIST CONTROL (HAC)

WITH

I/P CENTER CLUSTER

HIGH

ILLUMINATED ENTRY SYSTEM

ROOM LAMP W/ IP ILLUMINATION

INSIDE REAR VIEW MIRROR

EC MIRROR

INSTRUMENT FINISH PANEL

DYNAMIC

INTERMITTENT WIPER

RAIN SENSOR (AUTO)

JACK

WITHOUT

KEY PLATE

SMART-MASTER 2

KICK DOWN SWITCH SYSTEM

WITH

LANE CHANGE ASSIST

WITH BSM (+RCTA+LCA)

LANE KEEP ASSIST (LKA)

WITH

LIGHT CONTROL SYSTEM

ALC+FMH

LIGHT REMIND WARNING

WITH (AUTOCUT)

LOWER BACK AND BACK DOOR GARNISH

WITH

LUGGAGE AND BACK DOOR RELEASE

ELEC LOCK SMART

LUGGAGE ROOM & DECK TRIM

RR

LUGGAGE ROOM LAMP

WITH

LUGGAGE TRAY

LOW DECK FOR REPAIR KIT

MICROPHONE

WITH

MINUS ION GENERATOR

WITHOUT

MULTI INFO DISPLAY

4.2 COLOUR

OUTSIDE REAR VIEW MIRROR

HEATER A-FOLDING BSM LIGHT

OVER RUN & SPEED LIMIT

WITH

OWNER'S MANUAL

WITHOUT

PACKAGE TRAY TRIM & TONNEAU COVER

FLAT BOARD + NEEDLE PUNCH (REMOVAL)

PAINT PROTECTION WAX/FILM

WRAP GUARD

PARKING BRAKE

EPB

POWER DOOR LOCK

D-KEY LINK

POWER WINDOWS

WITH - ALL AUTO

PRE-CRASH SYSTEM

WITH (GSP)

REAR ARM REST

WITHOUT

REAR BUMPER

WITH

REAR COMBINATION LAMP

LED

REAR HEADRESTS

VERTICAL X3

REAR SEAT

40/60 FOLDING

REAR SEAT BELT

(PT+FL)*2 +(ELR)

REAR SIDE GLASS

PRIVACY

REAR SPOILER

WITH

REAR WINDOW DEFOGGER

WITH (HEAVY WITH TIMER)

REAR WINDOW WIPER

WITH (INT + WASHER)

REFRIGERANT CORRESPONDENT

WITH

REGISTER

COLOUR

REGULATION COMPLIANCY

WVTA NAME PLATE

ROCKER & DOOR LOWER MOULDING

BLACK

ROOM LAMP

DOME LAMP

SEAT BACK POCKET

WITH (DRIVER + PASSENGER)

SEAT BELT WARNING

WITH (D&P/RR LAMP&BUZZER)

SEAT HEATER

WITH (D+P CUSHION & BACK)

SEAT LUMBAR SUPPORT

WITH D (POWER)

SEAT MATERIAL

FABRIC B (DYNAMIC)

SHIFT LEVER & KNOB

LEATHER (CVT)

SHIFT LEVER BOOT

WITH

SIDE TURN SIGNAL LAMP

WITH OUTER MIRROR

SPARE TYRE

WITHOUT (REPAIR KIT)

SRS AIRBAG

WITH (D+P+SIDE+CSA+D-KNEE)

STABILIZER

FR & RR

STARTING SYSTEM

PUSH

STEERING

COLUMN EPS

STEERING COLUMN

TILT & TELESCOPIC (SIMPLE)

STEERING WHEEL

LEATHER

STEERING WHEEL SWITCHES

AU+TEL+VR+DISP(H)+GSP+ASL

SUN VISOR

PVC (D&P MIRROR + LIGHT)

SWITCH TRONICS

SEQUENTIAL

TIRE & DISC WHEEL

225/50R18 AL

TIRE BRAND

UNSPECIFIED

TOOL (PLANT INSTALL)

HOOK 1

TRAFFIC SIGN RECOGNITION

WITH

TRANSFER & CENTER DIFFERENTIAL

GF1A ATC 4WD

TRUNK & DECK CARPET & MAT

NEEDLE PUNCH SINGLE FLOOR

TYRE INFLATION PRESSURE WARNING

WITH

VSC

WITH (WITH CUT-OFF SW+TSR)

WASHER FLUID

ETHANOL (FULL)

WHEEL ARCH MOULDING

BLACK

WHEEL CAP

CENTER ORNAMENT

WINDSHIELD GLASS

GREEN LAMINATED

WIRELESS DOOR LOCK

SMART (D+P+BACK)

WVTA GENERATION SPEC

SEG A

Cronologie

S-au găsit 2 înregistrări

Cronologia înregistrărilor pentru acest vehicul

Ultimele înregistrări

2018-06

 **Țară necunoscută**



A fost înmatriculat

Înregistrarea reprezintă un eveniment administrativ. Acest lucru ar putea fi legat de o schimbare de proprietar, documente etc

2020-09

 **Belgia**



A fost la vânzare

Această înregistrare a fost creată deoarece vehiculul a fost listat pentru vânzare pe o anumită piață. Uneori, țara (sau statul) vânzătorului suprascrie locația reală a vehiculului.



+31

Surse de date

Am verificat 900+ de surse de date în **35 de țări**