

Škoda Octavia



VIN: TMBJG7NE2K0128045

Diesel

2019

Generat pe 2024-12-18 06:44



Odometru

✓ Arată bine



Statut legal

✓ Arată bine



Daune

✓ Arată bine



+31

Surse de date

Am verificat 900+ de surse de date în 35 de țări

Furt

Vehiculul este în prezent marcat ca furat? A fost furat în trecut? A fost recuperat?



Nu s-au găsit probleme

Nu am găsit nicio înregistrare că vehiculul a fost furat.



Notă

Verificarea bazei de date a poliției privind vehiculele furate finalizată în 8 țări: +2

Iată ce am verificat:



Căutat drept furat

✓ Nu s-a găsit nici o înregistrare



Furat în trecut

✓ Nu s-a găsit nici o înregistrare

Starea actuală necunoscută



Furat în trecut

✓ Nu s-a găsit nici o înregistrare

Vehiculul a fost recuperat

Baza de date aparținând poliției cu vehicule furate, **verificare finalizată în:**



România



Danemarca



Statele Unite ale Americii



Lituania



Slovacia




Suedia

Odometru

Există semne conform cărora kilometrajul a fost dat înapoi sau discrepanțe ale kilometrajului?

i Notă

Ultimul kilometraj cunoscut: 153.330 km



Disclaimer (declinarea responsabilității): acest grafic reprezintă o tendință estimată a kilometrajului. Deși se bazează pe înregistrări reale de kilometraj disponibile pentru acest vehicul, există lacune având în vedere că evoluția kilometrajului nu este înregistrată în mod constant. Pentru a lua în considerare aceste date lipsă, aplicăm un model patentat de analiză a datelor care prezice modul în care probabil s-a schimbat kilometrajul între evenimentele înregistrate. Acest lucru ajută la furnizarea unei imagini mai complete a utilizării vehiculului în timp.

Statut legal

A trecut vehiculul inspecțiile tehnice? A fost notat drept casat?

✓ Nu s-au găsit probleme

Nu s-au găsit înregistrări despre statutul legal al acestui vehicul

Legal



Inspecție tehnică periodică (ITP)

✓ Nu s-a găsit nici o înregistrare

Nu au fost găsite înregistrări ale inspecției tehnice



Casat

✓ Nu s-a găsit nici o înregistrare

Nu există nici o înregistrare că vehiculul a fost marcat drept casat

Daune

Acest vehicul a fost avariat în trecut ? Care a fost valoarea daunelor?

✓ Nu s-au găsit probleme

Înregistrări de daune



Ocazional pot apărea inexactități, mai ales la verificarea vehiculelor vechi. Atelierele clandestine de reparații pot deghiza ilegal defectele sau daunele vehiculelor, fără să declare nicăieri existența lor. Uneori până și plăcuțele VIN ale vehiculului pot fi înlocuite. Avem o varietate de metode de a detecta chiar și astfel de infracțiuni, dar este imposibil de oferit o garanție de 100%.

Dezastre naturale

Locația vehiculului a fost înregistrată în zona unui dezastru natural?

✓ **Nu s-au găsit probleme**

Locația vehiculului nu a fost înregistrată în zona unui dezastru natural

Emisii

Câte emisii de CO₂ produc vehiculele din acest model/an?

i **Notă**

Emisii CO₂: A (109 g/km)

Emisii CO₂

Emisiile CO₂ ale
vehiculului tău

109 g/km Clasă **A**

Până la 120

120 - 140

140 - 155

155 - 165

165 - 190

190 - 225

225 și peste

Emisii CO₂ g/km

Specificații și echipare

Ce specificații și echipamente sunt înregistrate pentru acest vehicul?

i **Notă**

Verificați dacă specificațiile și echipamentul acestui vehicul se potrivesc cu datele furnizate de vânzător.

Identificare și specificații tehnice



Producător

Škoda



Model

Octavia



Variantă

Combi



Tip caroserie

Break



An de fabricație

2019



Capacitate cilindrică

1,6 l



Putere motor

85 kW (114 cp)



Tip combustibil

Diesel



Cutie de viteze

Manuală



Tip transmisie

Tracțiune față (FWD)



Culoare

Gri



Nr. uși

4



Amplasarea volanului

Volan pe stânga



Nr. cilindri

4



Nr. locuri

5

Echipare

Cum a fost primit de la producător

0A2

4 DOORS

0AC

FRONT STABILIZER

0B3

WHEELBASE

0BA

WITHOUT REAR STABILIZER

0EJ

INSTALLATION DIFFERENTIATION FOR TRANSMISSION MQ 250 -- VEHICLE COMPONENTS --

0F5

FUEL SYSTEM FOR DIESEL ENGINE

0FA

STANDARD MANUFACTURING SEQUENCE

0K0

WITHOUT ALTERNATIVE DRIVE SYSTEM

0KA

WITHOUT DECALS AND EMBLEMS

0N1

STANDARD REAR AXLE

0P0

REAR EXHAUST TAILPIPE (STANDARD)

0TA

WITHOUT FLOOR MATS

0VC

INFORMATION KIT IN GERMAN

0Y1

STANDARD CLIMATIC ZONES

0YG

WEIGHT RANGE 7 INSTALLATION CONTROL ONLY, NO REQUIREMENT FORECAST

1AT

ELECTRONIC STABILITY CONTROL (ESC)

1D2

TRAILER HITCH, REMOVABLE AND LOCKABLE

1E9

WITHOUT ACTIVATED CARBON CANISTER WITH SCR

1EX

SPECIAL IDENTIFICATION PLATE FOR EC FOR M1 PASSENGER VEHICLE

1G2

STEEL SPARE WHEEL WITH ORIGINAL EQUIPMENT TIRE

1JA

REAR SHOCK ABSORPTION, BASIC VERSION 1

1KD

DISK BRAKES IN REAR

1N3

SPEED-RELATED VARIABLE STEERING ASSIST (SERVOTRONIC)

1NL

TRIMS FOR ALLOY WHEELS

1PF

STANDARD WHEEL BOLTS

1Q0

WITHOUT MASS DAMPER FOR STEERING WHEEL

1S1

TOOL KIT AND JACK

1SA

WITHOUT ADDITIONAL FRONT UNDERBODY GUARD

1U8

WITHOUT FOLDING TABLE ON FRONT SEAT BACKREST

1W2

GLOVE COMPARTMENT COOLING SYSTEM

1X0

FRONT WHEEL DRIVE

1Y3

ELECTRONIC DIFFERENTIAL LOCK XDS DYNAMIC TRACTION CONTROL

1Z0

INITIAL STANDARD FUEL FILLING

1ZF

DISK BRAKES IN FRONT (GEOMET D)

20A

WITHOUT ELECTRIC MOTOR (HYBRID)

2A0

WITHOUT DELIVERY EQUIPMENT

2B1

ADDITIONAL EXTERIOR NOISE SUPPRESSION

2H0

WITHOUT "DRIVE SELECT"

2JQ

SPORTS BUMPERS

2KW

LABELS/PLATES IN GERMAN, FRENCH, AND DUTCH

2V5

FRESH AIR INTAKE SYSTEM WITH COMBINATIONFILTER

2W6

FUEL FILLER CAP

2WA

WITHOUT ADDITIONAL TIRES

2ZW

LEATHER-WRAPPED MULTIFUNCTION STEERING WHEEL, HEATED

3B4

CHILD SEAT ANCHOR FOR CHILD SEAT SYSTEM ISOFIX

3CX

NET PARTITION

3D7

CENTER CONSOLE

3FA

WITHOUT ROOF INSERT (STANDARD ROOF)

3G0

WITHOUT CHILD SEAT ANCHOR FRONT (ISOFIX)

3GA

WITHOUT CARGO AREA

3H0

WITHOUT BACKREST RELEASE FOR FRONT SEATS

3L3

MANUAL HEIGHT ADJUSTMENT FOR FRONT SEATS

3LD

DOOR AND SIDE TRIM PANEL

3N3

STORAGE COMPARTMENTS IN TRUNK

3NU

REAR SEAT BENCH UNSPLIT, BACKREST SPLIT FOLDING WITH CENTER ARMREST

3QC

3-POINT SEAT BELTS IN FRONT

3S7

ROOF RAILS

3T2

THREE REAR HEAD RESTRAINTS

3U2

SLIDING TRUNK COVER

3W6

ADDITIONAL INTERIOR NOISE SUPPRESSION

3X0

WITHOUT LOAD-THROUGH HATCH

3Y0

WITHOUT ROLL-UP SUNSHADE

4A3

SEAT HEATER FOR FRONT SEATS SEPARATELY CONTROLLED

4E7

TAILGATE/TRUNK LID POWER CLOSING

4GX

WINDSHIELD IN HEAT-INSULATING GLASS, HEATED

4I3

CENTRAL LOCKING SYSTEM "KEYLESS ENTRY" WITHOUT SAFELOCK

4KF

SIDE WINDOWS IN HEAT-INSULATING GLASS, FROM B-PILLAR AND REAR WINDOW DARK TINTED

4L6

BREAKAWAY INTERIOR REARVIEW MIRROR, AUTO-DIMMING

4P3

REAR FLOOR PANEL MODULE, TYPE 4

4R4

POWER WINDOWS WITH COMFORT OPERATION AND CIRCUIT BREAKER

4UP

DRIVER AND FRONT PASSENGER AIRBAG WITH KNEE AIRBAG AND FRONT PASSENGER AIRBAG DEACTIVATION

4X3

SIDE AIRBAG IN FRONT, WITH CURTAIN AIRBAG

4ZC

MOLDINGS

5C0

WITHOUT SPECIAL BODY MEASURES

5D1

CARRIER FREQUENCY 433.92 MHZ-434.42 MHZ

5J0

WITHOUT REAR SPOILER

5K7

TRANSPORT PROTECTION FILM (MINIMUM PROTECTION) WITH ADDITIONAL TRANSPORT PROTECTION MEASURES

5RQ

RIGHT EXTERIOR MIRROR, CONVEX

5SJ

LEFT EXTERIOR MIRROR, CONVEX

5TE

DECORATIVE ALUMINUM INSERTS

5XB

SUN VISORS WITH MIRROR AND AIRBAG LABEL ON FRONT PASSENGER SIDE, AND AIRBAG LABEL ON SUN VISOR

5ZF

FRONT HEAD RESTRAINTS

6E3

CENTER ARMREST IN FRONT

6FF

BODY-COLORED EXTERIOR MIRROR HOUSINGS AND VARIOUS ADD-ON PARTS

6K3

FORWARD COLLISION WARNING INCL. AUTONOMOUS EMERGENCY BRAKING, FOR ADAPTIVE CRUISE CONTROL "LOW"

6M0

WITHOUT TIE DOWN STRAPS/NET/POCKET

6N0

WITHOUT MUD FLAP

6PC

HAND BRAKE LEVER HANDLE IN LEATHER

6Q2

LEATHER GEARSHIFT KNOB/HANDLE

6SG

LUGGAGE COMPARTMENT FLOOR COVERING "COMFORT"

6T2

INTERIOR LIGHT IN FOOTWELL IN FRONT AND REAR

6XK

EXTERIOR MIRRORS, AUTO-DIMMING, POWER-FOLDING/ADJUSTABLE/HEATED

7AA

ELECTRONIC ENGINE IMMOBILIZER

7B2

12-VOLT SOCKET IN LUGGAGE BOOT

7E6

ELECTRIC AUXILIARY AIR HEATER

7G0

WITHOUT PREPARATION FOR VTS (VEHICLE TRACKING SYSTEM)

7K1

DIRECT TIRE PRESSURE MONITORING SYSTEM

7L6

START/STOP SYSTEM WITH REGENERATIVE BRAKING

7LM

VEHICLE CLASS DIFFERENTIATION -5E0-

7M5

WITHOUT PROTECTIVE FILM FOR SCUFF PLATE

7N2

SPECTACLE STORAGE COMPARTMENT/BRACKET

7P4

MANUALLY ADJUSTABLE LUMBAR SUPPORT IN FRONT SEATS

7RE

SD CARD (EUROPE)

7UF

NAVIGATION SYSTEM - STANDARD

7W0

WITHOUT EXTENDED SAFETY SYSTEM

7X1

PARK DISTANCE CONTROL

7Y0

WITHOUT LANE CHANGE ASSIST

8G0

WITHOUT LIGHT CONTROL

8GV

ALTERNATOR 180 A

8IX

LED HEADLAMPS WITH CORNERING LIGHT (SEPARATE DAYTIME RUNNING LIGHTS WITH SPECIAL CLASS-A SURFACE)

8K3

SEPARATE DAYTIME RUNNING LIGHTS WITH AUTOMATIC HEADLAMP ACTIVATION AND COMING HOME FEATURE

8M1

REAR WINDOW WIPER AND WASHER SYSTEM WITH INTERMITTENT CONTROL

8N6

WINDSHIELD WIPER INTERMITTENT CONTROL WITH LIGHT/RAIN SENSOR

8Q5

HEADLIGHT RANGE ADJUSTMENT, AUTOMATIC/ DYNAMIC, WITH CORNERING LIGHT (AFS 1)

8QL

KEY FOR LOCKING SYSTEM WITH REMOTE CONTROL

8RM

8 SPEAKERS (PASSIVE)

8S6

2 READING LIGHTS IN FRONT

8SP

LED TAIL LAMP ASSEMBLY

8T7

ADAPTIVE CRUISE CONTROL (WITHOUT "FOLLOW-TO-STOP") AND SPEED LIMITER

8TB

REAR FOG LAMP

8W1

WASHER FLUID LEVEL INDICATOR

8WH

FRONT FOG LAMP AND CORNERING LAMP

8X1

HEADLAMP WASHER SYSTEM

8Y1

TWO-TONE HORN

8Z5

NOT HOT COUNTRY

8ZH

ANTENNA FOR AM/FM RECEPTION, "DIVERSITY"

9AK

CLIMATRONIC WITH IMPACT PRESSURE CONTROL, CFC-FREE

9D0

WITHOUT PREPARATION FOR TWO-WAY RADIO INSTALLATION

9E4

LUGGAGE COMPARTMENT LAMP

9HA

WITHOUT ADDITIONAL MALFUNCTION DISPLAY

9IH

COMFORT TELEPHONY WITH WLAN AND LTE AND WIRELESS CHARGING

9J0

WITHOUT SUPERTONE SYSTEM AND TONE SEQUENCE CONTROL

9JD

SMOKER'S PACKAGE, ASHTRAY IN FRONT

9M0

WITHOUT AUXILIARY HEATER/FUEL-FIRED PARKING HEATER

9P5

VISUAL AND ACOUSTIC SEAT BELT REMINDER, ELECTRIC CONTACT

9S5

MULTI-FUNCTION DISPLAY/ON-BOARD COMPUTER "MEDIUM"

9T1

HEATED WASHER NOZZLES IN FRONT

9TG

ADDITIONAL WARNING LIGHTS (DOOR AREA) INFRONT

9U0

WITHOUT BRAKE PAD WEAR INDICATOR

9WT

MIRRORLINK

9Z0

OPERATING VOLTAGE 12 V

A61

CATEGORY 1

A8D

LUXURY EQUIPMENT

AV1

DRIVING ON THE RIGHT

B01

TYPE APPROVAL COUNTRY GERMANY

B0A

COMPONENT PARTS SET WITHOUT COUNTRY-SPECIFIC BUILDING REGULATION

C32

OPERATING PERMIT, ALTERATION

DK8

4-CYL. TURBO DIES. ENG. 1.6 L/85 KW 4V TDI COMMON RAIL BASE ENGINE IS TJ1/TI7

E0A

NO SPECIAL EDITION

EA0

WITHOUT FOLLOW-ON WARRANTY

EFO

WITHOUT ECO FUNCTION

EL5

ONLINE SERVICE, WITH OCU, WITH HEAD UNIT CODING, WITHOUT ENGINE IMMOBILIZER INTERCONNECTION

EM1

DRIVER ALERT SYSTEM

ER1

REGIONAL CODE " ECE " FOR RADIO

ES0

WITHOUT VEHICLE INLET

F0A

NO SPECIAL PURPOSE VEHICLE, STANDARD EQUIPMENT

FB1

SPECIAL PAINT COATING

FM0

BASIC EQUIPMENT VARIANT

G01

SHOCK ABSORPTION IN FRONT

G0C

5-SPEED MANUAL TRANSMISSION

GM1

STANDARD ELECTRONIC ENGINE SOUND

HH7

TIRES 205/55 R16 91V

I8F

STANDARD RADIO (GEN2 GP)

J0V

BATTERY 420 A (70 AH)

K8D

WAGON/AVANT

KA2

WITH REAR VIEW CAMERA SYSTEM (TYPE 2)

KK3

REFRIGERANT R1234YF

L04

SUSPENSION RANGE 04 INSTALLATION CONTROL ONLY, NO REQUIREMENT FORECAST

L0L

LEFT-HAND DRIVE

N3U

SEAT TRIM COVERS IN LEATHER/FABRIC

ND1

ADAPTER

NZ4

PRIVATE EMERGENCY CALL SYSTEM

Q1A

STANDARD SEATS IN FRONT

QE5

STORAGE COMPARTMENT PACKAGE 3

QG1

SERVICE INTERVAL PROLONGATION

QH1

VOICE CONTROL

QI6

SERVICE INDICATOR 30 000 KM OR 2 YEARS (VARIABLE)

QJ9

CHROME PACKAGE

QK0

WITHOUT MULTIFUNCTION CAMERA

QQ9

INTERIOR AMBIENT LIGHTING, TYPE 2

QR8

WITHOUT DYNAMIC ROAD SIGN DISPLAY

QV3

DIGITAL RADIO RECEPTION

S4V

REGION

S11

PRICE SUPPORT

TJ1

4-CYLINDER DIESEL ENGINE 1.6 L UNIT 04L.1

U30

ALLOY WHEELS 6.5J X 16

U5A

INSTRUMENT CLUSTER, KM/H SPEEDOMETER

UG1

HILL START ASSIST

UH0

PARKING BRAKE

UI5

ELECTRIC INTERFACE FOR EXTERNAL USE, USB (IPOD-CAPABLE)

UK1

STANDARD REAR SEAT RELEASE

V1P

TIRE SUPPLIERS FOR EU COUNTRIES

VF0

STANDARD PEDAL CLUSTER

VL3

EXTENDED AND PROACTIVE PEDESTRIAN PROTECTION

X0A

EQUIPMENT OPTIONS SUBSET FOR GERMANY

Cronologie

S-au găsit 2 înregistrări

Cronologia înregistrărilor pentru acest vehicul

Ultimele înregistrări

2019-01

 Țară necunoscută



A fost fabricat

Țara (sau statul) indică fie locația centrului de producție, uzina de asamblare sau adresa de înregistrare a producătorului. Data poate fi aproximativă.

2024-12

 România



A fost înmatriculat

Înregistrarea reprezintă un eveniment administrativ. Acest lucru ar putea fi legat de o schimbare de proprietar, documente etc



+31

Surse de date

Am verificat 900+ de surse de date în **35 de țări**