

# Škoda Karoq

VIN: TMBLJ7NU9M2022426

Diesel

2020

Generat pe 2024-12-13 06:26



## Odometru

✓ Arată bine



## Statut legal

✓ Arată bine



## Daune

⚠ Necesită atenție



+31

## Surse de date

Am verificat 900+ de surse de date în 35 de țări

## Furt

Vehiculul este în prezent marcat ca furat? A fost furat în trecut? A fost recuperat?



### Nu s-au găsit probleme

Nu am găsit nicio înregistrare că vehiculul a fost furat.



### Notă

Verificarea bazei de date a poliției privind vehiculele furate finalizată în 8 țări: +2

## Iată ce am verificat:



### Căutat drept furat

✓ Nu s-a găsit nici o înregistrare



### Furat în trecut

✓ Nu s-a găsit nici o înregistrare

Starea actuală necunoscută



### Furat în trecut

✓ Nu s-a găsit nici o înregistrare

Vehiculul a fost recuperat

Baza de date aparținând poliției cu vehicule furate, **verificare finalizată în:**

România

Lituania

Statele Unite ale Americii




# Odometru

Există semne conform cărora kilometrajul a fost dat înapoi sau discrepanțe ale kilometrajului?

## Notă

Ultimul kilometraj cunoscut: 157.997 km




**Disclaimer (declinarea responsabilității):** acest grafic reprezintă o tendință estimată a kilometrajului. Deși se bazează pe înregistrări reale de kilometraj disponibile pentru acest vehicul, există lacune având în vedere că evoluția kilometrajului nu este înregistrată în mod constant. Pentru a lua în considerare aceste date lipsă, aplicăm un model patentat de analiză a datelor care prezice modul în care probabil s-a schimbat kilometrajul între evenimentele înregistrate. Acest lucru ajută la furnizarea unei imagini mai complete a utilizării vehiculului în timp.

## Statut legal

A trecut vehiculul inspecțiile tehnice? A fost notat drept casat?

**i Notă**

Inspekția tehnică a fost transmisă pe 2023-12 în  **România**

## Legal



### Inspekție tehnică periodică (ITP)

**A trecut** 2023-12

 **România**

A trecut cu succes inspekția tehnică

Valabil până la 2025-05



### Casat

✓ Nu s-a găsit nici o înregistrare

Nu există nici o înregistrare că vehiculul a fost marcat drept casat

## Daune

Acest vehicul a fost avariat în trecut ? Care a fost valoarea daunelor?

**! Ai grijă!**

Vehiculul a fost avariat de 2 ori!

**i Notă**

Daunele minore nu vor afecta în mod normal siguranța vehiculului și nu vor cauza probleme structurale

## Înregistrări de daune



Daune frontale:

**Față / Parbriz**

2023-05

 România

**Daune**

Costul estimativ al reparațiilor

**0 RON – 2.000 RON**

Cauza posibilă a daunelor

**Necunoscut**

Categorii de daune

Sticlă



Daune frontale:

**Față / Parbriz**

2024-08

 România

**Daune**

Costul estimativ al reparațiilor

**2.001 RON – 6.000 RON**

Cauza posibilă a daunelor

**Necunoscut**

Categorii de daune

Sticlă

**Disclaimer (declinarea responsabilității):** Majoritatea înregistrărilor de daune sunt legate de accidente, dar uneori nu este acesta cazul. Unele înregistrări provin din alte surse cum ar fi serviciile specializate pe lucrări de caroserie, cereri de daune, licitații sau inspecții ale vehiculelor. Aceste înregistrări arată că starea vehiculului a fost evaluată, chiar dacă nu a fost din cauza unui accident.

## Dezastre naturale

Locația vehiculului a fost înregistrată în zona unui dezastru natural?

**Nu s-au găsit probleme**

Locația vehiculului nu a fost înregistrată în zona unui dezastru natural

# Emisii

Câte emisii de CO2 produc vehiculele din acest model/an?

## Notă

Emisii CO2: C (151 g/km)

## Emisii CO<sub>2</sub>

Emisiile CO2 ale  
vehiculului tău

**151 g/km** Clasă **C**

Până la 120

120 - 140

140 - 155

155 - 165

165 - 190

190 - 225

225 și peste

Emisii CO<sub>2</sub> g/km

## Specificații și echipare

Ce specificații și echipamente sunt înregistrate pentru acest vehicul?

## Notă

Verificați dacă specificațiile și echipamentul acestui vehicul se potrivesc cu datele furnizate de vânzător.

## Identificare și specificații tehnice



Producător

**Škoda**



Model

**Karoq**



Tip caroserie

**Break**



An de fabricație

**2020**



An model

**2021**



Capacitate cilindrică

**2 l**




Putere motor


**110 kW (148 cp)**


 Tip combustibil  
**Diesel**


 Cutie de viteze  
**Automată**


 Tip transmisie  
**Tracțiune integrală (AWD)**

 Culoare  
**Albastru**

 Nr. uși  
**4**

 Amplasarea volanului  
**Volan pe stânga**

 Nr. cilindri  
**4**

 Nr. locuri  
**5**

---

## Echipare

Cum a fost primit de la producător

---

0A2

4 DOORS

0AE

FRONT STABILIZER

0B1

WHEELBASE

0BD

REAR STABILIZER

0F5

FUEL SYSTEM FOR DIESEL ENGINE

0J

INSTALLATION DIFFERENTIATION FOR TRANSMISSION "DQ381" -- VEHICLE COMPONENTS --

0K0

WITHOUT ALTERNATIVE DRIVE SYSTEM

0N4

4-LINK REAR SUSPENSION

0NP

NAMEPLATE SET

0P0

REAR EXHAUST TAILPIPE (STANDARD)

0TD

FLOOR MATS IN FRONT AND REAR

0XH

INFORMATION KIT IN ROMANIAN

0Y1

STANDARD CLIMATIC ZONES

0YD

WEIGHT RANGE 4 INSTALLATION CONTROL ONLY, NO REQUIREMENT FORECAST

1AT

ELECTRONIC STABILITY CONTROL (ESC)

1D0

WITHOUT TRAILER HITCH

1E9

WITHOUT ACTIVATED CARBON CANISTER WITH SCR

1EX

SPECIAL IDENTIFICATION PLATE FOR EC FOR M1 PASSENGER VEHICLE

1G9

SPACE-SAVING SPARE WHEEL FOR TEMPORARY USE, RADIAL TIRE (5-HOLE)

1L1

AIR CLEANER FOR DUSTY REGIONS

1N3

SPEED-RELATED VARIABLE STEERING ASSIST (SERVOTRONIC)

1NL

TRIMS FOR ALLOY WHEELS

1PF

STANDARD WHEEL BOLTS

1S1

TOOL KIT AND JACK

1SA

WITHOUT ADDITIONAL FRONT UNDERBODY GUARD

1U8

WITHOUT FOLDING TABLE ON FRONT SEAT BACKREST

1X1

FOUR WHEEL DRIVE

1Z0

INITIAL STANDARD FUEL FILLING

1ZK

DISK BRAKES IN FRONT

20A

WITHOUT ELECTRIC MOTOR ( HYBRID )

2A0

WITHOUT DELIVERY EQUIPMENT

2B1

ADDITIONAL EXTERIOR NOISE SUPPRESSION

2EJ

DISK BRAKES IN REAR

2F0

WITHOUT LOCKING AND STARTING SYSTEMS

2H5

DRIVING PROFILE SELECTION AND CONVENTIONAL SHOCK ABSORBER

2JB

STANDARD BUMPERS



2KL

LABELS/PLATES IN ROMANIAN AND ENGLISH

2W6

FUEL FILLER CAP

2ZA

MULTIFUNCTION STEERING WHEEL

3B4

CHILD SEAT ANCHOR FOR CHILD SEAT SYSTEM ISOFIX

3CA

WITHOUT PARTITION

3FA

WITHOUT ROOF INSERT (STANDARD ROOF)

3G0

WITHOUT CHILD SEAT ANCHOR FRONT (ISOFIX)

3GG

PLANE REAR CARGO AREA

3H0

WITHOUT BACKREST RELEASE FOR FRONT SEATS

3L3

MANUAL HEIGHT ADJUSTMENT FOR FRONT SEATS

3LD

DOOR AND SIDE TRIM PANEL

3N6

MOUNTING FIXTURE IN LUGGAGE COMPARTMENT

3NU

REAR SEAT BENCH UNSPLIT, BACKREST SPLIT FOLDING WITH CENTER ARMREST

3QT

3-POINT SEAT BELTS IN FRONT, WITH PRETENSIONER AND HEIGHT ADJUSTMENT

3S2

BLACK ROOF RAILS

3T2

THREE REAR HEAD RESTRAINTS

3W3

SPECIAL INTERIOR NOISE SUPPRESSION

3X0

WITHOUT LOAD-THROUGH HATCH

3ZU

3-POINT SEAT BELTS, OUTER REAR WITH ECE LABEL

4A3

SEAT HEATER FOR FRONT SEATS SEPARATELY CONTROLLED

4E6

SENSOR-CONTROLLED LUGGAGE COMPARTMENT OPENER

4GF

WINDSHIELD IN HEAT-INSULATING GLASS

4H3

MANUAL CHILD SAFETY LOCK

4I3

CENTRAL LOCKING SYSTEM "KEYLESS ENTRY" WITHOUT SAFELOCK

4KC

SIDE AND REAR WINDOWS IN HEAT-INSULATINGGLASS

4L6

BREAKAWAY INTERIOR REARVIEW MIRROR, AUTO-DIMMING

4P6

REAR FLOOR PANEL MODULE, TYPE 7

4R4

POWER WINDOWS WITH COMFORT OPERATION ANDCIRCUIT BREAKER

4UP

DRIVER AND FRONT PASSENGER AIRBAG WITH KNEE AIRBAG AND FRONT PASSENGER AIRBAG DEACTIVATION

4X3

SIDE AIRBAG IN FRONT, WITH CURTAIN AIRBAG

4ZE

BLACK MOLDINGS

5C0

WITHOUT SPECIAL BODY MEASURES

5D1

CARRIER FREQUENCY 433.92 MHZ-434.42 MHZ

5J3

ROOF SPOILER

5K5

TRANSIT COATING FILM WITH ADDITIONAL TRANSPORT PROTECTION MEASURES

5ML

DECORATIVE INSERTS

5N4

FOLDING GRAB HANDLES, MULTI-PIECE

5RQ

RIGHT EXTERIOR MIRROR, CONVEX

5SJ

LEFT EXTERIOR MIRROR, CONVEX

5XC

SUN VISORS WITH ILLUMINATED VANITY MIRROR ON DRIVER AND FRONT PASSENGER SIDE

5ZF

FRONT HEAD RESTRAINTS

6E3

CENTER ARMREST IN FRONT

6EA

WITHOUT ADDITIONAL SIDE BODY COVERS (STONE GUARD)

6F0

WITHOUT DECORATIVE FILMS / EMBLEMS

6FF

BODY-COLORED EXTERIOR MIRROR HOUSINGS AND VARIOUS ADD-ON PARTS

6I0

WITHOUT LANE KEEPING SYSTEM

6K4

FORWARD COLLISION WARNING INCL. AUTONOMOUS EMERGENCY BRAKING, FOR ADAPTIVE CRUISE CONTROL "HIGH"

6KD

RADIATOR GRILLE

6M3

TRUNK NET

6N0

WITHOUT MUD FLAP

6Q2

LEATHER GEARSHIFT KNOB/HANDLE

6SE

LUGGAGE COMPARTMENT FLOOR COVERING IN FLAT NEEDLE-PUNCHED NONWOVEN

6T5

INTERIOR LIGHT IN FOOTWELL IN FRONT AND REAR

6XK

EXTERIOR MIRRORS, AUTO-DIMMING, POWER-FOLDING/ADJUSTABLE/HEATED

7AA

ELECTRONIC ENGINE IMMOBILIZER

7B2

12-VOLT SOCKET IN LUGGAGE BOOT

7E6

ELECTRIC AUXILIARY AIR HEATER

7K1

DIRECT TIRE PRESSURE MONITORING SYSTEM

7L6

START/STOP SYSTEM WITH REGENERATIVE BRAKING

7LY

VEHICLE CLASS DIFFERENTIATION -5EP-

7M0

PLASTIC SCUFF PLATES IN DOOR APERTURES

7N2

SPECTACLE STORAGE COMPARTMENT/BRACKET

7P4

MANUALLY ADJUSTABLE LUMBAR SUPPORT IN FRONT SEATS

7UH

PREPARATION FOR NAVIGATION SYSTEM (MIB)

7W0

WITHOUT EXTENDED SAFETY SYSTEM

7X1

PARK DISTANCE CONTROL

7Y0

WITHOUT LANE CHANGE ASSIST

8AR

RADIO "GAMMA" WITH REMOVABLE OPERATING PANEL

8G0

WITHOUT LIGHT CONTROL

8GU

ALTERNATOR 140 A

8IX

LED HEADLAMPS WITH CORNERING LIGHT (SEPARATE DAYTIME RUNNING LIGHTS WITH SPECIAL CLASS-A SURFACE)

8K3

SEPARATE DAYTIME RUNNING LIGHTS WITH AUTOMATIC HEADLAMP ACTIVATION AND COMING HOME FEATURE

8M1

REAR WINDOW WIPER AND WASHER SYSTEM WITH INTERMITTENT CONTROL

8N6

WINDSHIELD WIPER INTERMITTENT CONTROL WITH LIGHT/RAIN SENSOR

8Q5

HEADLIGHT RANGE ADJUSTMENT, AUTOMATIC/ DYNAMIC, WITH CORNERING LIGHT (AFS 1)

8QL

KEY FOR LOCKING SYSTEM WITH REMOTE CONTROL

8RM

8 SPEAKERS (PASSIVE)

8S6

2 READING LIGHTS IN FRONT

8T8

ADAPTIVE CRUISE CONTROL (WITH "FOLLOW-TO-STOP") AND SPEED LIMITER

8TB

REAR FOG LAMP

8W1

WASHER FLUID LEVEL INDICATOR

8WH

FRONT FOG LAMP AND CORNERING LAMP

8X1

HEADLAMP WASHER SYSTEM

8Y1

TWO-TONE HORN

8Z5

NOT HOT COUNTRY

8ZQ

ANTENNA FOR FM RECEPTION ONLY, DIVERSITY

9AK

CLIMATRONIC WITH IMPACT PRESSURE CONTROL, CFC-FREE

9HA

WITHOUT ADDITIONAL MALFUNCTION DISPLAY

9J0

WITHOUT SUPERTONE SYSTEM AND TONE SEQUENCE CONTROL

9JD

SMOKER'S PACKAGE, ASHTRAY IN FRONT

9M0

WITHOUT AUXILIARY HEATER/FUEL-FIRED PARKING HEATER

9P9

SEAT BELT REMINDER, ELECTRIC CONTACT IN THE BUCKLE, ADVANCED SAFETY EQUIPMENT

9S6

MULTI-FUNCTION DISPLAY/ON-BOARD COMPUTER"COLOUR"

9T0

WITHOUT HEATED WASHER NOZZLES

9TC

ADDITIONAL REFLECTORS (DOOR AREA)

9U1

BRAKE PAD WEAR INDICATOR

9WJ

POWER SUPPLY/TV SIGNAL FOR CUSTOMIZED INSTALLATION

9Z0

OPERATING VOLTAGE 12 V

9ZX

MOBILE PHONE INTERFACE

A8D

LUXURY EQUIPMENT

AV1

DRIVING ON THE RIGHT

B0A

COMPONENT PARTS SET WITHOUT COUNTRY-SPECIFIC BUILDING REGULATION

B43

TYPE APPROVAL COUNTRY ROMANIA

C18

OPERATING PERMIT, ALTERATION

CD2

ALLOY WHEELS 7J X 17

DN4

4-CYL. TURBO DIESEL ENGINE 2.0 L/110 KW (4V) TDI COMMON RAIL; B.ENGINE T37/T6F  
TS1/TR1/T0P/T0N/T13/T29/TM4/TD1/TI9/T1I

E0A

NO SPECIAL EDITION

EA2

1 YEAR FOLLOW-ON WARRANTY, MAX. 60 000 KM

EF1

ECO FUNCTION

EG0

WITHOUT EMBLEM PACKAGE

EL5

ONLINE SERVICE, WITH OCU, WITH HEAD UNITCODING, WITHOUT ENGINE IMMOBILIZER INTERCONNECTION

EM0

WITHOUT DRIVER ALERT SYSTEM

ER1

REGIONAL CODE " ECE " FOR RADIO

ES0

WITHOUT VEHICLE INLET

F0A

NO SPECIAL PURPOSE VEHICLE, STANDARD EQUIPMENT

FB0

STANDARD PAINT COATING

FM0

BASIC EQUIPMENT VARIANT

G01



SHOCK ABSORPTION IN FRONT

G1D

7-SPEED AUTOMATIC TRANSMISSION FOR FOUR-WHEEL DRIVE

GM1

STANDARD ELECTRONIC ENGINE SOUND

IA0

WITHOUT BRACKET

IG1

CURB WEIGHT RANGE 1

IN1

REAR AXLE WEIGHT, TYPE 1

J0V

BATTERY 420 A (70 AH)

K8P

MPV

KA0

WITHOUT CAMERA SYSTEMS/ACCIDENT SENSORS

KK3

REFRIGERANT R1234YF

L03

SUSPENSION RANGE 03 INSTALLATION CONTROL ONLY, NO REQUIREMENT FORECAST

L0L

LEFT-HAND DRIVE

N3C

SEAT TRIM COVERS IN FABRIC

ND0

WITHOUT ADAPTER

NZ2

PAN-EUROPEAN EMERGENCY CALL SERVICE

Q2J

COMFORT SEATS IN FRONT

QE5

STORAGE COMPARTMENT PACKAGE 3

QG1

SERVICE INTERVAL PROLONGATION

QH1

VOICE CONTROL

QI6

SERVICE INDICATOR 30 000 KM OR 2 YEARS ( VARIABLE )

QJ3

CHROME PACKAGE (TYPE 2)

QK0

WITHOUT MULTIFUNCTION CAMERA

QQ9

INTERIOR AMBIENT LIGHTING, TYPE 2

QR8

WITHOUT DYNAMIC ROAD SIGN DISPLAY

QV3

DIGITAL RADIO RECEPTION

T6M

4-CYLINDER DIESEL ENGINE 2.0 L UNIT 05L.C

U5A

INSTRUMENT CLUSTER, KM/H SPEEDOMETER

U9B

1 X USB TYPE C AND CD PLAYER

UC7

REAR SHOCK ABSORPTION, SUSPENSION WITH INCREASED RIDE HEIGHT

UG1

HILL START ASSIST

UH2

PARKING BRAKE

UK3

MECHANICAL REAR SEAT RELEASE

V0A

TIRES WITHOUT SPECIFICATION OF TIRE BRAND

VF0

STANDARD PEDAL CLUSTER

VL3

EXTENDED AND PROACTIVE PEDESTRIAN PROTECTION

X4N

EQUIPMENT OPTIONS SUBSET FOR ROMANIA

## Cronologie

S-au găsit 5 înregistrări

Cronologia înregistrărilor pentru acest vehicul

### Ultimele înregistrări

2020-01

 Țară necunoscută



#### A fost fabricat

Țara (sau statul) indică fie locația centrului de producție, uzina de asamblare sau adresa de înregistrare a producătorului. Data poate fi aproximativă.

2020-11

 România



#### A fost înmatriculat

Înregistrarea reprezintă un eveniment administrativ. Acest lucru ar putea fi legat de o schimbare de proprietar, documente etc

2023-05

 România



#### Daună detectată



Avem indicii potrivit cărora acest vehicul a fost recunoscut ca avariat în această țară (sau stat). Pentru detalii, vă rugăm să consultați secțiunea „Daune”.

2023-12

 România



### A fost verificat

A fost înregistrat un eveniment de inspecție tehnică (cunoscut și sub denumirea de ITP, test tehnic sau test de control al emisiilor). Pot fi incluse atât instanțe reușite, cât și eșuate.

2024-08

 România



### Daună detectată

Avem indicii potrivit cărora acest vehicul a fost recunoscut ca avariat în această țară (sau stat). Pentru detalii, vă rugăm să consultați secțiunea „Daune”.



+31

### Surse de date

Am verificat 900+ de surse de date în **35 de țări**