

Škoda Superb

VIN: TMBLJ9NP8H7542387

Diesel

2017

Generat pe 2024-12-20 12:00



Odometru

✓ Arată bine



Statut legal

✓ Arată bine



Daune

✓ Arată bine



+31

Surse de date

Am verificat 900+ de surse de date în 35 de țări

Furt

Vehiculul este în prezent marcat ca furat? A fost furat în trecut? A fost recuperat?



Nu s-au găsit probleme

Nu am găsit nicio înregistrare că vehiculul a fost furat.



Notă

Verificarea bazei de date a poliției privind vehiculele furate finalizată în 8 țări: +2

Iată ce am verificat:



Căutat drept furat

✓ Nu s-a găsit nici o înregistrare



Furat în trecut

✓ Nu s-a găsit nici o înregistrare

Starea actuală necunoscută



Furat în trecut

✓ Nu s-a găsit nici o înregistrare

Vehiculul a fost recuperat

Baza de date aparținând poliției cu vehicule furate, **verificare finalizată în:**

România

Danemarca

Statele Unite ale Americii

Lituania

Italia


Slovacia

Odometru

Există semne conform cărora kilometrajul a fost dat înapoi sau discrepanțe ale kilometrajului?

Notă

Ultimul kilometraj cunoscut: 241.092 km



Disclaimer (declinarea responsabilității): acest grafic reprezintă o tendință estimată a kilometrajului. Deși se bazează pe înregistrări reale de kilometraj disponibile pentru acest vehicul, există lacune având în vedere că evoluția kilometrajului nu este înregistrată în mod constant. Pentru a lua în considerare aceste date lipsă, aplicăm un model patentat de analiză a datelor care prezice modul în care probabil s-a schimbat kilometrajul între evenimentele înregistrate. Acest lucru ajută la furnizarea unei imagini mai complete a utilizării vehiculului în timp.

Statut legal

A trecut vehiculul inspecțiile tehnice? A fost notat drept casat?

✓ Nu s-au găsit probleme

Nu s-au găsit înregistrări despre statutul legal al acestui vehicul

Legal



Inspecție tehnică periodică (ITP)

✓ Nu s-a găsit nici o înregistrare

Nu au fost găsite înregistrări ale inspecției tehnice



Casat

✓ Nu s-a găsit nici o înregistrare

Nu există nici o înregistrare că vehiculul a fost marcat drept casat

Daune

Acest vehicul a fost avariat în trecut ? Care a fost valoarea daunelor?

✓ Nu s-au găsit probleme

Înregistrări de daune



Ocazional pot apărea inexactități, mai ales la verificarea vehiculelor vechi. Atelierele clandestine de reparații pot deghiza ilegal defectele sau daunele vehiculelor, fără să declare nicăieri existența lor. Uneori până și plăcuțele VIN ale vehiculului pot fi înlocuite. Avem o varietate de metode de a detecta chiar și astfel de infracțiuni, dar este imposibil de oferit o garanție de 100%.

Dezastre naturale

Locația vehiculului a fost înregistrată în zona unui dezastru natural?

✓ **Nu s-au găsit probleme**

Locația vehiculului nu a fost înregistrată în zona unui dezastru natural

Emisii

Câte emisii de CO₂ produc vehiculele din acest model/an?

i **Notă**

Emisii CO₂: B (134 g/km)

Emisii CO₂

Emisiile CO₂ ale
vehiculului tău

134 g/km Clasă **B**

Până la 120

120 - 140

140 - 155

155 - 165

165 - 190

190 - 225

225 și peste

Emisii CO₂ g/km

Specificații și echipare

Ce specificații și echipamente sunt înregistrate pentru acest vehicul?

i **Notă**

Verificați dacă specificațiile și echipamentul acestui vehicul se potrivesc cu datele furnizate de vânzător.

Identificare și specificații tehnice



Producător

Škoda



Model

Superb



Tip caroserie

Break



An de fabricație

2017



Capacitate cilindrică

2 l



Putere motor

140 kW (188 cp)



Cuplu

400 Nm



Tip combustibil

Diesel



Cutie de viteze

Automată



Tip transmisie

Tracțiune integrală (AWD)



Culoare

Gri



Nr. uși

5



Amplasarea volanului

Volan pe stânga



Nr. cilindri

4



Nr. angrenaje

6

Echipare

Cum a fost primit de la producător

0B5

WHEELBASE

0ES

INSTALLATION DIFFERENTIATION FOR TRANSMISSION DQ250 -- VEHICLE COMPONENTS --

0F5

FUEL SYSTEM FOR DIESEL ENGINE

0FA

STANDARD MANUFACTURING SEQUENCE

0G7

TIPTRONIC

0K0

WITHOUT ALTERNATIVE DRIVE SYSTEM

0M4

FUEL TANK

0P0

REAR EXHAUST TAILPIPE (STANDARD)

0SB

LABELS/PLATES IN GERMAN

0TA

WITHOUT FLOOR MATS

0VC

INFORMATION KIT IN GERMAN

0Y1

STANDARD CLIMATIC ZONES

0YE

WEIGHT RANGE 5 INSTALLATION CONTROL ONLY, NO REQUIREMENT FORECAST

1AT

ELECTRONIC STABILITY CONTROL (ESC)

1D0

WITHOUT TRAILER HITCH

1E9

WITHOUT ACTIVATED CARBON CANISTER WITH SCR

1EX

SPECIAL IDENTIFICATION PLATE FOR EC FOR M1 PASSENGER VEHICLE

1G8

BREAKDOWN KIT

1JA

REAR SHOCK ABSORPTION, BASIC VERSION 1

1KU

DISK BRAKES IN REAR

1N3

SPEED-RELATED VARIABLE STEERING ASSIST (SERVOTRONIC)

1NL

TRIMS FOR ALLOY WHEELS

1PA

STANDARD WHEEL BOLTS

1Q3

MASS DAMPER FOR STEERING WHEEL, XX HZ

1S3

TOOL KIT

1SA

WITHOUT ADDITIONAL FRONT UNDERBODY GUARD

1VG

INSTALLATION PARTS FOR FOUR-CYLINDER ENGINE

1X1

FOUR WHEEL DRIVE

1Y3

ELECTRONIC DIFFERENTIAL LOCK XDS DYNAMIC TRACTION CONTROL

1Z0

INITIAL STANDARD FUEL FILLING

1ZA

DISK BRAKES IN FRONT

20A

WITHOUT ELECTRIC MOTOR (HYBRID)

2A0

WITHOUT DELIVERY EQUIPMENT

2B1

ADDITIONAL EXTERIOR NOISE SUPPRESSION

2G5

FILLER NECK MODULE 1 WITHOUT INSERT

2H0

WITHOUT "DRIVE SELECT"

2JV

BODY-COLORED BUMPERS

2PK

LEATHER-WRAPPED MULTIFUNCTION SPORTS STEERING WHEEL W/ TIPTRONIC

2WA

WITHOUT ADDITIONAL TIRES

3B4

CHILD SEAT ANCHOR FOR CHILD SEAT SYSTEM ISOFIX

3C7

3-POINT SEAT BELT FOR CENTER REAR SEAT

3CA

WITHOUT PARTITION

3D2

CENTER CONSOLE

3FA

WITHOUT ROOF INSERT (STANDARD ROOF)

3G0

WITHOUT CHILD SEAT ANCHOR FRONT (ISOFIX)

3GN

VARIABLE CARGO AREA

3H0

WITHOUT BACKREST RELEASE FOR FRONT SEATS

3L4

POWER SEAT ADJUSTMENT FOR BOTH FRONT SEATS, DRIVER SEAT WITH MEMORY FEATURE

3LC

DOOR AND SIDE TRIM PANEL IN FOAM FILM AND WOVEN FABRIC

3N2

STORAGE COMPARTMENTS WITH COVER IN TRUNKSIDE PANEL

3NU

REAR SEAT BENCH UNSPLIT, BACKREST SPLIT FOLDING WITH CENTER ARMREST

3QT

3-POINT SEAT BELTS IN FRONT, WITH PRETENSIONER AND HEIGHT ADJUSTMENT

3S9

ROOF RAILS

3T2

THREE REAR HEAD RESTRAINTS

3U2

SLIDING TRUNK COVER

3W3

SPECIAL INTERIOR NOISE SUPPRESSION

3X0

WITHOUT LOAD-THROUGH HATCH

3Y0

WITHOUT ROLL-UP SUNSHADE

3ZU

3-POINT SEAT BELTS, OUTER REAR WITH ECE LABEL

4A3

SEAT HEATER FOR FRONT SEATS SEPARATELY CONTROLLED

4D0

WITHOUT SEAT VENTILATION/MASSAGE SEAT

4E2

TAILGATE/TRUNK LID RELEASE FROM INSIDE (ELECTRICALLY)

4GW

HEAT INSULATING WINDSHIELD

4H5

POWER-OPERATED CHILD SAFETY LOCK

4I2

CENTRAL LOCKING WITH RADIO REMOTE CONTROL, INTERIOR RELEASE MECHANISM WITHOUT SAFELOCK

4KC

SIDE AND REAR WINDOWS IN HEAT-INSULATING GLASS

4L6

BREAKAWAY INTERIOR REARVIEW MIRROR, AUTO-DIMMING

4UP

DRIVER AND FRONT PASSENGER AIRBAG WITH KNEE AIRBAG AND FRONT PASSENGER AIRBAG DEACTIVATION

4V0

WITHOUT FRONT PASSENGER SEAT CONTROL

4X4

SIDE AIRBAG IN FRONT AND REAR WITH CURTAIN AIRBAG

4ZB

BRIGHT MOLDINGS

5C0

WITHOUT SPECIAL BODY MEASURES

5D1

CARRIER FREQUENCY 433.92 MHZ-434.42 MHZ

5J3

ROOF SPOILER

5K7

TRANSPORT PROTECTION FILM (MINIMUM PROTECTION) WITH ADDITIONAL TRANSPORT PROTECTION MEASURES

5MC

DECORATIVE INSERTS

5RQ

RIGHT EXTERIOR MIRROR, CONVEX

5SJ

LEFT EXTERIOR MIRROR, CONVEX

5XI

SUN VISORS WITH MIRROR, ILLUMINATED, AIRBAG LABEL ON SUN VISOR

5ZF

FRONT HEAD RESTRAINTS

6A0

WITHOUT FIRE EXTINGUISHER

6E3

CENTER ARMREST IN FRONT

6FF

BODY-COLORED EXTERIOR MIRROR HOUSINGS AND VARIOUS ADD-ON PARTS

6K4

FORWARD COLLISION WARNING INCL. AUTONOMOUS EMERGENCY BRAKING, FOR ADAPTIVE CRUISE CONTROL "HIGH"

6KJ

RADIATOR GRILLE WITH CHROME MOLDING

6M0

WITHOUT TIE DOWN STRAPS/NET/POCKET

6N0

WITHOUT MUD FLAP

6Q2

LEATHER GEARSHIFT KNOB/HANDLE

6T2

INTERIOR LIGHT IN FOOTWELL IN FRONT AND REAR

6XT

EXTERIOR MIRRORS WITH MEMORY FEATURE, AUTO-DIMMING, POWER-FOLDING/ADJUSTABLE, SEPARATELY HEATED

7AA

ELECTRONIC ENGINE IMMOBILIZER

7B3

12-VOLT SOCKET(S)

7E6

ELECTRIC AUXILIARY AIR HEATER

7K1

DIRECT TIRE PRESSURE MONITORING SYSTEM

7L6

START/STOP SYSTEM WITH REGENERATIVE BRAKING

7M3

SCUFF PLATES IN DOOR APERTURES

7MM

EMISSION STANDARD EU6 PLUS

7P1

POWER-ADJUSTABLE LUMBAR SUPPORT IN FRONTSEATS

7Q0

WITHOUT NAVIGATION DEVICE

7QA

WITHOUT CD/DVD FOR NAVIGATION

7U0

STANDARD ENGINE STARTER

7W2

WITH EXTENDED SAFETY SYSTEM (PROACTIVE PASSENGER PROTECTION SYSTEM, BASIC AND FRONT)

7X2

PARK DISTANCE CONTROL IN FRONT AND REAR

7Y9

BLIND SPOT MONITOR AND LANE KEEPING SYSTEM

7ZU

VEHICLE CLASS DIFFERENTIATION 3V0

8FA

WITHOUT SECOND BATTERY

8G1

HIGH-BEAM CONTROL

8GV

ALTERNATOR 180 A

8IP

GAS-DISCHARGE HEADLAMPS WITH VARIABLE LIGHT DISTRIBUTION

8K3

SEPARATE DAYTIME RUNNING LIGHTS WITH AUTOMATIC HEADLAMP ACTIVATION AND COMING HOME FEATURE

8M1

REAR WINDOW WIPER AND WASHER SYSTEM WITH INTERMITTENT CONTROL

8N6

WINDSHIELD WIPER INTERMITTENT CONTROL WITH LIGHT/RAIN SENSOR

8Q5

HEADLIGHT RANGE ADJUSTMENT, AUTOMATIC/ DYNAMIC, WITH CORNERING LIGHT (AFS 1)

8RM

8 SPEAKERS (PASSIVE)

8S4

TWO READING LIGHTS IN FRONT, TWO IN REAR

8SP

LED TAIL LAMP ASSEMBLY

8T8

ADAPTIVE CRUISE CONTROL (WITH "FOLLOW-TO-STOP") AND SPEED LIMITER

8TB

REAR FOG LAMP

8WH

FRONT FOG LAMP AND CORNERING LAMP

8X1

HEADLAMP WASHER SYSTEM

8Y1

TWO-TONE HORN

8Z5

NOT HOT COUNTRY

8ZQ

ANTENNA FOR FM RECEPTION ONLY, DIVERSITY

9AK

CLIMATRONIC WITH IMPACT PRESSURE CONTROL, CFC-FREE

9D0

WITHOUT PREPARATION FOR TWO-WAY RADIO INSTALLATION

9E3

LUGGAGE COMPARTMENT LIGHTING

9HA

WITHOUT ADDITIONAL MALFUNCTION DISPLAY

9JA

NON-SMOKER'S PACKAGE

9M0

WITHOUT AUXILIARY HEATER/FUEL-FIRED PARKING HEATER

9P5

VISUAL AND ACOUSTIC SEAT BELT REMINDER, ELECTRIC CONTACT

9S6

MULTI-FUNCTION DISPLAY/ON-BOARD COMPUTER"COLOUR"

9T1

HEATED WASHER NOZZLES IN FRONT

9TD

WARNING LIGHTS IN FRONT DOORS AND RETRO-REFLECTORS IN REAR DOORS

9WT

MIRRORLINK

9Z0

OPERATING VOLTAGE 12 V

9ZV

COMFORT TELEPHONY, WITHOUT ANTENNA CONNECTION

A61

CATEGORY 1

A8D

LUXURY EQUIPMENT

AV1

DRIVING ON THE RIGHT

B01

TYPE APPROVAL COUNTRY GERMANY

B0A

COMPONENT PARTS SET WITHOUT COUNTRY-SPECIFIC BUILDING REGULATION

C41

OPERATING PERMIT, ALTERATION

C6U

ALLOY WHEELS 7J X 17

DE5

4-CYL. TURBO DIESEL ENGINE 2.0 L/140 KW (4V) TDI COMMON RAIL BASE ENGINE IS TD1/TR1/T5S/T6F

E0A

NO SPECIAL EDITION

EA0

WITHOUT FOLLOW-ON WARRANTY

EF0

WITHOUT ECO FUNCTION

ELO

WITHOUT ONLINE SERVICE

EM0

WITHOUT DRIVER ALERT SYSTEM

ER1

REGIONAL CODE " ECE " FOR RADIO

ES0

WITHOUT VEHICLE INLET

EVO

WITHOUT CHARGING CABLE

F0A

NO SPECIAL PURPOSE VEHICLE, STANDARD EQUIPMENT

FB0

STANDARD PAINT COATING

FM0

BASIC EQUIPMENT VARIANT

G01

SHOCK ABSORPTION IN FRONT

G0R

6-SPEED AUTOMATIC TRANSMISSION FOR FOUR-WHEEL DRIVE VEHICLE

GM1

STANDARD ELECTRONIC ENGINE SOUND

H5C

TIRES 215/55 R17 94W

I8E

STANDARD RADIO (GEN2)

IA0

WITHOUT BRACKET

J2D

BATTERY 380 A (68 AH)

K8D

WAGON/AVANT

KA0

WITHOUT CAMERA SYSTEMS/ACCIDENT SENSORS

KK3

REFRIGERANT R1234YF

KS0

WITHOUT HEAD-UP DISPLAY

L08

SUSPENSION RANGE 08 INSTALLATION CONTROL ONLY, NO REQUIREMENT FORECAST

L0L

LEFT-HAND DRIVE

N0L

SEAT TRIM COVERS IN FABRIC

NS3

WITH UMBRELLA

NZ0

WITHOUT CALL FEATURE

Q2J

COMFORT SEATS IN FRONT

QA0

WITHOUT CHILD SEAT

QG1

SERVICE INTERVAL PROLONGATION

QH1

VOICE CONTROL

QI6

SERVICE INDICATOR 30 000 KM OR 2 YEARS (VARIABLE)

QJ3

CHROME PACKAGE (TYPE 2)

QK1

WITH MULTIFUNCTION CAMERA

QN0

WITHOUT DRAWERS UNDER FRONT SEATS

QQ0

WITHOUT ADD. LIGHTS (INTERIOR LIGHTING)

QR0

WITHOUT COMPASS/ROAD SIGN DISPLAY/ DYNAMIC ROAD SIGN DISPLAY

QV3

DIGITAL RADIO RECEPTION

S11

PRICE SUPPORT

TR1

4-CYLINDER DIESEL ENGINE 2.0 L UNIT 04L.A

U5A

INSTRUMENT CLUSTER, KM/H SPEEDOMETER

UG1

HILL START ASSIST

UH2

PARKING BRAKE

UI4

ELECTRIC INTERFACE FOR EXTERNAL USE, AUX-IN JACK, USB (IPOD-CAPABLE)

UK3

MECHANICAL REAR SEAT RELEASE

UP1

DIGITAL CLOCK

V0A

TIRES WITHOUT SPECIFICATION OF TIRE BRAND

VC0

WITHOUT REMOTE-CONTROLLED GARAGE DOOR OPENER

VF0

STANDARD PEDAL CLUSTER

VL1

EXTENDED PEDESTRIAN PROTECTION MEASURES

X0A

EQUIPMENT OPTIONS SUBSET FOR GERMANY

Cronologie

S-au găsit 2 înregistrări

Cronologia înregistrărilor pentru acest vehicul

Ultimele înregistrări

2017-01

 Țară necunoscută



A fost fabricat

Țara (sau statul) indică fie locația centrului de producție, uzina de asamblare sau adresa de înregistrare a producătorului. Data poate fi aproximativă.

2024-11

 România



A fost înmatriculat

Înregistrarea reprezintă un eveniment administrativ. Acest lucru ar putea fi legat de o schimbare de proprietar, documente etc



+31

Surse de date

Am verificat 900+ de surse de date în **35 de țări**