

Renault Duster

VIN: VF1HJD40967536395

Diesel

2021

Generat pe 2024-12-11 07:25



Odometru

✓ Arată bine



Statut legal

✓ Arată bine



Daune

⚠ Necesită atenție



+31

Surse de date

Am verificat 900+ de surse de date în 35 de țări

Furt

Vehiculul este în prezent marcat ca furat? A fost furat în trecut? A fost recuperat?



Nu s-au găsit probleme

Nu am găsit nicio înregistrare că vehiculul a fost furat.



Notă

Verificarea bazei de date a poliției privind vehiculele furate finalizată în 10 țări: +4

Iată ce am verificat:



Căutat drept furat

✓ Nu s-a găsit nici o înregistrare



Furat în trecut

✓ Nu s-a găsit nici o înregistrare

Starea actuală necunoscută



Furat în trecut

✓ Nu s-a găsit nici o înregistrare

Vehiculul a fost recuperat

Baza de date aparținând poliției cu vehicule furate, **verificare finalizată în:**

România

Statele Unite ale Americii

Lituania

 Slovacia

 Danemarca

 Suedia

 Cehia

 Finlanda

 Italia


 Slovenia

Odometru

Există semne conform cărora kilometrajul a fost dat înapoi sau discrepanțe ale kilometrajului?

Notă

Ultimul kilometraj cunoscut: 137.351 km




Disclaimer (declinarea responsabilității): acest grafic reprezintă o tendință estimată a kilometrajului. Deși se bazează pe înregistrări reale de kilometraj disponibile pentru acest vehicul, există lacune având în vedere că evoluția kilometrajului nu este înregistrată în mod constant. Pentru a lua în considerare aceste date lipsă, aplicăm un model patentat de analiză a datelor care prezice modul în care probabil s-a schimbat kilometrajul între evenimentele înregistrate. Acest lucru ajută la furnizarea unei imagini mai complete a utilizării vehiculului în timp.

Statut legal

A trecut vehiculul inspecțiile tehnice? A fost notat drept casat?

i Notă

Inspecția tehnică a fost transmisă pe 2024-07 în  **România**

Legal



Inspecție tehnică periodică (ITP)

A trecut 2024-07

 **România**

A trecut cu succes inspecția tehnică
Valabil până la 2026-07



Casat

✓ Nu s-a găsit nici o înregistrare

Nu există nici o înregistrare că vehiculul a fost marcat drept casat

Daune

Acest vehicul a fost avariat în trecut ? Care a fost valoarea daunelor?

! Ai grijă!

Vehiculul a fost avariat de 2 ori!

i Notă

Daunele minore nu vor afecta în mod normal siguranța vehiculului și nu vor cauza probleme structurale

Înregistrări de daune



Daune pe partea stângă **Stânga / Portieră față**

Daune frontale: **Față / Bară de protecție**

2022-12

 România

Daune

Costul estimativ al reparațiilor

0 RON - 2.000 RON

Cauza posibilă a daunelor

Necunoscut



Daune frontale: **Față / Parbriz**

2024-07

 România

Daune

Costul estimativ al reparațiilor

0 RON - 2.000 RON

Cauza posibilă a daunelor

Necunoscut

Categoriile de daune

Sticlă

Disclaimer (declinarea responsabilității): Majoritatea înregistrărilor de daune sunt legate de accidente, dar uneori nu este acesta cazul. Unele înregistrări provin din alte surse cum ar fi serviciile specializate pe lucrări de caroserie, cereri de daune, licitații sau inspecții ale vehiculelor. Aceste înregistrări arată că starea vehiculului a fost evaluată, chiar dacă nu a fost din cauza unui accident.

Dezastre naturale

Locația vehiculului a fost înregistrată în zona unui dezastru natural?



Nu s-au găsit probleme

Locația vehiculului nu a fost înregistrată în zona unui dezastru natural

Valoarea de piață

Cu cât s-a vândut vehiculul în trecut? Care este în medie prețul vehiculelor din acest model și an?

i Notă

- Prețul mediu de pe piață pentru un astfel de vehicul: 83.806 RON
- Atenție la problemele ascunse dacă vehiculul a fost la vânzare la un preț semnificativ mai mic decât prețul actual!

Valoarea de piață azi pentru Renault Duster 2021

Valoarea de piață este determinată prin examinarea prețului unui anumit model de mașină (fabricat în același an) în țara în care a fost generat raportul. Analizăm datele din ultimele 6 luni.

Cel mai mic preț

79.203 RON

Prețul mediu

83.806 RON

Cel mai mare preț

88.986 RON

Emisii

Câte emisii de CO2 produc vehiculele din acest model/an?

i Notă

Emisii CO2: C (144 g/km)

Emisii CO₂

Emisiile CO2 ale
vehiculului tău

144 g/km Clasă **C**

Până la 120

120 - 140

140 - 155

155 - 165

165 - 190

190 - 225

225 și peste

Emisii CO₂ g/km

Specificații și echipare

Ce specificații și echipamente sunt înregistrate pentru acest vehicul?

 **Notă**

Verificați dacă specificațiile și echipamentul acestui vehicul se potrivesc cu datele furnizate de vânzător.

Identificare și specificații tehnice



Producător

Renault



Model

Duster



Descriere

Duster



Tip caroserie

SUV



An de fabricație

2021



Capacitate cilindrică

1,5 l



Putere motor

85 kW (114 cp)



Tip combustibil

Diesel



Cutie de viteze

Manuală



Tip transmisie

Tracțiune integrală (AWD)



Culoare

Alb



Nr. locuri

5



Cod motor

K9K-U8



Categorie

m1



Omologare

e2*2001/116*0323*62

Echipare

Cum a fost primit de la producător

ACCESSORY SOCKET

COMPLEMENTARY OBJECT (SAN466)

ADDITIONAL HEADLIGHTS

FOG LIGHTS (PROJAB)

ADJUSTMENT OF FRONT SEAT BELTS

FIXED HEIGHT SEATBELTS (CEAVFX)

AIR DUCT TO REAR SEATS

WITH AIR DUCT TO REAR SEA (AIRAR)

AIRBAG CANCEL

DECONNEX AIRBAG PASS (AIRBDE)

ANTENNA TYPE

CONTEXT CRITERIOM (SANA07)

ANTI-LOCK BRAKING SYSTEM

WITH ANTI-LOCK BRAKING SYSTEM (ABS)

BATTERY POWER TRACTION

WIHTOUT BATTERY ENERGY (SSCABA)

BLIND SPOT DETECTION

WITHOUT DECTECTOR BLIND S (SDANGM)

BRAKING ASSISTANCE

BOOSTER EMERGENCY BRAKING (AFURGE)

CENTER CONSOLE

CONTEXT CRITERIOM (SAN536)

CERTIFICATION EVOLUTION

COMPLEMENTARY OBJECT (NOH12)

CKD GROUPING ZONE

COMPLEMENTARY OBJECT (NO031)

COLOR OF OUTSIDE MIRROR

EXT REAR VIEW MIRROR PAIN (REPNTC)

COMMERCIAL EVENT

COMPLEMENTARY OBJECT (SAN822)

COMMERCIAL EVENT 1

COMPLEMENTARY OBJECT (SAN778)

COMMERCIAL EVENT 2A

CRITERIA COMPLEMENTARY (SANF76)

COMMERCIAL EVENT MANAGEMENT 3

EVOLUTION 1 GAMME 1 (EV1GA1)

COMMERCIAL VERSION SUPPLEMENT

BASIC COMMERCIAL VERSION (VNOR)

COMMERCIAL VERSION SUPPLEMENT 5

WO COMMERCIAL VERSION (VSNOR)

CONDITIONING

STANDARD PROTECTION (CONDO)

COUNTER UNIT

KILOMETRES (KM)

COUNTRY OF APPLICATION OF TECHNICAL LEGISLATION

TECHNICAL REG : RP00 (TLRP00)

CUSTOMIZED VERSION

VERSION WITHOUT ADAPTATIO (SAN613)

DAYTIME RUNNING LIGHTS

DAYTIME RUNNING LIGHTS 1 (FDIU1)

DOOR OPENING REMOTE CONTROL TYPE

DOOR OPENING/CLOSING WITH (SOPC1C)

DRIVE RECORDER

COMPLEMENTARY OBJECT (NOG68)

DRIVER ATTENTION ALERT

COMPLEMENTARY OBJECT (SANF68)

DRIVER'S HANDBOOK

RUMANIAN GLOVE BOX LITERA (NOTROU)

DRIVING ASSISTANCE

DRIVING ASSISTANCE : VEHI (ADAC)

DUST PROTECTION

WITH DUST KIT (KITPOU)

ECONOMIC DRIVING

WITH ECO MODE (ECOMOD)

ELECTRIC TOLL COLLECTION

WO ELECTRONIC TOLL SYS SP (SSPTLP)

ELECTROMOTOR DOOR LOCKING

ELECTRIC DOOR LOCKING (CPE)

ELECTRONIC STABILITY PROGRAM

DIRECT STAB CON DOWN (ESPDES)

EMERGENCY CALL AND BREAKDOWN

WITHOUT CALL FONCTION (SSCALL)

ENGINE PRODUCTION PLANT

(D) VALLADOLID MOTORES (SPAIN) (APV002_D)

EXTERIOR REAR VIEW MIRRORS

DOOR MIRRORS 03 (RET03)

FAST TRACK

COMPLEMENTARY OBJECT (NOH70)

FIRE EXTINGUISHER

WITHOUT FIRE EXTINGUISHER (SEXTIN)

FORWARD EMERGENCY BRAKING

W/O EBPM (SFSSAC)

FRONT SEAT BELT PRETENSIONER

FRONT SEAT BELT WITH PRET (PTCAV)

FRONT SEAT SUITABLE FOR CHILDREN

ISOFIX SEAT (ISOFIX)

FRONT SEAT TYPE

FRONT SEAT TYPE N 04 (SGAV04)

FRONT SIDE AIRBAG

HEAD SIDE AIRBAG (ABLARI)

FRONT TYRES

215/65 R16 (98)H, 6.50 J 16 - 50 C1 B

GEAR SHIFT INDICATOR

WITH GEAR SHIFT INDICATOR (AVGSI)

GEARBOX PRODUCTION PLANT

(B) PITESTI (ROMANIA)/RENAULT MECANIQUE ROUMANIE SRL (APV003_B)

GEOGRAPHIC COUNTRY

GEO COUNTRY ROMANIA (ROU01)

GRILL GUARD

CONTEXT CRITERIOM (SAN512)

HEADLIGHT BEAM ADJUSTMENT

CONTEXT CRITERIOM (SAN081)

HEATED NOZZLES

CONTEXT CRITERIOM (SANS57)

HEATED STEERING WHEEL

COMPLEMENTARY OBJECT (SANF38)

HEATED WINDSHIELD

NON-HEATED WINDSCREEN (PBNCH)

HIGH MOUNTED STOP LAMP

WITH RAISED BRAKE LIGHT (FSTPO)

INTERIOR COLOUR STYLING

INTERIOR HARMONY 02 (HARM02)

INVARIANT PROCESS SHEET MODEL

MODEL ROUTING SHEET (XJD1SU)

LANE KEEP

W/O LANE DEPARTURE WARNI (SDLIGM)

MAKE OF TYRES

TYRE BRAND: UNMARKED FITT (BANAL)

MARKETING VERSION

COMMERCIAL VERSION (VEC457)

MISCELLANEOUS BENEFITS SEPT

COMPLEMENTARY OBJECT (SANE42)

NAVIGATION MAP

W/O MAPPING (SSMAP)

NAVIGATION/SMARTPHONE IMITATION

COMPLEMENTARY OBJECT (NOG72)

ON-BOARD WARRANTY/SERVICES

SERVICES BOOKLET (DDAVB1)

OPTIONAL FRONT TYRES

215/60 R17 (96)H, 6.50 J 17 - 50 215/65 R16 (98)H, 6.50 J 16 - 50

OPTIONAL REAR TYRES

215/60 R17 (96)H, 6.50 J 17 - 50 215/65 R16 (98)H, 6.50 J 16 - 50

OUTSIDE CAMERA

NO OUTSIDE CAMERA (NOCAM)

OUTSIDE DOOR HANDLE TYPE

COMPLEMENTARY OBJECT (SANA27)

OVERSPEED AUDIBLE WARNING DEVICE

WITHOUT EXCESS SPEED HORN (SASURV)

PARKING ASSIST SYSTEM

WITHOUT I/PARKING SYS (SSITPK)

PASSENGER COMPARTMENT HEATING TYPE

AIR-CONDITIONING TYPE N1 (CA01)

PASSENGER COMPARTMENT THERMAL REQUIREMENT

WITHOUT PASSENGER COMPARTMENT THERMAL REQUIREMENT (STHABT)

PERSONALIZATION EXT TYPE A

COMPLEMENTARY OBJECT (SANF02)

PERSONALIZATION TYPE C

COMPLEMENTARY OBJECT (SANF06)

PERSONALIZATION TYPE N

PERSONALIZATION TYPE N01 (PERN01)

PLANT ASSEMBLY LINE

ASSEMBLY LINE 2 (CHMON2)

PLANT MARKING FOR COMPLEX START

COMPLEMENTARY OBJECT (SAN593)

PRESTATION LEISURE

COMPLEMENTARY OBJECT (SANF42)

PRESTATION MAPCAR

COMPLEMENTARY OBJECT (NOH94)

PRICING

COMPLEMENTARY OBJECT (NOH02)

PROTECTION ELEMENTS

DR+AS AIRBAG (AIRBA2)

RADIO COVER

COMPLEMENTARY OBJECT (NO351)

REAR CENTRE SEATBELT

3-POINT CENTRE SEATBELT (CMAR3P)

REAR HEADREST TYPE

REAR HEADREST TYPE 3 (ATAR03)

REAR SEAT BELT PRETENSIONER

COMPLEMENTARY OBJECT (SAN776)

REAR SEAT TYPE

REAR SEAT N 02 (SGAR02)

REAR TYRES

215/65 R16 (98)H, 6.50 J 16 - 50 C1 B

REAR WINDOW

HEATED REAR SCREEN (LAC)

REAR WINDOW CONTROL

MOTOR UNIT (LVAREL)

REGLEMENTARY EVOLUTION

COMPLEMENTARY OBJECT (NOH82)

REVERSING LIGHTS

1 REVERSING LIGHT (1RVLG)

ROAD SEVERITY

TYPE OF ROAD SEVERITY 2 (TRSEV2)

ROOF RACK/BARS

LONGITUDINAL ROOF BAR OPT (BARLO1)

ROUTING SHEETS COUNTRY

ROMANIA (ROUM)

SEAT BELT REMINDER

SEAT BELT WARN TYPE 5 (ALOU5)

SEAT COVERS

FABRIC SEAT-LINING N 02 (DRAP02)

SEAT HEATER AND COOLER

NON-HEATED SEAT (SGSCHA)

SEAT TRIMS

VELVET CLOTH (DRA)

SERVICE DONGLE

COMPLEMENTARY OBJECT (NOH14)

SERVICE TMC

COMPLEMENTARY OBJECT (SANG18)

SMOKER'S ACCESSORIES

WITH SMOKER ACCESSORIES (AVCACF)

SPARE WHEEL

WITH A SPARE WHEEL (RSEC01)

SPECIAL BUILD (FACTORY)

SERIES VEHICLE (WITHOUT S (SERIE))

SPECIAL TECHNICAL FEATURES CODE

CONTEXT CRITERIOM (SAN393)

SPEED LIMITER

COMPLEMENTARY OBJECT (SAN886)

SPRUNG MASS/REAR AXLE

SPRUNG WEIGHT/REAR AXLE 2 (TAR27)

STARTUP CRITERIA

COMPLEMENTARY OBJECT (SAN58E)

STATIONARY HEATING SYSTEM

WITHOUT STATIO HEAT (SCHSTA)

STEERING SWITCH

COMPLEMENTARY OBJECT (SANA55)

STEERING WHEEL HEIGHT ADJUSTMENT

STEERING WHEEL WITH HEIGH (VOLRHP)

STEERING WHEEL MATERIAL

FOAM STEERING WHEEL (VLMOUS)

STEERING WHEEL POSITION

LEFT (DG)

STORAGE COMPARTMENT UNDER ASSIST

CONTEXT CRITERIOM (SANA11)

STRIPPING

WITHOUT STRIPPING (SSDECA)

SUSPENDED WEIGHT/FRONT AXLE

SPRUNG WEIGHT/FRONT AXLE2 (TAV29)

TECHNICAL EVOLUTION A

TECHNICAL EVOLUTION A (TCHA0)

TECHNICAL EVOLUTION B

COMPLEMENTARY OBJECT (NOH06)

TECHNICAL EVOLUTION C

TECHNICAL EVOLUTION C (TCHC0)

TECHNICAL EVOLUTION D

COMPLEMENTARY OBJECT (NOH16)

TECHNICAL EVOLUTION F

COMPLEMENTARY OBJECT (NOH20)

TECHNICAL EVOLUTION G

COMPLEMENTARY OBJECT (NOH22)

TECHNICAL EVOLUTION H

COMPLEMENTARY OBJECT (NOH28)

TECHNICAL EVOLUTION I

COMPLEMENTARY OBJECT (NOH30)

TECHNICAL EVOLUTION J

COMPLEMENTARY OBJECT (NOH32)

TECHNICAL EVOLUTION K

COMPLEMENTARY OBJECT (NOH38)

TECHNICAL EVOLUTION N

COMPLEMENTARY OBJECT (NOH56)

TECHNICAL EVOLUTION P

COMPLEMENTARY OBJECT (NOH74)

TECHNICAL EVOLUTION Q

COMPLEMENTARY OBJECT (NOH78)

TECHNICAL EVOLUTION T

COMPLEMENTARY OBJECT (NOH84)

TECHNICAL EVOLUTION V

COMPLEMENTARY OBJECT (NOH90)

TOPPED BY TIRES

COMPLEMENTARY OBJECT (SAN470)

TRUNK INSIDE OPENER TYPE

WO TRUNK INSIDE OPENER (SOUVCF)

TURN SIGNAL LAMP

INDICATORS WITH SIDE REPE (AVREPL)

TYPE OF CLIMATE

TEMPERATE CLIMATE (TEMP)

TYPE OF FRONT WINDOW WINDER

DRIVER: PULSE ELECTRICAL / PASSENGER: SIMPLE ELECTRICAL (LVCIPE)

TYPE OF HEADLIGHTS

COMPLEMENTARY OBJECT (SAN406)

TYPE OF REFRIGERANT GAS

GAS TYPE 1234YF (1234Y)

TYPE OF TIRES

COMPLEMENTARY OBJECT (SAN504)

TYPES OF RADIOS

RADIO 55C (RAD55C)

TYRE PRESSURE DETECTION

INDIRECT TYRE PRES MONIT (TPRM3)

UNDERBODY PROTECTION

WITH ANTIGRIT PROTECTION (KITGRV)

UNIVERSAL INTERCONNECT FUNCTION

WITHOUT AIVC (NOAIV)

UTILITY ADAPTATION COVER

WITHOUT ADAPTATION (SAN164)

UTILITY ADAPTATION COVER SPECIFI

COMPLEMENTARY OBJECT (NOH64)

VARIOUS ADDITIONAL FEATURES

COMPLEMENTARY OBJECT (SAN482)

VARIOUS FUNCTIONS

COMPLEMENTARY OBJECT (SAN270)

VEHICLE LIGHT CONVERSION

WO LIGHT ADAPTATION SVO (SANCML)

VEHICLE PRODUCTION PLANT

(A) PITESTI (ROMANIA) (APV001_A)

VEHICLE TRACKING SYSTEM

W/O SECURITY DEVICE (SDPSEC)

VEHICLE TRANSFORMATION

COMPLEMENTARY OBJECT (SAND30)

WATER PROTECTION

WITH RAIN FORD RIVER KIT (KITPGR)

WHEEL DISC PROTECTION

PROTECTIVE REAR BRAKE DIS (PRODIS)

WHEEL RIM TYPE

16 METAL WHEEL RIMS 1 (RTOL16)

WHEELS RIMS

DIFFERENT WHEEL 02 (RDIF02)

WINDOW TINT

TINTED WINDOWS (VT)

WIPER START-UP TYPE

AUTO HIGH LOW BEAM (ALAEVM)

WIRELESS PHONE CHARGE

COMPLEMENTARY OBJECT (SANF72)

Cronologie

S-au găsit 5 înregistrări

Cronologia înregistrărilor pentru acest vehicul

Ultimele înregistrări

2021-05

 Țară necunoscută



A fost fabricat

Țara (sau statul) indică fie locația centrului de producție, uzina de asamblare sau adresa de înregistrare a producătorului. Data poate fi aproximativă.

2021-05

 România



A fost înmatriculat

Înregistrarea reprezintă un eveniment administrativ. Acest lucru ar putea fi legat de o schimbare de proprietar, documente etc

2022-12

 România



Daună detectată

Avem indicii potrivit cărora acest vehicul a fost recunoscut ca avariat în această țară (sau stat). Pentru detalii, vă rugăm să consultați secțiunea „Daune”.

2024-07

 România



Daună detectată

Avem indicii potrivit cărora acest vehicul a fost recunoscut ca avariat în această țară (sau stat). Pentru detalii, vă rugăm să consultați secțiunea „Daune”.

2024-07

 România



A fost verificat

A fost înregistrat un eveniment de inspecție tehnică (cunoscut și sub denumirea de ITP, test tehnic sau test de control al emisiilor). Pot fi incluse atât instanțe reușite, cât și eșuate.



+31

Surse de date

Am verificat 900+ de surse de date în **35 de țări**