

Renault Clio



VIN: VF1R9800562939331

Diesel

2019

Generat pe 2024-09-13 12:51



Contor de parcurs

✓ Arată bine



Statut legal

✓ Arată bine



Daune

⚠ Necesită atenție



Surse de date

Am verificat 900+ de surse de date în 35 de țări

Furt

Vehiculul este în prezent marcat ca furat? A fost furat în trecut? A fost recuperat?

✓ Nu s-au găsit probleme

Nu am găsit nicio înregistrare că vehiculul a fost furat.

i Notă

Verificarea bazei de date a poliției privind vehiculele furate finalizată în 11 țări: +5

Iată ce am verificat:



Căutat drept furat

✓ Nu s-a găsit nici o înregistrare



Furat în trecut

✓ Nu s-a găsit nici o înregistrare

Starea actuală necunoscută



Furat în trecut

✓ Nu s-a găsit nici o înregistrare

Vehiculul a fost recuperat

Baza de date aparținând poliției cu vehicule furate, **verificare finalizată în:**

România

Statele Unite ale Americii

Lituania

Danemarca

Italia

Slovacia

Finlanda

Canada

Slovenia

Cehia


Suedia

Contor de parcurs

Există semne conform cărora kilometrajul a fost dat înapoi sau discrepanțe ale kilometrajului?

i Notă

- Ultimul kilometraj cunoscut: 69.752 km
- 7 înregistrări ale kilometrajului



— Kilometrăj tău — Kilometrăj tipic pentru acest model

Înregistrări ale contorului de parcurs

2019-03	11 km
2022-05	43.226 km
2022-12	50.000 km
2023-03	54.000 km
2024-02	66.000 km

Înregistrări ale contorului de parcurs

2024-04	68.000 km
2024-05	69.752 km

Statut legal

A trecut vehiculul inspecțiile tehnice? A fost notat drept casat?

i Notă

Inspecția tehnică a fost transmisă pe 2024-05 în 🇷🇴 România

Legal



Inspecție tehnică

A trecut 2024-05

🇷🇴 România

A trecut cu succes inspecția tehnică

Valabil până la 2026-05



Casat

✓ Nu s-a găsit nici o înregistrare

Nu există nici o înregistrare că vehiculul a fost marcat drept casat

Daune

Acest vehicul a fost avariat în trecut ? Care a fost valoarea daunelor?

⚠️ Ai grijă!

Vehiculul a fost avariat de 3 ori!

i Notă

Daunele minore nu vor afecta în mod normal siguranța vehiculului și nu vor cauza probleme structurale

Înregistrări de daune



2022-05

România

Daune

Costul estimativ al reparațiilor


**0 RON -
2.000 RON**

Cauza posibilă a daunelor

Necunoscut

Categoriile de daune

Părți exterioare ale caroseriei



2022-12

România

Daune

Costul estimativ al reparațiilor

**14.001 RON -
24.000 RON**

Cauza posibilă a daunelor


Necunoscut

Categoriile de daune

Părți exterioare ale caroseriei

Iluminat exterior

Elemente structurale ale caroseriei



2024-04

România

Daune

Costul estimativ al reparațiilor

**2.001 RON -
6.000 RON**

Cauza posibilă a daunelor

Necunoscut

Categoriile de daune

Părți exterioare ale caroseriei

Dezastru natural

Locația vehiculului a fost înregistrată în zona unui dezastru natural?



Nu s-au găsit probleme

Locația vehiculului nu a fost înregistrată în zona unui dezastru natural

Valoarea de piață

Cu cât s-a vândut vehiculul în trecut? Care este în medie prețul vehiculelor din acest model și an?

Notă

- Prețul mediu de pe piață pentru un astfel de vehicul: 42.259 RON
- Atenție la problemele ascunse dacă vehiculul a fost la vânzare la un preț semnificativ mai mic decât prețul actual!

Valoarea de piață azi pentru Renault Clio 2019

Valoarea de piață este determinată prin examinarea prețului unui anumit model de mașină (fabricat în același an) în țara în care a fost generat raportul. Analizăm datele din ultimele 6 luni.

Cel mai mic preț

37.802 RON

Prețul mediu

42.259 RON

Cel mai mare preț

46.751 RON

Emisii

Câte emisii de CO2 produc vehiculele din acest model/an?

Notă

Emisii CO2: B (129 g/km)

Emisii CO₂

Emisiile CO2 ale
vehiculului tău

129 g/km Clasă **B**

Până la 120

120 - 140

140 - 155

155 - 165

165 - 190

190 - 225

225 și peste

Emisii CO₂ g/km















Specificații și echipare

Ce specificații și echipamente sunt înregistrate pentru acest vehicul?

Notă

Verificați dacă specificațiile și echipamentul acestui vehicul se potrivesc cu datele furnizate de vânzător.

Identificare și specificații tehnice

 Producător Renault	 Model Clio	 Tip caroserie Hatchback
 An de fabricație 2019	 Capacitate cilindrică 1,5 l	 Putere motor 66 kW (89 cp)
 Tip combustibil Diesel	 Cutie de viteze Manuală	 Tip transmisie Tracțiune față (FWD)
 Culoare Alb	 Nr. uși 5	 Descriere motor 638 INDEX (638)
 Nr. locuri 5	 Cod motor K9K-E6	

Echipare

PRICING

COMPLEMENTARY OBJECT (NOH02)

STEERING WHEEL POSITION

LEFT (DG)

TYPE OF CLIMATE

TEMPERATE CLIMATE (TEMP)

CLIMATIC CONSTRAINT HOT COUNTRY

WO CLIMAT CONST WARM COUN (SSCCPC)

DRIVER'S HANDBOOK

RUMANIAN GLOVE BOX LITERA (NOTROU)

ON-BOARD WARRANTY/SERVICES

SERVICES BOOKLET (RSANB1)

ROUTING SHEETS COUNTRY

ROMANIA (ROUM)

GEOGRAPHIC COUNTRY

GEO COUNTRY ROMANIA (ROU01)

SPECIAL TECHNICAL FEATURES CODE

CONTEXT CRITERIOM (SAN393)

COUNTRY OF APPLICATION OF TECHNICAL LEGISLATION

TECHNICAL REG : ROUMANIA (TLROUM)

TYPE OF PARTITION

WITHOUT PARTITION (SANCL)

SPECIAL BUILD (FACTORY)

SERIES VEHICLE (WITHOUT S (SERIE)

UNDERBODY PROTECTION

WITH ANTIGRIT PROTECTION (KITGRV)

CUSTOMIZED VERSION

VERSION WITHOUT ADAPTATIO (SAN613)

UTILITY ADAPTATION COVER

WITHOUT ADAPTATION (SAN164)

VEHICLE LIGHT CONVERSION

WO LIGHT ADAPTATION SVO (SANCML)

DUST PROTECTION

WITH DUST KIT (KITPOU)

WATER PROTECTION

WITH RAIN FORD RIVER KIT (KITPGR)

FRONT AND REAR BODY CROSSMEMBER

WIHTOUT CROSSMEMBER (SSRCAR)

PRESTATION SOCIETE

COMPLEMENTARY OBJECT (NOG76)

ELECTRONIC STABILITY PROGRAM

DIRECTIONAL STABILITY CON (ASRESP)

ANTI-LOCK BRAKING SYSTEM

WITH ANTI-LOCK BRAKING SYSTEM (ABS)

BRAKING ASSISTANCE

BOOSTER EMERGENCY BRAKING (AFURGE)

TYPE OF BRAKE

COMPLEMENTARY OBJECT (SAN558)

BRAKE CALIPER

CALIPER TYPE 1 (ETRP01)

WHEEL DISC PROTECTION

WITHOUT PROTECTIVE REAR B (SPRODI)

SUSPENDED WEIGHT/FRONT AXLE

SPRUNG WEIGHT/FRONT AXLE3 (TAV37)

SPRUNG MASS/REAR AXLE

SPRUNG WEIGHT/REAR AXLE 2 (TAR27)

ROAD SEVERITY

TYPE OF ROAD SEVERITY 2 (TRSEV2)

REAR SUSPENSION TYPE

NORMAL (SUARNL)

WHEEL RIM TYPE

15 METAL WHEEL RIMS 1 (RTOL15)

MAKE OF TYRES

TYRE BRAND: UNMARKED FITT (BANAL)

TYRE PRESSURE DETECTION

TYRE PRESSURE DETECTION (DPRPN)

SPARE WHEEL

WITH A SPARE WHEEL (RSEC01)

WHEELS RIMS

DIFFERENT WHEEL 24 (RDIF24)

TYPE OF TIRES

RESISTANCE TYRE TYPE 2 (PNRR02)

CHASSIS TYPE

STANDARD WHEEL BASE (CHBASE)

FRONT TYRES

185/65 R15 (88)T, 6.00 J 15 - 40 C1 B

REAR TYRES

185/65 R15 (88)T, 6.00 J 15 - 40 C1 B

OPTIONAL FRONT TYRES

185/65 R15 (88)T, 6.00 J 15 - 40 B 185/65 R15 (88)T, 6.00 J 15 - 40 C 195/55 R16 (87)H, 6.50 J 16 - 44 A 195/55 R16 (87)H, 6.50 J 16 - 44 B 185/65 R15 (88)H, 6.00 J 15 - 40 E 205/45 R17 (88)V, 7.00 J 17 - 44 C (*) (*) MONTES SOUMISES À CONDITIONS TECHNIQUES, VEUILLEZ VOUS REPORTER À LA DOCUMENTATION DU VÉHICULE

OPTIONAL REAR TYRES

185/65 R15 (88)T, 6.00 J 15 - 40 B 185/65 R15 (88)T, 6.00 J 15 - 40 C 195/55 R16 (87)H, 6.50 J 16 - 44 A 195/55 R16 (87)H, 6.50 J 16 - 44 B 185/65 R15 (88)H, 6.00 J 15 - 40 E 205/45 R17 (88)V, 7.00 J 17 - 44 C (*) (*) MONTES SOUMISES À CONDITIONS TECHNIQUES, VEUILLEZ VOUS REPORTER À LA DOCUMENTATION DU VÉHICULE

PASSENGER COMPARTMENT HEATING TYPE

AIR-CONDITIONING (CA)

TYPE OF REFRIGERANT GAS

GAS TYPE 1234YF (1234Y)

INTERIOR COLOUR STYLING

INTERIOR HARMONY 01 (HARM01)

STEERING WHEEL MATERIAL

FOAM STEERING WHEEL (VLMOUS)

INSTRUMENT PANELS

COMPLEMENTARY OBJECT (SAN395)

COUNTER UNIT

KILOMETRES (KM)

OVERSPEED AUDIBLE WARNING DEVICE

WITHOUT EXCESS SPEED HORN (SASURV)

SEAT BELT REMINDER

WITH SEAT BELT NOT SECURE (ALOUIC)

SPEED LIMITER

COMPLEMENTARY OBJECT (SAN886)

ADDITIONAL SENSING INFORMATION

WITHOUT INSTRUMENT PANELS (SSTADB)

ECONOMIC DRIVING

COMPLEMENTARY OBJECT (SECODR)

UNIVERSAL INTERCONNECT FUNCTION

WITHOUT TCU (SSTCU)

GEAR SHIFT INDICATOR

WITH GEAR SHIFT INDICATOR (AVGSI)

PARKING ASSIST SYSTEM

WITHOUT I/PARKING SYS (SSITPK)

LEVEL OF NAVIGATION AID

WITHOUT NAVIGATION AID (SSNAV)

TYPES OF RADIOS

RADIO 50C (RAD50C)

NAVIGATION MAP

W/O MAPPING (SSMAP)

SERVICE TMC

WITHOUT SERVICE TMC (SSRTMC)

NAVIGATION/SMARTPHONE IMITATION

COMPLEMENTARY OBJECT (NOG72)

FRONT ARM REST

WITHOUT FRONT ARMREST (SACCAV)

SEAT TRIMS

VELVET CLOTH (DRA)

SEAT COVERS

FABRIC SEAT-LINING N 26 (DRAP26)

FRONT HEADREST TYPE

FRONT HEAD RESTRAINTS (ATAV)

FRONT SEAT TYPE

FRONT SEAT TYPE N 02 (SGAV02)

SEAT HEATER AND COOLER

NON-HEATED SEAT (SGSCHA)

REAR HEADREST TYPE

2 FULL REAR HEAD RESTRAIN (2ATRPH)

REAR SEAT TYPE

REAR BENCH SEAT FUNCTIONA (FBANAR)

TYPE OF HEADLIGHTS

HALOGENE HEAD LAMPS (LAHALO)

DAYTIME RUNNING LIGHTS

DAYTIME RUNNING LIGHTS 1 (FDIU1)

ADDITIONAL HEADLIGHTS

WITHOUT ADDITIONAL HEADLIGHT (SPROJA)

TURN SIGNAL LAMP

INDICATORS WITH SIDE REPE (AVREPL)

HIGH MOUNTED STOP LAMP

WITH RAISED BRAKE LIGHT (FSTPO)

WIPER START-UP TYPE

WITHOUT AUTOMATIC LIGHTS + WINDSCREEN WIPER (SALEVA)

INTERMITTENT WINDSHIELD WIPERS

WIPER WITH INTERMITTENT (EVC)

WINDOW TINT

TINTED WINDOWS (VT)

TYPE OF FRONT WINDOW WINDER

DRIVER: MOTOR UNIT / PASSENGER: MOTOR UNIT (LVAVEL)

REAR WINDOW CONTROL

MANUAL (LVARMA)

REAR WINDOW

HEATED REAR SCREEN (LAC)

EXTERIOR REAR VIEW MIRRORS

DOOR MIRRORS 02 (RET02)

INTERIOR REAR VIEW MIRROR

RRVIEW MIR DAYLIGHT/NIGHT (RETRJN)

COLOR OF OUTSIDE MIRROR

BODY COLOR EXTERIOR REARV (RETC)

LANE KEEP

W/O LANE DEPARTURE WARNI (SDLIGM)

BLIND SPOT DETECTION

WITHOUT DECTECTOR BLIND S (SDANGM)

ADJUSTMENT OF FRONT SEAT BELTS

HEIGHT ADJUSTABLE SEATBELTS (CEAVRH)

REAR CENTRE SEATBELT

3-POINT CENTRE SEATBELT (CMAR3P)

FRONT SEAT SUITABLE FOR CHILDREN

ISOFIX SEAT (ISOFIX)

PROTECTION ELEMENTS

DR+AS AIRBAG (AIRBA2)

FRONT SIDE AIRBAG

FRONT SIDE AIRBAG + HEADA (ABLAVI)

SIDE APPROACH WARNING SYS

WITHOUT SIDE APPROACH WAR (SRDLAT)

VEHICLE TRACKING SYSTEM

W/O SECURITY DEVICE (SDPSEC)

EMERGENCY CALL AND BREAKDOWN

WITHOUT CALL FONCTION (SSCALL)

ELECTROMOTOR DOOR LOCKING

ELECTRIC DOOR LOCKING (CPE)

DOOR OPENING REMOTE CONTROL TYPE

433 MHZ NORMAL DOOR OPENI (SOP01C)

ANTI-THEFT DEVICES

WITHOUT ANTI-THEFT DEVICE (SDPCLV)

LUGGAGE RETAINING DEVICE

WITHOUT A NET FOR HOLDING LUGGAGE (SFIRBA)

SMOKER'S ACCESSORIES

WITH SMOKER ACCESSORIES (AVCACF)

LUGGAGE COMPARTMENT FLOOR

FIXED (PLANFX)

FIRE EXTINGUISHER

WITHOUT EQUIPMENT LEVEL O (SPREXT)

LUGGAGE BOX

W/O LUGGAGE BOX (SRANCF)

PERSONALIZATION TYPE P

COMPLEMENTARY OBJECT (SPERTP)

ACCESSORY SUPPORT TELEPHONY

WO ACCES SUPPORT TELEPHO (SSACTE)

MISCELLANEOUS BEN GT RS LINE I

WITHOUT PRESTATION (SPGTLI)

LUGGAGE COVER

WITHOUT LUGGAGE COMPARTME (SCCHBA)

STRIPPING

WITHOUT STRIPPING (SSDECA)

REAR SPOILER

REAR SPOILER (BECQAR)

EXTERIOR ACCESSORIES

WITHOUT EXTERIOR ACCESSOR (SACEXT)

OUTSIDE DOOR HANDLE TYPE

OUTS DOOR HANDLE TYPE1 (PGPRT1)

INNER ROPE HOOK

WITHOUT INNER ROPE HOOK (SFXBAG)

PERSONALIZATION EXT TYPE A

PERSONALIZATION TYPE A08 (PERA08)

PERSONALIZATION TYPE D

COMPLEMENTARY OBJECT (SANF08)

PERSONALIZATION TYPE R

WO PERSONALIZATION R (SPERTR)

PERSONALIZATION TYPE S

WO PERSONALIZATION S (SPERTS)

MISCELLANEOUS BEN GT RS LINE E

WITHOUT PRESTATION (SPGTLE)

MISCELLANEOUS BENEFITS TER

COMPLEMENTARY OBJECT (SAN503)

MISCELLANEOUS BENEFITS SIXT

WITHOUT PRESTATION (SSPRLU)

MISCELLANEOUS BEN GT RS LINE S

WITHOUT PRESTATION (SPGTLS)

CONDITIONING

STANDARD PROTECTION (COND0)

PROTOTYPE VERSION

CONTEXT CRITERIOM (SAN244)

PLANT ASSEMBLY LINE

ASSEMBLY LINE 1 (CHMON1)

PLANT MARKING FOR COMPLEX START

COMPLEMENTARY OBJECT (SAN592)

STARTUP CRITERIA

COMPLEMENTARY OBJECT (SAN58Y)

COMMERCIAL VERSION SUPPLEMENT

BASIC COMMERCIAL VERSION (VNOR)

TYPE OF COVERING

CLOTH (PRTIS)

ELECTRIC TOLL COLLECTION

WO ELECTRONIC TOLL SYS SP (SSPTLP)

COMMERCIAL VERSION SUPPLEMENT 5

WO COMMERCIAL VERSION (VSNOR)

MARKETING VERSION

COMMERCIAL VERSION (VECA7K)

INVARIANT PROCESS SHEET MODEL

MODEL ROUTING SHEET (X982VP)

VEHICLE PRODUCTION PLANT

(R) OYAK (BURSA) (TURKEY) (APV001_R)

ENGINE PRODUCTION PLANT

(R) OYAK (BURSA) (TURKEY) (APV002_R)

GEARBOX PRODUCTION PLANT

(R) OYAK (BURSA) (TURKEY) (APV003_R)

MISCELLANEOUS BENEFITS : MASSES

CONTEXT CRITERIOM (SAND70)

COMMERCIAL EVENT MANAGEMENT 3

EVOLUTION 1 GAMME 2 (EV1GA2)

ELECTRONIC ARCHITECTURE

ELECTRONIC ARCHITEC T4VS (AVARC2)

CAR SHARING FEATURE

COMPLEMENTARY OBJECT (SANF90)

SERVICE AHA

WITHOUT SERVICE AHA (SSRAHA)

TECHNICAL EVOLUTION A

COMPLEMENTARY OBJECT (NOG66)

SERVICE DONGLE

COMPLEMENTARY OBJECT (NOH14)

TECHNICAL EVOLUTION D

COMPLEMENTARY OBJECT (NOH16)

Siguranță

Vehiculul are vreo rechemare pe motiv de siguranță? Care este ratingul său de siguranță?

Notă

Rating de siguranță Euro NCAP: ★★★★★

Rating de siguranță

★★★★★ **Siguranță de 5 stele**

Performanță generală excelentă la protecția împotriva accidentelor și bine echipat cu tehnologie amplă și robustă de evitare a accidentelor



96%

Ocupant adult

89%

Copil ocupant

72%

Utilizatori vulnerabili ai drumurilor

75%

Asistență de siguranță

Cronologie

S-au găsit 7 înregistrări

Cronologia înregistrărilor pentru acest vehicul

Ultimele înregistrări

2019-03

 **Tară necunoscută**



A fost fabricat

Țara (sau statul) indică fie locația centrului de producție, uzina de asamblare sau adresa de înregistrare a producătorului. Data poate fi aproximativă.

2019-03

 **România**



A fost înmatriculat

Înregistrarea reprezintă un eveniment administrativ. Acest lucru ar putea fi legat de o schimbare de proprietar, documente etc

2022-05

 **România**



Daună detectată

Avem indicii potrivit cărora acest vehicul a fost recunoscut ca avariat în această țară (sau stat). Pentru detalii, vă rugăm să consultați secțiunea „Daune”.

2022-05

 **România**



A fost verificat

A fost înregistrat un eveniment de inspecție tehnică (cunoscut și sub denumirea de ITP, test tehnic sau test de control al emisiilor). Pot fi incluse atât instanțe reușite, cât și eșuate.

2022-12

 **România**



Daună detectată

Avem indicii potrivit cărora acest vehicul a fost recunoscut ca avariat în această țară (sau stat). Pentru detalii, vă rugăm să consultați secțiunea „Daune”.

2024-04

 **România**



Daună detectată

Avem indicii potrivit cărora acest vehicul a fost recunoscut ca avariat în această țară (sau stat). Pentru detalii, vă rugăm să consultați secțiunea „Daune”.

2024-05

 **România**



A fost verificat

A fost înregistrat un eveniment de inspecție tehnică (cunoscut și sub denumirea de ITP, test tehnic sau test de control al emisiilor). Pot fi incluse atât instanțe reușite, cât și eșuate.



+31

Surse de date

Am verificat 900+ de surse de date în **35 de țări**