



Renault Clio

VIN: VF1R9800762521868

Diesel

2019

Generat pe 2024-09-10 12:14



Contor de parcurs

✓ Arată bine



Statut legal

✓ Arată bine



Daune

⚠ Necesită atenție



+31

Surse de date

Am verificat 900+ de surse de date în **35 de țări**

Furt

Vehiculul este în prezent marcat ca furat? A fost furat în trecut? A fost recuperat?



Nu s-au găsit probleme

Nu am găsit nicio înregistrare că vehiculul a fost furat.



Notă

Verificarea bazei de date a poliției privind vehiculele furate finalizată în **10 țări**:



+4

Iată ce am verificat:



Căutat drept furat

✓ Nu s-a găsit nici o înregistrare



Furat în trecut

✓ Nu s-a găsit nici o înregistrare

Starea actuală
necunoscută



Furat în trecut

✓ Nu s-a găsit nici o înregistrare

Vehiculul a fost recuperat

Baza de date aparținând poliției cu vehicule furate, **verificare finalizată în:**

 România

 Lituania

 Statele Unite ale Americii

 Italia

 Slovacia

 Finlanda

 Slovenia

 Canada

 Suedia


 Cehia

Contor de parcurs

Există semne conform cărora kilometrajul a fost dat înapoi sau discrepanțe ale kilometrajului?

Notă

- Ultimul kilometraj cunoscut: 80.000 km
- 3 înregistrări ale kilometrajului



Înregistrări ale contorului de parcurs

2019-02	11 km
2022-06	50.000 km
2024-07	80.000 km

Statut legal

A trecut vehiculul inspecțiile tehnice? A fost notat drept casat?



Nu s-au găsit probleme

Nu s-au găsit înregistrări despre statutul legal al acestui vehicul

Legal



Inspecție tehnică

✓ Nu s-a găsit nici o înregistrare

Nu au fost găsite înregistrări ale inspecției tehnice



Casat

✓ Nu s-a găsit nici o înregistrare

Nu există nici o înregistrare că vehiculul a fost marcat drept casat

Daune

Acest vehicul a fost avariat în trecut ? Care a fost valoarea daunelor?

Ai grijă!

Vehiculul a fost avariat de 2 ori!

Notă

Daunele minore nu vor afecta în mod normal siguranța vehiculului și nu vor cauza probleme structurale

Înregistrări de daune



2022-06

 România

Daune

Costul estimativ al reparațiilor

**0 RON -
2.000 RON**

Cauza posibilă a daunelor


Necunoscut

Categoriile de daune

Părți exterioare ale caroseriei

2024-07

România

**Daune**

Costul estimativ al reparațiilor

**6.001 RON -
14.000 RON**

Cauza posibilă a daunelor

Necunoscut

Categoriile de daune

Părți exterioare ale caroseriei

Sticlă

Dezastru natural

Locația vehiculului a fost înregistrată în zona unui dezastru natural?

- Nu s-au găsit probleme**
Locația vehiculului nu a fost înregistrată în zona unui dezastru natural

Valoarea de piață

Cu cât s-a vândut vehiculul în trecut? Care este în medie prețul vehiculelor din acest model și an?

- i Notă**
- Prețul mediu de pe piață pentru un astfel de vehicul: 42.262 RON
 - Atenție la problemele ascunse dacă vehiculul a fost la vânzare la un preț semnificativ mai mic decât prețul actual!

Valoarea de piață azi pentru Renault Clio 2019

Valoarea de piață este determinată prin examinarea prețului unui anumit model de mașină (fabricat în același an) în țara în care a fost generat raportul. Analizăm datele din ultimele 6 luni.

Cel mai mic preț

Prețul mediu

Cel mai mare preț

37.805 RON

42.262 RON

46.753 RON

Specificații și echipare

Ce specificații și echipamente sunt înregistrate pentru acest vehicul?

Notă

Verificați dacă specificațiile și echipamentul acestui vehicul se potrivesc cu datele furnizate de vânzător.

Identificare și specificații tehnice



Producător
Renault



Model
Clio



Tip caroserie
Hatchback



An de fabricație
2019



Capacitate cilindrică
1,5 l



Putere motor
66 kW (89 cp)



Tip combustibil
Diesel



Cutie de viteze
Manuală



Tip transmisie
**Tracțiune față
(FWD)**



Nr. uși
5



Descriere motor
638 INDEX (638)

Echipare

Cum a fost primit de la producător

PRICING

COMPLEMENTARY OBJECT (NOH02)

STEERING WHEEL POSITION

LEFT (DG)

TYPE OF CLIMATE

TEMPERATE CLIMATE (TEMP)

CLIMATIC CONSTRAINT HOT COUNTRY

WO CLIMAT CONST WARM COUN (SSCCPC)

DRIVER'S HANDBOOK

RUMANIAN GLOVE BOX LITERA (NOTROU)

ON-BOARD WARRANTY/SERVICES

SERVICES BOOKLET (RSANB1)

ROUTING SHEETS COUNTRY

ROMANIA (ROUM)

GEOGRAPHIC COUNTRY

GEO COUNTRY ROMANIA (ROU01)

SPECIAL TECHNICAL FEATURES CODE

CONTEXT CRITERIOM (SAN393)

COUNTRY OF APPLICATION OF TECHNICAL LEGISLATION

TECHNICAL REG : ROUMANIA (TLROUM)

TYPE OF PARTITION

WITHOUT PARTITION (SANCL)

SPECIAL BUILD (FACTORY)

SERIES VEHICLE (WITHOUT S (SERIE)

UNDERBODY PROTECTION

WITH ANTIGRIT PROTECTION (KITGRV)

CUSTOMIZED VERSION

VERSION WITHOUT ADAPTATIO (SAN613)

UTILITY ADAPTATION COVER

WITHOUT ADAPTATION (SAN164)

VEHICLE LIGHT CONVERSION

WO LIGHT ADAPTATION SVO (SANCML)

DUST PROTECTION

WITH DUST KIT (KITPOU)

WATER PROTECTION

WITH RAIN FORD RIVER KIT (KITPGR)

FRONT AND REAR BODY CROSSMEMBER

WIHTOUT CROSSMEMBER (SSRCAR)

PRESTATION SOCIETE

COMPLEMENTARY OBJECT (NOG76)

ELECTRONIC STABILITY PROGRAM

DIRECTIONAL STABILITY CON (ASRESP)

ANTI-LOCK BRAKING SYSTEM

WITH ANTI-LOCK BRAKING SYSTEM (ABS)

BRAKING ASSISTANCE

BOOSTER EMERGENCY BRAKING (AFURGE)

TYPE OF BRAKE

COMPLEMENTARY OBJECT (SAN558)

BRAKE CALIPER

CALIPER TYPE 1 (ETRP01)

WHEEL DISC PROTECTION

WITHOUT PROTECTIVE REAR B (SPRODI)

SUSPENDED WEIGHT/FRONT AXLE

SPRUNG WEIGHT/FRONT AXLE3 (TAV37)

SPRUNG MASS/REAR AXLE

SPRUNG WEIGHT/REAR AXLE 2 (TAR27)

ROAD SEVERITY

TYPE OF ROAD SEVERITY 2 (TRSEV2)

REAR SUSPENSION TYPE

NORMAL (SUARNL)

WHEEL RIM TYPE

15 METAL WHEEL RIMS 1 (RTOL15)

MAKE OF TYRES

TYRE BRAND: UNMARKED FITT (BANAL)

TYRE PRESSURE DETECTION

TYRE PRESSURE DETECTION (DPRPN)

SPARE WHEEL

WITH A SPARE WHEEL (RSEC01)

WHEELS RIMS

DIFFERENT WHEEL 24 (RDIF24)

TYPE OF TIRES

RESISTANCE TYRE TYPE 2 (PNRR02)

CHASSIS TYPE

STANDARD WHEEL BASE (CHBASE)

FRONT TYRES

185/65 R15 (88)T, 6.00 J 15 - 40 B

REAR TYRES

185/65 R15 (88)T, 6.00 J 15 - 40 B

OPTIONAL FRONT TYRES

185/65 R15 (88)T, 6.00 J 15 - 40 C 195/55 R16 (87)H, 6.50 J 16 - 44 A 195/55 R16 (87)H, 6.50 J 16 - 44 B
185/65 R15 (88)H, 6.00 J 15 - 40 E 205/45 R17 (88)V, 7.00 J 17 - 44 C (*) (*) MONTES SOUMISES À
CONDITIONS TECHNIQUES, VEUILLEZ VOUS REPORTER À LA DOCUMENTATION DU VÉHICULE

OPTIONAL REAR TYRES

185/65 R15 (88)T, 6.00 J 15 - 40 C 195/55 R16 (87)H, 6.50 J 16 - 44 A 195/55 R16 (87)H, 6.50 J 16 - 44 B
185/65 R15 (88)H, 6.00 J 15 - 40 E 205/45 R17 (88)V, 7.00 J 17 - 44 C (*) (*) MONTES SOUMISES À
CONDITIONS TECHNIQUES, VEUILLEZ VOUS REPORTER À LA DOCUMENTATION DU VÉHICULE

PASSENGER COMPARTMENT HEATING TYPE

AIR-CONDITIONING (CA)

TYPE OF REFRIGERANT GAS

GAS TYPE 1234YF (1234Y)

INTERIOR COLOUR STYLING

INTERIOR HARMONY 01 (HARM01)

STEERING WHEEL MATERIAL

FOAM STEERING WHEEL (VLMOUS)

INSTRUMENT PANELS

COMPLEMENTARY OBJECT (SAN395)

COUNTER UNIT

KILOMETRES (KM)

OVERSPEED AUDIBLE WARNING DEVICE

WITHOUT EXCESS SPEED HORN (SASURV)

SEAT BELT REMINDER

WITH SEAT BELT NOT SECURE (ALOUCC)

SPEED LIMITER

COMPLEMENTARY OBJECT (SAN886)

ADDITIONAL SENSING INFORMATION

WITHOUT INSTRUMENT PANELS (SSTADB)

ECONOMIC DRIVING

COMPLEMENTARY OBJECT (SECODR)

UNIVERSAL INTERCONNECT FUNCTION

WITHOUT TCU (SSTCU)

GEAR SHIFT INDICATOR

WITH GEAR SHIFT INDICATOR (AVGSI)

PARKING ASSIST SYSTEM

WITHOUT I/PARKING SYS (SSITPK)

LEVEL OF NAVIGATION AID

WITHOUT NAVIGATION AID (SSNAV)

TYPES OF RADIOS

RADIO 50C (RAD50C)

NAVIGATION MAP

W/O MAPPING (SSMAP)

SERVICE TMC

WITHOUT SERVICE TMC (SSRTMC)

NAVIGATION/SMARTPHONE IMITATION

COMPLEMENTARY OBJECT (NOG72)

FRONT ARM REST

WITHOUT FRONT ARMREST (SACCAV)

SEAT TRIMS

VELVET CLOTH (DRA)

SEAT COVERS

FABRIC SEAT-LINING N 26 (DRAP26)

FRONT HEADREST TYPE

FRONT HEAD RESTRAINTS (ATAV)

FRONT SEAT TYPE

FRONT SEAT TYPE N 02 (SGAV02)

SEAT HEATER AND COOLER

NON-HEATED SEAT (SGSCHA)

REAR HEADREST TYPE

2 FULL REAR HEAD RESTRAIN (2ATRPH)

REAR SEAT TYPE

REAR BENCH SEAT FUNCTIONA (FBANAR)

TYPE OF HEADLIGHTS

HALOGENE HEAD LAMPS (LAHALO)

DAYTIME RUNNING LIGHTS

DAYTIME RUNNING LIGHTS 1 (FDIU1)

ADDITIONAL HEADLIGHTS

WITHOUT ADDITIONAL HEADLIGHT (SPROJA)

TURN SIGNAL LAMP

INDICATORS WITH SIDE REPE (AVREPL)

HIGH MOUNTED STOP LAMP

WITH RAISED BRAKE LIGHT (FSTPO)

WIPER START-UP TYPE

WITHOUT AUTOMATIC LIGHTS + WINDSCREEN WIPER (SALEVA)

INTERMITTENT WINDSHIELD WIPERS

WIPER WITH INTERMITTENT (EVC)

WINDOW TINT

TINTED WINDOWS (VT)

TYPE OF FRONT WINDOW WINDER

DRIVER: MOTOR UNIT / PASSENGER: MOTOR UNIT (LVAVEL)

REAR WINDOW CONTROL

MANUAL (LVARMA)

REAR WINDOW

HEATED REAR SCREEN (LAC)

EXTERIOR REAR VIEW MIRRORS

DOOR MIRRORS 02 (RET02)

INTERIOR REAR VIEW MIRROR

RRVIEW MIR DAYLIGHT/NIGHT (RETRJN)

COLOR OF OUTSIDE MIRROR

BODY COLOR EXTERIOR REARV (RETC)

LANE KEEP

W/O LANE DEPARTURE WARNI (SDLIGM)

BLIND SPOT DETECTION

WITHOUT DECTECTOR BLIND S (SDANGM)

ADJUSTMENT OF FRONT SEAT BELTS

HEIGHT ADJUSTABLE SEATBELTS (CEAVRH)

REAR CENTRE SEATBELT

3-POINT CENTRE SEATBELT (CMAR3P)

FRONT SEAT SUITABLE FOR CHILDREN

ISOFIX SEAT (ISOFIX)

PROTECTION ELEMENTS

DR+AS AIRBAG (AIRBA2)

FRONT SIDE AIRBAG

FRONT SIDE AIRBAG + HEADS (ABLAVI)

SIDE APPROACH WARNING SYS

WITHOUT SIDE APPROACH WAR (SRDLAT)

VEHICLE TRACKING SYSTEM

W/O SECURITY DEVICE (SDPSEC)

EMERGENCY CALL AND BREAKDOWN

WITHOUT CALL FUNCTION (SSCALL)

ELECTROMOTOR DOOR LOCKING

ELECTRIC DOOR LOCKING (CPE)

DOOR OPENING REMOTE CONTROL TYPE

433 MHZ NORMAL DOOR OPENING (SOP01C)

ANTI-THEFT DEVICES

WITHOUT ANTI-THEFT DEVICE (SDPCLV)

LUGGAGE RETAINING DEVICE

WITHOUT A NET FOR HOLDING LUGGAGE (SFIRBA)

SMOKER'S ACCESSORIES

WITH SMOKER ACCESSORIES (AVCACF)

LUGGAGE COMPARTMENT FLOOR

FIXED (PLANFX)

FIRE EXTINGUISHER

WITHOUT EQUIPMENT LEVEL O (SPREXT)

LUGGAGE BOX

W/O LUGGAGE BOX (SRANCF)

PERSONALIZATION TYPE P

COMPLEMENTARY OBJECT (SPERTP)

ACCESSORY SUPPORT TELEPHONY

WO ACCES SUPPORT TELEPHO (SSACTE)

MISCELLANEOUS BEN GT RS LINE I

WITHOUT PRESTATION (SPGTLI)

LUGGAGE COVER

WITHOUT LUGGAGE COMPARTME (SCCHBA)

STRIPPING

WITHOUT STRIPPING (SSDECA)

REAR SPOILER

REAR SPOILER (BECQAR)

EXTERIOR ACCESSORIES

WITHOUT EXTERIOR ACCESSOR (SACEXT)

OUTSIDE DOOR HANDLE TYPE

OUTS DOOR HANDLE TYPE1 (PGPRT1)

INNER ROPE HOOK

WITHOUT INNER ROPE HOOK (SFXBAG)

PERSONALIZATION EXT TYPE A

PERSONALIZATION TYPE A08 (PERA08)

PERSONALIZATION TYPE D

COMPLEMENTARY OBJECT (SANF08)

PERSONALIZATION TYPE R

WO PERSONALIZATION R (SPERTR)

PERSONALIZATION TYPE S

WO PERSONALIZATION S (SPERTS)

MISCELLANEOUS BEN GT RS LINE E

WITHOUT PRESTATION (SPGTLE)

MISCELLANEOUS BENEFITS TER

COMPLEMENTARY OBJECT (SAN503)

MISCELLANEOUS BENEFITS SIXT

WITHOUT PRESTATION (SSPRLU)

MISCELLANEOUS BEN GT RS LINE S

WITHOUT PRESTATION (SPGTLS)

CONDITIONING

STANDARD PROTECTION (COND0)

PROTOTYPE VERSION

CONTEXT CRITERIOM (SAN244)

PLANT ASSEMBLY LINE

ASSEMBLY LINE 1 (CHMON1)

PLANT MARKING FOR COMPLEX START

COMPLEMENTARY OBJECT (SAN592)

STARTUP CRITERIA

COMPLEMENTARY OBJECT (SAN58Y)

COMMERCIAL VERSION SUPPLEMENT

BASIC COMMERCIAL VERSION (VNOR)

TYPE OF COVERING

CLOTH (PRTIS)

ELECTRIC TOLL COLLECTION

WO ELECTRONIC TOLL SYS SP (SSPTLP)

COMMERCIAL VERSION SUPPLEMENT 5

WO COMMERCIAL VERSION (VSNOR)

MARKETING VERSION

COMMERCIAL VERSION (VECA7K)

INVARIANT PROCESS SHEET MODEL

MODEL ROUTING SHEET (X982VP)

VEHICLE PRODUCTION PLANT

(R) OYAK (BURSA) (TURKEY) (APV001_R)

ENGINE PRODUCTION PLANT

(R) OYAK (BURSA) (TURKEY) (APV002_R)

GEARBOX PRODUCTION PLANT

(R) OYAK (BURSA) (TURKEY) (APV003_R)

MISCELLANEOUS BENEFITS : MASSES

CONTEXT CRITERIOM (SAND70)

COMMERCIAL EVENT MANAGEMENT 3

EVOLUTION 1 GAMME 2 (EV1GA2)

ELECTRONIC ARCHITECTURE

ELECTRONIC ARCHITEC T4VS (AVARC2)

CAR SHARING FEATURE

COMPLEMENTARY OBJECT (SANF90)

SERVICE AHA

WITHOUT SERVICE AHA (SSRAHA)

TECHNICAL EVOLUTION A

COMPLEMENTARY OBJECT (NOG66)

SERVICE DONGLE

COMPLEMENTARY OBJECT (NOH14)

TECHNICAL EVOLUTION D

COMPLEMENTARY OBJECT (NOH16)

Siguranță

Vehiculul are vreo rechemare pe motiv de siguranță? Care este ratingul său de siguranță?

Rating de siguranță

★★★★★ **Siguranță de 5 stele**

Performanță generală excelentă la protecția împotriva accidentelor și bine echipat cu tehnologie amplă și robustă de evitare a accidentelor



96%

Ocupant adult



89%

Copil ocupant



72%

Utilizatori
vulnerabili ai
drumurilor



75%

Asistență de
siguranță

Cronologie

S-au găsit 3 înregistrări

Cronologia înregistrărilor pentru acest vehicul

Ultimele înregistrări

2019-02

 **Țară necunoscută**



A fost fabricat

Țara (sau statul) indică fie locația centrului de producție, uzina de asamblare sau adresa de înregistrare a producătorului. Data poate fi aproximativă.

2022-06

 **România**



Daună detectată

Avem indicii potrivit cărora acest vehicul a fost recunoscut ca avariat în această țară (sau stat). Pentru detalii, vă rugăm să consultați secțiunea „Daune”.

2024-07

 România



Daună detectată

Avem indicii potrivit cărora acest vehicul a fost recunoscut ca avariat în această țară (sau stat). Pentru detalii, vă rugăm să consultați secțiunea „Daune”.



+31

Surse de date

Am verificat 900+ de surse de date în **35 de țări**