

# Audi

VIN: WAUZZZ4M7MD025407

Diesel

Generat pe 2024-11-25 14:40



## Contor de parcurs

✓ Arată bine



## Statut legal

✓ Arată bine



## Daune

⚠ Necesită atenție



+31

## Surse de date

Am verificat 900+ de surse de date în 35 de țări

## Furt

Vehiculul este în prezent marcat ca furat? A fost furat în trecut? A fost recuperat?




### Nu s-au găsit probleme

Nu am găsit nicio înregistrare că vehiculul a fost furat.



### Notă

Verificarea bazei de date a poliției privind vehiculele furate finalizată în 9 țări:  +3

## Iată ce am verificat:



### Căutat drept furat

✓ Nu s-a găsit nici o înregistrare



### Furat în trecut

✓ Nu s-a găsit nici o înregistrare

Starea actuală necunoscută



### Furat în trecut

✓ Nu s-a găsit nici o înregistrare

Vehiculul a fost recuperat

Baza de date aparținând poliției cu vehicule furate, **verificare finalizată în:**



România



Danemarca



Statele Unite ale Americii



Lituania



Finlanda



Slovacia



Suedia



Italia




Slovenia

## Contor de parcurs

Există semne conform cărora kilometrajul a fost dat înapoi sau discrepanțe ale kilometrajului?

### Notă

Ultimul kilometraj cunoscut: 39.006 km



**Disclaimer (declinarea responsabilității):** acest grafic reprezintă o tendință estimată a kilometrajului. Deși se bazează pe înregistrări reale de kilometraj disponibile pentru acest vehicul, există lacune având în vedere că evoluția kilometrajului nu este înregistrată în mod constant. Pentru a lua în considerare aceste date lipsă, aplicăm un model patentat de analiză a datelor care prezice modul în care probabil s-a schimbat kilometrajul între evenimentele înregistrate. Acest lucru ajută la furnizarea unei imagini mai complete a utilizării vehiculului în timp.

## Statut legal

A trecut vehiculul inspecțiile tehnice? A fost notat drept casat?

- ✓ **Nu s-au găsit probleme**  
Nu s-au găsit înregistrări despre statutul legal al acestui vehicul

## Legal



### Inspecție tehnică periodică (ITP)

- ✓ Nu s-a găsit nici o înregistrare

Nu au fost găsite înregistrări ale inspecției tehnice



### Casat

- ✓ Nu s-a găsit nici o înregistrare

Nu există nici o înregistrare că vehiculul a fost marcat drept casat

## Daune

Acest vehicul a fost avariat în trecut ? Care a fost valoarea daunelor?



### Ai grijă!

Vehiculul a fost avariat de 2 ori!



### Notă

Daunele minore nu vor afecta în mod normal siguranța vehiculului și nu vor cauza probleme structurale

## Înregistrări de daune



Daune pe partea dreaptă: **Spate / Bară de protecție**

**Spate stânga / Bară de protecție**

**Spate dreapta / Bară de protecție**

2022-11

 România

#### Daune

Costul estimativ al reparațiilor

**2.001 RON – 6.000 RON**

Cauza posibilă a daunelor

**Necunoscut**

Categoriile de daune

Părți exterioare ale caroseriei



2023-11

 România

#### Daune

Costul estimativ al reparațiilor

**6.001 RON – 14.000 RON**

Cauza posibilă a daunelor

**Necunoscut**

Categoriile de daune

Sistem de suspensie

**Disclaimer (declinarea responsabilității):** Majoritatea înregistrărilor de daune sunt legate de accidente, dar uneori nu este acesta cazul. Unele înregistrări provin din alte surse cum ar fi serviciile specializate pe lucrări de caroserie, cereri de daune, licitații sau inspecții ale vehiculelor. Aceste înregistrări arată că starea vehiculului a fost evaluată, chiar dacă nu a fost din cauza unui accident.

## Dezastru natural

Locația vehiculului a fost înregistrată în zona unui dezastru natural?

**Nu s-au găsit probleme**

Locația vehiculului nu a fost înregistrată în zona unui dezastru natural

# Specificații și echipare

Ce specificații și echipamente sunt înregistrate pentru acest vehicul?

## Notă

Verificați dacă specificațiile și echipamentul acestui vehicul se potrivesc cu datele furnizate de vânzător.

## Identificare și specificații tehnice



Producător

**Audi**



Tip caroserie

**SUV**



An model

**2021**



Capacitate cilindrică

**3 l**



Putere motor

**210 kW (282 cp)**



Tip combustibil

**Diesel**



Cutie de viteze

**Automată**



Nr. uși

**2**



Amplasarea volanului

**Volan pe stânga**



Nr. cilindri

**6**

## Echipare

Cum a fost primit de la producător

S LINE

0E2

LONG WHEELBASE

0F3

FUEL SYSTEM FOR DIESEL ENGINE

0FA

STANDARD MANUFACTURING SEQUENCE

0JL

WEIGHT CATEGORY FRONT AXLE WEIGHT RANGE 11

0K4

HYBRID PROPULSION SYSTEM I-HEV

0M5

FUEL TANK

0N5

STANDARD REAR AXLE

0NB

NAMEPLATE SET IN BASIC STYLE

0P0

REAR EXHAUST TAILPIPE (STANDARD)

0RZ

WITHOUT IGNITION/STARTER SWITCH LOCKING SYSTEM, WITHOUT STEERING LOCK

0TD

FLOOR MATS IN FRONT AND REAR

0XH

INFORMATION KIT IN ROMANIAN

0Y1

STANDARD CLIMATIC ZONES

0YH

WEIGHT RANGE 8 INSTALLATION CONTROL ONLY, NO REQUIREMENT FORECAST

1BK

4-CORNER AIR SUSPENSION WITH ELECTRONIC SHOCK ABSORPTION CONTROL

1EX

SPECIAL IDENTIFICATION PLATE FOR EC FOR M1 PASSENGER VEHICLE

1G8

BREAKDOWN KIT

1P0

STANDARD SUSPENSION

1PA

STANDARD WHEEL BOLTS

1S2

TOOL KIT

1SA

WITHOUT ADDITIONAL FRONT UNDERBODY GUARD

1T3

FIRST AID KIT WITH WARNING TRIANGLE

1VH

INSTALLATION PARTS FOR SIX-CYLINDER ENGINE

1Y6

AUTOMATIC SLIP-CONTROL DIFFERENTIAL

1Z5

INCREASE IN INITIAL STANDARD FUEL FILLING

1ZA

DISK BRAKES IN FRONT

20A

WITHOUT ELECTRIC MOTOR ( HYBRID )

2C5

AXIAL AND VERTICAL ADJUSTABLE STEERING COLUMN

2D0

WITHOUT CD ENHANCING UNDERBODY PANEL

2ED

DISK BRAKES IN REAR

2F0

WITHOUT LOCKING AND STARTING SYSTEMS

2G5

FILLER NECK MODULE 1 WITHOUT INSERT

2H9

DRIVE SELECT

2K7

REINFORCED BUMPERS

2KR

LABELS/PLATES IN ENGLISH AND GERMAN

2P2

STAINLESS STEEL LOADING EDGE PROTECTION

2PF

LEATHER-WRAPPED MULTIFUNCTION SPORTS STEERING WHEEL

2V5

FRESH AIR INTAKE SYSTEM WITH COMBINATIONFILTER

2WA

WITHOUT ADDITIONAL TIRES

2Z8

TYPE SIGN AND COMPANY LOGO

3B5

CHILD SEAT ANCHOR FOR CHILD SEAT SYSTEM ISOFIX

3CX

NET PARTITION

3FA

WITHOUT ROOF INSERT (STANDARD ROOF)

3G0

WITHOUT CHILD SEAT ANCHOR FRONT (ISOFIX)



3GD

PLANE REAR CARGO AREA

3L4

POWER SEAT ADJUSTMENT FOR BOTH FRONT SEATS, DRIVER SEAT WITH MEMORY FEATURE

3M3

PASSENGER CAR DESIGN

3S2

BLACK ROOF RAILS

3U7

LUGGAGE COMPARTMENT COVER

3Y0

WITHOUT ROLL-UP SUNSHADE

45X

ALLOY WHEELS 9J X 20

4A4

SEAT HEATER FOR FRONT AND REAR SEATS SEPARATELY CONTROLLED

4D0

WITHOUT SEAT VENTILATION/MASSAGE SEAT

4E7

TAILGATE/TRUNK LID POWER CLOSING

4GR

LAMINATED WINDSHIELD, HEATED

4I3

CENTRAL LOCKING SYSTEM "KEYLESS ENTRY" WITHOUT SAFELOCK

4KC

SIDE AND REAR WINDOWS IN HEAT-INSULATINGGLASS

4L6

BREAKAWAY INTERIOR REARVIEW MIRROR, AUTO-DIMMING

4UF

DRIVER AND FRONT PASSENGER AIRBAG WITH FRONT PASSENGER AIRBAG DEACTIVATION

4X3

SIDE AIRBAG IN FRONT, WITH CURTAIN AIRBAG

4ZD

BLACK MOLDINGS

5C0

WITHOUT SPECIAL BODY MEASURES

5D1

CARRIER FREQUENCY 433.92 MHZ-434.42 MHZ

5J3

ROOF SPOILER

5K5

TRANSIT COATING FILM WITH ADDITIONAL TRANSPORT PROTECTION MEASURES

5KA

THREE REAR SEATS

5L0

WITHOUT FRONT SPOILER

5RU

RIGHT EXTERIOR MIRROR: CONVEX (LARGE VIEWING FIELD)

5SL

LEFT EXTERIOR MIRROR: ASPHERICAL

5TG

DECORATIVE ALUMINUM INSERTS, DULLING

5XL

SUN VISORS WITH ILLUMINATED VANITY MIRROR ON DRIVER AND FRONT PASSENGER SIDE

5ZF

FRONT HEAD RESTRAINTS

6A0

WITHOUT FIRE EXTINGUISHER

6E6

CENTER ARMREST IN FRONT

6F7

EMBLEMS

6FA

COMPONENTS WITHOUT SPECIAL SURFACE APPEARANCE

6I3

LANE DEPARTURE WARNING

6K8

PRE SENSE CITY WITHOUT PRE CARE

6NQ

STANDARD MOLDED HEADLINER

6SS

LUGGAGE COMPARTMENT FLOOR COVERING

6U0

WITHOUT ADDITIONAL SEALS OUTSIDE

6V1

REAR TRIM PANEL (ECE)

6W6

FRONT LICENSE PLATE CARRIER

6XL

EXTERIOR MIRRORS WITH MEMORY FEATURE, AUTO-DIMMING, POWER-FOLDING/ADJUSTABLE/HEATED

6Y2

SPEED LIMITER

73A

WITHOUT CHARGING CABLE (INDUSTRIAL CONNECTOR)

76A

WITHOUT MODE 3 CHARGING CABLE

7A0

WITHOUT CD CHANGER/CD PLAYER

7AA

ELECTRONIC ENGINE IMMOBILIZER

7E6

ELECTRIC AUXILIARY AIR HEATER

7G0

WITHOUT PREPARATION FOR VTS (VEHICLE TRACKING SYSTEM)

7HA

WITHOUT LEATHER

7K1

DIRECT TIRE PRESSURE MONITORING SYSTEM

7L8

START/STOP SYSTEM WITH REGENERATIVE BRAKING

7P1

POWER-ADJUSTABLE LUMBAR SUPPORT IN FRONTSEATS

7UG

NAVIGATION SYSTEM - HIGH

7W3

WITH EXTENDED SAFETY SYSTEM (PROACTIVE PASSENGER PROTECTION SYSTEM, BASIC AND REAR)

7X5

PARK ASSIST

7Y1

LANE CHANGE ASSIST

7ZB

VEHICLE CLASS DIFFERENTIATION -4M0-

8G5

MULTIPLE MATRIX BEAM

8IZ

LED HEADLAMP WITH VARIABLE LIGHT DISTRIBUTION AND ADDITIONAL LASER HIGH BEAM

8K4

SEPARATE DAYTIME RUNNING LIGHTS -- NAR --

8T6

CRUISE CONTROL SYSTEM AND SPEED LIMITER

8X1

HEADLAMP WASHER SYSTEM

8Y1

TWO-TONE HORN

8Z5

NOT HOT COUNTRY

9AE

CLIMATRONIC IN FRONT, AND MULTI-ZONE CONTROLS IN THE REAR

9B0

WITHOUT TELEPAY DEVICE

9G8

BELT-DRIVEN STARTER ALTERNATOR 48 V 110-250 A

9JA

NON-SMOKER'S PACKAGE

9M0

WITHOUT AUXILIARY HEATER/FUEL-FIRED PARKING HEATER

9P6

SEAT BELT REMINDER, ELECTRIC CONTACT IN BUCKLE

9PA

STANDARD WIPER ARMS/BLADES

9R0

WITHOUT NIGHT VISION

9S9

.

9TA

WITHOUT ADDITIONAL WARNING LIGHTS

9VS

SOUND PACKAGE "BRANDED"

9WC

WITHOUT "MULTIMEDIA" IN VEHICLE

9ZE

COMFORT TELEPHONE SYSTEM

A00

NO SELF-COLLECTION

A51

AUDI AG

A8Y

OFF-ROAD

AQ0

STANDARD-PRODUCTION QUALITY

AV1

DRIVING ON THE RIGHT

B0A

COMPONENT PARTS SET WITHOUT COUNTRY-SPECIFIC BUILDING REGULATION

B43

TYPE APPROVAL COUNTRY ROMANIA

C51

OPERATING PERMIT, ALTERATION

DV8

6-CYL. TURBO DIES. ENG. 3.0 L/210 KW V6 TDI COMMON RAIL BASE ENGINE IS T7V

E0A

NO SPECIAL EDITION

EA6

2 YEARS FOLLOW-ON WARRANTY, MAX. 120 000 KM

EH0

WITHOUT CHARGING CABLE

ER1

REGIONAL CODE " ECE " FOR RADIO

ES0

WITHOUT VEHICLE INLET

EVO

WITHOUT CHARGING CABLE

EW0

WITHOUT MAINTENANCE CONTRACT

FOA

NO SPECIAL PURPOSE VEHICLE, STANDARD EQUIPMENT

FA0

CONTROL OF SERIES PRODUCTION

FK2

WITH ADDITIONAL TANK FOR SCR (24 LITERS)

FM0

BASIC EQUIPMENT VARIANT

FQ0

PRODUCTION WHEELS

FY0

.

FZ1

N.N.N. TYPE 1

G1G

8-SPEED AUTOMATIC TRANSMISSION FOR FOUR-WHEEL DRIVE

GA0

WITHOUT PRE-CONDITIONING

GB1

BOOSTER TYPE 1

GH1

BASIC REAR DIFFERENTIAL

GJ0

WITHOUT TRAFFIC JAM ASSIST/CO-PILOT IN HEAVY TRAFFIC

GM0

WITHOUT ELECTRONIC ENGINE SOUND MEASURES

GP1

VEHICLES WITH SPECIAL UPGRADE MEASURES

GZ2

DOOR POWER LATCHING

H7A

TIRES 285/45 R20 112Y XL LOW ROLLING RESISTANCE

I4Q

SPECIAL PLATES/DECALS/ SAFETY CERTIFICATES FOR ROMANIA

IT3

WITH CONNECT PACKAGE 3

IU1

WITH CONNECT PACKAGE 1

IW3

EMERGENCY CALL SERVICE AND ROADSIDE ASSISTANCE CALL

IX2

DIESEL ENGINE

J2D

BATTERY 380 A (68 AH)

JX1

WITH FRONT CROSS TRAFFIC ASSIST

K4H

CLOSED BODY

KA6

WITH FRONT AND REAR VIEW CAMERA SYSTEM AND TWO SIDE CAMERAS

KK3

REFRIGERANT R1234YF

KS0

WITHOUT HEAD-UP DISPLAY



L0L

LEFT-HAND DRIVE

N7K

SEAT TRIM COVERS IN ALCANTARA/LEATHER

NJ0

WITHOUT CHARGING DOCK

NT0

TRANSIT COATING (TYPE 1)

NY0

STANDARD BATTERY/ALTERNATOR CAPACITY

Q1D

SPORTS SEATS IN FRONT

QK1

WITH MULTIFUNCTION CAMERA

QL5

DARK TINTED GLASS IN REAR SEAT AREA (VENUS 35/PRIVACY) HEAT-INSULATING GLASS (GREEN) IN FRONT

QQ1

WITH ADDITIONAL LIGHTS (INTERIOR LIGHTING)

QR9

WITH DYNAMIC ROAD SIGN DISPLAY

QT5

WITHOUT STEP

QV3

DIGITAL RADIO RECEPTION

QZ7

POWER STEERING

S3Y

2-DOOR GTI FOR HONG KONG

T2P

4-CYLINDER SI ENGINE 1.6 L UNIT 051.W

U5A

INSTRUMENT CLUSTER, KM/H SPEEDOMETER

UF7

ELECTRIC INTERFACE FOR EXTERNAL USE

UH2

PARKING BRAKE

V0A

TIRES WITHOUT SPECIFICATION OF TIRE BRAND

VC0

WITHOUT REMOTE-CONTROLLED GARAGE DOOR OPENER

VF1

PEDAL CLUSTER

VH2

48-V ELECTRIC SYSTEM

VI1

SERVICE INDICATOR 30 000 KM OR 1 YEAR ( VARIABLE )

VL1

EXTENDED PEDESTRIAN PROTECTION MEASURES

VT5

SCUFF PLATES IN DOOR APERTURES

X4A

EQUIPMENT OPTIONS SUBSET FOR AUSTRIA

## Cronologie

**S-au găsit 2 înregistrări**

Cronologia înregistrărilor pentru acest vehicul

### Ultimele înregistrări

2022-11

 România



### Daună detectată

Avem indicii potrivit cărora acest vehicul a fost recunoscut ca avariat în această țară (sau stat). Pentru detalii, vă rugăm să consultați secțiunea „Daune”.

2023-11

 România



### Daună detectată

Avem indicii potrivit cărora acest vehicul a fost recunoscut ca avariat în această țară (sau stat). Pentru detalii, vă rugăm să consultați secțiunea „Daune”.



+31

### Surse de date

Am verificat 900+ de surse de date în **35 de țări**