

Audi Q3

VIN: WAUZZZ8U1ER079123

Diesel

2014

Generat pe 2024-11-27 08:26



Contor de parcurs

✓ Arată bine



Statut legal

✓ Arată bine



Daune

✓ Arată bine



+31

Surse de date

Am verificat 900+ de surse de date în 35 de țări

Furt

Vehiculul este în prezent marcat ca furat? A fost furat în trecut? A fost recuperat?



Nu s-au găsit probleme

Nu am găsit nicio înregistrare că vehiculul a fost furat.



Notă

Verificarea bazei de date a poliției privind vehiculele furate finalizată în 10 țări:



+4

Iată ce am verificat:



Căutat drept furat

✓ Nu s-a găsit nici o înregistrare



Furat în trecut

✓ Nu s-a găsit nici o înregistrare

Starea actuală necunoscută



Furat în trecut

✓ Nu s-a găsit nici o înregistrare

Vehiculul a fost recuperat

Baza de date aparținând poliției cu vehicule furate, **verificare finalizată în:**



România



Lituania



Danemarca



Statele Unite ale Americii



Slovacia



Finlanda



Cehia



Suedia



Slovenia




Italia

Contor de parcurs

Există semne conform cărora kilometrajul a fost dat înapoi sau discrepanțe ale kilometrajului?

Notă

Ultimul kilometraj cunoscut: 70.749 km




Disclaimer (declinarea responsabilității): acest grafic reprezintă o tendință estimată a kilometrajului. Deși se bazează pe înregistrări reale de kilometraj disponibile pentru acest vehicul, există lacune având în vedere că evoluția kilometrajului nu este înregistrată în mod constant. Pentru a lua în considerare aceste date lipsă, aplicăm un model patentat de analiză a datelor care prezice modul în care probabil s-a schimbat kilometrajul între evenimentele înregistrate. Acest lucru ajută la furnizarea unei imagini mai complete a utilizării vehiculului în timp.

Statut legal

A trecut vehiculul inspecțiile tehnice? A fost notat drept casat?

Notă

Inspecția tehnică a fost transmisă pe 2022-07 în  **Italia**

Legal



Inspecție tehnică periodică (ITP)

A trecut 2022-07

 **Italia**

A trecut cu succes inspecția tehnică

Valabil până la 2024-07



Casat

✓ Nu s-a găsit nici o înregistrare

Nu există nici o înregistrare că vehiculul a fost marcat drept casat

Daune

Acest vehicul a fost avariat în trecut ? Care a fost valoarea daunelor?

 **Nu s-au găsit probleme**

Înregistrări de daune



Ocazional pot apărea inexactități, mai ales la verificarea vehiculelor vechi. Atelierele clandestine de reparații pot deghiza ilegal defectele sau daunele vehiculelor, fără să declare nicăieri existența lor. Uneori până și plăcuțele VIN ale vehiculului pot fi înlocuite. Avem o varietate de metode de a detecta chiar și astfel de infracțiuni, dar este imposibil de oferit o garanție de 100%.

Dezastru natural

Locația vehiculului a fost înregistrată în zona unui dezastru natural?

✓ Nu s-au găsit probleme

Locația vehiculului nu a fost înregistrată în zona unui dezastru natural

Valoarea de piață

Cu cât s-a vândut vehiculul în trecut? Care este în medie prețul vehiculelor din acest model și an?

i Notă

- Prețul mediu de pe piață pentru un astfel de vehicul: 76.379 RON
- Atenție la problemele ascunse dacă vehiculul a fost la vânzare la un preț semnificativ mai mic decât prețul actual!

Valoarea de piață azi pentru Audi Q3 2014

Valoarea de piață este determinată prin examinarea prețului unui anumit model de mașină (fabricat în același an) în țara în care a fost generat raportul. Analizăm datele din ultimele 6 luni.

Cel mai mic preț

70.874 RON

Prețul mediu

76.379 RON

Cel mai mare preț

82.406 RON

Emisii

Câte emisii de CO2 produc vehiculele din acest model/an?

i Notă

Emisii CO2: C (152 g/km)

Emisii CO₂

Emisiile CO₂ ale
vehiculului tău

152 g/km Clasă **C**

Până la 120

120 - 140

140 - 155

155 - 165

165 - 190

190 - 225

225 și peste

Emisii CO₂ g/km

Specificații și echipare

Ce specificații și echipamente sunt înregistrate pentru acest vehicul?

Notă

Verificați dacă specificațiile și echipamentul acestui vehicul se potrivesc cu datele furnizate de vânzător.

Identificare și specificații tehnice



Producător

Audi



Model

Q3



Tip caroserie

Break



An de fabricație

2014



An model

2014



Capacitate cilindrică

2 l



Putere motor

103 kW (138 cp)



Tip combustibil

Diesel



Cutie de viteze

Automată



Tip transmisie

Tracțiune integrală (AWD)



Culoare
Gri



Amplasarea volanului
Volan pe stânga



Nr. locuri
5



Cod motor
CFF

Echipare

Cum a fost primit de la producător

0AK

FRONT STABILIZER

0BE

REAR STABILIZER

0C0

STANDARD

0EX

INSTALLATION DIFFERENTIATION FOR TRANSMISSION DQ500 -- VEHICLE COMPONENTS --

0F9

COOLED FUEL SYSTEM FOR DIESEL ENGINE

0FA

STANDARD MANUFACTURING SEQUENCE

0LK

WITH SPECIAL PLATES/LABELS/ SAFETY CERTIFICATES FOR ITALY

0NA

WITHOUT NAMEPLATE SET (WITHOUT MODEL DESIGNATION)

0P0

REAR EXHAUST TAILPIPE (STANDARD)

0TD

FLOOR MATS IN FRONT AND REAR

0U2

FUEL QUALITY < 50 PPM

0VG

INFORMATION KIT IN ITALIAN

0W1

LABEL FOR CENTRAL ELECTRIC GERMAN-SPEAKING COUNTRIES

0Y1

STANDARD CLIMATIC ZONES

0YF

WEIGHT RANGE 6 INSTALLATION CONTROL ONLY, NO REQUIREMENT FORECAST

1AT

ELECTRONIC STABILITY CONTROL (ESC)

1D0

WITHOUT TRAILER HITCH

1E0

WITHOUT ACTIVATED CARBON CANISTER

1EX

SPECIAL IDENTIFICATION PLATE FOR EC FOR M1 PASSENGER VEHICLE

1G8

BREAKDOWN KIT

1KU

DISK BRAKES IN REAR

1LJ

DISK BRAKES IN FRONT

1PA

STANDARD WHEEL BOLTS

1S1

TOOL KIT AND JACK

1SA

WITHOUT ADDITIONAL FRONT UNDERBODY GUARD

1T3

FIRST AID KIT WITH WARNING TRIANGLE

1U8

WITHOUT FOLDING TABLE ON FRONT SEAT BACKREST

1VG

INSTALLATION PARTS FOR FOUR-CYLINDER ENGINE

1X1

FOUR WHEEL DRIVE

1Z2

INCREASE IN INITIAL STANDARD FUEL FILLING

2D0

WITHOUT CD ENHANCING UNDERBODY PANEL

2G5

FILLER NECK MODULE 1 WITHOUT INSERT

2H0

WITHOUT "DRIVE SELECT"

2K1

REINFORCED BUMPERS

2KS

LABELS/PLATES IN ENGLISH AND ITALIAN

2P1

PLASTIC LOADING EDGE PROTECTION

2UA

STANDARD DESIGN

2WA

WITHOUT ADDITIONAL TIRES

2Z1

TYPE SIGN AT REAR AND "QUATTRO" NAMEPLATES RESPECTIVELY

2ZQ

LEATHER-WRAPPED MULTIFUNCTION STEERING WHEEL FOR AIRBAG SYSTEM

3B4

CHILD SEAT ANCHOR FOR CHILD SEAT SYSTEM ISOFIX

3C7

3-POINT SEAT BELT FOR CENTER REAR SEAT

3FU

BIG ROOF SYSTEM

3G0

WITHOUT CHILD SEAT ANCHOR FRONT (ISOFIX)

3GA

WITHOUT CARGO AREA

3H0

WITHOUT BACKREST RELEASE FOR FRONT SEATS

3K0

WITHOUT SAFETY HEAD RESTRAINT SYSTEM

3L5

POWER SEAT ADJUSTMENT FOR BOTH FRONT SEATS

3M0

WITHOUT SPECIAL MEASURES

3NZ

UNSPLIT REAR SEAT BENCH UNSPLIT, SPLIT FOLDING BACKREST

3S2

BLACK ROOF RAILS

3SB

STANDARD SEAT IN FRONT, RIGHT

3TB

STANDARD SEAT IN FRONT, LEFT

3X0

WITHOUT LOAD-THROUGH HATCH

4A0

WITHOUT SEAT HEATER

4E0

TAILGATE/TRUNK LID UNLOCKING FROM OUTSIDE

4GH

WINDSHIELD IN HEAT-INSULATING GLASS WITH SUNSHIELD

4K4

RADIO REMOTE CONTROLLED CENTRAL LOCKING

4KC

SIDE AND REAR WINDOWS IN HEAT-INSULATING GLASS

4L2

DIMMING BREAKAWAY INTERIOR REARVIEW MIRROR

4UE

AIRBAG FOR DRIVER AND FRONT PASSENGER

4X3

SIDE AIRBAG IN FRONT, WITH CURTAIN AIRBAG

4ZE

BLACK MOLDINGS

5C0

WITHOUT SPECIAL BODY MEASURES

5D1

CARRIER FREQUENCY 433.92 MHZ-434.42 MHZ

5J1

REAR SPOILER

5K5

TRANSIT COATING FILM WITH ADDITIONAL TRANSPORT PROTECTION MEASURES

5MA

DECORATIVE INSERTS

5NC

STANDARD TAILGATE/TRUNK LID STAY

5RU

RIGHT EXTERIOR MIRROR: CONVEX (LARGE VIEWING FIELD)

5SL

LEFT EXTERIOR MIRROR: ASPHERICAL

6E3

CENTER ARMREST IN FRONT

6F0

WITHOUT DECORATIVE FILMS / EMBLEMS

6FA

COMPONENTS WITHOUT SPECIAL SURFACE APPEARANCE

6NJ

STANDARD MOLDED HEADLINER

6SS

LUGGAGE COMPARTMENT FLOOR COVERING

6V1

REAR TRIM PANEL (ECE)

6W1

FRONT LICENSE PLATE CARRIER (LARGE)

6XE

EXTERIOR MIRRORS, POWER-FOLDING AND POWER-ADJUSTABLE/HEATED

7A7

WITHOUT CD CHANGER

7AA

ELECTRONIC ENGINE IMMOBILIZER

7E6

ELECTRIC AUXILIARY AIR HEATER

7F9

PLASTIC/LEATHER GEARSHIFT KNOB/HANDLE

7G0

WITHOUT PREPARATION FOR VTS (VEHICLE TRACKING SYSTEM)

7K0

WITHOUT DIRECT TIRE PRESSURE MONITORING SYSTEM

7KV

VEHICLE CLASS DIFFERENTIATION -8U0/8UD-

7L6

START/STOP SYSTEM WITH REGENERATIVE BRAKING

7M0

PLASTIC SCUFF PLATES IN DOOR APERTURES

7MJ

EMISSION STANDARD EU5 PLUS

7P1

POWER-ADJUSTABLE LUMBAR SUPPORT IN FRONTSEATS

7RE

SD CARD (EUROPE)

7T2

NAVIGATION SYSTEM (LOW)

7X4

PARK DISTANCE CONTROL IN FRONT AND REAR

7Y0

WITHOUT LANE CHANGE ASSIST

8AL

RADIO MEDIA CENTER (RMC)

8BP

BI-FUNCTIONAL HEADLAMP WITH GAS DISCHARGE LAMP

8GU

ALTERNATOR 140 A

8K4

SEPARATE DAYTIME RUNNING LIGHTS -- NAR --

8N6

WINDSHIELD WIPER INTERMITTENT CONTROL WITH LIGHT/RAIN SENSOR

8Q3

AUTOMATIC HEADLIGHT RANGE ADJUSTMENT DYNAMIC (SELF-ADJUSTING WHILE DRIVING)

8RX

PASSIVE SPEAKERS

8SK

LED TAIL LAMP ASSEMBLY

8T2

CRUISE CONTROL SYSTEM (CCS) ELECTRONIC

8TB

REAR FOG LAMP

8X1

HEADLAMP WASHER SYSTEM

8Y1

TWO-TONE HORN

8Z5

NOT HOT COUNTRY

9AK

CLIMATRONIC WITH IMPACT PRESSURE CONTROL, CFC-FREE

9JC

SMOKER'S VERSION

9M0

WITHOUT AUXILIARY HEATER/FUEL-FIRED PARKING HEATER

9P8

SEAT BELT REMINDER

9Q7

MULTI-FUNCTION DISPLAY/ON-BOARD COMPUTER

9WC

WITHOUT "MULTIMEDIA" IN VEHICLE

9Z0

OPERATING VOLTAGE 12 V

9ZX

MOBILE PHONE INTERFACE

A00

NO SELF-COLLECTION

A51

AUDI AG

A8S

STANDARD EQUIPMENT

AQ0

STANDARD-PRODUCTION QUALITY

AV1

DRIVING ON THE RIGHT

B0A

COMPONENT PARTS SET WITHOUT COUNTRY-SPECIFIC BUILDING REGULATION

B14

TYPE APPROVAL COUNTRY ITALY (SAN MARINO, VATICAN CITY)

C09

OPERATING PERMIT, ALTERATION

C2G

ALLOY WHEELS 7J X 17

D91

4-CYL.TURBO DIESEL ENG.2.0 L/103 KW (4V)TDI COMMON RAIL; BASE ENGINE IS TG3/TJ3/T5P/TU3/TU4/TL4/TP4/TM3/TW3/TR4/TS1/TN5

E0A

NO SPECIAL EDITION

EA0

WITHOUT FOLLOW-ON WARRANTY

EWO

WITHOUT MAINTENANCE CONTRACT

F0A

NO SPECIAL PURPOSE VEHICLE, STANDARD EQUIPMENT

FA0

CONTROL OF SERIES PRODUCTION

FC0

WITHOUT CUSTOMIZED INSTALLATION

FF1

WITH VIEWING WINDOW FOR VEHICLE IDENTIFICATION NUMBER

FM0

BASIC EQUIPMENT VARIANT

FQ0

PRODUCTION WHEELS

G05

SHOCK ABSORPTION IN FRONT

G1D

7-SPEED AUTOMATIC TRANSMISSION FOR FOUR-WHEEL DRIVE

GP1

VEHICLES WITH SPECIAL UPGRADE MEASURES

H50

TIRES 235/55 R17 99V

J2D

BATTERY 380 A (68 AH)

K4H

CLOSED BODY

KA0

WITHOUT CAMERA SYSTEMS/ACCIDENT SENSORS

KK1

REFRIGERANT R134A

L0L

LEFT-HAND DRIVE

L32

SUSPENSION RANGE 32 INSTALLATION CONTROL ONLY, NO REQUIREMENT FORECAST

N5W

SEAT TRIM COVERS IN LEATHER

NM1

ENGINE COVER

NT0

TRANSIT COATING (TYPE 1)

NY0

STANDARD BATTERY/ALTERNATOR CAPACITY

QE0

WITHOUT STORAGE COMPARTMENT PACKAGE/BOX

QG1

SERVICE INTERVAL PROLONGATION

QH1

VOICE CONTROL

QK0

WITHOUT MULTIFUNCTION CAMERA

QQ1

WITH ADDITIONAL LIGHTS (INTERIOR LIGHTING)

QR8

WITHOUT DYNAMIC ROAD SIGN DISPLAY

QV0

WITHOUT TV RECEPTION/DIGITAL RADIO RECEPTION

TL4

4-CYLINDER DIESEL ENGINE 2.0 L UNIT 03L.L

U1A

INSTRUMENT CLUSTER WITH KM/H SPEEDOMETER, CLOCK, TACHOMETER, AND TRIP ODOMETER

UA0

REAR SHOCK ABSORPTION

UF7

ELECTRIC INTERFACE FOR EXTERNAL USE

UG1

HILL START ASSIST

UH2

PARKING BRAKE

V0A

TIRES WITHOUT SPECIFICATION OF TIRE BRAND

VF0

STANDARD PEDAL CLUSTER

VG6

TYPE OF TIRE: DESIGN 2

VLO

STANDARD PEDESTRIAN PROTECTION MEASURES

X4C

EQUIPMENT OPTIONS SUBSET FOR ITALY

Cronologie

S-au găsit 5 înregistrări

Cronologia înregistrărilor pentru acest vehicul

Ultimele înregistrări

2014-01

 Țară necunoscută



A fost fabricat

Țara (sau statul) indică fie locația centrului de producție, uzina de asamblare sau adresa de înregistrare a producătorului. Data poate fi aproximativă.

2014-04

 Italia



A fost înmatriculat

Înregistrarea reprezintă un eveniment administrativ. Acest lucru ar putea fi legat de o schimbare de proprietar, documente etc

2022-07

 Italia



A fost verificat

A fost înregistrat un eveniment de inspecție tehnică (cunoscut și sub denumirea de ITP, test tehnic sau test de control al emisiilor). Pot fi incluse atât instanțe reușite, cât și eșuate.

2023-07

 România



A fost înmatriculat

Înregistrarea reprezintă un eveniment administrativ. Acest lucru ar putea fi legat de o schimbare de proprietar, documente etc

2023-08

 Italia



Mașină radiată

Înregistrarea indicată reprezintă un eveniment administrativ. Acesta ar putea fi legat de o schimbare de proprietar, o schimbare a documentelor sau o chestiune similară.



+31

Surse de date

Am verificat 900+ de surse de date în **35 de țări**