

Audi Q3

VIN: WAUZZZ8U4DR010358

Diesel

2013

Generat pe 2025-01-13 06:35



Odometru

✓ Arată bine



Statut legal

✓ Arată bine



Daune

✓ Arată bine



+31

Surse de date

Am verificat 900+ de surse de date în 35 de țări

Furt

Vehiculul este în prezent marcat ca furat? A fost furat în trecut? A fost recuperat?



Nu s-au găsit probleme

Nu am găsit nicio înregistrare că vehiculul a fost furat.



Notă

Verificarea bazei de date a poliției privind vehiculele furate finalizată în 8 țări: +2

Iată ce am verificat:



Căutat drept furat

✓ Nu s-a găsit nici o înregistrare



Furat în trecut

✓ Nu s-a găsit nici o înregistrare

Starea actuală necunoscută



Furat în trecut

✓ Nu s-a găsit nici o înregistrare

Vehiculul a fost recuperat

Baza de date aparținând poliției cu vehicule furate, **verificare finalizată în:**



România



Statele Unite ale Americii



Lituania



Danemarca



Slovacia




Slovenia

Odometru

Există semne conform cărora kilometrajul a fost dat înapoi sau discrepanțe ale kilometrajului?

Notă

Ultimul kilometraj cunoscut: 189.594 km




Disclaimer (declinarea responsabilității): acest grafic reprezintă o tendință estimată a kilometrajului. Deși se bazează pe înregistrări reale de kilometraj disponibile pentru acest vehicul, există lacune având în vedere că evoluția kilometrajului nu este înregistrată în mod constant. Pentru a lua în considerare aceste date lipsă, aplicăm un model patentat de analiză a datelor care prezice modul în care probabil s-a schimbat kilometrajul între evenimentele înregistrate. Acest lucru ajută la furnizarea unei imagini mai complete a utilizării vehiculului în timp.

Statut legal

A trecut vehiculul inspecțiile tehnice? A fost notat drept casat?

Notă

Inspekția tehnică a fost transmisă pe 2023-05 în  **România**

Legal



Inspekție tehnică periodică (ITP)

A trecut 2023-05

 **România**

A trecut cu succes inspekția tehnică
Valabil până la 2025-05



Casat

✓ Nu s-a găsit nici o înregistrare

Nu există nici o înregistrare că vehiculul a fost marcat drept casat

Daune

Acest vehicul a fost avariat în trecut ? Care a fost valoarea daunelor?

✓ **Nu s-au găsit probleme**

Înregistrări de daune



Ocazional pot apărea inexactități, mai ales la verificarea vehiculelor vechi. Atelierele clandestine de reparații pot deghiza ilegal defectele sau daunele vehiculelor, fără să declare nicăieri existența lor. Uneori până și plăcuțele VIN ale vehiculului pot fi înlocuite. Avem o varietate de metode de a detecta chiar și astfel de infracțiuni, dar este imposibil de oferit o garanție de 100%.

Dezastre naturale

Locația vehiculului a fost înregistrată în zona unui dezastru natural?

✓ Nu s-au găsit probleme

Locația vehiculului nu a fost înregistrată în zona unui dezastru natural

Valoarea de piață

Cu cât s-a vândut vehiculul în trecut? Care este în medie prețul vehiculelor din acest model și an?

i Notă

- Prețul mediu de pe piață pentru un astfel de vehicul: 67.734 RON
- Atenție la problemele ascunse dacă vehiculul a fost la vânzare la un preț semnificativ mai mic decât prețul actual!

Valoarea de piață azi pentru Audi Q3 2013

Valoarea de piață este determinată prin examinarea prețului unui anumit model de mașină (fabricat în același an) în țara în care a fost generat raportul. Analizăm datele din ultimele 6 luni.

Cel mai mic preț

66.093 RON

Prețul mediu

67.734 RON

Cel mai mare preț

71.912 RON

Emisii

Câte emisii de CO2 produc vehiculele din acest model/an?

i Notă

Emisii CO2: D (156 g/km)

Emisii CO₂

Emisiile CO₂ ale

Emisii CO₂ ale
vehiculului tău

156 g/km Clasă **D**

Până la 120

120 - 140

140 - 155

155 - 165

165 - 190

190 - 225

225 și peste

Emisii CO₂ g/km

Specificații și echipare

Ce specificații și echipamente sunt înregistrate pentru acest vehicul?

Notă

Verificați dacă specificațiile și echipamentul acestui vehicul se potrivesc cu datele furnizate de vânzător.

Identificare și specificații tehnice



Producător

Audi



Model

Q3



Tip caroserie

Break



An de fabricație

2013



Capacitate cilindrică

2 l



Putere motor

130 kW (174 cp)



Tip combustibil

Diesel



Cutie de viteze

Automată



Tip transmisie

Tracțiune integrală (AWD)



Culoare

Gri



Amplasarea volanului

Volan pe stânga



Nr. cilindri

4



Nr. locuri

5



Cod motor

CFG



Categorie

m1

Echipare

Cum a fost primit de la producător

OAK

FRONT STABILIZER

OBE

REAR STABILIZER

OC0

STANDARD

OEX

INSTALLATION DIFFERENTIATION FOR TRANSMISSION DQ500 -- VEHICLE COMPONENTS --

OF9

COOLED FUEL SYSTEM FOR DIESEL ENGINE

OFA

STANDARD MANUFACTURING SEQUENCE

OLZ

WITH SPECIAL PLATES/LABELS/ SAFETY CERTIFICATES FOR LUXEMBOURG

ONA

WITHOUT NAMEPLATE SET (WITHOUT MODEL DESIGNATION)

OST

LABELS/PLATES IN GERMAN AND FRENCH

0TD

FLOOR MATS IN FRONT AND REAR

0U2

FUEL QUALITY < 50 PPM

0VC

INFORMATION KIT IN GERMAN

0W1

LABEL FOR CENTRAL ELECTRIC GERMAN-SPEAKING COUNTRIES

0Y1

STANDARD CLIMATIC ZONES

0YF

WEIGHT RANGE 6 INSTALLATION CONTROL ONLY, NO REQUIREMENT FORECAST

1AT

ELECTRONIC STABILITY CONTROL (ESC)

1D0

WITHOUT TRAILER HITCH

1E0

WITHOUT ACTIVATED CARBON CANISTER

1EX

SPECIAL IDENTIFICATION PLATE FOR EC FOR M1 PASSENGER VEHICLE

1G9

SPACE-SAVING SPARE WHEEL FOR TEMPORARY USE, RADIAL TIRE (5-HOLE)

1KU

DISK BRAKES IN REAR

1LJ

DISK BRAKES IN FRONT

1PA

STANDARD WHEEL BOLTS

1S1

TOOL KIT AND JACK

1SA

WITHOUT ADDITIONAL FRONT UNDERBODY GUARD

1T3

FIRST AID KIT WITH WARNING TRIANGLE

1U8

WITHOUT FOLDING TABLE ON FRONT SEAT BACKREST

1VG

INSTALLATION PARTS FOR FOUR-CYLINDER ENGINE

1X1

FOUR WHEEL DRIVE

1Z1

INCREASE IN INITIAL STANDARD FUEL FILLING

2D0

WITHOUT CD ENHANCING UNDERBODY PANEL

2G5

FILLER NECK MODULE 1 WITHOUT INSERT

2H0

WITHOUT "DRIVE SELECT"

2K1

REINFORCED BUMPERS

2P1

PLASTIC LOADING EDGE PROTECTION

2UA

STANDARD DESIGN

2WA

WITHOUT ADDITIONAL TIRES

2Z0

ELIMINATION OF MODEL DESIGNATION

2ZQ

LEATHER-WRAPPED MULTIFUNCTION STEERING WHEEL FOR AIRBAG SYSTEM

3B4

CHILD SEAT ANCHOR FOR CHILD SEAT SYSTEM ISOFIX

3C7

3-POINT SEAT BELT FOR CENTER REAR SEAT

3FA

WITHOUT ROOF INSERT (STANDARD ROOF)

3G0

WITHOUT CHILD SEAT ANCHOR FRONT (ISOFIX)

3GD

PLANE REAR CARGO AREA

3H0

WITHOUT BACKREST RELEASE FOR FRONT SEATS

3K0

WITHOUT SAFETY HEAD RESTRAINT SYSTEM

3L3

MANUAL HEIGHT ADJUSTMENT FOR FRONT SEATS

3M0

WITHOUT SPECIAL MEASURES

3NZ

UNSPLIT REAR SEAT BENCH UNSPLIT, SPLIT FOLDING BACKREST

3S2

BLACK ROOF RAILS

3SB

STANDARD SEAT IN FRONT, RIGHT

3TB

STANDARD SEAT IN FRONT, LEFT

3X0

WITHOUT LOAD-THROUGH HATCH

4A3

SEAT HEATER FOR FRONT SEATS SEPARATELY CONTROLLED

4GH

WINDSHIELD IN HEAT-INSULATING GLASS WITH SUNSHIELD

4K4

RADIO REMOTE CONTROLLED CENTRAL LOCKING

4KC

SIDE AND REAR WINDOWS IN HEAT-INSULATING GLASS

4L6

BREAKAWAY INTERIOR REARVIEW MIRROR, AUTO-DIMMING

4UE

AIRBAG FOR DRIVER AND FRONT PASSENGER

4X3

SIDE AIRBAG IN FRONT, WITH CURTAIN AIRBAG

4ZE

BLACK MOLDINGS

5C0

WITHOUT SPECIAL BODY MEASURES

5D1

CARRIER FREQUENCY 433.92 MHz-434.42 MHz

5K5

TRANSIT COATING FILM WITH ADDITIONAL TRANSPORT PROTECTION MEASURES

5MF

DECORATIVE ALUMINUM INSERTS

5RU

RIGHT EXTERIOR MIRROR: CONVEX (LARGE VIEWING FIELD)

5SL

LEFT EXTERIOR MIRROR: ASPHERICAL

6E3

CENTER ARMREST IN FRONT

6F0

WITHOUT DECORATIVE FILMS / EMBLEMS

6NJ

STANDARD MOLDED HEADLINER

6SS

LUGGAGE COMPARTMENT FLOOR COVERING

6V1

REAR TRIM PANEL (ECE)

6W1

FRONT LICENSE PLATE CARRIER (LARGE)

6XE

EXTERIOR MIRRORS, POWER-FOLDING AND POWER-ADJUSTABLE/HEATED

7A7

WITHOUT CD CHANGER

7AA

ELECTRONIC ENGINE IMMOBILIZER

7E6

ELECTRIC AUXILIARY AIR HEATER

7F9

PLASTIC/LEATHER GEARSHIFT KNOB/HANDLE

7G0

WITHOUT PREPARATION FOR VTS (VEHICLE TRACKING SYSTEM)

7K0

WITHOUT DIRECT TIRE PRESSURE MONITORING SYSTEM

7KV

VEHICLE CLASS DIFFERENTIATION -8U0/8UD-

7L6

START/STOP SYSTEM WITH REGENERATIVE BRAKING

7M0

PLASTIC SCUFF PLATES IN DOOR APERTURES

7MQ

EMISSIONS STANDARD EU5 MOD

7P0

WITHOUT LUMBAR SUPPORT IN SEAT BACKRESTS

7QA

WITHOUT CD/DVD FOR NAVIGATION

7T6

NAVIGATION SYSTEM (MID)

7X4

PARK DISTANCE CONTROL IN FRONT AND REAR

7Y5

LANE CHANGE ASSIST AND LANE KEEPING SYSTEM

8BP

BI-FUNCTIONAL HEADLAMP WITH GAS DISCHARGE LAMP

8GU

ALTERNATOR 140 A

8K4

SEPARATE DAYTIME RUNNING LIGHTS -- NAR --

8N7

WINDSHIELD WIPER INTERMITTENT CONTROL WITH LIGHT/RAIN SENSOR

8Q3

AUTOMATIC HEADLIGHT RANGE ADJUSTMENT DYNAMIC (SELF-ADJUSTING WHILE DRIVING)

8RX

PASSIVE SPEAKERS

8SK

LED TAIL LAMP ASSEMBLY

8T2

CRUISE CONTROL SYSTEM (CCS) ELECTRONIC

8TB

REAR FOG LAMP

8X1

HEADLAMP WASHER SYSTEM

8YQ

RADIO "HIGH"

8Z5

NOT HOT COUNTRY

9AK

CLIMATRONIC WITH IMPACT PRESSURE CONTROL, CFC-FREE

9JA

NON-SMOKER'S PACKAGE

9M0

WITHOUT AUXILIARY HEATER/FUEL-FIRED PARKING HEATER

9P8

SEAT BELT REMINDER

9Q8

MULTI-FUNCTION DISPLAY/ON-BOARD COMPUTER

9WC

WITHOUT "MULTIMEDIA" IN VEHICLE

9Z0

OPERATING VOLTAGE 12 V

9ZX

MOBILE PHONE INTERFACE

A00

NO SELF-COLLECTION

A51

AUDI AG

A8S

STANDARD EQUIPMENT

AQ0

STANDARD-PRODUCTION QUALITY

AV1

DRIVING ON THE RIGHT

B0A

COMPONENT PARTS SET WITHOUT COUNTRY-SPECIFIC BUILDING REGULATION

B32

TYPE APPROVAL COUNTRY LUXEMBOURG

C05

OPERATING PERMIT, ALTERATION

C0Y

ALLOY WHEELS 6.5J X 16

DE2

4-CYL. TURBO DIES. ENG. 2.0 L/130 KW 4V TDI COMMON RAIL BASE ENGINE TR1,TD1,TM4/TL4/TP4

E0A

NO SPECIAL EDITION

EA9

3 YEARS FOLLOW-ON WARRANTY, MAX. 150 000 KM

EW0

WITHOUT MAINTENANCE CONTRACT

F0A

NO SPECIAL PURPOSE VEHICLE, STANDARD EQUIPMENT

FA0

CONTROL OF SERIES PRODUCTION

FC0

WITHOUT CUSTOMIZED INSTALLATION

FF0

WITHOUT VIEWING WINDOW FOR VEHICLE IDENTIFICATION NUMBER

FM0

BASIC EQUIPMENT VARIANT

FQ0

PRODUCTION WHEELS

G05

SHOCK ABSORPTION IN FRONT

G1D

7-SPEED AUTOMATIC TRANSMISSION FOR FOUR-WHEEL DRIVE

H4P

TIRES 215/65 R16 98V

J2D

BATTERY 380 A (68 AH)

K4H

CLOSED BODY

KA0

WITHOUT CAMERA SYSTEMS/ACCIDENT SENSORS

KK1

REFRIGERANT R134A

L0L

LEFT-HAND DRIVE

L32

SUSPENSION RANGE 32 INSTALLATION CONTROL ONLY, NO REQUIREMENT FORECAST

N5W

SEAT TRIM COVERS IN LEATHER

NT0

TRANSIT COATING (TYPE 1)

NY0

STANDARD BATTERY/ALTERNATOR CAPACITY

QE5

STORAGE COMPARTMENT PACKAGE 3

QG1

SERVICE INTERVAL PROLONGATION

QH1

VOICE CONTROL

QK1

WITH MULTIFUNCTION CAMERA

QQ0

WITHOUT ADD. LIGHTS (INTERIOR LIGHTING)

QR9

WITH DYNAMIC ROAD SIGN DISPLAY

QV0

WITHOUT TV RECEPTION/DIGITAL RADIO RECEPTION

TL4

4-CYLINDER DIESEL ENGINE 2.0 L UNIT 03L.L

U2A

INSTRUMENT CLUSTER WITH K M/H SPEEDOMETER, RADIO-CONTROLLED CLOCK,TACHOMETER AND TRIP ODOMETER

UA0

REAR SHOCK ABSORPTION

UF7

ELECTRIC INTERFACE FOR EXTERNAL USE

UG1

HILL START ASSIST

UH2

PARKING BRAKE

V0A

TIRES WITHOUT SPECIFICATION OF TIRE BRAND

VF0

STANDARD PEDAL CLUSTER

VG6

TYPE OF TIRE: DESIGN 2

VL0

STANDARD PEDESTRIAN PROTECTION MEASURES

X2D

Cronologie

S-au găsit 4 înregistrări

Cronologia înregistrărilor pentru acest vehicul

Ultimele înregistrări

2013-01  Țară necunoscută



A fost fabricat

Țara (sau statul) indică fie locația centrului de producție, uzina de asamblare sau adresa de înregistrare a producătorului. Data poate fi aproximativă.

2018-11  România



A fost înmatriculat

Înregistrarea reprezintă un eveniment administrativ. Acest lucru ar putea fi legat de o schimbare de proprietar, documente etc

2021-05  România



A fost verificat

A fost înregistrat un eveniment de inspecție tehnică (cunoscut și sub denumirea de ITP, test tehnic sau test de control al emisiilor). Pot fi incluse atât instanțe reușite, cât și eșuate.

2023-05  România



A fost verificat

A fost înregistrat un eveniment de inspecție tehnică (cunoscut și sub denumirea de ITP, test tehnic sau test de control al emisiilor). Pot fi incluse atât instanțe reușite, cât și eșuate.



+31

Surse de date

Am verificat 900+ de surse de date în **35 de țări**