

Audi



VIN: WAUZZZF84NN001111

1997

Generat pe 2024-11-15 09:40



Contor de parcurs

⚠ Necesită atenție



Statut legal

✓ Arată bine



Daune

✓ Arată bine



+31

Surse de date

Am verificat 900+ de surse de date în **35 de țări**

Furt

Vehiculul este în prezent marcat ca furat? A fost furat în trecut? A fost recuperat?



Nu s-au găsit probleme

Nu am găsit nicio înregistrare că vehiculul a fost furat.



Notă

Verificarea bazei de date a poliției privind vehiculele furate finalizată în **9 țări**: +3

Iată ce am verificat:



Căutat drept furat

✓ Nu s-a găsit nici o înregistrare



Furat în trecut

✓ Nu s-a găsit nici o înregistrare

Starea actuală necunoscută



Furat în trecut

✓ Nu s-a găsit nici o înregistrare

Vehiculul a fost recuperat

Baza de date aparținând poliției cu vehicule furate, **verificare finalizată în:**



România



Slovacia



Lituania



Statele Unite ale Americii



Danemarca



Suedia



Finlanda



Cehia



Slovenia

Contor de parcurs

Există semne conform cărora kilometrajul a fost dat înapoi sau discrepanțe ale kilometrajului?


⚠ Ai grijă!

Acest vehicul poate avea un kilometraj fals!

i Notă

Ultimul kilometraj cunoscut: 29.464 km

⚠ Dat înapoi



Disclaimer (declinarea responsabilității): acest grafic reprezintă o tendință estimată a kilometrajului. Deși se bazează pe înregistrări reale de kilometraj disponibile pentru acest vehicul, există lacune având în vedere că evoluția kilometrajului nu este înregistrată în mod constant. Pentru a lua în considerare aceste date lipsă, aplicăm un model patentat de analiză a datelor care prezice modul în care probabil s-a schimbat kilometrajul

Între evenimentele înregistrate. Acest lucru ajută la furnizarea unei imagini mai complete a utilizării vehiculului în timp.

Statut legal

A trecut vehiculul inspecțiile tehnice? A fost notat drept casat?

- ✓ **Nu s-au găsit probleme**
Nu s-au găsit înregistrări despre statutul legal al acestui vehicul

Legal



Inspecție tehnică periodică (ITP)

- ✓ Nu s-a găsit nici o înregistrare

Nu au fost găsite înregistrări ale inspecției tehnice



Casat

- ✓ Nu s-a găsit nici o înregistrare

Nu există nici o înregistrare că vehiculul a fost marcat drept casat

Daune

Acest vehicul a fost avariat în trecut? Care a fost valoarea daunelor?

- ✓ **Nu s-au găsit probleme**

Înregistrări de daune



Ocazional pot apărea inexactități, mai ales la verificarea vehiculelor vechi. Atelierele clandestine de reparații pot deghiza ilegal defectele sau daunele vehiculelor, fără să declare nicăieri existența lor. Uneori până și plăcuțele VIN ale vehiculului pot fi înlocuite. Avem o varietate de metode de a detecta chiar și astfel de infracțiuni, dar este imposibil de oferit o garanție de 100%.

Dezastru natural

Locația vehiculului a fost înregistrată în zona unui dezastru natural?



Nu s-au găsit probleme

Locația vehiculului nu a fost înregistrată în zona unui dezastru natural

Specificații și echipare

Ce specificații și echipamente sunt înregistrate pentru acest vehicul?



Notă

Verificați dacă specificațiile și echipamentul acestui vehicul se potrivesc cu datele furnizate de vânzător.

Identificare și specificații tehnice



Producător

Audi



Tip caroserie

Sedan



An de fabricație

1997



An model

2022



Capacitate cilindrică

4 l



Putere motor

420 kW (563 cp)



Cutie de viteze

Automată



Amplasarea volanului

Volan pe stânga



Nr. cilindri

6



Nr. angrenaje

8

Echipare

Cum a fost primit de la producător

0JM

WEIGHT CATEGORY FRONT AXLE WEIGHT RANGE 12

0K4

HYBRID PROPULSION SYSTEM I-HEV

0LW

WITH SPECIAL PLATES/LABELS/ SAFETY CERTIFICATES FOR GERMANY

0M1

FUEL TANK

0N5

STANDARD REAR AXLE

0P0

REAR EXHAUST TAILPIPE (STANDARD)

0RZ

WITHOUT IGNITION/STARTER SWITCH LOCKING SYSTEM, WITHOUT STEERING LOCK

0TF

WITH FLOOR MATS

0VC

INFORMATION KIT IN GERMAN

0Y1

STANDARD CLIMATIC ZONES

0YK

WEIGHT RANGE 10 INSTALLATION CONTROL ONLY, NO REQUIREMENT FORECAST

1A2

FUEL SYSTEM FOR SI ENGINE WITH DIRECT INJECTION (FSI)

1D3

TRAILER HITCH

1EX

SPECIAL IDENTIFICATION PLATE FOR EC FOR M1 PASSENGER VEHICLE

1G8

BREAKDOWN KIT

1KQ

DISK BRAKES IN REAR

1LB

DISK BRAKES IN FRONT

1PR

WHEEL BOLTS WITH THEFT PROTECTION AND LOOSE WHEEL DETECTION

1S2

TOOL KIT

1SA

WITHOUT ADDITIONAL FRONT UNDERBODY GUARD

1T3

FIRST AID KIT WITH WARNING TRIANGLE

1U0

WITHOUT TABLE

1VJ

INSTALLATION PARTS FOR EIGHT-CYLINDER ENGINE

1W2

GLOVE COMPARTMENT COOLING SYSTEM

1XP

LEATHER-WRAPPED MULTIFUNCTION SPORTS STEERING WHEEL

1Z6

INCREASE IN INITIAL STANDARD FUEL FILLING

2F1

LOCKING AND STARTING SYSTEMS

2K3

REINFORCED BUMPERS

2KR

LABELS/PLATES IN ENGLISH AND GERMAN

2L1

HEATED SURFACES IN FRONT

2MQ

SUSPENSION/SHOCK ABSORPTION

2V9

FRESH AIR INTAKE AND AIR IONIZER

2WA

WITHOUT ADDITIONAL TIRES

2Z8

TYPE SIGN AND COMPANY LOGO

3B4

CHILD SEAT ANCHOR FOR CHILD SEAT SYSTEM ISOFIX

3D1

CENTER CONSOLE

3FB

SPOILER ROOF

3PR

POWER SEAT ADJUSTMENT FOR BOTH FRONT SEATS WITH MEMORY FEATURE

3Q3

REAR HEAD RESTRAINTS

3X4

LOAD-THROUGH HATCH

3Y8

POWER-OPERATED ROLL-UP SUNSHADE FOR REARWINDOW AND FOR REAR SIDE WINDOWS

4A4

SEAT HEATER FOR FRONT AND REAR SEATS SEPARATELY CONTROLLED

4D2

SEAT VENTILATION/MESSAGE SEATS IN FRONT AND REAR

4E7

TAILGATE/TRUNK LID POWER CLOSING

4F2

CENTRAL LOCKING SYSTEM "KEYLESS ENTRY"

4GR

LAMINATED WINDSHIELD, HEATED

4UF

DRIVER AND FRONT PASSENGER AIRBAG WITH FRONT PASSENGER AIRBAG DEACTIVATION

4ZP

MOLDINGS

5C0

WITHOUT SPECIAL BODY MEASURES

5D1

CARRIER FREQUENCY 433.92 MHZ-434.42 MHZ

5K5

TRANSIT COATING FILM WITH ADDITIONAL TRANSPORT PROTECTION MEASURES

5KF

REAR SEAT BENCH/BACKREST, UNFOLDING

5N1

FOLDING GRAB HANDLES

5SL

LEFT EXTERIOR MIRROR: ASPHERICAL

5TL

DECORATIVE INSERTS IN PIANO LACQUER

5XH

SUN VISORS WITH MIRROR, ILLUMINATED

6A0

WITHOUT FIRE EXTINGUISHER

6C4

SIDE AIRBAG IN FRONT AND REAR, WITH CURTAIN AIRBAG AND INTERACTION AIRBAG IN FRONT

6E3

CENTER ARMREST IN FRONT

6F7

EMBLEMS

6FB

BODY-COLORED EXTERIOR MIRROR HOUSINGS

6I6

LANE KEEPING SYSTEM PLUS SEMI-AUTOMATIC VEHICLE CONTROL IN A MEDICAL EMERGENCY AND TRAFFIC JAM ASSIST

6K8

PRE SENSE CITY WITHOUT PRE CARE

6M1

TIE DOWN STRAPS

6NS

ALCANTARA MOLDED HEADLINER

6TS

RIGHT EXTERIOR MIRROR, ASPHERICAL, LARGE VIEWING FIELD

6V1

REAR TRIM PANEL (ECE)

6W6

FRONT LICENSE PLATE CARRIER

6XL

EXTERIOR MIRRORS WITH MEMORY FEATURE, AUTO-DIMMING, POWER-FOLDING/ADJUSTABLE/HEATED

6Y0

WITHOUT CRUISE CONTROL WARNING SYSTEM

73A

WITHOUT CHARGING CABLE (INDUSTRIAL CONNECTOR)

76A

WITHOUT MODE 3 CHARGING CABLE

7AL

ANTI-THEFT ALARM SYSTEM, INTERIOR MONITORING, BACKUP HORN, AND TOWING PROTECTION

7D5

DVD PLAYER

7E0

WITHOUT HEAT ACCUMULATOR/AUXILIARY HEATER

7F5

GEARSHIFT KNOB (SPECIAL EDITION)

7G0

WITHOUT PREPARATION FOR VTS (VEHICLE TRACKING SYSTEM)

7HC

LEATHER VARIANT 2

7IV

VEHICLE CLASS DIFFERENTIATION 4N0/4N4/4N6

7K3

DIRECT TIRE PRESSURE MONITORING SYSTEM, FREQUENCY 433 MHZ HIGH

7L8

START/STOP SYSTEM WITH REGENERATIVE BRAKING

7P3

POWER-ADJUSTABLE LUMBAR SUPPORT IN FRONTSEATS AND OUTER REAR SEATS

7UG

NAVIGATION SYSTEM - HIGH

7W3

WITH EXTENDED SAFETY SYSTEM (PROACTIVE PASSENGER PROTECTION SYSTEM, BASIC AND REAR)

7X5

PARK ASSIST

7Y1

LANE CHANGE ASSIST

8G5

MULTIPLE MATRIX BEAM

8IV

LED HEADLAMPS WITH VARIABLE LIGHT DISTRIBUTION

8K4

SEPARATE DAYTIME RUNNING LIGHTS -- NAR --

8S9

READING LIGHTS, BASE EQUIPMENT

8T8

ADAPTIVE CRUISE CONTROL (WITH "FOLLOW-TO-STOP") AND SPEED LIMITER

8X1

HEADLAMP WASHER SYSTEM

8Y1

TWO-TONE HORN

8Z5

NOT HOT COUNTRY

9AU

CLIMATRONIC WITH IMPACT PRESSURE CONTROL CFC-FREE, WITH CONTROLS IN THE REAR

9B0

WITHOUT TELEPAY DEVICE

9G8

BELT-DRIVEN STARTER ALTERNATOR 48 V 110-250 A

9JB

SMOKER'S PACKAGE, ASHTRAY IN FRONT AND REAR

9M9

FUEL-FIRED PARKING HEATER WITH RADIO REMOTE CONTROL

9P9

SEAT BELT REMINDER, ELECTRIC CONTACT IN THE BUCKLE, ADVANCED SAFETY EQUIPMENT

9PF

WIPER BLADES WITH INTEGRATED NOZZLES

9R0

WITHOUT NIGHT VISION

9S9

.

9TA

WITHOUT ADDITIONAL WARNING LIGHTS

9VS

SOUND PACKAGE "BRANDED"

9WP

MULTIMEDIA IN REAR COMPARTMENT

9Z3

12-V OPERATING VOLTAGE AND 230-V INVERTER

9ZE

COMFORT TELEPHONE SYSTEM

A00

NO SELF-COLLECTION

A51

AUDI AG

A60

CATEGORY 0

A8S

STANDARD EQUIPMENT

AQ0

STANDARD-PRODUCTION QUALITY

AV1

DRIVING ON THE RIGHT

B01

TYPE APPROVAL COUNTRY GERMANY

B0A

COMPONENT PARTS SET WITHOUT COUNTRY-SPECIFIC BUILDING REGULATION

C24

OPERATING PERMIT, ALTERATION

C5J

ALLOY WHEELS 9J X 21

D65

8-CYLINDER SI ENGINE 4.0 L/420 KW BITURBO, FSI, HOMOGENEOUS BASE ENGINE IS T1M

E0A

NO SPECIAL EDITION

EA8

3 YEARS FOLLOW-ON WARRANTY, MAX. 100 000 KM

EH0

WITHOUT CHARGING CABLE

EP1

WITH NOISE CANCELLATION (ANC ACTIVE NOISE CANCELLATION)

ER1

REGIONAL CODE " ECE " FOR RADIO

ES0

WITHOUT VEHICLE INLET

EVO

WITHOUT CHARGING CABLE

EW0

WITHOUT MAINTENANCE CONTRACT

F0A

NO SPECIAL PURPOSE VEHICLE, STANDARD EQUIPMENT

FA0

CONTROL OF SERIES PRODUCTION

FK0

WITHOUT ADDITIONAL TANK FOR SCR

FN0

"S" VARIANT

FQ1

WHEELS OF QUATTRO GMBH

FT1

PARK ASSIST WITH REMOTE CONTROL

FU0

COUNTRY GROUP A

FZ9

N.N.N. TYPE 9

G1G

8-SPEED AUTOMATIC TRANSMISSION FOR FOUR-WHEEL DRIVE

GA0

WITHOUT PRE-CONDITIONING

GB1

BOOSTER TYPE 1

GH2

REAR DIFFERENTIAL TORQUE VECTORING

GJ0

WITHOUT TRAFFIC JAM ASSIST/CO-PILOT IN HEAVY TRAFFIC

GM0

WITHOUT ELECTRONIC ENGINE SOUND MEASURES

GP1

VEHICLES WITH SPECIAL UPGRADE MEASURES

GT1

DECORATIVE ALUMINUM STRIPS

GZ2

DOOR POWER LATCHING

I8Z

WITHOUT RADIO, BUT WITH PRODUCTION DISPLAY

I99

TIRES 265/35 R21 101Y XL (TORUS ABSORBER)

IT3

WITH CONNECT PACKAGE 3

IU1

WITH CONNECT PACKAGE 1

IW3

EMERGENCY CALL SERVICE AND ROADSIDE ASSISTANCE CALL

IX1

SI ENGINE

J2D

BATTERY 380 A (68 AH)

JX1

WITH FRONT CROSS TRAFFIC ASSIST

K8B

NOTCHBACK

KA6

WITH FRONT AND REAR VIEW CAMERA SYSTEM AND TWO SIDE CAMERAS

KK3

REFRIGERANT R1234YF

KS1

HEAD-UP DISPLAY

L0L

LEFT-HAND DRIVE

N1W

SEAT TRIM COVERS IN LEATHER

NJ0

WITHOUT CHARGING DOCK

NT0

TRANSIT COATING (TYPE 1)

Q0B

DAB + TV WITH EXTERNAL CAS (PAY TV)

Q1D

SPORTS SEATS IN FRONT

QF8

PHONE BOX, ANTENNA FUNCTION IN THE REAR SEAT AREA, WITHOUT WIRELESS CHARGING, WITH RECEIVER FEATURE

QI6

SERVICE INDICATOR 30 000 KM OR 2 YEARS (VARIABLE)

QL5

DARK TINTED GLASS IN REAR SEAT AREA (VENUS 35/PRIVACY) HEAT-INSULATING GLASS (GREEN) IN FRONT

QQ2

WITH ADDITIONAL LIGHTS (INTERIOR LIGHTING)

QR9

WITH DYNAMIC ROAD SIGN DISPLAY

QW4

CENTRAL CONTROL UNIT WITH RADIO REMOTE CONTROL

S0C

INTRODUCTORY VOLUME

S3G

VEHICLES WITH SPECIAL CONVERSION/ INSTALLATION

T1M

8-CYLINDER SI ENGINE 4.0 L UNIT 0P2.A

U5A

INSTRUMENT CLUSTER, KM/H SPEEDOMETER

UE8

3 X USB TYPE A

V0A

TIRES WITHOUT SPECIFICATION OF TIRE BRAND

VC2

GARAGE DOOR OPENER

VF1

PEDAL CLUSTER

VL1

EXTENDED PEDESTRIAN PROTECTION MEASURES

VT5

SCUFF PLATES IN DOOR APERTURES

VW8

BURGLARY-RESISTANT SIDE AND REAR WINDOWS

X0A

EQUIPMENT OPTIONS SUBSET FOR GERMANY

Cronologie

S-a găsit 1 înregistrare

Cronologia înregistrărilor pentru acest vehicul

Ultimele înregistrări

1997-01

 Țară necunoscută



A fost fabricat

Țara (sau statul) indică fie locația centrului de producție, uzina de asamblare sau adresa de înregistrare a producătorului. Data poate fi aproximativă.



Surse de date

Am verificat 900+ de surse de date în **35 de țări**