



# Audi Q5

VIN: WAUZZZFY1K2089287

2019

Generat pe 2024-11-29 08:41



Odometru

✓ Arată bine



Statut legal

✓ Arată bine



Daune

✓ Arată bine



+31


Surse de date

Am verificat 900+ de surse de date în 35 de țări

## Fotografii

2023-09

17 fotografii






## Furt

Vehiculul este în prezent marcat ca furat? A fost furat în trecut? A fost recuperat?

**Nu s-au găsit probleme**  
Nu am găsit nicio înregistrare că vehiculul a fost furat.

**Notă**  
Verificarea bazei de date a poliției privind vehiculele furate finalizată în **10 țări:**  +4

**Iată ce am verificat:**



### Căutat drept furat

✓ Nu s-a găsit nici o înregistrare



### Furat în trecut

✓ Nu s-a găsit nici o înregistrare

Starea actuală necunoscută



### Furat în trecut

✓ Nu s-a găsit nici o înregistrare

Vehiculul a fost recuperat

Baza de date aparținând poliției cu vehicule furate, **verificare finalizată în:**

 România

 Italia

 Statele Unite ale Americii

 Danemarca

 Lituania

 Slovacia

 Slovenia

 Suedia

 Finlanda


 Cehia

## Odometru

Există semne conform cărora kilometrajul a fost dat înapoi sau discrepanțe ale kilometrajului?

### Notă

Ultimul kilometraj cunoscut: 44.199 km



**Disclaimer (declinarea responsabilității):** acest grafic reprezintă o tendință estimată a kilometrajului. Deși se bazează pe înregistrări reale de kilometraj disponibile pentru acest vehicul, există lacune având în vedere că evoluția kilometrajului nu este înregistrată în mod constant. Pentru a lua în considerare aceste date lipsă, aplicăm un model patentat de analiză a datelor care prezice modul în care probabil s-a schimbat kilometrajul între evenimentele înregistrate. Acest lucru ajută la furnizarea unei imagini mai complete a utilizării vehiculului în timp.

## Statut legal

A trecut vehiculul inspecțiile tehnice? A fost notat drept casat?



**Nu s-au găsit probleme**

Nu s-au găsit înregistrări despre statutul legal al acestui vehicul

## Legal



### Inspecție tehnică periodică (ITP)

✓ Nu s-a găsit nici o înregistrare

Nu au fost găsite înregistrări ale inspecției tehnice



### Casat

✓ Nu s-a găsit nici o înregistrare

Nu există nici o înregistrare că vehiculul a fost marcat drept casat

## Daune

Acest vehicul a fost avariat în trecut ? Care a fost valoarea daunelor?

✓ Nu s-au găsit probleme

## Înregistrări de daune



Ocazional pot apărea inexactități, mai ales la verificarea vehiculelor vechi. Atelierele clandestine de reparații pot deghiza ilegal defectele sau daunele vehiculelor, fără să declare nicăieri existența lor. Uneori până și plăcuțele VIN ale vehiculului pot fi înlocuite. Avem o varietate de metode de a detecta chiar și astfel de infracțiuni, dar este imposibil de oferit o garanție de 100%.

## Dezastre naturale

Locația vehiculului a fost înregistrată în zona unui dezastru natural?

✓ Nu s-au găsit probleme

Locația vehiculului nu a fost înregistrată în zona unui dezastru natural

# Valoarea de piață

Cu cât s-a vândut vehiculul în trecut? Care este în medie prețul vehiculelor din acest model și an?

## i Notă

- Ultimul preț de vânzare cunoscut: 211.450 RON
- Prețul mediu de pe piață pentru un astfel de vehicul: 155.078 RON
- Atenție la problemele ascunse dacă vehiculul a fost la vânzare la un preț semnificativ mai mic decât prețul actual!

## Valoarea de piață azi pentru Audi Q5 2019

Valoarea de piață este determinată prin examinarea prețului unui anumit model de mașină (fabricat în același an) în țara în care a fost generat raportul. Analizăm datele din ultimele 6 luni.

Cel mai mic preț

142.505 RON


Prețul mediu

155.078 RON

Cel mai mare preț

170.368 RON

## Istoricul prețurilor pieței





### Înregistrări de preț

2023-09 **205.255 RON**

2024-10 **211.450 RON**


## Emisii

Câte emisii de CO2 produc vehiculele din acest model/an?

### Notă

Emisii CO2: F (203 g/km)

## Emisii CO<sub>2</sub>



## Specificații și echipare

Ce specificații și echipamente sunt înregistrate pentru acest vehicul?

### Notă

Verificați dacă specificațiile și echipamentul acestui vehicul se potrivesc cu datele furnizate de vânzător.

## Identificare și specificații tehnice



Producător

**Audi**



Model

**Q5**



Tip caroserie

**SUV**



An de fabricație

**2019**



An model

**2019**



Capacitate cilindrică

**2 l**



Putere motor

**180 kW (241 cp)**



Cutie de viteze

**Automată**



Tip transmisie

**Tracțiune integrală (AWD)**



Culoare

**Albastru**



Nr. uși

**5**



Amplasarea volanului

**Volan pe stânga**



Nr. cilindri

**4**



Nr. angrenaje

**7**



Nr. locuri

**5**

---

## Echipare

Cum a fost primit de la producător

---

0C0

STANDARD

0FA

STANDARD MANUFACTURING SEQUENCE

0G7

TIPTRONIC

0JE



WEIGHT CATEGORY FRONT AXLE WEIGHT RANGE 5

0K4

HYBRID PROPULSION SYSTEM I-HEV

0LW

WITH SPECIAL PLATES/LABELS/ SAFETY CERTIFICATES FOR GERMANY

0M5

FUEL TANK

0NB

NAMEPLATE SET IN BASIC STYLE

0RZ

WITHOUT IGNITION/STARTER SWITCH LOCKING SYSTEM, WITHOUT STEERING LOCK

0TD

FLOOR MATS IN FRONT AND REAR

0VC

INFORMATION KIT IN GERMAN

0Y1

STANDARD CLIMATIC ZONES

0YE

WEIGHT RANGE 5 INSTALLATION CONTROL ONLY, NO REQUIREMENT FORECAST

1A2

FUEL SYSTEM FOR SI ENGINE WITH DIRECT INJECTION (FSI)

1BK

4-CORNER AIR SUSPENSION WITH ELECTRONIC SHOCK ABSORPTION CONTROL

1D0

WITHOUT TRAILER HITCH

1EX

SPECIAL IDENTIFICATION PLATE FOR EC FOR M1 PASSENGER VEHICLE

1G8

BREAKDOWN KIT

1KF

DISK BRAKES IN REAR

1LG

DISK BRAKES IN FRONT

1P0

STANDARD SUSPENSION

1PD

WHEEL BOLTS WITH ANTI-THEFT PROTECTION (UNLOCKABLE)

1S1

TOOL KIT AND JACK

1SA

WITHOUT ADDITIONAL FRONT UNDERBODY GUARD

1T3

FIRST AID KIT WITH WARNING TRIANGLE

1VG

INSTALLATION PARTS FOR FOUR-CYLINDER ENGINE

1X1

FOUR WHEEL DRIVE

1Z6

INCREASE IN INITIAL STANDARD FUEL FILLING

2C5

AXIAL AND VERTICAL ADJUSTABLE STEERING COLUMN

2F0

WITHOUT LOCKING AND STARTING SYSTEMS

2G1

INSERT FOR THE FILLING UP OF UNLEADED FUEL

2H9

DRIVE SELECT

2K7

REINFORCED BUMPERS

2KR

LABELS/PLATES IN ENGLISH AND GERMAN

2P2

STAINLESS STEEL LOADING EDGE PROTECTION

2PF

LEATHER-WRAPPED MULTIFUNCTION SPORTS STEERING WHEEL

2WD

ADDITIONAL SNOW TIRES

2Z0

ELIMINATION OF MODEL DESIGNATION

3B3

CHILD SEAT ANCHOR

3CX

NET PARTITION

3FU

BIG ROOF SYSTEM

3G4

CHILD SEAT ANCHOR IN FRONT

3GD

PLANE REAR CARGO AREA

3L4

POWER SEAT ADJUSTMENT FOR BOTH FRONT SEATS, DRIVER SEAT WITH MEMORY FEATURE

3M3

PASSENGER CAR DESIGN

3NS

SPLIT FOLDING REAR SEAT BENCH/BACKREST, WITH CENTER ARMREST

3S2

BLACK ROOF RAILS

3U4

LUGGAGE COMPARTMENT COVER

3Y0

WITHOUT ROLL-UP SUNSHADE

4A3

SEAT HEATER FOR FRONT SEATS SEPARATELY CONTROLLED

4D0

WITHOUT SEAT VENTILATION/MASSAGE SEAT

4E7

TAILGATE/TRUNK LID POWER CLOSING

4GF

WINDSHIELD IN HEAT-INSULATING GLASS

4H5

POWER-OPERATED CHILD SAFETY LOCK

4I3

CENTRAL LOCKING SYSTEM "KEYLESS ENTRY" WITHOUT SAFELOCK

4L6

BREAKAWAY INTERIOR REARVIEW MIRROR, AUTO-DIMMING

4M3

BEVERAGE HOLDERS

4UF

DRIVER AND FRONT PASSENGER AIRBAG WITH FRONT PASSENGER AIRBAG DEACTIVATION

4X3

SIDE AIRBAG IN FRONT, WITH CURTAIN AIRBAG

4ZD

BLACK MOLDINGS

5C0

WITHOUT SPECIAL BODY MEASURES

5D1

CARRIER FREQUENCY 433.92 MHZ-434.42 MHZ

5J3

ROOF SPOILER

5K4

TRANSPORT PROTECTION COVER (SHAPE- ADAPTED SYSTEM) WITH ADDITIONAL TRANSPORT PROTECTION MEASURES

5SL

LEFT EXTERIOR MIRROR: ASPHERICAL

5TG

DECORATIVE ALUMINUM INSERTS, DULLING

5XK

SUN VISORS ON DRIVER AND FRONT PASSENGERSIDE

5ZC

HEAD RESTRAINTS FOR FRONT SEATS (X-ADJUSTMENT)

6A0

WITHOUT FIRE EXTINGUISHER

6F1

EMBLEMS

6FJ

BLACK EXTERIOR MIRROR HOUSINGS

6I1

LANE KEEPING SYSTEM

6K9

PRE SENSE CITY WITH PRE CARE

6NQ

STANDARD MOLDED HEADLINER

6SS

LUGGAGE COMPARTMENT FLOOR COVERING

6TS

RIGHT EXTERIOR MIRROR, ASPHERICAL, LARGE VIEWING FIELD

6V1

REAR TRIM PANEL (ECE)

6W0

WITHOUT FRONT LICENSE PLATE CARRIER

6XL

EXTERIOR MIRRORS WITH MEMORY FEATURE, AUTO-DIMMING, POWER-FOLDING/ADJUSTABLE/HEATED

73A

WITHOUT CHARGING CABLE (INDUSTRIAL CONNECTOR)

76A

WITHOUT MODE 3 CHARGING CABLE

7AA

ELECTRONIC ENGINE IMMOBILIZER

7E0

WITHOUT HEAT ACCUMULATOR/AUXILIARY HEATER

7F9

PLASTIC/LEATHER GEARSHIFT KNOB/HANDLE

7G0

WITHOUT PREPARATION FOR VTS (VEHICLE TRACKING SYSTEM)

7HB

LEATHER VARIANT 1

7J

VEHICLE CLASS DIFFERENTIATION FY0-

7K1

DIRECT TIRE PRESSURE MONITORING SYSTEM

7L8

START/STOP SYSTEM WITH REGENERATIVE BRAKING

7P1

POWER-ADJUSTABLE LUMBAR SUPPORT IN FRONTSEATS

7UG

NAVIGATION SYSTEM - HIGH

7W3

WITH EXTENDED SAFETY SYSTEM (PROACTIVE PASSENGER PROTECTION SYSTEM, BASIC AND REAR)

7X5

PARK ASSIST

7Y1

LANE CHANGE ASSIST

8G4

MATRIX BEAM

8IT

LED HEADLAMPS

8K4

SEPARATE DAYTIME RUNNING LIGHTS -- NAR --

8Q3

AUTOMATIC HEADLIGHT RANGE ADJUSTMENT DYNAMIC (SELF-ADJUSTING WHILE DRIVING)

8SP

LED TAIL LAMP ASSEMBLY

8T8

ADAPTIVE CRUISE CONTROL (WITH "FOLLOW-TO-STOP") AND SPEED LIMITER

8X1

HEADLAMP WASHER SYSTEM

8Y1

TWO-TONE HORN

8Z5

NOT HOT COUNTRY

9AQ

AIR CONDITIONING SYSTEM PLUS

9G7

BELT-DRIVEN STARTER ALTERNATOR 12 V 110-180 A

9JA

NON-SMOKER'S PACKAGE

9M9

FUEL-FIRED PARKING HEATER WITH RADIO REMOTE CONTROL



9P6

SEAT BELT REMINDER, ELECTRIC CONTACT IN BUCKLE

9S8

MULTI-FUNCTION DISPLAY/ON-BOARD COMPUTER"FPK" (ACTIVE INFO DISPLAY)

9VS

SOUND PACKAGE "BRANDED"

9WC

WITHOUT "MULTIMEDIA" IN VEHICLE

9ZE

COMFORT TELEPHONE SYSTEM

A00

NO SELF-COLLECTION

A51

AUDI AG

A60

CATEGORY 0

A9D

"AMBITION" EQUIPMENT

AQ0

STANDARD-PRODUCTION QUALITY

AV1

DRIVING ON THE RIGHT

B01

TYPE APPROVAL COUNTRY GERMANY

B0A

COMPONENT PARTS SET WITHOUT COUNTRY-SPECIFIC BUILDING REGULATION

C12

OPERATING PERMIT, ALTERATION

DQ4

4-CYLINDER SI ENGINE 2.0 L/180 KW TFSI, HOMOGENEOUS. BASE ENGINE IS T2H/T2G/TX5/TX6/T0I/T3Q/TX9

E0A

NO SPECIAL EDITION

EA0

WITHOUT FOLLOW-ON WARRANTY

EL3

ONLINE SERVICE, WITHOUT OCU, WITH HEAD UNIT CODING, WITHOUT ENGINE IMMOBILIZER INTERCONNECTION

ER1

REGIONAL CODE " ECE " FOR RADIO

ES0

WITHOUT VEHICLE INLET

EVO

WITHOUT CHARGING CABLE

EW0

WITHOUT MAINTENANCE CONTRACT

F0A

NO SPECIAL PURPOSE VEHICLE, STANDARD EQUIPMENT

FA0

CONTROL OF SERIES PRODUCTION

FC1

CUSTOMIZED INSTALLATION

FK0

WITHOUT ADDITIONAL TANK FOR SCR

FM0

BASIC EQUIPMENT VARIANT

FQ1

WHEELS OF QUATTRO GMBH

FU0

COUNTRY GROUP A

G1D

7-SPEED AUTOMATIC TRANSMISSION FOR FOUR-WHEEL DRIVE

GA0

WITHOUT PRE-CONDITIONING

GB1

BOOSTER TYPE 1

GH4

REAR DIFFERENTIAL WITH UNCOUPLING FEATURE

GM0

WITHOUT ELECTRONIC ENGINE SOUND MEASURES

GP0

VEHICLES WITHOUT SPECIAL UPGRADE MEASURES

HN1

TIRES 255/45 R20 101W

I8H

HIGH RADIO (GEN2)

IT3

WITH CONNECT PACKAGE 3

IV0

WITHOUT CONNECT PLUS

IW3

EMERGENCY CALL SERVICE AND ROADSIDE ASSISTANCE CALL

IX1

SI ENGINE

J2D

BATTERY 380 A (68 AH)

K4H

CLOSED BODY

KA6

WITH FRONT AND REAR VIEW CAMERA SYSTEM AND TWO SIDE CAMERAS

KK3

REFRIGERANT R1234YF

KS0

WITHOUT HEAD-UP DISPLAY

L0L

LEFT-HAND DRIVE

N7N

SEAT TRIM COVERS IN ALCANTARA/LEATHER

NJ0

WITHOUT CHARGING DOCK

NT1

TRANSIT COATING (TYPE 2)

Q1D

SPORTS SEATS IN FRONT

QE1

STORAGE COMPARTMENT PACKAGE 1

QI6

SERVICE INDICATOR 30 000 KM OR 2 YEARS ( VARIABLE )

QK1

WITH MULTIFUNCTION CAMERA

QQ2

WITH ADDITIONAL LIGHTS (INTERIOR LIGHTING)

QR9

WITH DYNAMIC ROAD SIGN DISPLAY

QT5

WITHOUT STEP

QV3

DIGITAL RADIO RECEPTION

QZ7

POWER STEERING

TX5

4-CYLINDER SI ENGINE 2.0 L UNIT 06L.P

U5A

INSTRUMENT CLUSTER, KM/H SPEEDOMETER

U74

ALLOY WHEELS 8J X 20

UE4

ELECTRIC INTERFACE FOR EXTERNAL USE, AUX-IN AND USB JACK

UH2

PARKING BRAKE

V0A

TIRES WITHOUT SPECIFICATION OF TIRE BRAND

VC0

WITHOUT REMOTE-CONTROLLED GARAGE DOOR OPENER

VF1

PEDAL CLUSTER

VH0

STANDARD ELECTRIC

VL1

EXTENDED PEDESTRIAN PROTECTION MEASURES

VT5

SCUFF PLATES IN DOOR APERTURES

VW4

SIDE AND REAR WINDOWS

VY0

WITHOUT DANGER ALARM SYSTEM

X0A

EQUIPMENT OPTIONS SUBSET FOR GERMANY

## Cronologie

## S-au găsit 5 înregistrări

Cronologia înregistrărilor pentru acest vehicul

### Ultimele înregistrări

2019-01

 Țară necunoscută



#### A fost fabricat

Țara (sau statul) indică fie locația centrului de producție, uzina de asamblare sau adresa de înregistrare a producătorului. Data poate fi aproximativă.

2019-07

 Țară necunoscută



#### A fost înmatriculat

Înregistrarea reprezintă un eveniment administrativ. Acest lucru ar putea fi legat de o schimbare de proprietar, documente etc

2023-09

 Germania



#### A fost la vânzare

Această înregistrare a fost creată deoarece vehiculul a fost listat pentru vânzare pe o anumită piață. Uneori, țara (sau statul) vânzătorului suprascrie locația reală a vehiculului.

2023-12

 România



#### A fost înmatriculat

Înregistrarea reprezintă un eveniment administrativ. Acest lucru ar putea fi legat de o schimbare de proprietar, documente etc

2024-10

 România



#### A fost la vânzare

Această înregistrare a fost creată deoarece vehiculul a fost listat pentru vânzare pe o anumită piață. Uneori, țara (sau statul) vânzătorului suprascrie locația reală a vehiculului.



+31

#### Surse de date

Am verificat 900+ de surse de date în **35 de țări**