

# Volkswagen T6



VIN: WV2ZZZ7HZMH088645

Diesel

2020

Generat pe 2024-10-28 08:08



## Contor de parcurs

✓ Arată bine



## Statut legal

✓ Arată bine



## Daune

⚠ Necesită atenție



+31

### Surse de date

Am verificat 900+ de surse de date în **35 de țări**

## Furt

Vehiculul este în prezent marcat ca furat? A fost furat în trecut? A fost recuperat?

### ✓ Nu s-au găsit probleme

Nu am găsit nicio înregistrare că vehiculul a fost furat.

### i Notă

Verificarea bazei de date a poliției privind vehiculele furate finalizată în **9 țări**:



+3

## Iată ce am verificat:



### Căutat drept furat

✓ Nu s-a găsit nici o înregistrare



### Furat în trecut

✓ Nu s-a găsit nici o înregistrare

Starea actuală necunoscută



### Furat în trecut

✓ Nu s-a găsit nici o înregistrare

Vehiculul a fost recuperat

Baza de date aparținând poliției cu vehicule furate, **verificare finalizată în:**

 **România**

 **Danemarca**

 **Lituania**

 **Statele Unite ale Americii**

 **Slovacia**

 **Finlanda**

 **Slovenia**

 **Cehia**


 **Suedia**

## Contor de parcurs

Există semne conform cărora kilometrajul a fost dat înapoi sau discrepanțe ale kilometrajului?

### Notă

Ultimul kilometraj cunoscut: 81.527 km



#### Înregistrări ale contorului de parcurs

2020-01	<b>12 km</b>
2020-04	<b>1.914 km</b>
2020-08	<b>4.463 km</b>
2020-12	<b>7.012 km</b>
2021-01	<b>7.660 km</b>
2021-04	<b>9.544 km</b>
2021-08	<b>12.029 km</b>
2021-12	<b>15.993 km</b>
2022-01	<b>17.993 km</b>
2022-04	<b>24.115 km</b>

#### Înregistrări ale contorului de parcurs

2022-08	<b>34.852 km</b>
2022-12	<b>43.446 km</b>
2023-01	<b>45.498 km</b>
2023-04	<b>50.910 km</b>
2023-08	<b>59.006 km</b>
2023-12	<b>68.850 km</b>
2024-01	<b>70.706 km</b>
2024-04	<b>76.091 km</b>
2024-08	<b>81.527 km</b>

**Disclaimer (declinarea responsabilității):** acest grafic reprezintă o tendință estimată a kilometrajului. Deși se bazează pe înregistrări reale de kilometraj disponibile pentru acest vehicul, există lacune având în vedere că evoluția kilometrajului nu este înregistrată în mod constant. Pentru a lua în considerare aceste date lipsă, aplicăm un model patentat de analiză a datelor care prezice modul în care probabil s-a schimbat kilometrajul între evenimentele înregistrate. Acest lucru ajută la furnizarea unei imagini mai complete a utilizării vehiculului în timp.

## Statut legal

A trecut vehiculul inspecțiile tehnice? A fost notat drept casat?



**Nu s-au găsit probleme**

Nu s-au găsit înregistrări despre statutul legal al acestui vehicul

## Legal



### Inspecție tehnică periodică (ITP)

✓ Nu s-a găsit nici o înregistrare

Nu au fost găsite înregistrări ale inspecției tehnice



### Casat

✓ Nu s-a găsit nici o înregistrare

Nu există nici o înregistrare că vehiculul a fost marcat drept casat

## Daune

Acest vehicul a fost avariat în trecut ? Care a fost valoarea daunelor?

### ⚠ Ai grijă!

Vehiculul a fost avariat de 3 ori!

### ℹ Notă

Daunele minore nu vor afecta în mod normal siguranța vehiculului și nu vor cauza probleme structurale

## Înregistrări de daune



2021-09

România

### Daune

Costul estimativ al reparațiilor

**6.001 RON -  
14.000 RON**

Cauza posibilă a daunelor

**Necunoscut**

Categoriile de daune

Sistem de suspensie



Daune pe partea dreaptă:

**Dreapta / Portieră față**

Daune pe partea dreaptă:

**Spate dreapta / Bară de protecție**

2022-05

 România

#### Daune

Costul estimativ al reparațiilor

**14.001 RON -  
24.000 RON**

Cauza posibilă a daunelor

**Necunoscut**

Categoriile de daune

Părți exterioare ale caroseriei



Daune pe partea dreaptă:

**Dreapta / Portieră față**

Daune pe partea dreaptă:

**Spate / Bară de protecție**

**Spate dreapta / Bară de protecție**

2023-04

 România

#### Daune

Costul estimativ al reparațiilor

**24.001 RON -  
48.000 RON**

Cauza posibilă a daunelor

**Necunoscut**

Categoriile de daune

Părți exterioare ale caroseriei

Sistem de suspensie

**Disclaimer (declinarea responsabilității):** Majoritatea înregistrărilor de daune sunt legate de accidente, dar uneori nu este acesta cazul. Unele înregistrări provin din alte surse cum ar fi serviciile specializate pe lucrări de caroserie, cereri de daune, licitații sau inspecții ale vehiculelor. Aceste înregistrări arată că starea vehiculului a fost evaluată, chiar dacă nu a fost din cauza unui accident.

## Dezastru natural

Locația vehiculului a fost înregistrată în zona unui dezastru natural?

✓ **Nu s-au găsit probleme**

Locația vehiculului nu a fost înregistrată în zona unui dezastru natural


## Emisii

Câte emisii de CO2 produc vehiculele din acest model/an?

**i** **Notă**

Emisii CO2: G (227 g/km)

## Emisii CO<sub>2</sub>



## Specificații și echipare

Ce specificații și echipamente sunt înregistrate pentru acest vehicul?

**i** **Notă**

Verificați dacă specificațiile și echipamentul acestui vehicul se potrivesc cu datele furnizate de vânzător.

## Identificare și specificații tehnice



Producător

**Volkswagen**



Model

**T6**



Tip caroserie

**Dubă**



An de fabricație

**2020**



An model  
**2021**



Capacitate cilindrică  
**2,2 l**



Putere motor  
**150 kW (201 cp)**



Tip combustibil  
**Diesel**



Cutie de viteze  
**Automată**



Tip transmisie  
**Tracțiune integrală (AWD)**



Nr. uși  
**4**



Amplasarea volanului  
**Volan pe stânga**



Nr. cilindri  
**4**



Nr. locuri  
**2**



Cod motor  
**DMZA**

---

## Echipare

Cum a fost primit de la producător

---

**0E1**

SHORT WHEELBASE

**0F3**

FUEL SYSTEM FOR DIESEL ENGINE

**0FA**

STANDARD MANUFACTURING SEQUENCE

**0JF**

WEIGHT CATEGORY FRONT AXLE WEIGHT RANGE 6

0NP

NAMEPLATE SET

0TA

WITHOUT FLOOR MATS

0WS

GROSS VEHICLE WEIGHT RATING

0XH

INFORMATION KIT IN ROMANIAN

0Y1

STANDARD CLIMATIC ZONES

0YD

WEIGHT RANGE 4 INSTALLATION CONTROL ONLY, NO REQUIREMENT FORECAST

1AS

ELECTRONIC STABILITY CONTROL (ESC)

1BQ

SUSPENSION/SHOCK ABSORP. (CLOSED-LOOP)

1D2

TRAILER HITCH, REMOVABLE AND LOCKABLE

1EX

SPECIAL IDENTIFICATION PLATE FOR EC FOR M1 PASSENGER VEHICLE

1G8

BREAKDOWN KIT

1HZ

LABELS WITHOUT COUNTRY GROUP

1L0

STANDARD AIR CLEANER

1N3

SPEED-RELATED VARIABLE STEERING ASSIST (SERVOTRONIC)



1NL

TRIMS FOR ALLOY WHEELS

1PA

STANDARD WHEEL BOLTS

1S2

TOOL KIT

1T0

WITHOUT FIRST AID KIT AND WARNING TRIANGLE

1U5

TABLE FOR CAMPER W/ FOLDING CHAIRS

1W1

REFRIGERATOR

1Y0

WITHOUT DIFFERENTIAL LOCK

1Z0

INITIAL STANDARD FUEL FILLING

2A0

WITHOUT DELIVERY EQUIPMENT

2E4

17-INCH CHASSIS

2FD

WOODEN MULTIFUNCTION STEERING WHEEL FOR TIPTRONIC

2I0

ADAPTIVE CHASSIS CONTROL WITH CONTINUOUS OPERATION

2JG

BODY-COLORED BUMPERS

2N4

SPECIAL ANTI-DRUM MEASURES IN CAB AND PASSENGER COMPARTMENT

2P1

PLASTIC LOADING EDGE PROTECTION

2Q0

WITHOUT MODULAR SEAT MOUNTING

2WA

WITHOUT ADDITIONAL TIRES

3B3

CHILD SEAT ANCHOR

3CA

WITHOUT PARTITION

3JA

WITHOUT ROOF INSERT IN LOAD AND PASSENGER COMPARTMENT

3L1

MANUAL HEIGHT ADJUSTMENT FOR LEFT FRONT SEAT

3LP

PAINTED DOOR TRIM PANEL

3QN

3-POINT SEAT BELT IN FRONT WITH ELECTRIC SEAT BELT PRETENSIONER

3RJ

WITHOUT REAR WING DOOR WITH APERTURE

3S4

PREPARATION FOR ROOF LOAD RACK

3SQ

RIGHT SWIVEL SEAT IN CAB WITH LUMBAR SUPPORT

3TF

COMFORT SEAT IN FRONT, LEFT

3U1

FOLDING TRUNK COVER

3VX

3-SEATER BENCH WITH STORAGE COMPARTMENT,MOVABLE AND RECLINING SEAT MECHANISM

3W7

ACOUSTICS PACKAGE "EXTRA"

3WA

WITHOUT BENCH

3Y0

WITHOUT ROLL-UP SUNSHADE

4A3

SEAT HEATER FOR FRONT SEATS SEPARATELY CONTROLLED

4C0

1 SWIVEL SEAT W/ LONGITUDINAL ADJUSTMENT ON RAIL SYSTEM

4E0

TAILGATE/TRUNK LID UNLOCKING FROM OUTSIDE

4FJ

SLIDING WINDOW WITH FLY SCREEN IN PASSENGER COMPARTMENT LEFT

4GR

LAMINATED WINDSHIELD, HEATED

4H5

POWER-OPERATED CHILD SAFETY LOCK

4HS

HEATED REAR WINDOW WITH REAR WIPER

4I2

CENTRAL LOCKING WITH RADIO REMOTE CONTROL, INTERIOR RELEASE MECHANISM WITHOUT SAFELOCK

4JJ

SLIDING WINDOW WITH FLY SCREEN PASSENGER COMPARTMENT FRONT RIGHT

4L6

BREAKAWAY INTERIOR REARVIEW MIRROR, AUTO-DIMMING

4N3

COMFORT DASHBOARD

4S1

ARMRESTS FOR BOTH FRONT SEATS

4UF

DRIVER AND FRONT PASSENGER AIRBAG WITH FRONT PASSENGER AIRBAG DEACTIVATION

4X3

SIDE AIRBAG IN FRONT, WITH CURTAIN AIRBAG

4Y0

WITHOUT STORAGE COMPARTMENT/SAFE BOX

4Z5

GLOVE COMPARTMENT DOOR WITH LIGHT

51A

WITHOUT ADHESIVE FILM

5AB

VELOUR NONWOVEN FLOOR COVERING IN CAB

5BE

TOUGH PLASTIC LINING IN PASSENGER COMPARTMENT

5C0

WITHOUT SPECIAL BODY MEASURES

5CQ

ROOF TRIM FOR CAMPER

5D1

CARRIER FREQUENCY 433.92 MHZ-434.42 MHZ

5DK

SIDE TRIM PANEL, CALIFORNIA BEACH

5EW

REGISTRATION AS PASSENGER CAR

5FA

WITHOUT ADDITIONAL STORAGE COMPARTMENTS IN CAB

5G2

DARKENING SYSTEM

5K0

WITHOUT SURFACE PROTECTION, WITH ADDITIONAL TRANSPORT PROTECTION MEASURES

5N6

FOLDING GRAB HANDLES AT ROOF FRAME SOFT FOLD-AWAY

5Q0

WITHOUT DOOR IN LOAD/PASSENGER COMPARTMENT LEFT (CLOSED SIDE PANEL)

5R7

POWER LATCHING FOR SLIDING DOOR RIGHT

5RQ

RIGHT EXTERIOR MIRROR, CONVEX

5Sj

LEFT EXTERIOR MIRROR, CONVEX

5V3

HINGES FOR TAILGATES/TRUNK LID (STANDARD DESIGN)

5XI

SUN VISORS WITH MIRROR, ILLUMINATED, AIRBAG LABEL ON SUN VISOR

5ZU

HEAD RESTRAINTS

6B3

LASHING RINGS FOR REINFORCED FLOOR COVERING

6CA

WITHOUT REAR HEATING/VENTILATION DUCT

6FF

BODY-COLORED EXTERIOR MIRROR HOUSINGS AND VARIOUS ADD-ON PARTS

6K4

FORWARD COLLISION WARNING INCL. AUTONOMOUS EMERGENCY BRAKING, FOR ADAPTIVE CRUISE CONTROL "HIGH"

6KE

RADIATOR GRILLE

6L0

WITHOUT C-RAILS

6N2

MUD FLAP IN FRONT AND REAR

6U1

ADDITIONAL DUST SEAL OUTSIDE

6X4

ENTRY HANDLE ON A PILLAR ON DRIVER AND FRONT PASSENGER SIDE

6XP

EXTERIOR MIRRORS, POWER-FOLDING, POWER-ADJUSTABLE, SEPARATELY HEATED

7AA

ELECTRONIC ENGINE IMMOBILIZER

7B5

12-VOLT SOCKET(S)

7K1

DIRECT TIRE PRESSURE MONITORING SYSTEM

7L6

START/STOP SYSTEM WITH REGENERATIVE BRAKING

7P4

MANUALLY ADJUSTABLE LUMBAR SUPPORT IN FRONT SEATS

7TC

DECORATIVE INSERTS

7UG

NAVIGATION SYSTEM - HIGH

7VF

FUEL-FIRED PARKING HEATER WITH RADIO REMOTE CONTROL AND ELECTRIC AUXILIARY HEATER

7X5

PARK ASSIST

7Y5

LANE CHANGE ASSIST AND LANE KEEPING SYSTEM

8AR

RADIO "GAMMA" WITH REMOVABLE OPERATING PANEL

8FE

SECOND BATTERY

8G1

HIGH-BEAM CONTROL

8IY

LED HEADLAMPS WITH LENS

8K3

SEPARATE DAYTIME RUNNING LIGHTS WITH AUTOMATIC HEADLAMP ACTIVATION AND COMING HOME FEATURE

8N6

WINDSHIELD WIPER INTERMITTENT CONTROL WITH LIGHT/RAIN SENSOR

8Q3

AUTOMATIC HEADLIGHT RANGE ADJUSTMENT DYNAMIC (SELF-ADJUSTING WHILE DRIVING)

8QM

KEY FOR LOCKING SYSTEM

8RL

6 SPEAKERS (PASSIVE)

8T8

ADAPTIVE CRUISE CONTROL (WITH "FOLLOW-TO-STOP") AND SPEED LIMITER

8U0

WITHOUT ADDITIONAL INSTRUMENTS FOR DISTANCE MEASUREMENT

8WH

FRONT FOG LAMP AND CORNERING LAMP

8Y0

SINGLE-TONE HORN

8Z5

NOT HOT COUNTRY

9AH

CLIMATRONIC WITH SECOND EVAPORATOR AND SECOND HEATING SYSTEM

9CI

INTERIOR LIGHT CONCEPT FOR CAMPER "COMFORT" IN PASSENGER COMPARTMENT

9G6

ALTERNATOR 160-250 A

9H0

WITHOUT ROOF TURN SIGNALS

9HA

WITHOUT ADDITIONAL MALFUNCTION DISPLAY

9J

COMFORT TELEPHONY WITH LTE AND WIRELESS CHARGING

9JC

SMOKER'S VERSION

9KA

WITHOUT IDENTIFICATION LIGHTS

9LA

WITHOUT ROTATING BEACON

9N1

STEP ILLUMINATION, SLIDING DOOR(S)

9NA

WITHOUT TACHOGRAPH

9P1

SEAT BELT REMINDER, ELECTRIC CONTACT IN BUCKLE

9S0

MULTI-FUNCTION DISPLAY/TRIP COMPUTER ACTIVE INFO DISPLAY "ENTRY"

9WJ

POWER SUPPLY/TV SIGNAL FOR CUSTOMIZED INSTALLATION

9Z3

12-V OPERATING VOLTAGE AND 230-V INVERTER

A9A

CALIFORNIA BEACH

AF2

ROOF BED AND STOWAGE COMPARTMENT



AV1

DRIVING ON THE RIGHT

B0A

COMPONENT PARTS SET WITHOUT COUNTRY-SPECIFIC BUILDING REGULATION

B43

TYPE APPROVAL COUNTRY ROMANIA

C5G

ALLOY WHEELS 8J X 18

DN7

4-CYL. TURBO DIESEL ENGINE 2.0 L/150 KW (4V) TDI, BIT COMMON RAIL BASE ENGINE IS T12/T47/T6F/T98

E0A

NO SPECIAL EDITION

EA0

WITHOUT FOLLOW-ON WARRANTY

EL5

ONLINE SERVICE, WITH OCU, WITH HEAD UNITCODING, WITHOUT ENGINE IMMOBILIZER INTERCONNECTION

EM1

DRIVER ALERT SYSTEM

ER1

REGIONAL CODE " ECE " FOR RADIO

EU3

WITH SOCKET IN FRONT, WITH FLASHLIGHT

EW0

WITHOUT MAINTENANCE CONTRACT

F0A

NO SPECIAL PURPOSE VEHICLE, STANDARD EQUIPMENT

FM0

BASIC EQUIPMENT VARIANT

FS6

6 SEATS

G1D

7-SPEED AUTOMATIC TRANSMISSION FOR FOUR-WHEEL DRIVE

IG1

CURB WEIGHT RANGE 1

IM0

FRONT AXLE WEIGHT, STANDARD

IN0

REAR AXLE WEIGHT, STANDARD

J1N

BATTERY 420 A (75 AH)

J22

SUSPENSION RANGE 22

K4L

CAMPER

KA1

WITH REAR VIEW CAMERA SYSTEM (TYPE 1)

KJ1

WITH SIDE-WIND COMPENSATION

KK3

REFRIGERANT R1234YF

L0L

LEFT-HAND DRIVE

N0B

SEAT TRIM COVERS IN FABRIC

NF4

AWNING + AWNING RAIL SILVER

NR9

INSERT/BADGES (INTERIOR)

NY0

STANDARD BATTERY/ALTERNATOR CAPACITY

NZ2

PAN-EUROPEAN EMERGENCY CALL SERVICE

QA0

WITHOUT CHILD SEAT

QE9

STORAGE COMPARTMENT PACKAGE

QH1

VOICE CONTROL

QI8

SERVICE INDICATOR 40 000 KM OR 2 YEARS ( VARIABLE )

QJ0

WITHOUT ALUMINUM/CHROME PACKAGE

QL6

LAMINATED GLASS

QR9

WITH DYNAMIC ROAD SIGN DISPLAY

QV3

DIGITAL RADIO RECEPTION

S6L

INTERNAL CONTROL NUMBER

T3A

5-CYLINDER SI ENGINE 2.2 L UNIT 034.7

U5A

INSTRUMENT CLUSTER, KM/H SPEEDOMETER

U9B

1 X USB TYPE C AND CD PLAYER

UG1

HILL START ASSIST

VOA

TIRES WITHOUT SPECIFICATION OF TIRE BRAND

X7Y

EQUIPMENT OPTIONS SUBSET FOR EXPORT (OTHERS)

## Cronologie

**S-au găsit 4 înregistrări**

Cronologia înregistrărilor pentru acest vehicul

### Ultimele înregistrări

2020-01

 **Țară necunoscută****A fost fabricat**

Țara (sau statul) indică fie locația centrului de producție, uzina de asamblare sau adresa de înregistrare a producătorului. Data poate fi aproximativă.

2022-05

 **România****Daună detectată** 

Avem indicii potrivit cărora acest vehicul a fost recunoscut ca avariat în această țară (sau stat). Pentru detalii, vă rugăm să consultați secțiunea „Daune”.

2023-04

 **România****Daună detectată** 

Avem indicii potrivit cărora acest vehicul a fost recunoscut ca avariat în această țară (sau stat). Pentru detalii, vă rugăm să consultați secțiunea „Daune”.

2024-05

 **România****A fost înmatriculat**

Înregistrarea reprezintă un eveniment administrativ. Acest lucru ar putea fi legat de o schimbare de proprietar, documente etc

**Surse de date**Am verificat 900+ de surse de date în **35 de țări**