

Volkswagen



VIN: WVGZZZ5NXLW403568

Diesel

Generat pe 2024-12-03 08:10



Odometru

✓ Arată bine



Statut legal

✓ Arată bine



Daune

✓ Arată bine



+31

Surse de date

Am verificat 900+ de surse de date în 35 de țări

Furt

Vehiculul este în prezent marcat ca furat? A fost furat în trecut? A fost recuperat?



Nu s-au găsit probleme

Nu am găsit nicio înregistrare că vehiculul a fost furat.



Notă

Verificarea bazei de date a poliției privind vehiculele furate finalizată în 10 țări: +4

Iată ce am verificat:



Căutat drept furat

✓ Nu s-a găsit nici o înregistrare



Furat în trecut

✓ Nu s-a găsit nici o înregistrare

Starea actuală necunoscută



Furat în trecut

✓ Nu s-a găsit nici o înregistrare

Vehiculul a fost recuperat

Baza de date aparținând poliției cu vehicule furate, **verificare finalizată în:**



România



Statele Unite ale Americii



Lituania



Danemarca



Slovacia



Slovenia



Italia



Finlanda



Cehia




Suedia

Odometru

Există semne conform cărora kilometrajul a fost dat înapoi sau discrepanțe ale kilometrajului?

Notă

Ultimul kilometraj cunoscut: 83.302 km



Disclaimer (declinarea responsabilității): acest grafic reprezintă o tendință estimată a kilometrajului. Deși se bazează pe înregistrări reale de kilometraj disponibile pentru acest vehicul, există lacune având în vedere că evoluția kilometrajului nu este înregistrată în mod constant. Pentru a lua în considerare aceste date lipsă, aplicăm un model patentat de analiză a datelor care prezice modul în care probabil s-a schimbat kilometrajul între evenimentele înregistrate. Acest lucru ajută la furnizarea unei imagini mai complete a utilizării vehiculului în timp.

Statut legal

A trecut vehiculul inspecțiile tehnice? A fost notat drept casat?

✓ Nu s-au găsit probleme

Nu s-au găsit înregistrări despre statutul legal al acestui vehicul

Legal



Inspecție tehnică periodică (ITP)

✓ Nu s-a găsit nici o înregistrare

Nu au fost găsite înregistrări ale inspecției tehnice



Casat

✓ Nu s-a găsit nici o înregistrare

Nu există nici o înregistrare că vehiculul a fost marcat drept casat

Daune

Acest vehicul a fost avariat în trecut ? Care a fost valoarea daunelor?

✓ Nu s-au găsit probleme

Înregistrări de daune



Ocazional pot apărea inexactități, mai ales la verificarea vehiculelor vechi. Atelierele clandestine de reparații pot deghiza ilegal defectele sau daunele vehiculelor, fără să declare nicăieri existența lor. Uneori până și plăcuțele VIN ale vehiculului pot fi înlocuite. Avem o varietate de metode de a detecta chiar și astfel de infracțiuni, dar este imposibil de oferit o garanție de 100%.

Dezastre naturale

Locația vehiculului a fost înregistrată în zona unui dezastru natural?

✓ Nu s-au găsit probleme

Locația vehiculului nu a fost înregistrată în zona unui dezastru natural

Specificații și echipare

Ce specificații și echipamente sunt înregistrate pentru acest vehicul?

i Notă

Verificați dacă specificațiile și echipamentul acestui vehicul se potrivesc cu datele furnizate de vânzător.

Identificare și specificații tehnice



Producător

Volkswagen



Tip caroserie

Hatchback



An model

2020



Capacitate cilindrică

2 l



Putere motor

140 kW (188 cp)



Tip combustibil

Diesel



Cutie de viteze

Automată



Amplasarea volanului

Volan pe stânga



Nr. cilindri

4

Echipare

Cum a fost primit de la producător

0AL

FRONT STABILIZER

0B3

WHEELBASE

0BG

REAR STABILIZER

0EX

INSTALLATION DIFFERENTIATION FOR TRANSMISSION DQ500 -- VEHICLE COMPONENTS --

0F5

FUEL SYSTEM FOR DIESEL ENGINE

0FA

STANDARD MANUFACTURING SEQUENCE

0K0

WITHOUT ALTERNATIVE DRIVE SYSTEM

0KA

WITHOUT DECALS AND EMBLEMS

0NB

NAMEPLATE SET IN BASIC STYLE

0RE

WITHOUT ELECTRONIC STEERING COLUMN LOCK

0TD

FLOOR MATS IN FRONT AND REAR

0VC

INFORMATION KIT IN GERMAN

0Y1

STANDARD CLIMATIC ZONES

0YT

WEIGHT RANGE 18 INSTALLATION CONTROL ONLY, NO REQUIREMENT FORECAST

1AT

ELECTRONIC STABILITY CONTROL (ESC)

1E9

WITHOUT ACTIVATED CARBON CANISTER WITH SCR

1EX

SPECIAL IDENTIFICATION PLATE FOR EC FOR M1 PASSENGER VEHICLE

1G8

BREAKDOWN KIT

1JA

REAR SHOCK ABSORPTION, BASIC VERSION 1

1LA

DISK BRAKES IN FRONT

1M6

TRAILER HITCH MECHANICALLY SWIVELING AND POWER-DETACHABLE

1N3

SPEED-RELATED VARIABLE STEERING ASSIST (SERVOTRONIC)

1NL

TRIMS FOR ALLOY WHEELS

1PA

STANDARD WHEEL BOLTS

1S1

TOOL KIT AND JACK

1SA

WITHOUT ADDITIONAL FRONT UNDERBODY GUARD

1T9

FIRST AID KIT WITH WARNING TRIANGLE AND SAFETY VEST

1U9

FOLDING TABLE ON FRONT SEAT BACKRESTS

1X1

FOUR WHEEL DRIVE

1XX

LEATHER-WRAPPED MULTIFUNCTION SPORTS STEERING WHEEL W/ TIPTRONIC

1Z0

INITIAL STANDARD FUEL FILLING

2A0

WITHOUT DELIVERY EQUIPMENT

2EM

DISK BRAKES IN REAR

2H5

DRIVING PROFILE SELECTION AND CONVENTIONAL SHOCK ABSORBER

2JL

COMFORT BUMPERS

2KW

LABELS/PLATES IN GERMAN, FRENCH, AND DUTCH

2WG

ADDITIONAL SNOW TIRES

31K

FRONT AND REAR LICENSE PLATE CARRIER (ECE)

3A0

CHILD SEAT ANCHOR FOR CHILD SEAT SYSTEM I-SIZE, 2X TOP TETHER

3C7

3-POINT SEAT BELT FOR CENTER REAR SEAT

3CA

WITHOUT PARTITION

3FA

WITHOUT ROOF INSERT (STANDARD ROOF)

3GB

CARGO AREA WITH SPLIT FUNCTION

3H2

BACKREST RELEASE FOR RIGHT FRONT SEAT

3L3

MANUAL HEIGHT ADJUSTMENT FOR FRONT SEATS

3LM

DOOR AND SIDE TRIM PANEL

3QT

3-POINT SEAT BELTS IN FRONT, WITH PRETENSIONER AND HEIGHT ADJUSTMENT

3S1

BRIGHT ROOF RAILS

3T2

THREE REAR HEAD RESTRAINTS

3ZU

3-POINT SEAT BELTS, OUTER REAR WITH ECE LABEL

4A3

SEAT HEATER FOR FRONT SEATS SEPARATELY CONTROLLED

4D0

WITHOUT SEAT VENTILATION/MASSAGE SEAT

4E7

TAILGATE/TRUNK LID POWER CLOSING

4GF

WINDSHIELD IN HEAT-INSULATING GLASS

4K3

RADIO REMOTE CONTROLLED CENTRAL LOCKING OPERATED FROM INSIDE AND SAFELOCK

4KC

SIDE AND REAR WINDOWS IN HEAT-INSULATINGGLASS

4L6

BREAKAWAY INTERIOR REARVIEW MIRROR, AUTO-DIMMING

4UP

DRIVER AND FRONT PASSENGER AIRBAG WITH KNEE AIRBAG AND FRONT PASSENGER AIRBAG DEACTIVATION

4X3

SIDE AIRBAG IN FRONT, WITH CURTAIN AIRBAG

4ZB

BRIGHT MOLDINGS

5C0

WITHOUT SPECIAL BODY MEASURES

5D1

CARRIER FREQUENCY 433.92 MHZ-434.42 MHZ

5J0

WITHOUT REAR SPOILER

5K7

TRANSPORT PROTECTION FILM (MINIMUM PROTECTION) WITH ADDITIONAL TRANSPORT PROTECTION MEASURES

5KR

REAR SEAT BENCH/BACKREST, SPLIT FOLDING

5MJ

DECORATIVE INSERTS

5RQ

RIGHT EXTERIOR MIRROR, CONVEX

5SL

LEFT EXTERIOR MIRROR: ASPHERICAL

5XJ

SUN VISORS WITH MIRROR, ILLUMINATED, WITH AIRBAG LABEL ON SUN VISOR AND B-PILLAR

5ZC

HEAD RESTRAINTS FOR FRONT SEATS (X-ADJUSTMENT)

6A0

WITHOUT FIRE EXTINGUISHER

6E4

CENTER ARMREST IN FRONT

6FF

BODY-COLORED EXTERIOR MIRROR HOUSINGS AND VARIOUS ADD-ON PARTS

6K4

FORWARD COLLISION WARNING INCL. AUTONOMOUS EMERGENCY BRAKING, FOR ADAPTIVE CRUISE CONTROL "HIGH"

6KL

RADIATOR GRILLE

6M0

WITHOUT TIE DOWN STRAPS/NET/POCKET

6NA

UNSPLIT MOLDED HEADLINER

6Q2

LEATHER GEARSHIFT KNOB/HANDLE

6T1

INTERIOR LIGHT IN FOOTWELL

6XP

EXTERIOR MIRRORS, POWER-FOLDING, POWER-ADJUSTABLE, SEPARATELY HEATED

7AS

ANTI-THEFT ALARM SYSTEM, INTERIOR MONITORING, BACKUP HORN, AND TOWING PROTECTION

7B3

12-VOLT SOCKET(S)

7E6

ELECTRIC AUXILIARY AIR HEATER

7IX

VEHICLE CLASS DIFFERENTIATION -550-

7K1

DIRECT TIRE PRESSURE MONITORING SYSTEM

7L6

START/STOP SYSTEM WITH REGENERATIVE BRAKING

7N1

OVERHEAD STORAGE COMPARTMENT

7P4

MANUALLY ADJUSTABLE LUMBAR SUPPORT IN FRONT SEATS

7UF

NAVIGATION SYSTEM - STANDARD

7W2

WITH EXTENDED SAFETY SYSTEM (PROACTIVE PASSENGER PROTECTION SYSTEM, BASIC AND FRONT)

7X5

PARK ASSIST

7Y4

LANE KEEPING SYSTEM

8FA

WITHOUT SECOND BATTERY

8G1

HIGH-BEAM CONTROL

8GU

ALTERNATOR 140 A

8IT

LED HEADLAMPS

8K3

SEPARATE DAYTIME RUNNING LIGHTS WITH AUTOMATIC HEADLAMP ACTIVATION AND COMING HOME FEATURE

8N6

WINDSHIELD WIPER INTERMITTENT CONTROL WITH LIGHT/RAIN SENSOR

8Q3

AUTOMATIC HEADLIGHT RANGE ADJUSTMENT DYNAMIC (SELF-ADJUSTING WHILE DRIVING)

8RM

8 SPEAKERS (PASSIVE)

8S6

2 READING LIGHTS IN FRONT

8SQ

LED TAIL LAMP ASSEMBLY

8T8

ADAPTIVE CRUISE CONTROL (WITH "FOLLOW-TO-STOP") AND SPEED LIMITER

8TB

REAR FOG LAMP

8W1

WASHER FLUID LEVEL INDICATOR

8WH

FRONT FOG LAMP AND CORNERING LAMP

8X1

HEADLAMP WASHER SYSTEM

8Y1

TWO-TONE HORN

8Z5

NOT HOT COUNTRY

8ZQ

ANTENNA FOR FM RECEPTION ONLY, DIVERSITY

9E5

LUGGAGE COMPARTMENT LAMP

9J

COMFORT TELEPHONY WITH LTE AND WIRELESS CHARGING

9JA

NON-SMOKER'S PACKAGE

9M0

WITHOUT AUXILIARY HEATER/FUEL-FIRED PARKING HEATER

9P9

SEAT BELT REMINDER, ELECTRIC CONTACT IN THE BUCKLE, ADVANCED SAFETY EQUIPMENT

9S0

MULTI-FUNCTION DISPLAY/TRIP COMPUTER ACTIVE INFO DISPLAY "ENTRY"

9T1

HEATED WASHER NOZZLES IN FRONT

9WX

MIRROR LINK AND WIRELESS RSE "APP"

9Z0

OPERATING VOLTAGE 12 V

A8F

SPORTS EQUIPMENT

AV1

DRIVING ON THE RIGHT

B01

TYPE APPROVAL COUNTRY GERMANY

B0A

COMPONENT PARTS SET WITHOUT COUNTRY-SPECIFIC BUILDING REGULATION

BG

ESC SPECIAL VEHICLE 14

C3I

ALLOY WHEELS 7J X 18

C48

OPERATING PERMIT, ALTERATION

DE5

4-CYL. TURBO DIESEL ENGINE 2.0 L/140 KW (4V) TDI COMMON RAIL BASE ENGINE IS TD1/TR1/T5S/T6F

E0A

NO SPECIAL EDITION

EA0

WITHOUT FOLLOW-ON WARRANTY

EF1

ECO FUNCTION

EL5

ONLINE SERVICE, WITH OCU, WITH HEAD UNITCODING, WITHOUT ENGINE IMMOBILIZER INTERCONNECTION

EM1

DRIVER ALERT SYSTEM

ER1

REGIONAL CODE " ECE " FOR RADIO

ES0

WITHOUT VEHICLE INLET

F0A

NO SPECIAL PURPOSE VEHICLE, STANDARD EQUIPMENT

FB0

STANDARD PAINT COATING

FC0

WITHOUT CUSTOMIZED INSTALLATION

FM0

BASIC EQUIPMENT VARIANT

G01

SHOCK ABSORPTION IN FRONT

G1D

7-SPEED AUTOMATIC TRANSMISSION FOR FOUR-WHEEL DRIVE

GP0

VEHICLES WITHOUT SPECIAL UPGRADE MEASURES

I8F

STANDARD RADIO (GEN2 GP)

J0V

BATTERY 420 A (70 AH)

J94

SUSPENSION RANGE 94

K8G

HATCHBACK

KA2

WITH REAR VIEW CAMERA SYSTEM (TYPE 2)

KH7

CLIMATRONIC (3-ZONE) WITH REAR AIR CONDITIONING CONTROL PANEL

KK3

REFRIGERANT R1234YF

KL1

LED LICENSE PLATE LIGHTING

KS0

WITHOUT HEAD-UP DISPLAY

L05

SUSPENSION RANGE 05 INSTALLATION CONTROL ONLY, NO REQUIREMENT FORECAST

L0L

LEFT-HAND DRIVE

N0R

SEAT TRIM COVERS IN

NY0

STANDARD BATTERY/ALTERNATOR CAPACITY

NZ4

PRIVATE EMERGENCY CALL SYSTEM

Q4H

SPORTS COMFORT SEATS IN FRONT

QG1

SERVICE INTERVAL PROLONGATION

QH1

VOICE CONTROL

QI6

SERVICE INDICATOR 30 000 KM OR 2 YEARS (VARIABLE)

QJ3

CHROME PACKAGE (TYPE 2)

QK1

WITH MULTIFUNCTION CAMERA

QN3

DRAWERS UNDER FRONT SEATS

QQ8

INTERIOR AMBIENT LIGHTING, TYPE 1

QR9

WITH DYNAMIC ROAD SIGN DISPLAY

QV0

WITHOUT TV RECEPTION/DIGITAL RADIO RECEPTION

TR1

4-CYLINDER DIESEL ENGINE 2.0 L UNIT 04L.A

U5A

INSTRUMENT CLUSTER, KM/H SPEEDOMETER

UG2

HILL DESCENT CONTROL

UH2

PARKING BRAKE

UK3

MECHANICAL REAR SEAT RELEASE

UQ2

3 X USB TYPE A AND AUX-IN JACK

V0A

TIRES WITHOUT SPECIFICATION OF TIRE BRAND

VF0

STANDARD PEDAL CLUSTER

VL4

EXTENDED AND CRASH-ACTIVE AND PROACTIVE PEDESTRIAN PROTECTION

VT2

SCUFF PLATES IN DOOR APERTURES (ILLUMINATED)

X0A

EQUIPMENT OPTIONS SUBSET FOR GERMANY



+31

Surse de date

Am verificat 900+ de surse de date în **35 de țări**