



Volkswagen Touareg

VIN: WVGZZZCRZKD040481

Diesel

Generat pe 2024-11-04 10:55



Contor de parcurs

✓ Arată bine



Statut legal

✓ Arată bine



Daune

⚠ Necesită atenție



+31

Surse de date

Am verificat 900+ de surse de date în 35 de țări

Furt

Vehiculul este în prezent marcat ca furat? A fost furat în trecut? A fost recuperat?




Nu s-au găsit probleme

Nu am găsit nicio înregistrare că vehiculul a fost furat.



Notă

Verificarea bazei de date a poliției privind vehiculele furate finalizată în 9 țări:  +3

Iată ce am verificat:



Căutat drept furat

✓ Nu s-a găsit nici o înregistrare



Furat în trecut

✓ Nu s-a găsit nici o înregistrare

Starea actuală necunoscută



Furat în trecut

✓ Nu s-a găsit nici o înregistrare

Vehiculul a fost recuperat

Baza de date aparținând poliției cu vehicule furate, **verificare finalizată în:**



România



Statele Unite ale Americii



Danemarca



Slovenia



Slovacia



Suedia



Cehia



Lituania




Finlanda

Contor de parcurs

Există semne conform cărora kilometrajul a fost dat înapoi sau discrepanțe ale kilometrajului?

Notă

Ultimul kilometraj cunoscut: 139.225 km



Disclaimer (declinarea responsabilității): acest grafic reprezintă o tendință estimată a kilometrajului. Deși se bazează pe înregistrări reale de kilometraj disponibile pentru acest vehicul, există lacune având în vedere că evoluția kilometrajului nu este înregistrată în mod constant. Pentru a lua în considerare aceste date lipsă, aplicăm un model patentat de analiză a datelor care prezice modul în care probabil s-a schimbat kilometrajul între evenimentele înregistrate. Acest lucru ajută la furnizarea unei imagini mai complete a utilizării vehiculului în timp.

Statut legal

A trecut vehiculul inspecțiile tehnice? A fost notat drept casat?

✓ **Nu s-au găsit probleme**

Nu s-au găsit înregistrări despre statutul legal al acestui vehicul

Legal



Inspecție tehnică periodică (ITP)

✓ Nu s-a găsit nici o înregistrare

Nu au fost găsite înregistrări ale inspecției tehnice



Casat

✓ Nu s-a găsit nici o înregistrare

Nu există nici o înregistrare că vehiculul a fost marcat drept casat

Daune

Acest vehicul a fost avariat în trecut ? Care a fost valoarea daunelor?

⚠ **Ai grijă!**

Vehiculul a fost avariat de 2 ori!

ℹ **Notă**

Daunele minore nu vor afecta în mod normal siguranța vehiculului și nu vor cauza probleme structurale

Înregistrări de daune



Daune frontale:

Față / Bară de protecție

Față stânga / Bară de protecție

2020-10

 România

Daune

Costul estimativ al reparațiilor

2.001 RON – 6.000 RON

Cauza posibilă a daunelor

Necunoscut

Categoriile de daune

Părți exterioare ale caroseriei



Daune pe partea dreaptă: **Dreapta / Portieră față**

Daune pe partea dreaptă: **Spate dreapta / Bară de protecție**

2022-08

 România

Daune

Costul estimativ al reparațiilor

2.001 RON – 6.000 RON

Cauza posibilă a daunelor

Necunoscut

Categoriile de daune

Părți exterioare ale caroseriei

Disclaimer (declinarea responsabilității): Majoritatea înregistrărilor de daune sunt legate de accidente, dar uneori nu este acesta cazul. Unele înregistrări provin din alte surse cum ar fi serviciile specializate pe lucrări de caroserie, cereri de daune, licitații sau inspecții ale vehiculelor. Aceste înregistrări arată că starea vehiculului a fost evaluată, chiar dacă nu a fost din cauza unui accident.

Dezastru natural

Locația vehiculului a fost înregistrată în zona unui dezastru natural?

✓ **Nu s-au găsit probleme**

Locația vehiculului nu a fost înregistrată în zona unui dezastru natural

Valoarea de piață

Cu cât s-a vândut vehiculul în trecut? Care este în medie prețul vehiculelor din acest model și an?

i Notă

- Prețul mediu de pe piață pentru un astfel de vehicul: 215.684 RON
- Atenție la problemele ascunse dacă vehiculul a fost la vânzare la un preț semnificativ mai mic decât prețul actual!

Valoarea de piață azi pentru Volkswagen Touareg

Valoarea de piață este determinată prin examinarea prețului unui anumit model de mașină (fabricat în același an) în țara în care a fost generat raportul. Analizăm datele din ultimele 6 luni.

Cel mai mic preț

197.582 RON

Prețul mediu

215.684 RON

Cel mai mare preț

236.229 RON

Emisii

Câte emisii de CO2 produc vehiculele din acest model/an?

i Notă

Emisii CO2: E (173 g/km)

Emisii CO₂

Emisiile CO2 ale
vehiculului tău

173 g/km Clasă **E**

Până la 120

120 - 140

140 - 155

155 - 165

165 - 190

190 - 225

225 și peste

Emisii CO₂ g/km

Specificații și echipare

Ce specificații și echipamente sunt înregistrate pentru acest vehicul?

Notă

Verificați dacă specificațiile și echipamentul acestui vehicul se potrivesc cu datele furnizate de vânzător.

Identificare și specificații tehnice



Producător

Volkswagen



Model

Touareg



Tip caroserie

SUV



An model

2019



Capacitate cilindrică

3 l



Putere motor

210 kW (282 cp)



Tip combustibil

Diesel



Cutie de viteze

Automată



Tip transmisie

Tracțiune integrală (AWD)



Nr. uși

5



Amplasarea volanului

Volan pe stânga



Nr. cilindri

6



Nr. angrenaje

8



Nr. locuri

5



Intervalul de ani al modelului

2018

Echipare

Cum a fost primit de la producător

0E1

SHORT WHEELBASE

0F3

FUEL SYSTEM FOR DIESEL ENGINE

0JK

WEIGHT CATEGORY FRONT AXLE WEIGHT RANGE 10

0K0

WITHOUT ALTERNATIVE DRIVE SYSTEM

0LA

WITHOUT SPECIAL PLATES/LABELS/SAFETY CERTIFICATES

0M0

FUEL TANK

0N5

STANDARD REAR AXLE

0NB

NAMEPLATE SET IN BASIC STYLE

0P6

REAR EXHAUST TAILPIPE

0RC

STARTER SWITCH LOCKING SYSTEM

0SA

WITHOUT SPECIAL LABELS/PLATES

0TD

FLOOR MATS IN FRONT AND REAR

0XH

INFORMATION KIT IN ROMANIAN

0Y1

STANDARD CLIMATIC ZONES

0YJ

WEIGHT RANGE 9 INSTALLATION CONTROL ONLY, NO REQUIREMENT FORECAST

1BK

4-CORNER AIR SUSPENSION WITH ELECTRONIC SHOCK ABSORPTION CONTROL

1D9

TRAILER HITCH, POWER-FOLDING

1EX

SPECIAL IDENTIFICATION PLATE FOR EC FOR M1 PASSENGER VEHICLE

1G1

SPACE-SAVING SPARE WHEEL

1NM

TRIMS FOR ALLOY WHEELS

1P0

STANDARD SUSPENSION

1PA

STANDARD WHEEL BOLTS

1S1

TOOL KIT AND JACK

1SA

WITHOUT ADDITIONAL FRONT UNDERBODY GUARD

1T2

WARNING TRIANGLE

1VH

INSTALLATION PARTS FOR SIX-CYLINDER ENGINE

1Y6

AUTOMATIC SLIP-CONTROL DIFFERENTIAL

1Z0

INITIAL STANDARD FUEL FILLING

1ZA

DISK BRAKES IN FRONT

2A0

WITHOUT DELIVERY EQUIPMENT

2C5

AXIAL AND VERTICAL ADJUSTABLE STEERING COLUMN

2ED

DISK BRAKES IN REAR

2G5

FILLER NECK MODULE 1 WITHOUT INSERT

2H4

DRIVING PROFILE SELECTION AND HYDRAULIC DAMPER CONTROL

2JC

COMFORT BUMPERS

2P2

STAINLESS STEEL LOADING EDGE PROTECTION

2V5

FRESH AIR INTAKE SYSTEM WITH COMBINATIONFILTER

2WA

WITHOUT ADDITIONAL TIRES

2ZS

LEATHER-WRAPPED MULTIFUNCTION STEERING WHEEL WITH TIPTRONIC

31K

FRONT AND REAR LICENSE PLATE CARRIER (ECE)

3A0

CHILD SEAT ANCHOR FOR CHILD SEAT SYSTEM I-SIZE, 2X TOP TETHER

3CA

WITHOUT PARTITION

3D3

CENTER CONSOLE

3FU

BIG ROOF SYSTEM

3G0

WITHOUT CHILD SEAT ANCHOR FRONT (ISOFIX)

3GD

PLANE REAR CARGO AREA

3L7

POWER SEAT ADJUSTMENT FOR BOTH FRONT SEATS, LEFT SEAT WITH MEMORY FEATURE AND SEAT DEPTH ADJUSTMENT

3M0

WITHOUT SPECIAL MEASURES

3NS

SPLIT FOLDING REAR SEAT BENCH/BACKREST, WITH CENTER ARMREST

3QT

3-POINT SEAT BELTS IN FRONT, WITH PRETENSIONER AND HEIGHT ADJUSTMENT

3S5

BLACK ROOF RAILS

3U7

LUGGAGE COMPARTMENT COVER

3W5

SPECIAL NOISE SUPPRESSION MEASURE FOR PASSENGER COMPARTMENT, WITHOUT DEADENER FOR ENCLOSURE

3Y0

WITHOUT ROLL-UP SUNSHADE

3ZU

3-POINT SEAT BELTS, OUTER REAR WITH ECE LABEL

4A3

SEAT HEATER FOR FRONT SEATS SEPARATELY CONTROLLED

4AV

DOOR AND SIDE TRIM PANEL

4D5

SEAT VENTILATION/MASSAGE SEAT(S) IN FRONT

4E7

TAILGATE/TRUNK LID POWER CLOSING

4GF

WINDSHIELD IN HEAT-INSULATING GLASS

4I7

CENTRAL LOCKING SYSTEM "KEYLESS-GO" WITHOUT SAFELOCK

4KF

SIDE WINDOWS IN HEAT-INSULATING GLASS, FROM B-PILLAR AND REAR WINDOW DARK TINTED

4UP

DRIVER AND FRONT PASSENGER AIRBAG WITH KNEE AIRBAG AND FRONT PASSENGER AIRBAG DEACTIVATION

4X4

SIDE AIRBAG IN FRONT AND REAR WITH CURTAIN AIRBAG

4ZN

BRIGHT MOLDINGS

5C0

WITHOUT SPECIAL BODY MEASURES

5D1

CARRIER FREQUENCY 433.92 MHZ-434.42 MHZ

5K7

TRANSPORT PROTECTION FILM (MINIMUM PROTECTION) WITH ADDITIONAL TRANSPORT PROTECTION MEASURES

5RQ

RIGHT EXTERIOR MIRROR, CONVEX

5SL

LEFT EXTERIOR MIRROR: ASPHERICAL

5TF

DECORATIVE WOOD INSERTS

5ZD

FRONT HEAD RESTRAINTS

6A0

WITHOUT FIRE EXTINGUISHER

6D1

CENTER ARMREST IN REAR

6E3

CENTER ARMREST IN FRONT

6F0

WITHOUT DECORATIVE FILMS / EMBLEMS

6FG

EXTERIOR MIRROR HOUSINGS PAINTED

6GA

WITHOUT ADD-ON KIT

6I1

LANE KEEPING SYSTEM

6K8

PRE SENSE CITY WITHOUT PRE CARE

6KE

RADIATOR GRILLE

6M0

WITHOUT TIE DOWN STRAPS/NET/POCKET

6MB

DOUBLE SUN VISORS WITH MIRROR, ILLUMINATED, AIRBAG LABEL ON SUN VISOR

6NJ

STANDARD MOLDED HEADLINER

6SF

STANDARD LUGGAGE COMPARTMENT FLOOR COVERING

6U0

WITHOUT ADDITIONAL SEALS OUTSIDE

6XL

EXTERIOR MIRRORS WITH MEMORY FEATURE, AUTO-DIMMING, POWER-FOLDING/ADJUSTABLE/HEATED

73A

WITHOUT CHARGING CABLE (INDUSTRIAL CONNECTOR)

7AA

ELECTRONIC ENGINE IMMOBILIZER

7E6

ELECTRIC AUXILIARY AIR HEATER

7G0

WITHOUT PREPARATION FOR VTS (VEHICLE TRACKING SYSTEM)

7IG

VEHICLE CLASS DIFFERENTIATION -760-

7K1

DIRECT TIRE PRESSURE MONITORING SYSTEM

7L8

START/STOP SYSTEM WITH REGENERATIVE BRAKING

7M9

SCUFF PLATES IN DOOR APERTURES

7US

PREMIUM NAVIGATION SYSTEM

7W0

WITHOUT EXTENDED SAFETY SYSTEM

7X5

PARK ASSIST

7Y0

WITHOUT LANE CHANGE ASSIST

8G4

MATRIX BEAM

8I6

LUMBAR SUPPORT, PNEUMATICALLY ADJUSTABLE

8IU

LED HEADLAMPS WITH VARIABLE LIGHT DISTRIBUTION

8Q3

AUTOMATIC HEADLIGHT RANGE ADJUSTMENT DYNAMIC (SELF-ADJUSTING WHILE DRIVING)

8RM

8 SPEAKERS (PASSIVE)

8SP

LED TAIL LAMP ASSEMBLY

8T8

ADAPTIVE CRUISE CONTROL (WITH "FOLLOW-TO-STOP") AND SPEED LIMITER

8TC

REAR FOG LAMP FOR DRIVING ON THE RIGHT

8WF

ALL-WEATHER LIGHT

8X1

HEADLAMP WASHER SYSTEM

8Y1

TWO-TONE HORN

8Z5

NOT HOT COUNTRY

8ZH

ANTENNA FOR AM/FM RECEPTION, "DIVERSITY"

9AD

CLIMATRONIC, CFC-FREE

9G5

ALTERNATOR 140-210 A

9I5

SEPARATE DAYTIME RUNNING LIGHTS WITH AUTOMATIC HEADLAMP ACTIVATION AND COMING HOME FEATURE (AUTOMATIC)

9JB

SMOKER'S PACKAGE, ASHTRAY IN FRONT AND REAR

9M0

WITHOUT AUXILIARY HEATER/FUEL-FIRED PARKING HEATER

9P4

SEAT BELT REMINDER, ELECTRIC CONTACT IN FRONT AND REAR, VISUAL AND ACOUSTICAL

9R0

WITHOUT NIGHT VISION

9S8

MULTI-FUNCTION DISPLAY/ON-BOARD COMPUTER"FPK" (ACTIVE INFO DISPLAY)

9T1

HEATED WASHER NOZZLES IN FRONT

9WX

MIRROR LINK AND WIRELESS RSE "APP"

9Z0

OPERATING VOLTAGE 12 V

9ZC

COMFORT TELEPHONY WITH EXTERIOR ANTENNA AND (RSAP)

A60

CATEGORY 0

A8S

STANDARD EQUIPMENT

AV1

DRIVING ON THE RIGHT

B0A

COMPONENT PARTS SET WITHOUT COUNTRY-SPECIFIC BUILDING REGULATION

B43

TYPE APPROVAL COUNTRY ROMANIA

C04

OPERATING PERMIT, ALTERATION

C2T

ALLOY WHEELS 8J X 19

DV8

6-CYL. TURBO DIES. ENG. 3.0 L/210 KW V6 TDI COMMON RAIL BASE ENGINE IS T7V

E0A

NO SPECIAL EDITION

EA0

WITHOUT FOLLOW-ON WARRANTY

EL3

ONLINE SERVICE, WITHOUT OCU, WITH HEAD UNIT CODING, WITHOUT ENGINE IMMOBILIZER INTERCONNECTION

EM1

DRIVER ALERT SYSTEM

ER1

REGIONAL CODE " ECE " FOR RADIO

ES0

WITHOUT VEHICLE INLET

EVO

WITHOUT CHARGING CABLE

F0A

NO SPECIAL PURPOSE VEHICLE, STANDARD EQUIPMENT

FC0

WITHOUT CUSTOMIZED INSTALLATION

FK1

WITH ADDITIONAL TANK FOR SCR (12 LITERS)

FM0

BASIC EQUIPMENT VARIANT

FT0

WITHOUT PARK ASSIST WITH REMOTE CONTROL/GARAGE PARKING ASSIST

G1G

8-SPEED AUTOMATIC TRANSMISSION FOR FOUR-WHEEL DRIVE

GH1

BASIC REAR DIFFERENTIAL

GJ0

WITHOUT TRAFFIC JAM ASSIST/CO-PILOT IN HEAVY TRAFFIC

GM0

WITHOUT ELECTRONIC ENGINE SOUND MEASURES

GP0

VEHICLES WITHOUT SPECIAL UPGRADE MEASURES

GY1

POWER LATCHING FOR TAILGATE

GZ0

MANUALLY OPERATED DOORS

I40

TIRES 255/55 R19 107W

I8T

RADIO HIGH PLUS (GEN2)

IT0

WITHOUT AUDI CONNECT PACKAGE 1

IW3

EMERGENCY CALL SERVICE AND ROADSIDE ASSISTANCE CALL

J0B

BATTERY 520 A (92 AH)

JX0

WITHOUT FRONT CROSS TRAFFIC ASSIST

K4H

CLOSED BODY

KA2

WITH REAR VIEW CAMERA SYSTEM (TYPE 2)

KB0

WITHOUT BATTERY CHARGER

KK3

REFRIGERANT R1234YF

KS0

WITHOUT HEAD-UP DISPLAY

L0L

LEFT-HAND DRIVE

N5E

SEAT TRIM COVERS IN LEATHER

NT0

TRANSIT COATING (TYPE 1)

NZ4

PRIVATE EMERGENCY CALL SYSTEM

Q2J

COMFORT SEATS IN FRONT

QG1

SERVICE INTERVAL PROLONGATION

QI6

SERVICE INDICATOR 30 000 KM OR 2 YEARS (VARIABLE)

QK1

WITH MULTIFUNCTION CAMERA

QQ2

WITH ADDITIONAL LIGHTS (INTERIOR LIGHTING)

QR9

WITH DYNAMIC ROAD SIGN DISPLAY

QV0

WITHOUT TV RECEPTION/DIGITAL RADIO RECEPTION

QZ7

POWER STEERING

T7V

6-CYLINDER DIESEL ENGINE 3.0 L UNIT 059.N

U5A

INSTRUMENT CLUSTER, KM/H SPEEDOMETER

UH4

PARKING BRAKE

UK3

MECHANICAL REAR SEAT RELEASE

UQ7

ELECTRIC INTERFACE FOR EXTERNAL USE, 4 X USB

V0A

TIRES WITHOUT SPECIFICATION OF TIRE BRAND

VC0

WITHOUT REMOTE-CONTROLLED GARAGE DOOR OPENER

VF0

STANDARD PEDAL CLUSTER

VH0

STANDARD ELECTRIC

VL1

EXTENDED PEDESTRIAN PROTECTION MEASURES

X4N

EQUIPMENT OPTIONS SUBSET FOR ROMANIA

Cronologie

S-au găsit 2 înregistrări

Cronologia înregistrărilor pentru acest vehicul

Ultimele înregistrări

2020-10

 **România**



Daună detectată

Avem indicii potrivit cărora acest vehicul a fost recunoscut ca avariat în această țară (sau stat). Pentru detalii, vă rugăm să consultați secțiunea „Daune”.

2022-08

 **România**



Daună detectată

Avem indicii potrivit cărora acest vehicul a fost recunoscut ca avariat în această țară (sau stat). Pentru detalii, vă rugăm să consultați secțiunea „Daune”.



+31

Surse de date

Am verificat 900+ de surse de date în **35 de țări**