

Volkswagen

VIN: WWZZZ3CZME124662

Diesel

Generat pe 2024-11-25 11:09



Contor de parcurs

✓ Arată bine



Statut legal

✓ Arată bine



Daune

✓ Arată bine



+31

Surse de date

Am verificat 900+ de surse de date în **35 de țări**

Furt

Vehiculul este în prezent marcat ca furat? A fost furat în trecut? A fost recuperat?




Nu s-au găsit probleme

Nu am găsit nicio înregistrare că vehiculul a fost furat.



Notă

Verificarea bazei de date a poliției privind vehiculele furate finalizată în **7 țări**:  +1

Iată ce am verificat:



Căutat drept furat

✓ Nu s-a găsit nici o înregistrare



Furat în trecut

✓ Nu s-a găsit nici o înregistrare

Starea actuală necunoscută



Furat în trecut

✓ Nu s-a găsit nici o înregistrare

Vehiculul a fost recuperat

Baza de date aparținând poliției cu vehicule furate, **verificare finalizată în:**



România



Danemarca



Lituania



Slovacia



Finlanda



Slovenia




Suedia

Contor de parcurs

Există semne conform cărora kilometrajul a fost dat înapoi sau discrepanțe ale kilometrajului?

Notă

Ultimul kilometraj cunoscut: 115.343 km



Disclaimer (declinarea responsabilității): acest grafic reprezintă o tendință estimată a kilometrajului. Deși se bazează pe înregistrări reale de kilometraj disponibile pentru acest vehicul, există lacune având în vedere că evoluția kilometrajului nu este înregistrată în mod constant. Pentru a lua în considerare aceste date lipsă, aplicăm un model patentat de analiză a datelor care prezice modul în care probabil s-a schimbat kilometrajul între evenimentele înregistrate. Acest lucru ajută la furnizarea unei imagini mai complete a utilizării vehiculului în timp.

Statut legal

A trecut vehiculul inspecțiile tehnice? A fost notat drept casat?

✓ **Nu s-au găsit probleme**

Nu s-au găsit înregistrări despre statutul legal al acestui vehicul

Legal



Inspecție tehnică periodică (ITP)

✓ Nu s-a găsit nici o înregistrare

Nu au fost găsite înregistrări ale inspecției tehnice



Casat

✓ Nu s-a găsit nici o înregistrare

Nu există nici o înregistrare că vehiculul a fost marcat drept casat

Daune

Acest vehicul a fost avariat în trecut ? Care a fost valoarea daunelor?

✓ **Nu s-au găsit probleme**

Înregistrări de daune



Ocazional pot apărea inexactități, mai ales la verificarea vehiculelor vechi. Atelierele clandestine de reparații pot deghiza ilegal defectele sau daunele vehiculelor, fără să declare nicăieri existența lor. Uneori până și plăcuțele VIN ale vehiculului pot fi înlocuite. Avem o varietate de metode de a detecta chiar și astfel de infracțiuni, dar este imposibil de oferit o garanție de 100%.

Dezastru natural

Locația vehiculului a fost înregistrată în zona unui dezastru natural?

Nu s-au găsit probleme

Locația vehiculului nu a fost înregistrată în zona unui dezastru natural

Specificații și echipare

Ce specificații și echipamente sunt înregistrate pentru acest vehicul?

Notă

Verificați dacă specificațiile și echipamentul acestui vehicul se potrivesc cu datele furnizate de vânzător.

Identificare și specificații tehnice



Producător

Volkswagen



Tip caroserie

Break



An model

2021



Capacitate cilindrică

2 l



Putere motor

110 kW (148 cp)



Tip combustibil

Diesel



Cutie de viteze

Automată



Tip transmisie

Tracțiune față (FWD)



Amplasarea volanului

Volan pe stânga



Nr. cilindri

4

Echipare

Cum a fost primit de la producător

0B4

WHEELBASE

0F5

FUEL SYSTEM FOR DIESEL ENGINE

0FA

STANDARD MANUFACTURING SEQUENCE

0J

INSTALLATION DIFFERENTIATION FOR TRANSMISSION "DQ381" -- VEHICLE COMPONENTS --

0K0

WITHOUT ALTERNATIVE DRIVE SYSTEM

0M4

FUEL TANK

0NB

NAMEPLATE SET IN BASIC STYLE

0P0

REAR EXHAUST TAILPIPE (STANDARD)

0RF

WITH ELECTRONIC STEERING COLUMN LOCK

0SB

LABELS/PLATES IN GERMAN

0TD

FLOOR MATS IN FRONT AND REAR

0VC

INFORMATION KIT IN GERMAN

0Y1

STANDARD CLIMATIC ZONES

0YD

WEIGHT RANGE 4 INSTALLATION CONTROL ONLY, NO REQUIREMENT FORECAST

1AQ

BRS FOR VEHICLES WITHOUT ELECTRIC DRIVE (ESC AND ELECTRIC BRAKE BOOSTER)

1D0

WITHOUT TRAILER HITCH

1E9

WITHOUT ACTIVATED CARBON CANISTER WITH SCR

1EX

SPECIAL IDENTIFICATION PLATE FOR EC FOR M1 PASSENGER VEHICLE

1G3

ALLOY SPARE WHEEL WITH ORIGINAL EQUIPMENT TIRES

1JP

REAR SHOCK ABSORPTION

1N3

SPEED-RELATED VARIABLE STEERING ASSIST (SERVOTRONIC)

1PE

WHEEL BOLTS WITH ANTI-THEFT PROTECTION (UNLOCKABLE)

1Q2

MASS DAMPER FOR STEERING WHEEL, 36 HZ

1S1

TOOL KIT AND JACK

1SA

WITHOUT ADDITIONAL FRONT UNDERBODY GUARD

1T9

FIRST AID KIT WITH WARNING TRIANGLE AND SAFETY VEST

1X0

FRONT WHEEL DRIVE

1Y0

WITHOUT DIFFERENTIAL LOCK

1Z0

INITIAL STANDARD FUEL FILLING

1ZK

DISK BRAKES IN FRONT

20A

WITHOUT ELECTRIC MOTOR (HYBRID)

2A0

WITHOUT DELIVERY EQUIPMENT

2EM

DISK BRAKES IN REAR

2F0

WITHOUT LOCKING AND STARTING SYSTEMS

2FT

SPORTS MULTIFUNCTION STEERING WHEEL WITH TIPTRONIC (LEATHER + WOOD)

2I0

ADAPTIVE CHASSIS CONTROL WITH CONTINUOUS OPERATION

2JP

BUMPERS

2P1

PLASTIC LOADING EDGE PROTECTION

2R9

POWER SEAT ADJUSTM. F. FRONT SEATS, LEFTSEAT W/ MEMORY FEATURE, SEAT CUSHION DEPTH ADJUSTM. + SMART COMFORT ENTRY AID

2WA

WITHOUT ADDITIONAL TIRES

31K

FRONT AND REAR LICENSE PLATE CARRIER (ECE)

3A0

CHILD SEAT ANCHOR FOR CHILD SEAT SYSTEM I-SIZE, 2X TOP TETHER

3C7

3-POINT SEAT BELT FOR CENTER REAR SEAT

3CX

NET PARTITION

3D3

CENTER CONSOLE

3FA

WITHOUT ROOF INSERT (STANDARD ROOF)

3GA

WITHOUT CARGO AREA

3H0

WITHOUT BACKREST RELEASE FOR FRONT SEATS

3LC

DOOR AND SIDE TRIM PANEL IN FOAM FILM AND WOVEN FABRIC

3NT

REAR SEAT BENCH UNSPLIT, BACKREST SPLIT FOLDING (THREE PIECES) WITH CENTER ARMREST

3QT

3-POINT SEAT BELTS IN FRONT, WITH PRETENSIONER AND HEIGHT ADJUSTMENT

3S1

BRIGHT ROOF RAILS

3T2

THREE REAR HEAD RESTRAINTS

3U7

LUGGAGE COMPARTMENT COVER

3Y0

WITHOUT ROLL-UP SUNSHADE

3ZB

3-POINT SEAT BELTS, OUTER REAR WITH ECE LABEL

4A3

SEAT HEATER FOR FRONT SEATS SEPARATELY CONTROLLED

4B3

PROTECTIVE SIDE MOLDING

4D0

WITHOUT SEAT VENTILATION/MASSAGE SEAT

4F2

CENTRAL LOCKING SYSTEM "KEYLESS ENTRY"

4GF

WINDSHIELD IN HEAT-INSULATING GLASS

4H3

MANUAL CHILD SAFETY LOCK

4KF

SIDE WINDOWS IN HEAT-INSULATING GLASS, FROM B-PILLAR AND REAR WINDOW DARK TINTED

4L6

BREAKAWAY INTERIOR REARVIEW MIRROR, AUTO-DIMMING

4M6

BEVERAGE HOLDERS

4UF

DRIVER AND FRONT PASSENGER AIRBAG WITH FRONT PASSENGER AIRBAG DEACTIVATION

4V0

WITHOUT FRONT PASSENGER SEAT CONTROL

4X3

SIDE AIRBAG IN FRONT, WITH CURTAIN AIRBAG

4ZB

BRIGHT MOLDINGS

5C0

WITHOUT SPECIAL BODY MEASURES

5D1

CARRIER FREQUENCY 433.92 MHZ-434.42 MHZ

5J0

WITHOUT REAR SPOILER

5K7

TRANSPORT PROTECTION FILM (MINIMUM PROTECTION) WITH ADDITIONAL TRANSPORT PROTECTION MEASURES

5MV

DECORATIVE INSERTS

5RQ

RIGHT EXTERIOR MIRROR, CONVEX

5SL

LEFT EXTERIOR MIRROR: ASPHERICAL

5XV

SUN VISORS WITH MIRROR, ILLUMINATED, WITH AIRBAG LABEL ON SUN VISOR AND B-PILLAR

5ZC

HEAD RESTRAINTS FOR FRONT SEATS (X-ADJUSTMENT)

6A0

WITHOUT FIRE EXTINGUISHER

6E3

CENTER ARMREST IN FRONT

6I6

LANE KEEPING SYSTEM PLUS SEMI-AUTOMATIC VEHICLE CONTROL IN A MEDICAL EMERGENCY AND TRAFFIC JAM ASSIST

6K4

FORWARD COLLISION WARNING INCL. AUTONOMOUS EMERGENCY BRAKING, FOR ADAPTIVE CRUISE CONTROL "HIGH"

6M0

WITHOUT TIE DOWN STRAPS/NET/POCKET

6NA

UNSPLIT MOLDED HEADLINER

6Q2

LEATHER GEARSHIFT KNOB/HANDLE

6SM

LUGGAGE COMPARTMENT FLOOR COVERING IN NEEDLE-PUNCHED NONWOVEN (DILOURS)

6T1

INTERIOR LIGHT IN FOOTWELL

6XT

EXTERIOR MIRRORS WITH MEMORY FEATURE, AUTO-DIMMING, POWER-FOLDING/ADJUSTABLE, SEPARATELY HEATED

7AL

ANTI-THEFT ALARM SYSTEM, INTERIOR MONITORING, BACKUP HORN, AND TOWING PROTECTION

7B3

12-VOLT SOCKET(S)

7E6

ELECTRIC AUXILIARY AIR HEATER

7G0

WITHOUT PREPARATION FOR VTS (VEHICLE TRACKING SYSTEM)

7K3

DIRECT TIRE PRESSURE MONITORING SYSTEM, FREQUENCY 433 MHZ HIGH

7L6

START/STOP SYSTEM WITH REGENERATIVE BRAKING

7M0

PLASTIC SCUFF PLATES IN DOOR APERTURES

7QA

WITHOUT CD/DVD FOR NAVIGATION

7U0

STANDARD ENGINE STARTER

7W4

WITH EXTENDED SAFETY SYSTEM (PROACTIVE PASSENGER PROTECTION SYSTEM, BASIC, FRONT, AND REAR)

7X5

PARK ASSIST

7Y1

LANE CHANGE ASSIST

7ZD

VEHICLE CLASS DIFFERENTIATION -3G0-

8AR

RADIO "GAMMA" WITH REMOVABLE OPERATING PANEL

8FA

WITHOUT SECOND BATTERY

8G1

HIGH-BEAM CONTROL

8GU

ALTERNATOR 140 A

8I0

POWER-ADJUSTABLE LUMBAR SUPPORT IN FRONTSEAT BACKRESTS AND MASSAGE FEATURE ON THE LEFT

8IT

LED HEADLAMPS

8K3

SEPARATE DAYTIME RUNNING LIGHTS WITH AUTOMATIC HEADLAMP ACTIVATION AND COMING HOME FEATURE

8N6

WINDSHIELD WIPER INTERMITTENT CONTROL WITH LIGHT/RAIN SENSOR

8Q1

HEADLIGHT RANGE ADJUSTMENT

8RM

8 SPEAKERS (PASSIVE)

8S6

2 READING LIGHTS IN FRONT

8T8

ADAPTIVE CRUISE CONTROL (WITH "FOLLOW-TO-STOP") AND SPEED LIMITER

8WH

FRONT FOG LAMP AND CORNERING LAMP

8X0

WITHOUT HEADLAMP WASHER SYSTEM

8Y1

TWO-TONE HORN

8Z5

NOT HOT COUNTRY

8ZQ

ANTENNA FOR FM RECEPTION ONLY, DIVERSITY

9B0

WITHOUT TELEPAY DEVICE

9D0

WITHOUT PREPARATION FOR TWO-WAY RADIO INSTALLATION

9F0

WITHOUT SOUND COMBINATION FOR ROTATING EMERGENCY LIGHT AND RADIO ANTENNA PREPARATION

9J

COMFORT TELEPHONY WITH LTE AND WIRELESS CHARGING

9JA

NON-SMOKER'S PACKAGE

9M0

WITHOUT AUXILIARY HEATER/FUEL-FIRED PARKING HEATER

9P9

SEAT BELT REMINDER, ELECTRIC CONTACT IN THE BUCKLE, ADVANCED SAFETY EQUIPMENT

9S6

MULTI-FUNCTION DISPLAY/ON-BOARD COMPUTER"COLOUR"

9T1

HEATED WASHER NOZZLES IN FRONT

9TJ

ADDITIONAL LED WARNING LIGHT (DOOR AREA)IN FRONT

9WJ

POWER SUPPLY/TV SIGNAL FOR CUSTOMIZED INSTALLATION

9Z3

12-V OPERATING VOLTAGE AND 230-V INVERTER

A60

CATEGORY 0

A8C

COMFORT EQUIPMENT

AV1

DRIVING ON THE RIGHT

B01

TYPE APPROVAL COUNTRY GERMANY

B0A

COMPONENT PARTS SET WITHOUT COUNTRY-SPECIFIC BUILDING REGULATION

CN3

ALLOY WHEELS 7J X 17

DN4

4-CYL. TURBO DIESEL ENGINE 2.0 L/110 KW (4V) TDI COMMON RAIL; B.ENGINE T37/T6F
TS1/TR1/T0P/T0N/T13/T29/TM4/TD1/TI9/T1I

E0A

NO SPECIAL EDITION

EA0

WITHOUT FOLLOW-ON WARRANTY

EF1

ECO FUNCTION

EL5

ONLINE SERVICE, WITH OCU, WITH HEAD UNITCODING, WITHOUT ENGINE IMMOBILIZER INTERCONNECTION

EM1

DRIVER ALERT SYSTEM

ER1

REGIONAL CODE " ECE " FOR RADIO

ES0

WITHOUT VEHICLE INLET

EVO

WITHOUT CHARGING CABLE

F0A

NO SPECIAL PURPOSE VEHICLE, STANDARD EQUIPMENT

FC0

WITHOUT CUSTOMIZED INSTALLATION

FM0

BASIC EQUIPMENT VARIANT

G04

SHOCK ABSORPTION IN FRONT

G1C

SEVEN-SPEED AUTOMATIC TRANSMISSION

GM1

STANDARD ELECTRONIC ENGINE SOUND

GP1

VEHICLES WITH SPECIAL UPGRADE MEASURES

J0V

BATTERY 420 A (70 AH)

J85

SUSPENSION RANGE 85

K8D

WAGON/AVANT

KA2

WITH REAR VIEW CAMERA SYSTEM (TYPE 2)

KH7

CLIMATRONIC (3-ZONE) WITH REAR AIR CONDITIONING CONTROL PANEL

KK3

REFRIGERANT R1234YF

KS2

COMBINER HEAD-UP DISPLAY

L07

SUSPENSION RANGE 07 INSTALLATION CONTROL ONLY, NO REQUIREMENT FORECAST

L0L

LEFT-HAND DRIVE

N0U

SEAT TRIM COVERS IN VELOUR

NY0

STANDARD BATTERY/ALTERNATOR CAPACITY

NZ4

PRIVATE EMERGENCY CALL SYSTEM

Q2J

COMFORT SEATS IN FRONT

QA0

WITHOUT CHILD SEAT

QG1

SERVICE INTERVAL PROLONGATION

QH1

VOICE CONTROL

QI6

SERVICE INDICATOR 30 000 KM OR 2 YEARS (VARIABLE)

QJ1

CHROME PACKAGE

QK1

WITH MULTIFUNCTION CAMERA

QQ0

WITHOUT ADD. LIGHTS (INTERIOR LIGHTING)

QR9

WITH DYNAMIC ROAD SIGN DISPLAY

QV3

DIGITAL RADIO RECEPTION

T3Y

4-CYLINDER DIESEL ENGINE 2.0 L UNIT 05L.D

U5A

INSTRUMENT CLUSTER, KM/H SPEEDOMETER

U9C

2 X USB TYPE C

UG6

HILL START ASSIST

UH2

PARKING BRAKE

UP9

WITHOUT CLOCK

V0A

TIRES WITHOUT SPECIFICATION OF TIRE BRAND

VC0

WITHOUT REMOTE-CONTROLLED GARAGE DOOR OPENER

VF0

STANDARD PEDAL CLUSTER

VL3

EXTENDED AND PROACTIVE PEDESTRIAN PROTECTION

X0A

EQUIPMENT OPTIONS SUBSET FOR GERMANY



+31

Surse de date

Am verificat 900+ de surse de date în **35 de țări**