

Volkswagen Arteon

VIN: WWZZZ3HZJE531314

Diesel

2018

Generat pe 2024-12-03 12:31



Odometru

✓ Arată bine



Statut legal

✓ Arată bine



Daune

⚠ Necesită atenție



+31

Surse de date

Am verificat 900+ de surse de date în 35 de țări

Furt

Vehiculul este în prezent marcat ca furat? A fost furat în trecut? A fost recuperat?



Nu s-au găsit probleme

Nu am găsit nicio înregistrare că vehiculul a fost furat.



Notă

Verificarea bazei de date a poliției privind vehiculele furate finalizată în 8 țări: +2

Iată ce am verificat:



Căutat drept furat

✓ Nu s-a găsit nici o înregistrare



Furat în trecut

✓ Nu s-a găsit nici o înregistrare

Starea actuală necunoscută



Furat în trecut

✓ Nu s-a găsit nici o înregistrare

Vehiculul a fost recuperat

Baza de date aparținând poliției cu vehicule furate, **verificare finalizată în:**

România

Statele Unite ale Americii


Danemarca

Odometru

Există semne conform cărora kilometrajul a fost dat înapoi sau discrepanțe ale kilometrajului?

Notă

Ultimul kilometraj cunoscut: 75.558 km




Disclaimer (declinarea responsabilității): acest grafic reprezintă o tendință estimată a kilometrajului. Deși se bazează pe înregistrări reale de kilometraj disponibile pentru acest vehicul, există lacune având în vedere că evoluția kilometrajului nu este înregistrată în mod constant. Pentru a lua în considerare aceste date lipsă, aplicăm un model patentat de analiză a datelor care prezice modul în care probabil s-a schimbat kilometrajul între evenimentele înregistrate. Acest lucru ajută la furnizarea unei imagini mai complete a utilizării vehiculului în timp.

Statut legal

A trecut vehiculul inspecțiile tehnice? A fost notat drept casat?

i Notă

Inspekția tehnică a fost transmisă pe 2023-06 în  **România**

Legal



Inspekție tehnică periodică (ITP)

A trecut 2023-06

 **România**

A trecut cu succes inspekția tehnică

Valabil până la 2025-06



Casat

✓ Nu s-a găsit nici o înregistrare

Nu există nici o înregistrare că vehiculul a fost marcat drept casat

Daune

Acest vehicul a fost avariat în trecut ? Care a fost valoarea daunelor?

! Ai grijă!

Vehiculul a fost avariat de 3 ori!

i Notă

Daunele minore nu vor afecta în mod normal siguranța vehiculului și nu vor cauza probleme structurale

Înregistrări de daune



Daune frontale:

Față / Parbriz

2019-02

 România

Daune

Costul estimativ al reparațiilor

2.001 RON – 6.000 RON

Cauza posibilă a daunelor

Necunoscut

Categoriile de daune

Sticlă



Daune pe partea stângă

Stânga / Portieră față

2021-04

 România

Daune

Costul estimativ al reparațiilor

0 RON – 2.000 RON

Cauza posibilă a daunelor

Necunoscut

2022-10

 România**Daune**

Costul estimativ al reparațiilor

24.001 RON – 48.000 RON

Cauza posibilă a daunelor


Necunoscut

Categoriile de daune

Părți exterioare ale caroseriei

Elemente structurale ale caroseriei

Sistem de suspensie

Daune pe partea dreaptă: **Dreapta / Portieră față**Daune pe partea dreaptă: **Spate dreapta / Bară de protecție**

Disclaimer (declinarea responsabilității): Majoritatea înregistrărilor de daune sunt legate de accidente, dar uneori nu este acesta cazul. Unele înregistrări provin din alte surse cum ar fi serviciile specializate pe lucrări de caroserie, cereri de daune, licitații sau inspecții ale vehiculelor. Aceste înregistrări arată că starea vehiculului a fost evaluată, chiar dacă nu a fost din cauza unui accident.

Dezastre naturale

Locația vehiculului a fost înregistrată în zona unui dezastru natural?

✓ Nu s-au găsit probleme

Locația vehiculului nu a fost înregistrată în zona unui dezastru natural

Valoarea de piață

Cu cât s-a vândut vehiculul în trecut? Care este în medie prețul vehiculelor din acest model și an?

i Notă

- Prețul mediu de pe piață pentru un astfel de vehicul: 121.986 RON
- Atenție la problemele ascunse dacă vehiculul a fost la vânzare la un preț semnificativ mai mic decât prețul actual!

Valoarea de piață azi pentru Volkswagen Arteon 2018

Valoarea de piață este determinată prin examinarea prețului unui anumit model de mașină (fabricat în același an) în țara în care a fost generat raportul. Analizăm datele din ultimele 6 luni.

Cel mai mic preț

113.242 RON

Prețul mediu

121.986 RON

Cel mai mare preț

133.165 RON

Emisii

Câte emisii de CO₂ produc vehiculele din acest model/an?

i Notă

Emisii CO₂: B (134 g/km)

Emisii CO₂

Emisiile CO₂ ale
vehiculului tău

134 g/km Clasă **B**

Până la 120

120 - 140

140 - 155

155 - 165

165 - 190

190 - 225

225 și peste

Emisii CO₂ g/km

Specificații și echipare

Ce specificații și echipamente sunt înregistrate pentru acest vehicul?

i Notă

Verificați dacă specificațiile și echipamentul acestui vehicul se potrivesc cu datele furnizate de vânzător.

Identificare și specificații tehnice



Producător

Volkswagen



Model

Arteon



Tip caroserie

Hatchback



An de fabricație

2018



An model

2018



Capacitate cilindrică

2 l



Putere motor

140 kW (188 cp)



Tip combustibil

Diesel



Cutie de viteze

Automată



Tip transmisie

Tracțiune integrală (AWD)



Culoare

Galben



Nr. uși

5



Amplasarea volanului

Volan pe stânga



Nr. cilindri

4



Nr. locuri

5

Echipare

Cum a fost primit de la producător

0B5

WHEELBASE

0F5

FUEL SYSTEM FOR DIESEL ENGINE

0FA

STANDARD MANUFACTURING SEQUENCE

0IJ

INSTALLATION DIFFERENTIATION FOR TRANSMISSION "DQ381" -- VEHICLE COMPONENTS --

0K0

WITHOUT ALTERNATIVE DRIVE SYSTEM

0M4

FUEL TANK

0NB

NAMEPLATE SET IN BASIC STYLE

0P0

REAR EXHAUST TAILPIPE (STANDARD)

0SC

LABELS/PLATES IN ENGLISH

0TE

FLOOR MATS IN FRONT AND REAR

0XH

INFORMATION KIT IN ROMANIAN

0Y1

STANDARD CLIMATIC ZONES

0YF

WEIGHT RANGE 6 INSTALLATION CONTROL ONLY, NO REQUIREMENT FORECAST

1AT

ELECTRONIC STABILITY CONTROL (ESC)

1D0

WITHOUT TRAILER HITCH

1E9

WITHOUT ACTIVATED CARBON CANISTER WITH SCR

1EX

SPECIAL IDENTIFICATION PLATE FOR EC FOR M1 PASSENGER VEHICLE

1G3

ALLOY SPARE WHEEL WITH ORIGINAL EQUIPMENT TIRES

1JA

REAR SHOCK ABSORPTION, BASIC VERSION 1

1KU

DISK BRAKES IN REAR

1N7

DYNAMIC STEERING

1NL

TRIMS FOR ALLOY WHEELS

1PE

WHEEL BOLTS WITH ANTI-THEFT PROTECTION (UNLOCKABLE)

1Q2

MASS DAMPER FOR STEERING WHEEL, 36 HZ

1S1

TOOL KIT AND JACK

1SA

WITHOUT ADDITIONAL FRONT UNDERBODY GUARD

1T2

WARNING TRIANGLE

1X1

FOUR WHEEL DRIVE

1XX

LEATHER-WRAPPED MULTIFUNCTION SPORTS STEERING WHEEL W/ TIPTRONIC

1Y0

WITHOUT DIFFERENTIAL LOCK

1Z0

INITIAL STANDARD FUEL FILLING

1ZA

DISK BRAKES IN FRONT

20A

WITHOUT ELECTRIC MOTOR (HYBRID)

2A0

WITHOUT DELIVERY EQUIPMENT

2H0

WITHOUT "DRIVE SELECT"

2JC

COMFORT BUMPERS

2WA

WITHOUT ADDITIONAL TIRES

31K

FRONT AND REAR LICENSE PLATE CARRIER (ECE)

3A0

CHILD SEAT ANCHOR FOR CHILD SEAT SYSTEM I-SIZE, 2X TOP TETHER

3D3

CENTER CONSOLE

3FB

SPOILER ROOF

3GA

WITHOUT CARGO AREA

3H0

WITHOUT BACKREST RELEASE FOR FRONT SEATS

3KB

UNSPLIT REAR SEAT BENCH, SPLIT FOLDING BACKREST, WITH CENTER ARMREST

3LJ

DOOR AND SIDE TRIM PANEL IN FOAM FILM, INSERT IN LEATHERETTE

3PW

MAN. HEIGHT ADJUSTM. F. FRONT SEATS AND SEAT CUSHION TILT AND DEPTH ADJUST. LEFTPLUS ELECTRIC BACKREST ADJUSTM. LEFT

3QT

3-POINT SEAT BELTS IN FRONT, WITH PRETENSIONER AND HEIGHT ADJUSTMENT

3T2

THREE REAR HEAD RESTRAINTS

3U1

FOLDING TRUNK COVER

3W4

ACOUSTICS PACKAGE "STANDARD"

3Y0

WITHOUT ROLL-UP SUNSHADE

3ZU

3-POINT SEAT BELTS, OUTER REAR WITH ECE LABEL

4A4

SEAT HEATER FOR FRONT AND REAR SEATS SEPARATELY CONTROLLED

4B4

PROTECTIVE SIDE MOLDING

4D0

WITHOUT SEAT VENTILATION/MESSAGE SEAT

4GW

HEAT INSULATING WINDSHIELD

4I3

CENTRAL LOCKING SYSTEM "KEYLESS ENTRY" WITHOUT SAFELOCK

4KF

SIDE WINDOWS IN HEAT-INSULATING GLASS, FROM B-PILLAR AND REAR WINDOW DARK TINTED

4L6

BREAKAWAY INTERIOR REARVIEW MIRROR, AUTO-DIMMING

4UN

DRIVER AND FRONT PASSENGER AIRBAG WITH FRONT PASSENGER AIRBAG DEACTIVATION, INCLUDING KNEE AIRBAG ON DRIVER SIDE

4V0

WITHOUT FRONT PASSENGER SEAT CONTROL

4X3

SIDE AIRBAG IN FRONT, WITH CURTAIN AIRBAG

4ZB

BRIGHT MOLDINGS

5C0

WITHOUT SPECIAL BODY MEASURES

5D1

CARRIER FREQUENCY 433.92 MHZ-434.42 MHZ

5I6

SENSOR-CONTROLLED LUGGAGE COMPARTMENT OPENER AND EASY CLOSE

5K7

TRANSPORT PROTECTION FILM (MINIMUM PROTECTION) WITH ADDITIONAL TRANSPORT PROTECTION MEASURES

5MD

DECORATIVE ALUMINUM INSERTS

5RQ

RIGHT EXTERIOR MIRROR, CONVEX

5SL

LEFT EXTERIOR MIRROR: ASPHERICAL

5XJ

SUN VISORS WITH MIRROR, ILLUMINATED, WITH AIRBAG LABEL ON SUN VISOR AND B-PILLAR

5ZF

FRONT HEAD RESTRAINTS

6A0

WITHOUT FIRE EXTINGUISHER

6E3

CENTER ARMREST IN FRONT

6K4

FORWARD COLLISION WARNING INCL. AUTONOMOUS EMERGENCY BRAKING, FOR ADAPTIVE CRUISE CONTROL "HIGH"

6NA

UNSPLIT MOLDED HEADLINER

6Q2

LEATHER GEARSHIFT KNOB/HANDLE

6SE

LUGGAGE COMPARTMENT FLOOR COVERING IN FLAT NEEDLE-PUNCHED NONWOVEN

6T1

INTERIOR LIGHT IN FOOTWELL

6XI

EXT. MIRR., AUTO-DIMMING, ELECTR. FOLD./ADJUSTABLE, HEATED, W/ FRONT PASSENGER EXTERIOR MIRROR LOWERING FUNCTION

77G

DATA STORAGE DEVICE FOR EU, INTEGRATED

79D

LANE CHANGE ASSIST, LANE KEEPING SYSTEM, TRAFFIC JAM ASSIST, AND EMERGENCY ASSIST

7AA

ELECTRONIC ENGINE IMMOBILIZER

7B6

12-VOLT SOCKET(S)

7E6

ELECTRIC AUXILIARY AIR HEATER

7G0

WITHOUT PREPARATION FOR VTS (VEHICLE TRACKING SYSTEM)

7K1

DIRECT TIRE PRESSURE MONITORING SYSTEM

7L6

START/STOP SYSTEM WITH REGENERATIVE BRAKING

7M1

SCUFF PLATES IN DOOR APERTURES WITH METAL CORES

7MV

EMISSION STANDARD EU6 ZD/E/F

7U0

STANDARD ENGINE STARTER

7UG

NAVIGATION SYSTEM - HIGH

7W0

WITHOUT EXTENDED SAFETY SYSTEM

7X5

PARK ASSIST

7ZS

VEHICLE CLASS DIFFERENTIATION -3H0-

8FA

WITHOUT SECOND BATTERY

8G3

ADVANCED HIGH-BEAM CONTROL

8GV

ALTERNATOR 180 A

8I2

POWER-ADJUSTABLE LUMBAR SUPPORT FOR FRONT LEFT SEAT BACKREST WITH MASSAGE FEATURE

8IU

LED HEADLAMPS WITH VARIABLE LIGHT DISTRIBUTION

8K3

SEPARATE DAYTIME RUNNING LIGHTS WITH AUTOMATIC HEADLAMP ACTIVATION AND COMING HOME FEATURE

8N6

WINDSHIELD WIPER INTERMITTENT CONTROL WITH LIGHT/RAIN SENSOR

8Q5

HEADLIGHT RANGE ADJUSTMENT, AUTOMATIC/ DYNAMIC, WITH CORNERING LIGHT (AFS 1)

8S7

2 READING LIGHTS IN FRONT

8SH

LED TAIL LAMP ASSEMBLY (SEQUENTIAL TURN SIGNAL)

8T8

ADAPTIVE CRUISE CONTROL (WITH "FOLLOW-TO-STOP") AND SPEED LIMITER

8TB

REAR FOG LAMP

8WM

CORNERING AND ALL-WEATHER LIGHT

8X1

HEADLAMP WASHER SYSTEM

8Y1

TWO-TONE HORN

8Z5

NOT HOT COUNTRY

8ZQ

ANTENNA FOR FM RECEPTION ONLY, DIVERSITY

9D0

WITHOUT PREPARATION FOR TWO-WAY RADIO INSTALLATION

9JC

SMOKER'S VERSION

9M0

WITHOUT AUXILIARY HEATER/FUEL-FIRED PARKING HEATER

9P9

SEAT BELT REMINDER, ELECTRIC CONTACT IN THE BUCKLE, ADVANCED SAFETY EQUIPMENT

9S8

MULTI-FUNCTION DISPLAY/ON-BOARD COMPUTER"FPK" (ACTIVE INFO DISPLAY)

9T1

HEATED WASHER NOZZLES IN FRONT

9TJ

ADDITIONAL LED WARNING LIGHT (DOOR AREA)IN FRONT

9VC

DIGITAL SOUND PACKAGE AND SUBWOOFER AND CENTRAL SPEAKER

9WX

MIRROR LINK AND WIRELESS RSE "APP"

9Z3

12-V OPERATING VOLTAGE AND 230-V INVERTER

9ZX

MOBILE PHONE INTERFACE

A62

CATEGORY 2

A8C

COMFORT EQUIPMENT

AV1

DRIVING ON THE RIGHT

B0A

COMPONENT PARTS SET WITHOUT COUNTRY-SPECIFIC BUILDING REGULATION

B43

TYPE APPROVAL COUNTRY ROMANIA

C04

OPERATING PERMIT, ALTERATION

DE5

4-CYL. TURBO DIESEL ENGINE 2.0 L/140 KW (4V) TDI COMMON RAIL BASE ENGINE IS TD1/TR1/T5S/T6F

E0A

NO SPECIAL EDITION

EA0

WITHOUT FOLLOW-ON WARRANTY

EF0

WITHOUT ECO FUNCTION

EL5

ONLINE SERVICE, WITH OCU, WITH HEAD UNIT CODING, WITHOUT ENGINE IMMOBILIZER INTERCONNECTION

EM1

DRIVER ALERT SYSTEM

ER1

REGIONAL CODE " ECE " FOR RADIO

ES0

WITHOUT VEHICLE INLET

EVO

WITHOUT CHARGING CABLE

F0A

NO SPECIAL PURPOSE VEHICLE, STANDARD EQUIPMENT

FC1

CUSTOMIZED INSTALLATION

FN8

VARIANT

G02

SHOCK ABSORPTION IN FRONT

G1D

7-SPEED AUTOMATIC TRANSMISSION FOR FOUR-WHEEL DRIVE

GM1

STANDARD ELECTRONIC ENGINE SOUND

GP0

VEHICLES WITHOUT SPECIAL UPGRADE MEASURES

I8J

RADIO HIGH (GEN2 GP)

J2D

BATTERY 380 A (68 AH)

K8C

COUPE

KA2

WITH REAR VIEW CAMERA SYSTEM (TYPE 2)

KH7

CLIMATRONIC (3-ZONE) WITH REAR AIR CONDITIONING CONTROL PANEL

KK3

REFRIGERANT R1234YF

KS0

WITHOUT HEAD-UP DISPLAY

L0L

LEFT-HAND DRIVE

L47

SUSPENSION RANGE 47 INSTALLATION CONTROL ONLY, NO REQUIREMENT FORECAST

N7K

SEAT TRIM COVERS IN ALCANTARA/LEATHER

NY0

STANDARD BATTERY/ALTERNATOR CAPACITY

NZ4

PRIVATE EMERGENCY CALL SYSTEM

Q48

TIRES 245/40 R19 94W (POLYMER COATING)

Q4H

SPORTS COMFORT SEATS IN FRONT

QA0

WITHOUT CHILD SEAT

QG1

SERVICE INTERVAL PROLONGATION

QH1

VOICE CONTROL

QI6

SERVICE INDICATOR 30 000 KM OR 2 YEARS (VARIABLE)

QJ3

CHROME PACKAGE (TYPE 2)

QK1

WITH MULTIFUNCTION CAMERA

QQ9

INTERIOR AMBIENT LIGHTING, TYPE 2

QR9

WITH DYNAMIC ROAD SIGN DISPLAY

QV0

WITHOUT TV RECEPTION/DIGITAL RADIO RECEPTION

TR1

4-CYLINDER DIESEL ENGINE 2.0 L UNIT 04L.A

U5A

INSTRUMENT CLUSTER, KM/H SPEEDOMETER

UG6

HILL START ASSIST

UH2

PARKING BRAKE

UP0

ANALOG CLOCK

UQ2

3 X USB TYPE A AND AUX-IN JACK

V0A

TIRES WITHOUT SPECIFICATION OF TIRE BRAND

V30

ALLOY WHEELS 8J X 19

VC0

WITHOUT REMOTE-CONTROLLED GARAGE DOOR OPENER

VF1

PEDAL CLUSTER

VL4

EXTENDED AND CRASH-ACTIVE AND PROACTIVE PEDESTRIAN PROTECTION

X4N

Cronologie

S-au găsit 7 înregistrări

Cronologia înregistrărilor pentru acest vehicul

Ultimele înregistrări

2018-01

 Țară necunoscută



A fost fabricat

Țara (sau statul) indică fie locația centrului de producție, uzina de asamblare sau adresa de înregistrare a producătorului. Data poate fi aproximativă.

2018-07

 România



A fost înmatriculat

Înregistrarea reprezintă un eveniment administrativ. Acest lucru ar putea fi legat de o schimbare de proprietar, documente etc

2019-02

 România



Daună detectată

Avem indicii potrivit cărora acest vehicul a fost recunoscut ca avariat în această țară (sau stat). Pentru detalii, vă rugăm să consultați secțiunea „Daune”.

2021-04

 România



Daună detectată

Avem indicii potrivit cărora acest vehicul a fost recunoscut ca avariat în această țară (sau stat). Pentru detalii, vă rugăm să consultați secțiunea „Daune”.

2021-07

 România



A fost verificat

A fost înregistrat un eveniment de inspecție tehnică (cunoscut și sub denumirea de ITP, test tehnic sau test de control al emisiilor). Pot fi incluse atât instanțe reușite, cât și eșuate.

2022-10

 România



Daună detectată

Avem indicii potrivit cărora acest vehicul a fost recunoscut ca avariat în această țară (sau stat). Pentru detalii, vă rugăm să consultați secțiunea „Daune”.

2023-06

 România



A fost verificat

A fost înregistrat un eveniment de inspecție tehnică (cunoscut și sub denumirea de ITP, test tehnic sau test de control al emisiilor). Pot fi incluse atât instanțe reușite, cât și eșuate.



+31

Surse de date

Am verificat 900+ de surse de date în **35 de țări**