

Volkswagen Golf

VIN: **WVWZZZAUZH554867**

Diesel

2017

Generat pe **2024-02-05 14:50**



Contor de parcurs



**Situație financiară și
juridică**



Daune



Lucruri de știut despre Volkswagen Golf 2017



Generat de
AI

Volkswagen Golf 2017 este un vehicul versatil care are la dispoziție diferite opțiuni de motorizare și tipuri de caroserie din care poți alege. Haideți să explorăm diferențele dintre ele.

Opțiuni de motorizare:

Volkswagen Golf 2017 are trei opțiuni diferite de motorizare: un motor turbo de 1,8 litri cu patru cilindri (170 de cai putere), un motor turbo de 2,0 litri cu patru cilindri (210 cai putere) și un motor turbodiesel de 2,0 litri cu patru cilindri (150 de cai putere). Motorul de 1,8 litri este cel mai eficient din punct de vedere al consumului de combustibil, având un consum estimat de 29 mpg în regim mixt. Motorul turbo de 2,0 litri este cel mai puternic și obține 27 mpg în regim mixt. Motorul turbodiesel este cel mai eficient din punct de vedere al consumului de combustibil, cu o valoare estimată de 36 mpg în regim mixt.

Tipuri de caroserie:

Volkswagen Golf 2017 are două tipuri de caroserie diferite: un hatchback și un wagon. Hatchback-ul vine în trei niveluri de echipare, S, SE și SEL. Wagonul vine doar în nivelul de echipare SE. Hatchback-ul are o zonă de încărcare mai mare decât wagonul, cu un spațiu de 22,8 picioare cubice față de 30,4 picioare cubice de spațiu pentru wagon. Cu toate acestea, wagonul are mai mult spațiu pentru pasageri, ceea ce îl face mai confortabil pentru călătoriile lungi.

Alte specificații:

Volkswagen Golf 2017 vine cu dotări standard, cum ar fi o cameră de luat vederi

spate, faruri HID, sistem de infotainment cu ecran tactil și integrare smartphone. Nivelul de echipare SEL vine cu caracteristici suplimentare, cum ar fi farurile adaptive, avertizarea de părăsire a benzii de rulare și frânarea automată de urgență.

În general, Volkswagen Golf 2017 este un vehicul excelent care oferă diferite opțiuni de motorizare și tipuri de caroserie pentru a se potrivi nevoilor diferiților șoferi. Fie că sunteți în căutarea unui vehicul cu consum redus de combustibil sau a unei mașini puternice, Volkswagen Golf 2017 are ceva pentru fiecare.

Această descriere a fost generată de AI și nu a fost supusă unei examinări umane pentru a detecta potențiale inexactități.



+31

Surse de date

Am verificat 900+ de surse de date în **35 de țări**

Furt

Vehiculul este în prezent marcat ca furat? A fost furat în trecut? A fost recuperat?



Nu am găsit nicio înregistrare că vehiculul a fost furat.



Verificarea bazei de date a poliției privind vehiculele furate finalizată în **10 țări**:



+4

Iată ce am verificat:



Căutat drept furat



Nu s-a găsit nici o înregistrare



Furat în trecut



Nu s-a găsit nici o înregistrare

Starea actuală
necunoscută



Furat în trecut



Nu s-a găsit nici o înregistrare

Vehiculul a fost recuperat

Baza de date aparținând poliției cu vehicule furate, **verificare finalizată în:**

 România

 Ucraina

 Lituania

 Statele Unite ale Americii

 Danemarca

 Slovacia

 Slovenia

 Finlanda

 Cehia


 Canada

Contor de parcurs

Există semne conform cărora kilometrajul a fost dat înapoi sau discrepanțe ale kilometrajului?

 Ultimul kilometraj cunoscut: 58.933 km

 11 înregistrări ale kilometrajului



Înregistrări ale contorului de parcurs

2018-01	15 km
2018-11	14.916 km
2019-01	16.052 km
2020-01	26.881 km
2021-01	36.493 km
2022-01	47.186 km

Înregistrări ale contorului de parcurs

2022-06	52.000 km
2022-07	51.673 km
2022-10	55.469 km
2022-12	57.838 km
2023-03	58.933 km

Situație financiară și juridică

Vehiculul a trecut inspecțiile tehnice? Are restricții asupra drepturilor de proprietate sau împrumuturi restante?



Nu s-au găsit restricții financiare pentru acest vehicul

Restricții financiare



Lease



Nu s-a găsit nici o înregistrare

Nu există date disponibile despre împrumuturi restante sau acorduri de finanțare



Leasing operațional



Nu s-a găsit nici o înregistrare

Nu există nici o înregistrare a vehiculului ca fiind în leasing operațional



Unitate de stocare



Nu s-a găsit nici o înregistrare

Nu există nicio înregistrare că vehiculul ar fi sub finanțare pentru stocuri

Legal



Inspecție tehnică



Nu s-a găsit nici o înregistrare

Nu au fost găsite înregistrări ale inspecției tehnice



Casat



Nu s-a găsit nici o înregistrare

Nu există nici o înregistrare că vehiculul a fost marcat drept casat



Exportat, Importat



Nu s-a găsit nici o înregistrare

Nu au fost găsite înregistrări de import sau export

Daune

Acest vehicul a fost avariat în trecut ? Care a fost valoarea daunelor?



Vehiculul a fost avariat de 2 ori!



Daunele minore nu vor afecta în mod normal siguranța vehiculului și nu vor cauza probleme structurale

Înregistrări de daune



Spate dreapta / Bară de protecție

2018-11

România

Daune

Costul estimativ al reparațiilor

**2.001 RON -
6.000 RON**

Cauza posibilă a daunelor

Necunoscut

Categoriile de daune

Părți exterioare ale caroseriei

2022-06

România

**Daune**

Costul estimativ al reparațiilor

**6.001 RON -
14.000 RON**

Cauza posibilă a daunelor

Necunoscut

Categoriile de daune

Părți exterioare ale caroseriei

Iluminat exterior

Valoarea de piață

Cu cât s-a vândut vehiculul în trecut? Care este în medie prețul vehiculelor din acest model și an?



Ultimul preț de vânzare cunoscut: 82.612 RON



Prețul mediu de pe piață pentru un astfel de vehicul: 64.246 RON



Atenție la problemele ascunse dacă vehiculul a fost la vânzare la un preț semnificativ mai mic decât prețul actual!

Valoarea de piață azi pentru Volkswagen Golf 2017

Valoarea de piață este determinată prin examinarea prețului unui anumit model de mașină (fabricat în același an) în țara în care a fost generat raportul. Analizăm datele din ultimele 6 luni.

Cel mai mic preț

56.206 RON


Prețul mediu

64.246 RON

Cel mai mare preț

75.065 RON

Istoricul prețurilor pieței



2023

Înregistrări de preț

2023-03 **82.612 RON**

Specificații și echipare

Ce specificații și echipamente sunt înregistrate pentru acest vehicul?



Verificați dacă specificațiile și echipamentul acestui vehicul se potrivesc cu datele furnizate de vânzător.

Identificare și specificații tehnice



Producător
Volkswagen



Model
Golf



Tip caroserie
Autovehicul multifuncțional



An de fabricație
2017



Capacitate cilindrică
1,6 l



Putere motor
85 kW (114 cp)



Tip combustibil
Diesel



Cutie de viteze
Automată



Tip transmisie
**Tracțiune față
(FWD)**



Culoare
Gri



Nr. uși
4



Amplasarea volanului
Volan pe stânga



Nr. cilindri
4



Cod motor
DDYA

Echipare

AV1

DRIVING ON THE RIGHT

A8C

COMFORT EQUIPMENT

B43

TYPE APPROVAL COUNTRY ROMANIA

C24

OPERATING PERMIT, ALTERATION

EF0

WITHOUT ECO FUNCTION

EM1

DRIVER ALERT SYSTEM

E0A

NO SPECIAL EDITION

FC0

WITHOUT CUSTOMIZED INSTALLATION

F0A

NO SPECIAL PURPOSE VEHICLE, STANDARD EQUIPMENT

A62

CATEGORY 2

B0A

COMPONENT PARTS SET WITHOUT COUNTRY-SPECIFIC BUILDING REGULATION

C2L

4 ALLOY WHEELS "TORONTO" 6.5J X 16, DIAMOND-TURNED SURFACE

DK8

4-CYL. TURBO DIES. ENG. 1.6 L/85 KW 4V TDI COMMON RAIL BASE ENGINE IS TJ1/TI7

EL0

WITHOUT ONLINE SERVICE

ER1

REGIONAL CODE " ECE " FOR RADIO

FB0

STANDARD PAINT COATING

FM0

BASIC EQUIPMENT VARIANT

GM1

STANDARD ELECTRONIC ENGINE SOUND

G05

SHOCK ABSORPTION IN FRONT

HH7

TIRES 205/55 R16

J0V

BATTERY 420 A (70 AH)

KK3

REFRIGERANT R1234YF

L0L

LEFT-HAND DRIVE

NY0

STANDARD BATTERY/ALTERNATOR CAPACITY

N3F

SEAT TRIM COVERS IN FABRIC "ZOOM"

PJ3

TORONTO 6.5J X 16 (5-DOUBLE-SPOKE STYLE)

TIRES 205/55 R16

PU2

LEATHER-WRAPPED MULTI-FUNCTION STEERING
WHEEL

QG1

ONGLIFE SERVICE REGIME

QI6

SERVICE INDICATOR 30 000 KM OR 2 YEARS
(VARIABLE)

QK0

WITHOUT MULTIFUNCTION CAMERA

QQ0

WITHOUT ADD. LIGHTS (INTERIOR LIGHTING)

QV0

WITHOUT TV RECEPTION/DIGITAL RADIO
RECEPTION

G1C

7-SPEED AUTOMATIC OR DSG NOTE: FAMILY EDF

I8E

RADIO "COMPOSITION MEDIA"

KA0

WITHOUT CAMERA SYSTEMS/ACCIDENT SENSORS

K8P

MPV

L07

SUSPENSION RANGE 07 INSTALLATION CONTROL
ONLY, NO REQUIREMENT FORECAST

NZ0

WITHOUT CALL FEATURE

PH2

AIR CARE CLIMATRONIC

PLA

LIGHTS&VISION PACKAGE

QE0

WITHOUT STORAGE COMPARTMENT
PACKAGE/BOX

QH0

WITHOUT VOICE CONTROL

QJ1

CHROME TRIM ON ROTARY LIGHT SWITCH,
CHROME ELEMENTS ON POWER MIRROR SWITCH

QN3

DRAWERS UNDER FRONT SEATS

QR8

WITHOUT DYNAMIC ROAD SIGN DISPLAY

Q2J

COMFORT SEATS, IN FRONT

TJ1

4-CYLINDER DIESEL ENGINE 1.6 L UNIT 04L.1

UI4

USB INTERFACE ALSO FOR IPOD/IPHONE,
INCLUDING AUX-IN JACK

U5A

INSTRUMENT CLUSTER WITH ELECTRONIC
SPEEDOMETER, ODOMETER AND TRIP
ODOMETER, TACHOMETER

VL0

STANDARD PEDESTRIAN PROTECTION MEASURES

WDA

PARK DISTANCE CONTROL

W67

ROMANIA: SPORTSVAN STYLE CL/HL FORCES
WDA,PLA,4KF,ZCB,9WT,UI4,PJ3,WW1

0AE

FRONT STABILIZER BAR

0BA

WITHOUT REAR STABILIZER BAR

0EG

INSTALLATION DIFFERENTIATION FOR
TRANSMISSION DQ200 -- VEHICLE COMPONENTS

--

0F5

FUEL SYSTEM FOR DIESEL ENGINE

0N1

STANDARD REAR AXLE

0TA

ELIMINATION OF CARPET MATS IN FRONT AND
REAR

0YE

UH2

ELECTROMECHANICAL PARKING BRAKE WITH
AUTO HOLD FUNCTION

UK5

MECHANICAL REAR SEAT RELEASE

VF0

STANDARD PEDAL CLUSTER

V1P

TIRE SUPPLIERS FOR EU COUNTRIES

WW1

WINTER PACKAGE

ZCE

RADIO "COMPOSITION MEDIA"

0A2

4 DOORS

0B3

WHEELBASE

0FA

STANDARD MANUFACTURING SEQUENCE

OK0

WITHOUT ALTERNATIVE DRIVE SYSTEM

OP7

REAR TAILPIPE

0XH

INFORMATION KIT IN ROMANIAN

0Y1

STANDARD CLIMATIC ZONES

WEIGHT RANGE 5 INSTALLATION CONTROL ONLY,
NO REQUIREMENT FORECAST

1AT

ELECTRONIC STABILITY CONTROL W/ DRIVER
STEERING RECOMMENDATION, ABS, ASR, EDL,
EDTC AND TRAILER STABILIZATION

1D0

WITHOUT TRAILER HITCH

1E0

WITHOUT ACTIVATED CARBON CANISTER

1JA

REAR SHOCK ABSORPTION, BASIC VERSION 1

1NL

TRIMS FOR ALLOY WHEELS

1PE

WHEEL LOCKS WITH EXTENDED THEFT
PROTECTION

1SA

WITHOUT ADDITIONAL FRONT UNDERBODY
GUARD

1T2

WARNING TRIANGLE

1W2

GLOVE COMPARTMENT WITH COOLING SYSTEM

1ZE

VENTILATED DISC BRAKES, FRONT

2A0

WITHOUT DELIVERY EQUIPMENT

2H0

1DG

NAMEPLATE SET "TDI"

1EX

SPECIAL IDENTIFICATION LABEL FOR EC FOR M1
PASSENGER VEHICLES

1G6

SPACE AND WEIGHT SAVING SPARE WHEEL 3.5J X
16

1KE

DISK BRAKES IN REAR

1N3

ELECTROMECHANICAL SPEED-SENSITIVE POWER
STEERING

1Q2

MASS DAMPER FOR STEERING WHEEL, 36 HZ

1S1

TOOL KIT AND JACK

1U9

FOLDING TABLES ON THE BACK OF THE FRONT
SEATS

1X0

FRONT-WHEEL DRIVE

1Z0

INITIAL STANDARD FUEL FILLING

2G5

INCORRECT FILLING PROTECTION (FOR
DIESELFUEL ONLY)

2JB

WITHOUT ADAPTIVE CHASSIS CONTROL

2KL

LABELS IN ROMANIAN AND ENGLISH

2WA

WITHOUT ADDITIONAL TIRES

3B4

ISOFIX ANCHORAGE POINTS (MOUNTING FIXTURE FOR 2 CHILD SEATS ON REAR BENCH SEAT)

3C7

3-POINT BELT FOR CENTER REAR SEAT

3FA

WITHOUT ROOF INSERT (STANDARD ROOF)

3H0

WITHOUT BACKREST RELEASE FOR FRONT SEATS

3M0

WITHOUT SPECIAL MEASURES

3S0

WITHOUT ROOF RAILS

3U1

LUGGAGE COMPARTMENT COVER, STOWABLE

31F

FRONT LICENSE PLATE CARRIER (LARGE)

4A3

HEATED FRONT SEATS

4H3

CHILD SAFETY LOCK

BODY-COLORED BUMPERS

2V5

PARTICLE FILTER WITH ACTIVATED CARBON INSERT

2ZH

LEATHER-WRAPPED MULTIFUNCTION STEERING WHEEL (3-SPOKE) W/ CONTROLS FOR MULTI-FUNCTION DISPLAY, RADIO, AND TELEPHONE

3CA

WITHOUT PARTITION

3D2

DECORATIVE INSERTS "DARK SILVER BRUSHED" FOR CENTER CONSOLE

3GN

HEIGHT-ADJUSTABLE AND REMOVABLE LUGGAGE COMPARTMENT FLOOR

3L3

FRONT SEATS WITH HEIGHT ADJUSTMENT

3QT

3-POINT SEAT BELTS FRONT WITH HEIGHT ADJUSTMENT AND BELT TENSIONER

3T2

3 HEAD RESTRAINTS IN REAR

3ZB

3-POINT SEAT BELTS, IN REAR

4AF

DOOR AND SIDE TRIM PANEL IN FOAM FILM AND WOVEN FABRIC

4GF

HEAT-INSULATING GLASS WINDSHIELD

4I2

CENTRAL LOCKING SYSTEM WITHOUT SAFELOCK, WITH RADIO REMOTE CONTROL AND 2 REMOTE

4KF

65% LIGHT-ABSORBING GLASS IN REAR SIDE WINDOWS AND REAR WINDOW

4P2

REAR FLOOR PANEL MODULE, TYPE 3

4UP

DRIVER AND FRONT PASSENGER AIRBAG WITH FRONT PASSENGER AIRBAG DEACTIVATION, INCLUDING KNEE AIRBAG ON DRIVER SIDE

4X3

CURTAIN AIRBAG SYSTEM FOR FRONT AND REARPASSENGERS INCLUDING SIDE AIRBAGS, FRONT

5C0

WITHOUT SPECIAL BODY MEASURES

5J0

WITHOUT REAR SPOILER

5K7

TRANSPORT PROTECTION FILM (MINIMUM PROTECTION) WITH ADDITIONAL TRANSPORT PROTECTION MEASURES

5RQ

RIGHT EXTERIOR MIRROR, CONVEX

5XJ

ILLUMINATED VANITY MIRRORS IN SUN VISORS

6A0

WITHOUT FIRE EXTINGUISHER

6FF

BODY-COLORED EXTERIOR MIRROR HOUSINGS AND DOOR HANDLES

CONTROL FOLDING KEYS

4L6

AUTO-DIMMING INTERIOR REARVIEW MIRROR

4R4

POWER WINDOWS, FRONT AND REAR

4U5

MAP POCKETS ON THE BACK OF EACH FRONT SEAT

4ZE

BLACK DECORATIVE TRIMS

5D1

CARRIER FREQUENCY 433.92 MHZ-434.42 MHZ

5KR

REAR BENCH SEAT ASYMM. SPLIT FOLDING, LONG. MOVABLE A. FOLDING;CENTER ARMREST,LOAD-THROUGH HATCH

5MB

DECORATIVE INSERTS "DARK SILVER BRUSHED"FOR DASHBOARD AND FOR DOOR TRIM PANELS

5SL

ASPHERICAL EXTERIOR MIRROR ON DRIVER SIDE

5ZF

SAFETY-OPTIMIZED FRONT HEAD RESTRAINTS

6E3

FRONT CENTER ARMREST, HEIGHT- AND LONGITUDINALLY ADJUSTABLE, WITH STORAGE COMPARTMENT, 2 VENTS, AND 12-V OUTLET

6KF

BLACK PAINTED RADIATOR GRILLE WITH CHROME MOLDINGS ON THE FINS

6K0

ELIMINATION OF FORWARD COLLISION
WARNINGFRONT ASSIST WITH AUTONOMOUS
EMERGENCY BRAKING

6PB

WITHOUT HAND BRAKE LEVER HANDLE

6T0

WITHOUT INTERIOR LIGHT IN FOOTWELL

7AA

ELECTRONIC IMMOBILIZER

7E6

ELECTRIC AUXILIARY AIR HEATER

7LX

VEHICLE CLASS DIFFERENTIATION -5GP-

7MM

EMISSION STANDARD EU6 PLUS

7N3

OVERHEAD STORAGE COMPARTMENT WITH LID

7QA

WITHOUT CD/DVD FOR NAVIGATION

7W1

PROACTIVE PASSENGER PROTECTION SYSTEM

7Y0

WITHOUT LANE CHANGE ASSIST

8G0

WITHOUT LIGHT CONTROL

8K3

6NA

HEADLINER PEARL GRAY (FOR INTERIOR TRIM XW
IN SHETLAND)

6Q2

GEARSHIFT KNOB IN LEATHER

6XQ

EXT. MIRRORS, POWER-ADJUST., FOLDING A.
HEATED, W/SURROUND LIGHTING, FRONT
PASS.EXTERIOR MIRROR LOWERING FUNC.+
MEMORY

7B2

12-V OUTLET IN LUGGAGE COMPARTMENT

7K1

TIRE PRESSURE MONITORING SYSTEM

7L6

START-STOP SYSTEM WITH GENERATIVE BRAKING

7M5

WITHOUT PROTECTIVE FILM FOR SCUFF PLATE

7P4

LUMBAR SUPPORTS IN FRONT

7Q0

WITHOUT NAVIGATION DEVICE

7X2

PARK DISTANCE CONTROL - ACOUSTIC
WARNINGSIGNAL FOR OBSTACLES IN THE FRONT
AND REAR

8GU

ALTERNATOR 140 A

8ID

HALOGEN HEADLAMPS AND TURN SIGNAL LAMPS
UNDER ONE CLEAR LENS

8M1

AUT. HEADLIGHT CONTROL W/ SEPARATE
DAYTIME RUNNING LIGHT, LEAVING HOME AND
MANUAL COMING HOME FEATURE

8N6

RAIN SENSOR

8RM

8 SPEAKERS

8S4

2 READING LIGHTS IN FRONT AND 2 IN REAR

8T6

CRUISE CONTROL SYSTEM INCL. SPEED LIMITER

8W1

WARNING LIGHT FOR WASHER FLUID LEVEL

8Y1

TWO-TONE HORN

8Z5

NOT HOT COUNTRY

9D0

WITHOUT PREPARATION FOR TWO-WAY RADIO
INSTALLATION

9M0

WITHOUT AUXILIARY HEATER/PARKING HEATER

9S5

MULTI-FUNCTION DISPLAY "PLUS"

9T1

AUTOMATICALLY-HEATED WASHER NOZZLES IN
FRONT

9WT

APP-CONNECT

9Z0

REAR WINDOW WIPER WITH INTERMITTENT
CONTROL

8Q1

HEADLIGHT RANGE CONTROL

8SA

REAR COMBINATION LAMP, STANDARD DESIGN

8TB

REAR FOG LAMP

8WH

FRONT FOG LAMPS AND CORNERING LIGHT

8X1

HEADLAMP WASHER SYSTEM

8ZQ

DIVERSITY ANTENNA FOR FM RECEPTION

9AK

AIR CARE CLIMATRONIC WITH 2 ZONE
AUTOMATIC CLIMATE CONTROL WITH ALLERGEN
FILTER

9JB

SMOKER'S PACKAGE: REMOVABLE ASHTRAY AND
CIGARETTE LIGHTER IN FRONT

9P9

WARNING SIGNAL AND WARNING LIGHT FOR
FRONT AND REAR SEAT BELTS NOT FASTENED

9TC

RETRO-REFLECTORS IN ALL DOORS

9U1

BRAKE PAD WEAR INDICATOR

9ZX

MOBILE PHONE INTERFACE

X4N

Cronologie

S-au găsit 5 înregistrări

Cronologia înregistrărilor pentru acest vehicul

Ultimele înregistrări

2017-02

 **Țară necunoscută**



A fost fabricat

Țara (sau statul) indică fie locația centrului de producție, uzina de asamblare sau adresa de înregistrare a producătorului. Data poate fi aproximativă.

2018-01

 **România**



A fost înmatriculat

Înregistrarea reprezintă un eveniment administrativ. Acest lucru ar putea fi legat de o schimbare de proprietar, documente etc

2018-11

 **România**



Daună detectată

Avem indicii potrivit cărora acest vehicul a fost recunoscut ca avariat în această țară (sau stat). Pentru detalii, vă rugăm să consultați secțiunea „Daune”.

2022-06

 **România**



Daună detectată

Avem indicii potrivit cărora acest vehicul a fost recunoscut ca avariat în această țară (sau stat). Pentru detalii, vă rugăm să consultați secțiunea „Daune”.

2023-03

 **România**



A fost la vânzare

Această înregistrare a fost creată deoarece vehiculul a fost listat pentru vânzare pe o anumită piață. Uneori, țara (sau statul) vânzătorului suprascrie locația reală a vehiculului.



Surse de date

Am verificat 900+ de surse de date în **35 de țări**