

Volkswagen

VIN: WWZZZAUZLW063811

Diesel

Generat pe 2024-11-06 12:57



Contor de parcurs

✓ Arată bine



Statut legal

✓ Arată bine



Daune

✓ Arată bine



+31

Surse de date

Am verificat 900+ de surse de date în **35 de țări**

Furt

Vehiculul este în prezent marcat ca furat? A fost furat în trecut? A fost recuperat?




Nu s-au găsit probleme

Nu am găsit nicio înregistrare că vehiculul a fost furat.



Notă

Verificarea bazei de date a poliției privind vehiculele furate finalizată în **8 țări**:  +2

Iată ce am verificat:



Căutat drept furat

✓ Nu s-a găsit nici o înregistrare



Furat în trecut

✓ Nu s-a găsit nici o înregistrare

Starea actuală necunoscută



Furat în trecut

✓ Nu s-a găsit nici o înregistrare

Vehiculul a fost recuperat

Baza de date aparținând poliției cu vehicule furate, **verificare finalizată în:**



România



Slovacia



Statele Unite ale Americii



Lituania



Suedia



Finlanda



Cehia



Slovenia


Contor de parcurs

Există semne conform cărora kilometrajul a fost dat înapoi sau discrepanțe ale kilometrajului?



Notă

Ultimul kilometraj cunoscut: 89.960 km



Disclaimer (declinarea responsabilității): acest grafic reprezintă o tendință estimată a kilometrajului. Deși se bazează pe înregistrări reale de kilometraj disponibile pentru acest vehicul, există lacune având în vedere că evoluția kilometrajului nu este înregistrată în mod constant. Pentru a lua în considerare aceste date lipsă, aplicăm un model patentat de analiză a datelor care prezice modul în care probabil s-a schimbat kilometrajul între evenimentele înregistrate. Acest lucru ajută la furnizarea unei imagini mai complete a utilizării vehiculului în timp.

Statut legal

A trecut vehiculul inspecțiile tehnice? A fost notat drept casat?

✓ **Nu s-au găsit probleme**

Nu s-au găsit înregistrări despre statutul legal al acestui vehicul

Legal



Inspecție tehnică periodică (ITP)

✓ Nu s-a găsit nici o înregistrare

Nu au fost găsite înregistrări ale inspecției tehnice



Casat

✓ Nu s-a găsit nici o înregistrare

Nu există nici o înregistrare că vehiculul a fost marcat drept casat

Daune

Acest vehicul a fost avariat în trecut ? Care a fost valoarea daunelor?

✓ **Nu s-au găsit probleme**

Înregistrări de daune



Ocazional pot apărea inexactități, mai ales la verificarea vehiculelor vechi. Atelierele clandestine de reparații pot deghiza ilegal defectele sau daunele vehiculelor, fără să declare nicăieri existența lor. Uneori până și plăcuțele VIN ale vehiculului pot fi înlocuite. Avem o varietate de metode de a detecta chiar și astfel de infracțiuni, dar este imposibil de oferit o garanție de 100%.

Dezastru natural

Locația vehiculului a fost înregistrată în zona unui dezastru natural?

Nu s-au găsit probleme

Locația vehiculului nu a fost înregistrată în zona unui dezastru natural

Specificații și echipare

Ce specificații și echipamente sunt înregistrate pentru acest vehicul?

Notă

Verificați dacă specificațiile și echipamentul acestui vehicul se potrivesc cu datele furnizate de vânzător.

Identificare și specificații tehnice



Producător

Volkswagen



Tip caroserie

Hatchback



An model

2020



Capacitate cilindrică

1,6 l



Putere motor

85 kW (114 cp)



Tip combustibil

Diesel



Cutie de viteze

Manuală



Tip transmisie

Tracțiune față (FWD)



Nr. uși

4



Amplasarea volanului

Volan pe stânga



Nr. cilindri

4

Echipare

Cum a fost primit de la producător

0A2

4 DOORS

0AD

FRONT STABILIZER

0B1

WHEELBASE

0BA

WITHOUT REAR STABILIZER

0EJ

INSTALLATION DIFFERENTIATION FOR TRANSMISSION MQ 250 -- VEHICLE COMPONENTS --

0F5

FUEL SYSTEM FOR DIESEL ENGINE

0FA

STANDARD MANUFACTURING SEQUENCE

0K0

WITHOUT ALTERNATIVE DRIVE SYSTEM

0N1

STANDARD REAR AXLE

0NB

NAMEPLATE SET IN BASIC STYLE

0P0

REAR EXHAUST TAILPIPE (STANDARD)

0TA

WITHOUT FLOOR MATS

0XH

INFORMATION KIT IN ROMANIAN

0Y1

STANDARD CLIMATIC ZONES

0YC

WEIGHT RANGE 3 INSTALLATION CONTROL ONLY, NO REQUIREMENT FORECAST

1AT

ELECTRONIC STABILITY CONTROL (ESC)

1D0

WITHOUT TRAILER HITCH

1E9

WITHOUT ACTIVATED CARBON CANISTER WITH SCR

1EX

SPECIAL IDENTIFICATION PLATE FOR EC FOR M1 PASSENGER VEHICLE

1G6

SPACE-SAVING SPARE WHEEL

1JA

REAR SHOCK ABSORPTION, BASIC VERSION 1

1KE

DISK BRAKES IN REAR

1MM

STEERING WHEEL

1N3

SPEED-RELATED VARIABLE STEERING ASSIST (SERVOTRONIC)

1NC

WHEEL TRIMS

1PA

STANDARD WHEEL BOLTS

1Q2

MASS DAMPER FOR STEERING WHEEL, 36 HZ

1S1

TOOL KIT AND JACK

1SA

WITHOUT ADDITIONAL FRONT UNDERBODY GUARD

1T2

WARNING TRIANGLE

1U8

WITHOUT FOLDING TABLE ON FRONT SEAT BACKREST

1W2

GLOVE COMPARTMENT COOLING SYSTEM

1X0

FRONT WHEEL DRIVE

1Y3

ELECTRONIC DIFFERENTIAL LOCK XDS DYNAMIC TRACTION CONTROL

1Z0

INITIAL STANDARD FUEL FILLING

1ZE

DISK BRAKES IN FRONT (GEOMET D)

20A

WITHOUT ELECTRIC MOTOR (HYBRID)

2A0

WITHOUT DELIVERY EQUIPMENT

2H0

WITHOUT "DRIVE SELECT"

2JB

STANDARD BUMPERS

2KL

LABELS/PLATES IN ROMANIAN AND ENGLISH

2V5

FRESH AIR INTAKE SYSTEM WITH COMBINATIONFILTER

2WA

WITHOUT ADDITIONAL TIRES

31F

FRONT LICENSE PLATE CARRIER (LARGE)

3B4

CHILD SEAT ANCHOR FOR CHILD SEAT SYSTEM ISOFIX

3C7

3-POINT SEAT BELT FOR CENTER REAR SEAT

3CA

WITHOUT PARTITION

3D1

CENTER CONSOLE

3FA

WITHOUT ROOF INSERT (STANDARD ROOF)

3H0

WITHOUT BACKREST RELEASE FOR FRONT SEATS

3L1

MANUAL HEIGHT ADJUSTMENT FOR LEFT FRONT SEAT

3NZ

UNSPLIT REAR SEAT BENCH UNSPLIT, SPLIT FOLDING BACKREST

3QT

3-POINT SEAT BELTS IN FRONT, WITH PRETENSIONER AND HEIGHT ADJUSTMENT

3S0

WITHOUT ROOF RAILS/ROOF LOAD RACK

3T2

THREE REAR HEAD RESTRAINTS

3ZB

3-POINT SEAT BELTS, OUTER REAR WITH ECE LABEL

4A0

WITHOUT SEAT HEATER

4AF

DOOR AND SIDE TRIM PANEL IN FOAM FILM AND WOVEN FABRIC

4GF

WINDSHIELD IN HEAT-INSULATING GLASS

4I2

CENTRAL LOCKING WITH RADIO REMOTE CONTROL, INTERIOR RELEASE MECHANISM WITHOUT SAFELOCK

4KC

SIDE AND REAR WINDOWS IN HEAT-INSULATING GLASS

4L2

DIMMING BREAKAWAY INTERIOR REARVIEW MIRROR

4P0

REAR FLOOR PANEL MODULE, TYPE 1

4R4

POWER WINDOWS WITH COMFORT OPERATION AND CIRCUIT BREAKER

4UP

DRIVER AND FRONT PASSENGER AIRBAG WITH KNEE AIRBAG AND FRONT PASSENGER AIRBAG DEACTIVATION

4X3

SIDE AIRBAG IN FRONT, WITH CURTAIN AIRBAG

51A

WITHOUT ADHESIVE FILM

5C0

WITHOUT SPECIAL BODY MEASURES

5D1

CARRIER FREQUENCY 433.92 MHZ-434.42 MHZ

5J0

WITHOUT REAR SPOILER

5K7

TRANSPORT PROTECTION FILM (MINIMUM PROTECTION) WITH ADDITIONAL TRANSPORT PROTECTION MEASURES

5MA

DECORATIVE INSERTS

5RQ

RIGHT EXTERIOR MIRROR, CONVEX

5SL

LEFT EXTERIOR MIRROR: ASPHERICAL

5XS

SUN VISORS WITH MIRROR, ON FRONT PASSENGER SIDE WITH AIRBAG LABEL ON SUN VISOR AND B-PILLAR

5ZF

FRONT HEAD RESTRAINTS

6A0

WITHOUT FIRE EXTINGUISHER

6E3

CENTER ARMREST IN FRONT

6FF

BODY-COLORED EXTERIOR MIRROR HOUSINGS AND VARIOUS ADD-ON PARTS

6K2

FORWARD COLLISION WARNING INCL. AUTONOMOUS EMERGENCY BRAKING, WITHOUT ADAPTIVE CRUISE CONTROL

6KC

RADIATOR GRILLE

6NA

UNSPLIT MOLDED HEADLINER

6Q1

PLASTIC GEARSHIFT KNOB/HANDLE

6T0

WITHOUT INTERIOR LIGHT IN FOOTWELL

6XR

EXTERIOR MIRRORS WITH MEMORY FEATURE, POWER-ADJUSTABLE, SEPARATELY HEATED

6Y8

SPEED LIMITER

7AA

ELECTRONIC ENGINE IMMOBILIZER

7B0

WITHOUT SOCKET

7E6

ELECTRIC AUXILIARY AIR HEATER

7K1

DIRECT TIRE PRESSURE MONITORING SYSTEM

7L6

START/STOP SYSTEM WITH REGENERATIVE BRAKING

7LG

VEHICLE CLASS DIFFERENTIATION -5G0-

7M5

WITHOUT PROTECTIVE FILM FOR SCUFF PLATE

7P0

WITHOUT LUMBAR SUPPORT IN SEAT BACKRESTS

7Q0

WITHOUT NAVIGATION DEVICE

7QA

WITHOUT CD/DVD FOR NAVIGATION

7W0

WITHOUT EXTENDED SAFETY SYSTEM

7X2

PARK DISTANCE CONTROL IN FRONT AND REAR

7Y0

WITHOUT LANE CHANGE ASSIST

8G0

WITHOUT LIGHT CONTROL

8GU

ALTERNATOR 140 A

8IE

HALOGEN TWIN HEADLAMPS AND SEPARATE LED DAYTIME RUNNING LIGHTS

8K1

SEPARATE DAYTIME RUNNING LIGHTS

8M1

REAR WINDOW WIPER AND WASHER SYSTEM WITH INTERMITTENT CONTROL

8N4

WINDSHIELD WIPER INTERMITTENT CONTROL WITH POTENTIOMETER (FOUR SPEEDS)

8Q1

HEADLIGHT RANGE ADJUSTMENT

8RE

4 SPEAKERS (PASSIVE)

8S1

READING LIGHT IN FRONT

8SQ

LED TAIL LAMP ASSEMBLY

8T0

WITHOUT CRUISE CONTROL SYSTEM (CCS)

8TB

REAR FOG LAMP

8W0

WITHOUT WASHER FLUID LEVEL INDICATOR

8WH

FRONT FOG LAMP AND CORNERING LAMP

8X0

WITHOUT HEADLAMP WASHER SYSTEM

8Y1

TWO-TONE HORN

8Z5

NOT HOT COUNTRY

8ZQ

ANTENNA FOR FM RECEPTION ONLY, DIVERSITY

9AK

CLIMATRONIC WITH IMPACT PRESSURE CONTROL, CFC-FREE

9D0

WITHOUT PREPARATION FOR TWO-WAY RADIO INSTALLATION

9F0

WITHOUT SOUND COMBINATION FOR ROTATING EMERGENCY LIGHT AND RADIO ANTENNA PREPARATION

9JB

SMOKER'S PACKAGE, ASHTRAY IN FRONT AND REAR

9M0

WITHOUT AUXILIARY HEATER/FUEL-FIRED PARKING HEATER

9P3

BELT CONTROL, ELECTRIC CONTACT IN BUCKLE

9S5

MULTI-FUNCTION DISPLAY/ON-BOARD COMPUTER"MEDIUM"

9T0

WITHOUT HEATED WASHER NOZZLES

9TC

ADDITIONAL REFLECTORS (DOOR AREA)

9U1

BRAKE PAD WEAR INDICATOR

9WC

WITHOUT "MULTIMEDIA" IN VEHICLE

9Z0

OPERATING VOLTAGE 12 V

9ZX

MOBILE PHONE INTERFACE

A60

CATEGORY 0

A8B

BASIC EQUIPMENT

AV1

DRIVING ON THE RIGHT

B0A

COMPONENT PARTS SET WITHOUT COUNTRY-SPECIFIC BUILDING REGULATION

B43

TYPE APPROVAL COUNTRY ROMANIA

C43

OPERATING PERMIT, ALTERATION

CX9

STEEL WHEELS 6J X 15 WEIGHT-OPTIMIZED

DK8

4-CYL. TURBO DIES. ENG. 1.6 L/85 KW 4V TDI COMMON RAIL BASE ENGINE IS TJ1/TI7

E0A

NO SPECIAL EDITION

EA0

WITHOUT FOLLOW-ON WARRANTY

EF0

WITHOUT ECO FUNCTION

ELO

WITHOUT ONLINE SERVICE

EM1

DRIVER ALERT SYSTEM

ER1

REGIONAL CODE " ECE " FOR RADIO

ES0

WITHOUT VEHICLE INLET

EVO

WITHOUT CHARGING CABLE

F0A

NO SPECIAL PURPOSE VEHICLE, STANDARD EQUIPMENT

FB0

STANDARD PAINT COATING

FC0

WITHOUT CUSTOMIZED INSTALLATION

FM0

BASIC EQUIPMENT VARIANT

G05

SHOCK ABSORPTION IN FRONT

G0C

5-SPEED MANUAL TRANSMISSION

GM1

STANDARD ELECTRONIC ENGINE SOUND

GP1

VEHICLES WITH SPECIAL UPGRADE MEASURES

H7F

TIRES 195/65 R15 91H

I8C

ENTRY RADIO (GEN2)

IG0

STANDARD CURB WEIGHT RANGE

J0V

BATTERY 420 A (70 AH)

K8G

HATCHBACK

KA0

WITHOUT CAMERA SYSTEMS/ACCIDENT SENSORS

KK3

REFRIGERANT R1234YF

KL0

STANDARD LICENSE PLATE LIGHTING

L06

SUSPENSION RANGE 06 INSTALLATION CONTROL ONLY, NO REQUIREMENT FORECAST

LOL

LEFT-HAND DRIVE

N4C

SEAT TRIM COVERS IN FABRIC

NY0

STANDARD BATTERY/ALTERNATOR CAPACITY

NZ0

WITHOUT CALL FEATURE

Q1A

STANDARD SEATS IN FRONT

QG1

SERVICE INTERVAL PROLONGATION

QH0

WITHOUT VOICE CONTROL

QI6

SERVICE INDICATOR 30 000 KM OR 2 YEARS (VARIABLE)

QJ0

WITHOUT ALUMINUM/CHROME PACKAGE

QK0

WITHOUT MULTIFUNCTION CAMERA

QN0

WITHOUT DRAWERS UNDER FRONT SEATS

QQ0

WITHOUT ADD. LIGHTS (INTERIOR LIGHTING)

QR8

WITHOUT DYNAMIC ROAD SIGN DISPLAY

QV0

WITHOUT TV RECEPTION/DIGITAL RADIO RECEPTION

TJ1

4-CYLINDER DIESEL ENGINE 1.6 L UNIT 04L.1

U5A

INSTRUMENT CLUSTER, KM/H SPEEDOMETER

UH2

PARKING BRAKE

UI5

ELECTRIC INTERFACE FOR EXTERNAL USE, USB (IPOD-CAPABLE)

UK1

STANDARD REAR SEAT RELEASE

V1P

TIRE SUPPLIERS FOR EU COUNTRIES

VF0

STANDARD PEDAL CLUSTER

VL3

EXTENDED AND PROACTIVE PEDESTRIAN PROTECTION

X4N

EQUIPMENT OPTIONS SUBSET FOR ROMANIA



Surse de date

Am verificat 900+ de surse de date în **35 de țări**