

# Volkswagen Golf

VIN: WWZZZCDZMW001209

Diesel

2020

Generat pe 2024-12-03 08:39



## Odometru

✓ Arată bine



## Statut legal

✓ Arată bine



## Daune

⚠ Necesită atenție



+31

## Surse de date

Am verificat 900+ de surse de date în 35 de țări

## Furt

Vehiculul este în prezent marcat ca furat? A fost furat în trecut? A fost recuperat?



### Nu s-au găsit probleme

Nu am găsit nicio înregistrare că vehiculul a fost furat.



### Notă

Verificarea bazei de date a poliției privind vehiculele furate finalizată în 10 țări: +4

## Iată ce am verificat:



### Căutat drept furat

✓ Nu s-a găsit nici o înregistrare



### Furat în trecut

✓ Nu s-a găsit nici o înregistrare

Starea actuală necunoscută



### Furat în trecut

✓ Nu s-a găsit nici o înregistrare

Vehiculul a fost recuperat

Baza de date aparținând poliției cu vehicule furate, **verificare finalizată în:**

România

Danemarca

Lituania



 Slovacia

 Statele Unite ale Americii

 Italia

 Finlanda

 Slovenia

 Cehia


 Suedia

## Odometru

Există semne conform cărora kilometrajul a fost dat înapoi sau discrepanțe ale kilometrajului?

### Notă

Ultimul kilometraj cunoscut: 8.000 km




**Disclaimer (declinarea responsabilității):** acest grafic reprezintă o tendință estimată a kilometrajului. Deși se bazează pe înregistrări reale de kilometraj disponibile pentru acest vehicul, există lacune având în vedere că evoluția kilometrajului nu este înregistrată în mod constant. Pentru a lua în considerare aceste date lipsă, aplicăm un model patentat de analiză a datelor care prezice modul în care probabil s-a schimbat kilometrajul între evenimentele înregistrate. Acest lucru ajută la furnizarea unei imagini mai complete a utilizării vehiculului în timp.

## Statut legal

A trecut vehiculul inspecțiile tehnice? A fost notat drept casat?

**i Notă**

Inspecția tehnică a fost transmisă pe 2023-09 în  **România**

## Legal



### Inspecție tehnică periodică (ITP)

**A trecut** 2023-09

 **România**

A trecut cu succes inspecția tehnică  
Valabil până la 2025-01



### Casat

✓ Nu s-a găsit nici o înregistrare

Nu există nici o înregistrare că vehiculul a fost marcat drept casat

## Daune

Acest vehicul a fost avariat în trecut ? Care a fost valoarea daunelor?

**! Ai grijă!**

Vehiculul a fost avariat de 2 ori!

**i Notă**

Daunele minore nu vor afecta în mod normal siguranța vehiculului și nu vor cauza probleme structurale

## Înregistrări de daune



Daune frontale:

**Față / Bară de protecție**

**Față dreapta / Bară de protecție**

2024-03

România

**Daune**

Costul estimativ al reparațiilor

**2.001 RON – 6.000 RON**

Cauza posibilă a daunelor

**Necunoscut**

Categoriile de daune

Părți exterioare ale caroseriei



Daune pe partea stângă

**Stânga / Portieră față**

2024-09

România

**Daune**

Costul estimativ al reparațiilor

**0 RON – 2.000 RON**

Cauza posibilă a daunelor

**Necunoscut**

**Disclaimer (declinarea responsabilității):** Majoritatea înregistrărilor de daune sunt legate de accidente, dar uneori nu este acesta cazul. Unele înregistrări provin din alte surse cum ar fi serviciile specializate pe lucrări de caroserie, cereri de daune, licitații sau inspecții ale vehiculelor. Aceste înregistrări arată că starea vehiculului a fost evaluată, chiar dacă nu a fost din cauza unui accident.

## Dezastre naturale

Locația vehiculului a fost înregistrată în zona unui dezastru natural?



**Nu s-au găsit probleme**

Locația vehiculului nu a fost înregistrată în zona unui dezastru natural

# Valoarea de piață

Cu cât s-a vândut vehiculul în trecut? Care este în medie prețul vehiculelor din acest model și an?

## i Notă

- Prețul mediu de pe piață pentru un astfel de vehicul: 88.834 RON
- Atenție la problemele ascunse dacă vehiculul a fost la vânzare la un preț semnificativ mai mic decât prețul actual!

## Valoarea de piață azi pentru Volkswagen Golf 2020

Valoarea de piață este determinată prin examinarea prețului unui anumit model de mașină (fabricat în același an) în țara în care a fost generat raportul. Analizăm datele din ultimele 6 luni.

Cel mai mic preț

79.796 RON

Prețul mediu

88.834 RON

Cel mai mare preț

97.475 RON

## Emisii

Câte emisii de CO2 produc vehiculele din acest model/an?

## i Notă

Emisii CO2: A (107 g/km)

## Emisii CO<sub>2</sub>

Emisiile CO2 ale  
vehiculului tău

107 g/km Clasă **A**

Până la 120

120 - 140

140 - 155

155 - 165

165 - 190

190 - 225

225 și peste

Emisii CO<sub>2</sub> g/km

## Specificații și echipare

Ce specificații și echipamente sunt înregistrate pentru acest vehicul?

 **Notă**

Verificați dacă specificațiile și echipamentul acestui vehicul se potrivesc cu datele furnizate de vânzător.

## Identificare și specificații tehnice



Producător

**Volkswagen**



Model

**Golf**



Tip caroserie

**Hatchback**



An de fabricație

**2020**



An model

**2021**



Capacitate cilindrică

**2 l**



Putere motor

**85 kW (114 cp)**



Tip combustibil

**Diesel**



Cutie de viteze

**Manuală**



Tip transmisie

**Tracțiune față (FWD)**



Culoare

**Gri**



Amplasarea volanului

**Volan pe stânga**



Nr. cilindri

**4**



Nr. locuri

**5**



Cod motor

**DSUD**

# Echipare

Cum a fost primit de la producător

---

0AD

FRONT STABILIZER

0B1

WHEELBASE

0BA

WITHOUT REAR STABILIZER

0ED

INSTALLATION DIFFERENTIATION FOR TRANSMISSION MQ 380 -- VEHICLE COMPONENTS --

0F5

FUEL SYSTEM FOR DIESEL ENGINE

0FA

STANDARD MANUFACTURING SEQUENCE

0K0

WITHOUT ALTERNATIVE DRIVE SYSTEM

0KA

WITHOUT DECALS AND EMBLEMS

0N1

STANDARD REAR AXLE

0NB

NAMEPLATE SET IN BASIC STYLE

0P0

REAR EXHAUST TAILPIPE (STANDARD)

0SA

WITHOUT SPECIAL LABELS/PLATES

0TA

WITHOUT FLOOR MATS

0XH

INFORMATION KIT IN ROMANIAN

0Y1

STANDARD CLIMATIC ZONES

0YE

WEIGHT RANGE 5 INSTALLATION CONTROL ONLY, NO REQUIREMENT FORECAST

1AQ

BRS FOR VEHICLES WITHOUT ELECTRIC DRIVE (ESC AND ELECTRIC BRAKE BOOSTER)

1D0

WITHOUT TRAILER HITCH

1E9

WITHOUT ACTIVATED CARBON CANISTER WITH SCR

1EX

SPECIAL IDENTIFICATION PLATE FOR EC FOR M1 PASSENGER VEHICLE

1G9

SPACE-SAVING SPARE WHEEL FOR TEMPORARY USE, RADIAL TIRE (5-HOLE)

1J2

SOUND DEADENING PACKAGE AND ADDITIONAL ENCLOSURES FOR SOME UNITS

1JA

REAR SHOCK ABSORPTION, BASIC VERSION 1

1KE

DISK BRAKES IN REAR

1N3

SPEED-RELATED VARIABLE STEERING ASSIST (SERVOTRONIC)

1PF

STANDARD WHEEL BOLTS

1S1

TOOL KIT AND JACK

1SA

WITHOUT ADDITIONAL FRONT UNDERBODY GUARD



1T2

WARNING TRIANGLE

1X0

FRONT WHEEL DRIVE

1Y3

ELECTRONIC DIFFERENTIAL LOCK XDS DYNAMIC TRACTION CONTROL

1Z0

INITIAL STANDARD FUEL FILLING

1ZE

DISK BRAKES IN FRONT (GEOMET D)

20A

WITHOUT ELECTRIC MOTOR ( HYBRID )

2CM

VEHICLE CLASS DIFFERENTIATION 5H0

2F0

WITHOUT LOCKING AND STARTING SYSTEMS

2FD

WOODEN MULTIFUNCTION STEERING WHEEL FOR TIPTRONIC

2H0

WITHOUT "DRIVE SELECT"

2JB

STANDARD BUMPERS

2WA

WITHOUT ADDITIONAL TIRES

31K

FRONT AND REAR LICENSE PLATE CARRIER (ECE)

3C7

3-POINT SEAT BELT FOR CENTER REAR SEAT

3CA

WITHOUT PARTITION

3D1

CENTER CONSOLE

3FA

WITHOUT ROOF INSERT (STANDARD ROOF)

3H0

WITHOUT BACKREST RELEASE FOR FRONT SEATS

3L3

MANUAL HEIGHT ADJUSTMENT FOR FRONT SEATS

3NU

REAR SEAT BENCH UNSPLIT, BACKREST SPLIT FOLDING WITH CENTER ARMREST

3QT

3-POINT SEAT BELTS IN FRONT, WITH PRETENSIONER AND HEIGHT ADJUSTMENT

3S0

WITHOUT ROOF RAILS/ROOF LOAD RACK

3T2

THREE REAR HEAD RESTRAINTS

3ZU

3-POINT SEAT BELTS, OUTER REAR WITH ECE LABEL

4A0

WITHOUT SEAT HEATER

4AF

DOOR AND SIDE TRIM PANEL IN FOAM FILM AND WOVEN FABRIC

4D0

WITHOUT SEAT VENTILATION/MASSAGE SEAT

4E0

TAILGATE/TRUNK LID UNLOCKING FROM OUTSIDE

4G1

STORAGE COMPARTMENT, DIRECTION OF TRAVEL LEFT, 1ST ROW OF SEATS

4GF

WINDSHIELD IN HEAT-INSULATING GLASS

4I7

CENTRAL LOCKING SYSTEM "KEYLESS-GO" WITHOUT SAFELOCK

4KC

SIDE AND REAR WINDOWS IN HEAT-INSULATINGGLASS

4L2

DIMMING BREAKAWAY INTERIOR REARVIEW MIRROR

4P0

REAR FLOOR PANEL MODULE, TYPE 1

4UF

DRIVER AND FRONT PASSENGER AIRBAG WITH FRONT PASSENGER AIRBAG DEACTIVATION

4X3

SIDE AIRBAG IN FRONT, WITH CURTAIN AIRBAG

4ZQ

WITHOUT ADDITIONAL MOLDINGS

5C0

WITHOUT SPECIAL BODY MEASURES

5F1

1 ARMREST FOR LEFT FRONT SEAT AND 2 ARMRESTS FOR RIGHT FRONT SEAT

5J4

BODY-COLORED REAR SPOILER

5JA

WITHOUT AMBULANCE SEAT FOR MEDICAL STAFF

5K7

TRANSPORT PROTECTION FILM (MINIMUM PROTECTION) WITH ADDITIONAL TRANSPORT PROTECTION MEASURES

5MB

DECORATIVE INSERTS

5XJ

SUN VISORS WITH MIRROR, ILLUMINATED, WITH AIRBAG LABEL ON SUN VISOR AND B-PILLAR

5ZF

## FRONT HEAD RESTRAINTS

6A0

WITHOUT FIRE EXTINGUISHER

6E3

CENTER ARMREST IN FRONT

6FF

BODY-COLORED EXTERIOR MIRROR HOUSINGS AND VARIOUS ADD-ON PARTS

6I1

LANE KEEPING SYSTEM

6NA

UNSPLIT MOLDED HEADLINER

6Q2

LEATHER GEARSHIFT KNOB/HANDLE

6T0

WITHOUT INTERIOR LIGHT IN FOOTWELL

6XR

EXTERIOR MIRRORS WITH MEMORY FEATURE, POWER-ADJUSTABLE, SEPARATELY HEATED

6Y8

SPEED LIMITER

76A

WITHOUT MODE 3 CHARGING CABLE

7AA

ELECTRONIC ENGINE IMMOBILIZER

7B2

12-VOLT SOCKET IN LUGGAGE BOOT

7E6

ELECTRIC AUXILIARY AIR HEATER

7K1

DIRECT TIRE PRESSURE MONITORING SYSTEM

7L6

START/STOP SYSTEM WITH REGENERATIVE BRAKING

7P4

MANUALLY ADJUSTABLE LUMBAR SUPPORT IN FRONT SEATS

7Q0

WITHOUT NAVIGATION DEVICE

7U0

STANDARD ENGINE STARTER

7W0

WITHOUT EXTENDED SAFETY SYSTEM

7X2

PARK DISTANCE CONTROL IN FRONT AND REAR

7Y0

WITHOUT LANE CHANGE ASSIST

8FA

WITHOUT SECOND BATTERY

8G0

WITHOUT LIGHT CONTROL

8GU

ALTERNATOR 140 A

8J3

HAND BRAKE/LOW BRAKE FLUID LEVEL WARNINGLIGHT AND INSCRIPTION

8N8

WINDSHIELD WIPER INTERMITTENT CONTROL WITH PHOTOSENSOR

8Q3

AUTOMATIC HEADLIGHT RANGE ADJUSTMENT DYNAMIC (SELF-ADJUSTING WHILE DRIVING)

8RT

SPEAKERS IN FRONT AND REAR

8S6

2 READING LIGHTS IN FRONT

8T8

ADAPTIVE CRUISE CONTROL (WITH "FOLLOW-TO-STOP") AND SPEED LIMITER

8WJ

"HIGHWAY LIGHT"

8X6

WITHOUT HEADLAMP WASHER SYSTEM, WITHOUT WASHER FLUID LEVEL INDICATOR

8Y1

TWO-TONE HORN

8Z5

NOT HOT COUNTRY

8ZQ

ANTENNA FOR FM RECEPTION ONLY, DIVERSITY

9D0

WITHOUT PREPARATION FOR TWO-WAY RADIO INSTALLATION

9F0

WITHOUT SOUND COMBINATION FOR ROTATING EMERGENCY LIGHT AND RADIO ANTENNA PREPARATION

9I5

SEPARATE DAYTIME RUNNING LIGHTS WITH AUTOMATIC HEADLAMP ACTIVATION AND COMING HOME FEATURE (AUTOMATIC)

9JB

SMOKER'S PACKAGE, ASHTRAY IN FRONT AND REAR

9M0

WITHOUT AUXILIARY HEATER/FUEL-FIRED PARKING HEATER

9P4

SEAT BELT REMINDER, ELECTRIC CONTACT IN FRONT AND REAR, VISUAL AND ACOUSTICAL

9T0

WITHOUT HEATED WASHER NOZZLES

9WT

MIRRORLINK

9Z0

OPERATING VOLTAGE 12 V

9ZV

COMFORT TELEPHONY, WITHOUT ANTENNA CONNECTION

A8C

COMFORT EQUIPMENT

AV1

DRIVING ON THE RIGHT

B0A

COMPONENT PARTS SET WITHOUT COUNTRY-SPECIFIC BUILDING REGULATION

B43

TYPE APPROVAL COUNTRY ROMANIA

BD

ESC SPECIAL VEHICLE 11

C06

OPERATING PERMIT, ALTERATION

C2F

ALLOY WHEELS 7J X 16

DE4

4-CYL. TURBO DIES. ENG. 2.0 L/85 KW (4V)TDI COMMON RAIL BASE ENGINE IS TL4/TR1

E0A

NO SPECIAL EDITION

EA0

WITHOUT FOLLOW-ON WARRANTY

EL2

ONLINE SERVICE, WITH OCU, WITHOUT HEAD UNIT CODING, WITHOUT ENGINE IMMOBILIZER INTERCONNECTION

EM1

DRIVER ALERT SYSTEM

ER1

REGIONAL CODE " ECE " FOR RADIO

EVO

WITHOUT CHARGING CABLE

F0A

NO SPECIAL PURPOSE VEHICLE, STANDARD EQUIPMENT

FB0

STANDARD PAINT COATING

FC0

WITHOUT CUSTOMIZED INSTALLATION

FM0

BASIC EQUIPMENT VARIANT

G01

SHOCK ABSORPTION IN FRONT

G0K

6-SPEED MANUAL TRANSMISSION

GM1

STANDARD ELECTRONIC ENGINE SOUND

GP0

VEHICLES WITHOUT SPECIAL UPGRADE MEASURES

GW2

CAR2X "HIGH" VARIANT

HH7

TIRES 205/55 R16 91V

J0V

BATTERY 420 A (70 AH)

K8G

HATCHBACK

KA0

WITHOUT CAMERA SYSTEMS/ACCIDENT SENSORS

KC0

CLIMATRONIC (1-ZONE)



KK3

REFRIGERANT R1234YF

KS0

WITHOUT HEAD-UP DISPLAY

L06

SUSPENSION RANGE 06 INSTALLATION CONTROL ONLY, NO REQUIREMENT FORECAST

L0L

LEFT-HAND DRIVE

N3B

SEAT TRIM COVERS IN FABRIC

NY0

STANDARD BATTERY/ALTERNATOR CAPACITY

NZ4

PRIVATE EMERGENCY CALL SYSTEM

Q2J

COMFORT SEATS IN FRONT

QG1

SERVICE INTERVAL PROLONGATION

QH0

WITHOUT VOICE CONTROL

QI6

SERVICE INDICATOR 30 000 KM OR 2 YEARS ( VARIABLE )

QJ1

CHROME PACKAGE

QK1

WITH MULTIFUNCTION CAMERA

QQ8

INTERIOR AMBIENT LIGHTING, TYPE 1

QR8

WITHOUT DYNAMIC ROAD SIGN DISPLAY

QV0

WITHOUT TV RECEPTION/DIGITAL RADIO RECEPTION

S0T

PRE-PRODUCTION SERIES/SOP NEXT MY

SB0

PLANT EMPLOYEE LEASING - HN

T6M

4-CYLINDER DIESEL ENGINE 2.0 L UNIT 05L.C

U5A

INSTRUMENT CLUSTER, KM/H SPEEDOMETER

U9C

2 X USB TYPE C

UG0

WITHOUT HILL START ASSIST/HILL DESCENT CONTROL/COMFORT DRIVING ASSIST

UH2

PARKING BRAKE

UK1

STANDARD REAR SEAT RELEASE

V1P

TIRE SUPPLIERS FOR EU COUNTRIES

VF0

STANDARD PEDAL CLUSTER

VL1

EXTENDED PEDESTRIAN PROTECTION MEASURES

X4N

EQUIPMENT OPTIONS SUBSET FOR ROMANIA

## Cronologie

S-au găsit 5 înregistrări

## Ultimele înregistrări

2020-01

 Țară necunoscută



### A fost fabricat

Țara (sau statul) indică fie locația centrului de producție, uzina de asamblare sau adresa de înregistrare a producătorului. Data poate fi aproximativă.

2020-09

 România



### A fost înmatriculat

Înregistrarea reprezintă un eveniment administrativ. Acest lucru ar putea fi legat de o schimbare de proprietar, documente etc

2023-09

 România



### A fost verificat

A fost înregistrat un eveniment de inspecție tehnică (cunoscut și sub denumirea de ITP, test tehnic sau test de control al emisiilor). Pot fi incluse atât instanțe reușite, cât și eșuate.

2024-03

 România



### Daună detectată

Avem indicii potrivit cărora acest vehicul a fost recunoscut ca avariat în această țară (sau stat). Pentru detalii, vă rugăm să consultați secțiunea „Daune”.

2024-09

 România



### Daună detectată

Avem indicii potrivit cărora acest vehicul a fost recunoscut ca avariat în această țară (sau stat). Pentru detalii, vă rugăm să consultați secțiunea „Daune”.



### Surse de date

Am verificat 900+ de surse de date în **35 de țări**