

Volkswagen

VIN: WWZZZCDZMW500853

Diesel

Generat pe 2024-12-18 12:26



Odometru

✓ Arată bine



Statut legal

✓ Arată bine



Daune

⚠ Necesită atenție



+31

Surse de date

Am verificat 900+ de surse de date în 35 de țări

Furt

Vehiculul este în prezent marcat ca furat? A fost furat în trecut? A fost recuperat?



Nu s-au găsit probleme

Nu am găsit nicio înregistrare că vehiculul a fost furat.



Notă

Verificarea bazei de date a poliției privind vehiculele furate finalizată în 8 țări: +2

Iată ce am verificat:



Căutat drept furat

✓ Nu s-a găsit nici o înregistrare



Furat în trecut

✓ Nu s-a găsit nici o înregistrare

Starea actuală necunoscută



Furat în trecut

✓ Nu s-a găsit nici o înregistrare

Vehiculul a fost recuperat

Baza de date aparținând poliției cu vehicule furate, **verificare finalizată în:**

România

Italia

Lituania




Odometru

Există semne conform cărora kilometrajul a fost dat înapoi sau discrepanțe ale kilometrajului?

Notă

Ultimul kilometraj cunoscut: 133.463 km



Disclaimer (declinarea responsabilității): acest grafic reprezintă o tendință estimată a kilometrajului. Deși se bazează pe înregistrări reale de kilometraj disponibile pentru acest vehicul, există lacune având în vedere că evoluția kilometrajului nu este înregistrată în mod constant. Pentru a lua în considerare aceste date lipsă, aplicăm un model patentat de analiză a datelor care prezice modul în care probabil s-a schimbat kilometrajul între evenimentele înregistrate. Acest lucru ajută la furnizarea unei imagini mai complete a utilizării vehiculului în timp.

Statut legal

A trecut vehiculul inspecțiile tehnice? A fost notat drept casat?

✓ Nu s-au găsit probleme

Nu s-au găsit înregistrări despre statutul legal al acestui vehicul

Legal



Inspecție tehnică periodică (ITP)

✓ Nu s-a găsit nici o înregistrare

Nu au fost găsite înregistrări ale inspecției tehnice



Casat

✓ Nu s-a găsit nici o înregistrare

Nu există nici o înregistrare că vehiculul a fost marcat drept casat

Daune

Acest vehicul a fost avariat în trecut ? Care a fost valoarea daunelor?

⚠ Ai grijă!

Vehiculul a fost avariat de 2 ori!

i Notă

Daunele minore nu vor afecta în mod normal siguranța vehiculului și nu vor cauza probleme structurale

Înregistrări de daune



2021-04

Germania

Daune

Costul estimativ al reparațiilor

6.001 RON – 14.000 RON

Cauza posibilă a daunelor

Necunoscut



2022-08

Germania

Daune

Costul estimativ al reparațiilor

2.001 RON – 6.000 RON

Cauza posibilă a daunelor

Necunoscut

Disclaimer (declinarea responsabilității): Majoritatea înregistrărilor de daune sunt legate de accidente, dar uneori nu este acesta cazul. Unele înregistrări provin din alte surse cum ar fi serviceurile specializate pe lucrări de caroserie, cereri de daune, licitații sau inspecții ale vehiculelor. Aceste înregistrări arată că starea vehiculului a fost evaluată, chiar dacă nu a fost din cauza unui accident.

Dezastre naturale

Locația vehiculului a fost înregistrată în zona unui dezastru natural?

✓ Nu s-au găsit probleme

Locația vehiculului nu a fost înregistrată în zona unui dezastru natural

Specificații și echipare

Ce specificații și echipamente sunt înregistrate pentru acest vehicul?

i Notă

Verificați dacă specificațiile și echipamentul acestui vehicul se potrivesc cu datele furnizate de vânzător.

Identificare și specificații tehnice



Producător

Volkswagen

Tip caroserie

Break



An model

2021



Capacitate cilindrică

2 l



Putere motor

110 kW (148 cp)



Tip combustibil

Diesel



Cutie de viteze

Automată



Tip transmisie

Tracțiune față (FWD)



Amplasarea volanului

Volan pe stânga



Nr. cilindri

4

Echipare

Cum a fost primit de la producător

0AE

FRONT STABILIZER

0B3

WHEELBASE

0BD

REAR STABILIZER

0F5

FUEL SYSTEM FOR DIESEL ENGINE

0FA

STANDARD MANUFACTURING SEQUENCE

0J

INSTALLATION DIFFERENTIATION FOR TRANSMISSION "DQ381" -- VEHICLE COMPONENTS --

0K0

WITHOUT ALTERNATIVE DRIVE SYSTEM

0KA

WITHOUT DECALS AND EMBLEMS

0N4

4-LINK REAR SUSPENSION

0NB

NAMEPLATE SET IN BASIC STYLE

0P0

REAR EXHAUST TAILPIPE (STANDARD)

0TD

FLOOR MATS IN FRONT AND REAR

0VC

INFORMATION KIT IN GERMAN

0Y1

STANDARD CLIMATIC ZONES

0YF

WEIGHT RANGE 6 INSTALLATION CONTROL ONLY, NO REQUIREMENT FORECAST

1AQ

BRS FOR VEHICLES WITHOUT ELECTRIC DRIVE (ESC AND ELECTRIC BRAKE BOOSTER)

1D0

WITHOUT TRAILER HITCH

1E9

WITHOUT ACTIVATED CARBON CANISTER WITH SCR

1EX

SPECIAL IDENTIFICATION PLATE FOR EC FOR M1 PASSENGER VEHICLE

1G8

BREAKDOWN KIT

1J2

SOUND DEADENING PACKAGE AND ADDITIONAL ENCLOSURES FOR SOME UNITS

1JA

REAR SHOCK ABSORPTION, BASIC VERSION 1

1KE

DISK BRAKES IN REAR

1N3

SPEED-RELATED VARIABLE STEERING ASSIST (SERVOTRONIC)

1PE

WHEEL BOLTS WITH ANTI-THEFT PROTECTION (UNLOCKABLE)

1R0

STANDARD FRONT BRAKE LINING

1S3

TOOL KIT

1SA

WITHOUT ADDITIONAL FRONT UNDERBODY GUARD

1T9

FIRST AID KIT WITH WARNING TRIANGLE AND SAFETY VEST

1X0

FRONT WHEEL DRIVE

1Y3

ELECTRONIC DIFFERENTIAL LOCK XDS DYNAMIC TRACTION CONTROL

1Z0

INITIAL STANDARD FUEL FILLING

1ZK

DISK BRAKES IN FRONT

20A

WITHOUT ELECTRIC MOTOR (HYBRID)

2CM

VEHICLE CLASS DIFFERENTIATION 5H0

2F1

LOCKING AND STARTING SYSTEMS

2FT

SPORTS MULTIFUNCTION STEERING WHEEL WITH TIPTRONIC (LEATHER + WOOD)

2H0

WITHOUT "DRIVE SELECT"

2JD

SPORTS BUMPERS

2KW

LABELS/PLATES IN GERMAN, FRENCH, AND DUTCH

2WA

WITHOUT ADDITIONAL TIRES

31K

FRONT AND REAR LICENSE PLATE CARRIER (ECE)

3C7

3-POINT SEAT BELT FOR CENTER REAR SEAT

3CX

NET PARTITION

3D3

CENTER CONSOLE

3FA

WITHOUT ROOF INSERT (STANDARD ROOF)

3H0

WITHOUT BACKREST RELEASE FOR FRONT SEATS

3LM

DOOR AND SIDE TRIM PANEL

3NU

REAR SEAT BENCH UNSPLIT, BACKREST SPLIT FOLDING WITH CENTER ARMREST

3QT

3-POINT SEAT BELTS IN FRONT, WITH PRETENSIONER AND HEIGHT ADJUSTMENT

3S2

BLACK ROOF RAILS

3T2

THREE REAR HEAD RESTRAINTS

3ZU

3-POINT SEAT BELTS, OUTER REAR WITH ECE LABEL

4A3

SEAT HEATER FOR FRONT SEATS SEPARATELY CONTROLLED

4D0

WITHOUT SEAT VENTILATION/MASSAGE SEAT

4E0

TAILGATE/TRUNK LID UNLOCKING FROM OUTSIDE

4G0

WITHOUT STORAGE COMPARTMENTS, 1ST ROW OF SEATS

4GF

WINDSHIELD IN HEAT-INSULATING GLASS

4K6

CENTRAL LOCKING SYSTEM "KEYLESS ENTRY" WITH FINGERPRINT "TWO-STAGE UNLOCKING"

4KF

SIDE WINDOWS IN HEAT-INSULATING GLASS, FROM B-PILLAR AND REAR WINDOW DARK TINTED

4L6

BREAKAWAY INTERIOR REARVIEW MIRROR, AUTO-DIMMING

4P3

REAR FLOOR PANEL MODULE, TYPE 4

4UF

DRIVER AND FRONT PASSENGER AIRBAG WITH FRONT PASSENGER AIRBAG DEACTIVATION

4X4

SIDE AIRBAG IN FRONT AND REAR WITH CURTAIN AIRBAG

4ZN

BRIGHT MOLDINGS

5C0

WITHOUT SPECIAL BODY MEASURES

5F1

1 ARMREST FOR LEFT FRONT SEAT AND 2 ARMRESTS FOR RIGHT FRONT SEAT

5J4

BODY-COLORED REAR SPOILER

5JA

WITHOUT AMBULANCE SEAT FOR MEDICAL STAFF

5K7

TRANSPORT PROTECTION FILM (MINIMUM PROTECTION) WITH ADDITIONAL TRANSPORT PROTECTION MEASURES

5MJ

DECORATIVE INSERTS

5XJ

SUN VISORS WITH MIRROR, ILLUMINATED, WITH AIRBAG LABEL ON SUN VISOR AND B-PILLAR

5ZF

FRONT HEAD RESTRAINTS

6A0

WITHOUT FIRE EXTINGUISHER

6E3

CENTER ARMREST IN FRONT

6FF

BODY-COLORED EXTERIOR MIRROR HOUSINGS AND VARIOUS ADD-ON PARTS

6I6

LANE KEEPING SYSTEM PLUS SEMI-AUTOMATIC VEHICLE CONTROL IN A MEDICAL EMERGENCY AND TRAFFIC JAM ASSIST

6NA

UNSPLIT MOLDED HEADLINER

6Q1

PLASTIC GEARSHIFT KNOB/HANDLE

6T2

INTERIOR LIGHT IN FOOTWELL IN FRONT AND REAR

6XQ

EXTERIOR MIRRORS: WITH MEMORY FEATURE, POWER-FOLDING/ADJUSTABLE, SEPARATELY HEATED

6Y8

SPEED LIMITER

76A

WITHOUT MODE 3 CHARGING CABLE

7AL

ANTI-THEFT ALARM SYSTEM, INTERIOR MONITORING, BACKUP HORN, AND TOWING PROTECTION

7B2

12-VOLT SOCKET IN LUGGAGE BOOT

7E6

ELECTRIC AUXILIARY AIR HEATER

7K1

DIRECT TIRE PRESSURE MONITORING SYSTEM

7L6

START/STOP SYSTEM WITH REGENERATIVE BRAKING

7U0

STANDARD ENGINE STARTER

7UG

NAVIGATION SYSTEM - HIGH

7W4

WITH EXTENDED SAFETY SYSTEM (PROACTIVE PASSENGER PROTECTION SYSTEM, BASIC, FRONT, AND REAR)

7X5

PARK ASSIST

7Y1

LANE CHANGE ASSIST

8AR

RADIO "GAMMA" WITH REMOVABLE OPERATING PANEL

8FA

WITHOUT SECOND BATTERY

8G5

MULTIPLE MATRIX BEAM

8GU

ALTERNATOR 140 A

8I2

POWER-ADJUSTABLE LUMBAR SUPPORT FOR FRONT LEFT SEAT BACKREST WITH MASSAGE FEATURE

8IU

LED HEADLAMPS WITH VARIABLE LIGHT DISTRIBUTION

8J3

HAND BRAKE/LOW BRAKE FLUID LEVEL WARNINGLIGHT AND INSCRIPTION

8N6

WINDSHIELD WIPER INTERMITTENT CONTROL WITH LIGHT/RAIN SENSOR

8Q5

HEADLIGHT RANGE ADJUSTMENT, AUTOMATIC/ DYNAMIC, WITH CORNERING LIGHT (AFS 1)

8RT

SPEAKERS IN FRONT AND REAR

8S6

2 READING LIGHTS IN FRONT

8T8

ADAPTIVE CRUISE CONTROL (WITH "FOLLOW-TO-STOP") AND SPEED LIMITER

8WP

FRONT FOG LAMP, CORNERING AND ALL-WEATHER LIGHT

8X7

WITHOUT HEADLAMP WASHER SYSTEM / WITH WASHER FLUID LEVEL INDICATOR

8Y1

TWO-TONE HORN

8Z5

NOT HOT COUNTRY

8ZQ

ANTENNA FOR FM RECEPTION ONLY, DIVERSITY

9D0

WITHOUT PREPARATION FOR TWO-WAY RADIO INSTALLATION

9F0

WITHOUT SOUND COMBINATION FOR ROTATING EMERGENCY LIGHT AND RADIO ANTENNA PREPARATION

9I5

SEPARATE DAYTIME RUNNING LIGHTS WITH AUTOMATIC HEADLAMP ACTIVATION AND COMING HOME FEATURE (AUTOMATIC)

9J

COMFORT TELEPHONY WITH LTE AND WIRELESS CHARGING

9JB

SMOKER'S PACKAGE, ASHTRAY IN FRONT AND REAR

9M0

WITHOUT AUXILIARY HEATER/FUEL-FIRED PARKING HEATER

9P4

SEAT BELT REMINDER, ELECTRIC CONTACT IN FRONT AND REAR, VISUAL AND ACOUSTICAL

9T1

HEATED WASHER NOZZLES IN FRONT

9WJ

POWER SUPPLY/TV SIGNAL FOR CUSTOMIZED INSTALLATION

9Z0

OPERATING VOLTAGE 12 V

A8F

SPORTS EQUIPMENT

AV1

DRIVING ON THE RIGHT

B01

TYPE APPROVAL COUNTRY GERMANY

B0A

COMPONENT PARTS SET WITHOUT COUNTRY-SPECIFIC BUILDING REGULATION

C00

OPERATING PERMIT, INITIAL REGISTRATION

C0T

ALLOY WHEELS 7.5J X 18

DN4

4-CYL. TURBO DIESEL ENGINE 2.0 L/110 KW (4V) TDI COMMON RAIL; B.ENGINE T37/T6F
TS1/TR1/T0P/T0N/T13/T29/TM4/TD1/TI9/T1I

E0A

NO SPECIAL EDITION

EA0

WITHOUT FOLLOW-ON WARRANTY

EL5

ONLINE SERVICE, WITH OCU, WITH HEAD UNITCODING, WITHOUT ENGINE IMMOBILIZER INTERCONNECTION

EM1

DRIVER ALERT SYSTEM

ER1

REGIONAL CODE " ECE " FOR RADIO

EVO

WITHOUT CHARGING CABLE

F0A

NO SPECIAL PURPOSE VEHICLE, STANDARD EQUIPMENT

FB0

STANDARD PAINT COATING

FC0

WITHOUT CUSTOMIZED INSTALLATION

FM0

BASIC EQUIPMENT VARIANT

G1C

SEVEN-SPEED AUTOMATIC TRANSMISSION

G22

SHOCK ABSORPTION IN FRONT

GM1

STANDARD ELECTRONIC ENGINE SOUND

GP0

VEHICLES WITHOUT SPECIAL UPGRADE MEASURES

GW2

CAR2X "HIGH" VARIANT

H7D

TIRES 225/40 R18 92Y XL

J0V

BATTERY 420 A (70 AH)

K8D

WAGON/AVANT

KA2

WITH REAR VIEW CAMERA SYSTEM (TYPE 2)

KH7

CLIMATRONIC (3-ZONE) WITH REAR AIR CONDITIONING CONTROL PANEL

KK3

REFRIGERANT R1234YF

KS1

HEAD-UP DISPLAY

L08

SUSPENSION RANGE 08 INSTALLATION CONTROL ONLY, NO REQUIREMENT FORECAST

L0L

LEFT-HAND DRIVE

N0R

SEAT TRIM COVERS IN

NY0

STANDARD BATTERY/ALTERNATOR CAPACITY

NZ4

PRIVATE EMERGENCY CALL SYSTEM

Q4H

SPORTS COMFORT SEATS IN FRONT

QG1

SERVICE INTERVAL PROLONGATION

QH1

VOICE CONTROL

QI6

SERVICE INDICATOR 30 000 KM OR 2 YEARS (VARIABLE)

QJ1

CHROME PACKAGE

QK1

WITH MULTIFUNCTION CAMERA

QQ9

INTERIOR AMBIENT LIGHTING, TYPE 2

QR9

WITH DYNAMIC ROAD SIGN DISPLAY

QV3

DIGITAL RADIO RECEPTION

S0C

INTRODUCTORY VOLUME

SB0

PLANT EMPLOYEE LEASING - HN

T3Y

4-CYLINDER DIESEL ENGINE 2.0 L UNIT 05L.D

U5A

INSTRUMENT CLUSTER, KM/H SPEEDOMETER

U9C

2 X USB TYPE C

UG0

WITHOUT HILL START ASSIST/HILL DESCENT CONTROL/COMFORT DRIVING ASSIST

UH2

PARKING BRAKE

UK3

MECHANICAL REAR SEAT RELEASE

V1P

TIRE SUPPLIERS FOR EU COUNTRIES

VF0

STANDARD PEDAL CLUSTER

VL1

EXTENDED PEDESTRIAN PROTECTION MEASURES

X0A

EQUIPMENT OPTIONS SUBSET FOR GERMANY

Cronologie

S-au găsit 3 înregistrări

Cronologia înregistrărilor pentru acest vehicul

Ultimele înregistrări

2021-04

 Germania



Daună detectată 

Avem indicii potrivit cărora acest vehicul a fost recunoscut ca avariat în această țară (sau stat). Pentru detalii, vă rugăm să consultați secțiunea „Daune”.

2021-04

 Germania



A fost la vânzare

Această înregistrare a fost creată deoarece vehiculul a fost listat pentru vânzare pe o anumită piață. Uneori, țara (sau statul) vânzătorului suprascrie locația reală a vehiculului.

2022-08

 Germania



Daună detectată 

Avem indicii potrivit cărora acest vehicul a fost recunoscut ca avariat în această țară (sau stat). Pentru detalii, vă rugăm să consultați secțiunea „Daune”.



+31

Surse de date

Am verificat 900+ de surse de date în **35 de țări**