

# Volkswagen

VIN: WWZZZCDZNW508663

Diesel

Generat pe 2024-12-20 08:24



## Odometru

✓ Arată bine



## Statut legal

✓ Arată bine



## Daune

✓ Arată bine



+31

## Surse de date

Am verificat 900+ de surse de date în 35 de țări

## Furt

Vehiculul este în prezent marcat ca furat? A fost furat în trecut? A fost recuperat?



### Nu s-au găsit probleme

Nu am găsit nicio înregistrare că vehiculul a fost furat.



### Notă

Verificarea bazei de date a poliției privind vehiculele furate finalizată în 8 țări: +2

## Iată ce am verificat:



### Căutat drept furat

✓ Nu s-a găsit nici o înregistrare



### Furat în trecut

✓ Nu s-a găsit nici o înregistrare

Starea actuală necunoscută



### Furat în trecut

✓ Nu s-a găsit nici o înregistrare

Vehiculul a fost recuperat

Baza de date aparținând poliției cu vehicule furate, **verificare finalizată în:**



România



Danemarca



Statele Unite ale Americii



Lituania



Slovacia




Suedia

# Odometru

Există semne conform cărora kilometrajul a fost dat înapoi sau discrepanțe ale kilometrajului?

**i Notă**

Ultimul kilometraj cunoscut: 87.893 km



**Disclaimer (declinarea responsabilității):** acest grafic reprezintă o tendință estimată a kilometrajului. Deși se bazează pe înregistrări reale de kilometraj disponibile pentru acest vehicul, există lacune având în vedere că evoluția kilometrajului nu este înregistrată în mod constant. Pentru a lua în considerare aceste date lipsă, aplicăm un model patentat de analiză a datelor care prezice modul în care probabil s-a schimbat kilometrajul între evenimentele înregistrate. Acest lucru ajută la furnizarea unei imagini mai complete a utilizării vehiculului în timp.

## Statut legal

A trecut vehiculul inspecțiile tehnice? A fost notat drept casat?

**✓ Nu s-au găsit probleme**

Nu s-au găsit înregistrări despre statutul legal al acestui vehicul

## Legal



### Inspecție tehnică periodică (ITP)

✓ Nu s-a găsit nici o înregistrare

Nu au fost găsite înregistrări ale inspecției tehnice



### Casat

✓ Nu s-a găsit nici o înregistrare

Nu există nici o înregistrare că vehiculul a fost marcat drept casat

## Daune

Acest vehicul a fost avariat în trecut ? Care a fost valoarea daunelor?

✓ Nu s-au găsit probleme

## Înregistrări de daune



Ocazional pot apărea inexactități, mai ales la verificarea vehiculelor vechi. Atelierele clandestine de reparații pot deghiza ilegal defectele sau daunele vehiculelor, fără să declare nicăieri existența lor. Uneori până și plăcuțele VIN ale vehiculului pot fi înlocuite. Avem o varietate de metode de a detecta chiar și astfel de infracțiuni, dar este imposibil de oferit o garanție de 100%.

## Dezastre naturale


Locația vehiculului a fost înregistrată în zona unui dezastru natural?

 **Nu s-au găsit probleme**

Locația vehiculului nu a fost înregistrată în zona unui dezastru natural

## Specificații și echipare

Ce specificații și echipamente sunt înregistrate pentru acest vehicul?

 **Notă**

Verificați dacă specificațiile și echipamentul acestui vehicul se potrivesc cu datele furnizate de vânzător.

## Identificare și specificații tehnice



Producător

**Volkswagen**



Tip caroserie

**Break**



An model

**2022**



Capacitate cilindrică

**2 l**



Putere motor

**110 kW (148 cp)**



Tip combustibil

**Diesel**



Cutie de viteze

**Automată**



Tip transmisie

**Tracțiune față (FWD)**



Amplasarea volanului

**Volan pe stânga**



Nr. cilindri

**4**

# Echipare

Cum a fost primit de la producător

---

0AE

FRONT STABILIZER

0B3

WHEELBASE

0BD

REAR STABILIZER

0F5

FUEL SYSTEM FOR DIESEL ENGINE

0FA

STANDARD MANUFACTURING SEQUENCE

0J

INSTALLATION DIFFERENTIATION FOR TRANSMISSION "DQ381" -- VEHICLE COMPONENTS --

0K0

WITHOUT ALTERNATIVE DRIVE SYSTEM

0KA

WITHOUT DECALS AND EMBLEMS

0N4

4-LINK REAR SUSPENSION

0NB

NAMEPLATE SET IN BASIC STYLE

0P0

REAR EXHAUST TAILPIPE (STANDARD)

0TD

FLOOR MATS IN FRONT AND REAR

0VC

INFORMATION KIT IN GERMAN

0Y1

STANDARD CLIMATIC ZONES

0YF

WEIGHT RANGE 6 INSTALLATION CONTROL ONLY, NO REQUIREMENT FORECAST

1AQ

BRS FOR VEHICLES WITHOUT ELECTRIC DRIVE (ESC AND ELECTRIC BRAKE BOOSTER)

1D0

WITHOUT TRAILER HITCH

1E9

WITHOUT ACTIVATED CARBON CANISTER WITH SCR

1EX

SPECIAL IDENTIFICATION PLATE FOR EC FOR M1 PASSENGER VEHICLE

1G8

BREAKDOWN KIT

1J2

SOUND DEADENING PACKAGE AND ADDITIONAL ENCLOSURES FOR SOME UNITS

1JA

REAR SHOCK ABSORPTION, BASIC VERSION 1

1KE

DISK BRAKES IN REAR

1N3

SPEED-RELATED VARIABLE STEERING ASSIST (SERVOTRONIC)

1PF

STANDARD WHEEL BOLTS

1R0

STANDARD FRONT BRAKE LINING

1S1

TOOL KIT AND JACK

1SA

WITHOUT ADDITIONAL FRONT UNDERBODY GUARD

1T9

FIRST AID KIT WITH WARNING TRIANGLE AND SAFETY VEST

1X0

FRONT WHEEL DRIVE

1Y3

ELECTRONIC DIFFERENTIAL LOCK XDS DYNAMIC TRACTION CONTROL

1Z0

INITIAL STANDARD FUEL FILLING

1ZK

DISK BRAKES IN FRONT

20A

WITHOUT ELECTRIC MOTOR ( HYBRID )

2CM

VEHICLE CLASS DIFFERENTIATION 5H0

2F0

WITHOUT LOCKING AND STARTING SYSTEMS

2FT

SPORTS MULTIFUNCTION STEERING WHEEL WITH TIPTRONIC (LEATHER + WOOD)

2H0

WITHOUT "DRIVE SELECT"

2JD

SPORTS BUMPERS

2KW

LABELS/PLATES IN GERMAN, FRENCH, AND DUTCH

2YK

ADDITIONAL SNOW TIRES

31K

FRONT AND REAR LICENSE PLATE CARRIER (ECE)

3C7

3-POINT SEAT BELT FOR CENTER REAR SEAT

3CX

NET PARTITION

3D3

CENTER CONSOLE

3FA

WITHOUT ROOF INSERT (STANDARD ROOF)

3H0

WITHOUT BACKREST RELEASE FOR FRONT SEATS

3NU

REAR SEAT BENCH UNSPLIT, BACKREST SPLIT FOLDING WITH CENTER ARMREST

3QT

3-POINT SEAT BELTS IN FRONT, WITH PRETENSIONER AND HEIGHT ADJUSTMENT

3S2

BLACK ROOF RAILS

3T2

THREE REAR HEAD RESTRAINTS

3ZU

3-POINT SEAT BELTS, OUTER REAR WITH ECE LABEL

4A3

SEAT HEATER FOR FRONT SEATS SEPARATELY CONTROLLED

4AF

DOOR AND SIDE TRIM PANEL IN FOAM FILM AND WOVEN FABRIC

4D0

WITHOUT SEAT VENTILATION/MASSAGE SEAT

4E0

TAILGATE/TRUNK LID UNLOCKING FROM OUTSIDE

4G3

STORAGE COMPARTMENT, LEFT AND RIGHT 1ST ROW OF SEATS

4GF

WINDSHIELD IN HEAT-INSULATING GLASS



4I7

CENTRAL LOCKING SYSTEM "KEYLESS-GO" WITHOUT SAFELOCK

4KF

SIDE WINDOWS IN HEAT-INSULATING GLASS, FROM B-PILLAR AND REAR WINDOW DARK TINTED

4L2

DIMMING BREAKAWAY INTERIOR REARVIEW MIRROR

4P3

REAR FLOOR PANEL MODULE, TYPE 4

4UF

DRIVER AND FRONT PASSENGER AIRBAG WITH FRONT PASSENGER AIRBAG DEACTIVATION

4X3

SIDE AIRBAG IN FRONT, WITH CURTAIN AIRBAG

4ZN

BRIGHT MOLDINGS

5C0

WITHOUT SPECIAL BODY MEASURES

5F1

1 ARMREST FOR LEFT FRONT SEAT AND 2 ARMRESTS FOR RIGHT FRONT SEAT

5J4

BODY-COLORED REAR SPOILER

5JA

WITHOUT AMBULANCE SEAT FOR MEDICAL STAFF

5K7

TRANSPORT PROTECTION FILM (MINIMUM PROTECTION) WITH ADDITIONAL TRANSPORT PROTECTION MEASURES

5MJ

DECORATIVE INSERTS

5XJ

SUN VISORS WITH MIRROR, ILLUMINATED, WITH AIRBAG LABEL ON SUN VISOR AND B-PILLAR

5ZF

## FRONT HEAD RESTRAINTS

6A0

WITHOUT FIRE EXTINGUISHER

6E3

CENTER ARMREST IN FRONT

6FF

BODY-COLORED EXTERIOR MIRROR HOUSINGS AND VARIOUS ADD-ON PARTS

6I6

LANE KEEPING SYSTEM PLUS SEMI-AUTOMATIC VEHICLE CONTROL IN A MEDICAL EMERGENCY AND TRAFFIC JAM ASSIST

6NA

UNSPLIT MOLDED HEADLINER

6Q1

PLASTIC GEARSHIFT KNOB/HANDLE

6T2

INTERIOR LIGHT IN FOOTWELL IN FRONT AND REAR

6XR

EXTERIOR MIRRORS WITH MEMORY FEATURE, POWER-ADJUSTABLE, SEPARATELY HEATED

6Y8

SPEED LIMITER

76A

WITHOUT MODE 3 CHARGING CABLE

7AA

ELECTRONIC ENGINE IMMOBILIZER

7B2

12-VOLT SOCKET IN LUGGAGE BOOT

7E6

ELECTRIC AUXILIARY AIR HEATER

7K1

DIRECT TIRE PRESSURE MONITORING SYSTEM

7L6

START/STOP SYSTEM WITH REGENERATIVE BRAKING

7U0

STANDARD ENGINE STARTER

7W2

WITH EXTENDED SAFETY SYSTEM (PROACTIVE PASSENGER PROTECTION SYSTEM, BASIC AND FRONT)

7X2

PARK DISTANCE CONTROL IN FRONT AND REAR

7Y0

WITHOUT LANE CHANGE ASSIST

8AR

RADIO "GAMMA" WITH REMOVABLE OPERATING PANEL

8FA

WITHOUT SECOND BATTERY

8G0

WITHOUT LIGHT CONTROL

8GU

ALTERNATOR 140 A

8I2

POWER-ADJUSTABLE LUMBAR SUPPORT FOR FRONT LEFT SEAT BACKREST WITH MASSAGE FEATURE

8IY

LED HEADLAMPS WITH LENS

8J3

HAND BRAKE/LOW BRAKE FLUID LEVEL WARNINGLIGHT AND INSCRIPTION

8N8

WINDSHIELD WIPER INTERMITTENT CONTROL WITH PHOTOSENSOR

8Q3

AUTOMATIC HEADLIGHT RANGE ADJUSTMENT DYNAMIC (SELF-ADJUSTING WHILE DRIVING)

8RT

SPEAKERS IN FRONT AND REAR

8S6

2 READING LIGHTS IN FRONT

8T8

ADAPTIVE CRUISE CONTROL (WITH "FOLLOW-TO-STOP") AND SPEED LIMITER

8WP

FRONT FOG LAMP, CORNERING AND ALL-WEATHER LIGHT

8X7

WITHOUT HEADLAMP WASHER SYSTEM / WITH WASHER FLUID LEVEL INDICATOR

8Y1

TWO-TONE HORN

8Z5

NOT HOT COUNTRY

8ZQ

ANTENNA FOR FM RECEPTION ONLY, DIVERSITY

9D0

WITHOUT PREPARATION FOR TWO-WAY RADIO INSTALLATION

9F0

WITHOUT SOUND COMBINATION FOR ROTATING EMERGENCY LIGHT AND RADIO ANTENNA PREPARATION

9I5

SEPARATE DAYTIME RUNNING LIGHTS WITH AUTOMATIC HEADLAMP ACTIVATION AND COMING HOME FEATURE (AUTOMATIC)

9J

COMFORT TELEPHONY WITH LTE AND WIRELESS CHARGING

9JA

NON-SMOKER'S PACKAGE

9M0

WITHOUT AUXILIARY HEATER/FUEL-FIRED PARKING HEATER

9P4

SEAT BELT REMINDER, ELECTRIC CONTACT IN FRONT AND REAR, VISUAL AND ACOUSTICAL

9T1

HEATED WASHER NOZZLES IN FRONT

9WJ

POWER SUPPLY/TV SIGNAL FOR CUSTOMIZED INSTALLATION

9Z0

OPERATING VOLTAGE 12 V

A8F

SPORTS EQUIPMENT

AV1

DRIVING ON THE RIGHT

B01

TYPE APPROVAL COUNTRY GERMANY

B0A

COMPONENT PARTS SET WITHOUT COUNTRY-SPECIFIC BUILDING REGULATION

BD

ESC SPECIAL VEHICLE 11

C05

OPERATING PERMIT, ALTERATION

C0X

ALLOY WHEELS 7.5J X 17

DN4

4-CYL. TURBO DIESEL ENGINE 2.0 L/110 KW (4V) TDI COMMON RAIL; B.ENGINE T37/T6F  
TS1/TR1/T0P/T0N/T13/T29/TM4/TD1/TI9/T1I

E0A

NO SPECIAL EDITION

EA0

WITHOUT FOLLOW-ON WARRANTY

EL5

ONLINE SERVICE, WITH OCU, WITH HEAD UNITCODING, WITHOUT ENGINE IMMOBILIZER INTERCONNECTION

EM1

DRIVER ALERT SYSTEM

ER1

REGIONAL CODE " ECE " FOR RADIO

EVO

WITHOUT CHARGING CABLE

F0A

NO SPECIAL PURPOSE VEHICLE, STANDARD EQUIPMENT

FB0

STANDARD PAINT COATING

FC0

WITHOUT CUSTOMIZED INSTALLATION

FM0

BASIC EQUIPMENT VARIANT

G1C

SEVEN-SPEED AUTOMATIC TRANSMISSION

G22

SHOCK ABSORPTION IN FRONT

GM1

STANDARD ELECTRONIC ENGINE SOUND

GP0

VEHICLES WITHOUT SPECIAL UPGRADE MEASURES

GW2

CAR2X "HIGH" VARIANT

H6L

TIRES 225/45 R17 91W

IG9

WITHOUT CURB WEIGHT RANGE

J0V

BATTERY 420 A (70 AH)

K8D

WAGON/AVANT

KA0

WITHOUT CAMERA SYSTEMS/ACCIDENT SENSORS

KH7

CLIMATRONIC (3-ZONE) WITH REAR AIR CONDITIONING CONTROL PANEL

KK3

REFRIGERANT R1234YF

KS0

WITHOUT HEAD-UP DISPLAY

L07

SUSPENSION RANGE 07 INSTALLATION CONTROL ONLY, NO REQUIREMENT FORECAST

L0L

LEFT-HAND DRIVE

N0R

SEAT TRIM COVERS IN

NY0

STANDARD BATTERY/ALTERNATOR CAPACITY

NZ4

PRIVATE EMERGENCY CALL SYSTEM

Q4H

SPORTS COMFORT SEATS IN FRONT

QG1

SERVICE INTERVAL PROLONGATION

QH1

VOICE CONTROL

QI6

SERVICE INDICATOR 30 000 KM OR 2 YEARS ( VARIABLE )

QJ1

CHROME PACKAGE

QK1

WITH MULTIFUNCTION CAMERA

QQ9

INTERIOR AMBIENT LIGHTING, TYPE 2

QR9

WITH DYNAMIC ROAD SIGN DISPLAY

QV3

DIGITAL RADIO RECEPTION

T3Y

4-CYLINDER DIESEL ENGINE 2.0 L UNIT 05L.D

U5A

INSTRUMENT CLUSTER, KM/H SPEEDOMETER

U9C

2 X USB TYPE C

UG0

WITHOUT HILL START ASSIST/HILL DESCENT CONTROL/COMFORT DRIVING ASSIST

UH2

PARKING BRAKE

UK3

MECHANICAL REAR SEAT RELEASE

V1P

TIRE SUPPLIERS FOR EU COUNTRIES

VF0

STANDARD PEDAL CLUSTER

VL1

EXTENDED PEDESTRIAN PROTECTION MEASURES

X0A

EQUIPMENT OPTIONS SUBSET FOR GERMANY



+31

**Surse de date**

Am verificat 900+ de surse de date în **35 de țări**