

# Toyota Corolla

VIN: NMTBZ3BE80R035275

Benzină

2019

Generat pe 2025-01-14 09:14



## Odometru

✓ Arată bine



## Statut legal

✓ Arată bine



## Daune

✓ Arată bine



+31

## Surse de date

Am verificat 900+ de surse de date în 35 de țări

## Furt

Vehiculul este în prezent marcat ca furat? A fost furat în trecut? A fost recuperat?



### Nu s-au găsit probleme

Nu am găsit nicio înregistrare că vehiculul a fost furat.



### Notă

Verificarea bazei de date a poliției privind vehiculele furate finalizată în 8 țări: +2

## Iată ce am verificat:



### Căutat drept furat

✓ Nu s-a găsit nici o înregistrare



### Furat în trecut

✓ Nu s-a găsit nici o înregistrare

Starea actuală necunoscută



### Furat în trecut

✓ Nu s-a găsit nici o înregistrare

Vehiculul a fost recuperat

Baza de date aparținând poliției cu vehicule furate, **verificare finalizată în:**



România



Slovacia



Statele Unite ale Americii



Lituania



Danemarca




Cehia

# Odometru

Există semne conform cărora kilometrajul a fost dat înapoi sau discrepanțe ale kilometrajului?

## Notă

Ultimul kilometraj cunoscut: 51.443 km




**Disclaimer (declinarea responsabilității):** acest grafic reprezintă o tendință estimată a kilometrajului. Deși se bazează pe înregistrări reale de kilometraj disponibile pentru acest vehicul, există lacune având în vedere că evoluția kilometrajului nu este înregistrată în mod constant. Pentru a lua în considerare aceste date lipsă, aplicăm un model patentat de analiză a datelor care prezice modul în care probabil s-a schimbat kilometrajul între evenimentele înregistrate. Acest lucru ajută la furnizarea unei imagini mai complete a utilizării vehiculului în timp.

## Statut legal

A trecut vehiculul inspecțiile tehnice? A fost notat drept casat?

## Notă

Inspecția tehnică a fost transmisă pe 2023-02 în  România

## Legal



### Inspecție tehnică periodică (ITP)

A trecut

2023-02  România

A trecut cu succes inspecția tehnică

Valabil până la 2025-07



### Casat

✓ Nu s-a găsit nici o înregistrare

Nu există nici o înregistrare că vehiculul a fost marcat drept casat

## Daune

Acest vehicul a fost avariat în trecut ? Care a fost valoarea daunelor?

✓ Nu s-au găsit probleme

## Înregistrări de daune



Ocazional pot apărea inexactități, mai ales la verificarea vehiculelor vechi. Atelierele clandestine de reparații pot deghiza ilegal defectele sau daunele vehiculelor, fără să declare nicăieri existența lor. Uneori până și

plăcuțele VIN ale vehiculului pot fi înlocuite. Avem o varietate de metode de a detecta chiar și astfel de infracțiuni, dar este imposibil de oferit o garanție de 100%.

## Dezastre naturale

Locația vehiculului a fost înregistrată în zona unui dezastru natural?

### ✓ Nu s-au găsit probleme

Locația vehiculului nu a fost înregistrată în zona unui dezastru natural

## Valoarea de piață

Cu cât s-a vândut vehiculul în trecut? Care este în medie prețul vehiculelor din acest model și an?

### i Notă

- Prețul mediu de pe piață pentru un astfel de vehicul: 91.605 RON
- Atenție la problemele ascunse dacă vehiculul a fost la vânzare la un preț semnificativ mai mic decât prețul actual!

## Valoarea de piață azi pentru Toyota Corolla 2019

Valoarea de piață este determinată prin examinarea prețului unui anumit model de mașină (fabricat în același an) în țara în care a fost generat raportul. Analizăm datele din ultimele 6 luni.

Cel mai mic preț

85.950 RON

Prețul mediu

91.605 RON

Cel mai mare preț

97.577 RON

## Emisii

Câte emisii de CO2 produc vehiculele din acest model/an?

### i Notă

Emisii CO2: A (102 g/km)

## Emisii CO<sub>2</sub>

Emisiile CO<sub>2</sub> ale

Emisii CO<sub>2</sub> ale  
vehiculului tău

**102 g/km** Clasă **A**

Până la 120

120 - 140

140 - 155

155 - 165

165 - 190

190 - 225

225 și peste

Emisii CO<sub>2</sub> g/km

## Specificații și echipare

Ce specificații și echipamente sunt înregistrate pentru acest vehicul?

### Notă

Verificați dacă specificațiile și echipamentul acestui vehicul se potrivesc cu datele furnizate de vânzător.

## Identificare și specificații tehnice



Producător

**Toyota**



Model

**Corolla**



Descriere

**Corolla**



Tip caroserie

**Sedan**



An de fabricație

**2019**



Capacitate cilindrică

**1,8 l**



Putere motor

**72 kW (97 cp)**



Cuplu

**142 Nm**



Tip combustibil

**Benzină**



Cutie de viteze

**Automată**



Tip transmisie

**Tracțiune față (FWD)**



Culoare

**Alb**



Nr. uși

**5**



Amplasarea volanului

**Volan pe stânga**



Nr. cilindri

**4**

---

## Echipare

Cum a fost primit de la producător

---

**A/C**

AUTO (DUAL MODE)

**ABS**

WITH

**ACCELERATOR PEDAL**

ELECTRIC TYPE

**ACCESSORY CONNECTOR (NO 1)**

CONSOLE BOX

**ACCESSORY CONNECTOR (NO 2)**

CONSOLE BOX1

**ADDITIONAL HEATER**

WITHOUT

**AIR BAG MANUAL ON-OFF SW**

P SEAT WITH INDICATOR

**ANTENNA**

RR WINDOW + SFIN

**ANTI-THEFT LABEL**

WITHOUT

**ANTI-THEFT SYSTEM**

IMMOBILIZER

**ASHTRAY**

WITHOUT

**ASSIST GRIP**

FR2, RR2

**AUDIO**

T1 (8") WITOUT CD WITH BT, USB 6SP

**AUDIO JACK**

WITH

**BACK GLASS**

GREEN 70%

**BACK MONITOR**

CAMERA + W/H

**BATTERY**

LN1 36AH

**BLACK OUT**

RADIATOR SP + ID PLATE + SASH

**BRAKE CONT VALVE- EDB CONTROL**

EBD

**BRAKE M/CYLIND & BOOSTER**

AHB-R

**BUMPER**

PP COLOUR

**CHILD PROTECTOR**

WITH (REAR DOOR ONLY)

**CHILD RESTRAINT SYSTEM**

ISIZE + TOP TETHER\*2

**CHILD SEAT**

WITHOUT

CIGARETTE LIGHTER

WITHOUT

CLEAN AIR FILTER

POLLEN FILTER

CLEARANCE & BACK SONAR

FRONT+BACK SONAR

CLOCK

AUDIO + METER

COAT HOOK

WITH

COLD AREA PACKAGE

SUB-COLD AREA SPEC

CONSOLE BOX

RESIN

COOLER REAR DUCT

WITH

CRUISE CONTROL

WITH (FULL RANGE ACC)

CUP HOLDER

FR:2 RR:2

DATA COMMUNICATION MODULE

WITH E-CALL

DAYTIME RUNNING LIGHT SYSTEM

WITH (LED TYPE)

DESTINATION PACKAGE

WITHOUT

DESTINATION PACKAGE (EXC/ ERP)

WITHOUT

DOOR ARM REST

FABRIC



DOOR BELT MOULDING

BLACK

DOOR INSIDE HANDLE

PLATING

DOOR OUTSIDE HANDLE

BODYCOLOUR D: W/ KEY P:W/O

DOOR POCKET

FR&RR

DOOR SCUFF PLATE

WITH

DOOR TRIM

FR&RR: HARD WITH NV FELT

DOOR TRIM ORNAMENT

RESIN + SATIN PLATING

DOOR WINDOW FRAME

PLATING

DRIVE MODE

TOGGLE DMS 3

EMERGENCY BRAKE LIGHTS

WITH

ENGINE MARK

HV

ENGINE UNDER COVER & PROTECTION

WITH (WITHOUT ACOUSTIC MAT)

EXHAUST EMISSION CONTROL

EURO6D TEMP WITH OBD

EXHAUST TAIL PIPE & DIFFUSER

SINGLE WITHOUT DIFFUSER

FENDER LINER

FR (WITH SILENCER) & RR

**FLOOR MAT**

TEX FM 520G HYBRID

**FRONT FLOOR CARPET AND MAT**

DILOUR (WITH HEEL PAD)

**FRONT FOG LAMPS**

WITH (LED + MAT BLK + SILVER)

**FRONT HEADRESTS**

VERTICAL X2

**FRONT PERSONAL LAMP**

WITH (BULB)

**FRONT SEAT**

NORMAL

**FRONT SEAT BELT**

D,P: 3ELR + PT + F/L\*2

**FRONT SEAT SLIDE**

260MM D&P MANUAL

**FRONT SEAT VERTICAL ADJUSTER**

D: 2WAY MANUAL

**FRONT SIDE GLASS**

GREEN 70%

**FRONT WHEEL BRAKE**

15" DISC (B)

**FUEL CAUTION LABEL**

E5, E10 REG.

**GLOVE BOX**

BIN TYPE W/O LOCK

**GLOVE BOX LAMP**

WITH

**GRADE MARK**

WITHOUT

**GRADE PACKAGE**

WITHOUT

**HEAD UP DISPLAY**

WITHOUT

**HEADLAMP AIMING**

RH AIMING (FOR LHD CAR)

**HEADLAMP CLEANER**

WITHOUT

**HEADLAMP LEVELLING**

MANUAL

**HEADLAMPS**

BI PES LED + AHB

**HEATER CONTROL PANEL**

AUTO DUAL + SATIN

**HIGH MOUNT STOP LAMP**

WITH (LED TYPE/CABIN)

**HILL ASSIST CONTROL (HAC)**

WITH (HAC3)

**I/P CENTER CLUSTER**

SATIN PLATING/PIANO BLACK

**I/P UNDER COVER**

WITH (D, P)

**ILLUMINATED ENTRY SYSTEM**

WITH (ROOM + MAP LAMP)

**INSIDE REAR VIEW MIRROR**

EC MIRROR

**INSTRUMENT FINISH PANEL**

AUDIO PANEL & METER CLUSTER SATIN (PLATING)

**INSTRUMENT PANEL**

SOFT W/ STITCH (P-PAD)

JACK

WITH

KEY PLATE

SMART-MASTER 2

LANE CHANGE ASSIST

WITHOUT

LANE KEEP ASSIST (LKA)

WITH (LTA)

LIGHT CONTROL SYSTEM

ALC + FMH 3 POSITION

LIGHT REMIND WARNING

WITH (AUTOCUT)

LOWER BACK AND BACK DOOR GARNISH

WITH (PLATING)

LUGGAGE AND BACK DOOR RELEASE

CABLE + ELEC LOCK

LUGGAGE ROOM & DECK TRIM

SIDE (WITH FELT) + RR + 1 CON FK

LUGGAGE ROOM LAMP

WITH

LUGGAGE TRAY

WITH

MIKE & MIKE AMP

WITH (OHC)

MUD GUARDS

WITHOUT

MULTI INFO DISPLAY

WITH (7")

NCAP

EURO

OUTSIDE REAR VIEW MIRROR

AUTO FOLD, ELEC, HEATER

OVERHEAD CONSOLE

WITH (WITH SOS SW, WITHOUT HOLDER)

OWNER'S MANUAL

WITHOUT

PACKAGE OPTION 3

MID

PACKAGE TRAY TRIM & TONNEAU COVER

GLASS FIBER WITH FELT LO

PAINT PROTECTION WAX/FILM

WITH WRAP TYPE

PARKING BRAKE

EPB

POWER DOOR LOCK

WITH

POWER STEERING

EPS

POWER WINDOWS

FR & RR 4 ONE TOUCH UP/DOWN HI

RADIATOR GRILLE

BLACK PAINT + PLATING

RADIATOR LOWER GRILLE

MATERIAL BLACK

REAR ARM REST

WITH CUP HOLDER

REAR BUMPER

PP PAINT COLOR

**REAR COMBINATION LAMP**

LED (STOP/TURN) + MULTI LED (TAIL)

**REAR CONSOLE BOX**

FAB W/O STITCH W/ SLIDE P-BLK

**REAR FOG LAMP**

WITH

**REAR HEADRESTS**

VERTICAL\*2 + FIXED\*1

**REAR SEAT**

6:4 SPLIT FOLD

**REAR SEAT BELT**

3ELR-PT-FL\*2 3ELR\*1

**REAR SIDE GLASS**

GREEN 70%

**REAR WINDOW DEFOGGER**

WITH TIMER

**REGISTER**

FR & RR: SATIN

**REGULATION COMPLIANCY**

WVTA LABEL

**ROOM LAMP**

PERSONAL TYPE

**ROUGH ROAD PACKAGE**

WITHOUT

**SAFETY SENSE**

TSS2

**SEAT BACK POCKET**

WITH (PASSENGER ONLY)

**SEAT BELT WARNING**

FR & RR (BUZZER + LAMP)

**SEAT HEATER**

WITH (D+P CUSHION & BACK)

**SEAT LUMBAR SUPPORT**

WITH D (POWER)

**SEAT MATERIAL**

FABRIC B MID

**SHIFT LEVER & KNOB**

LEATHER (CVT)

**SHIFT LEVER BOOT**

WITH SATIN PLATING + P-BLK BEZEL

**SHIFT POSITION INDICATOR**

WITH (METER)

**SIDE TURN SIGNAL LAMP**

WITH OUTER MIRROR

**SPARE TYRE**

TEMP 125/70D17

**SPEED WARNING**

WITH ASL

**SPEEDOMETER**

KM/H + RESIN

**SRS AIRBAG**

D&P SNGL HI+SD (FR) + CSA + KN

**STABILIZER**

FR & RR

**STARTER HOLDING CONTROL**

WITHOUT

**STARTING SYSTEM**

PUSH (WITH SMART)

**STEERING COLUMN**

TILT & TELESCOPIC

**STEERING WHEEL**

3-SPOKE LEATHER

**STEERING WHEEL SWITCHES**

DISP (H) + TEL + VOICE + AUDIO + ACC + ASL + LDA

**SUN ROOF & MOON ROOF**

WITHOUT

**SUN VISOR**

PVC (D&P MIRROR + LIGHT)

**SWITCH TRONICS**

STRAIGHT W/O PADDLE

**TIRE & DISC WHEEL**

205/55R16 AL-1

**TOOL (PLANT INSTALL)**

H/N WRENCH + JACK HANDLE

**TRAFFIC SIGN RECOGNITION**

WITH CAMERA

**TRUNK & DECK CARPET & MAT**

NEEDLE PUNCH

**TYRE INFLATION PRESSURE WARNING**

WITH (433MHZ) DIRECT

**VSC**

WITH (AHB-R)

**WASHER FLUID**

ETHANOL (FULL)

**WASHER FLUID LEVEL WARNING**

WITHOUT

**WHEEL CAP**

CENTRE ORNAMENT (FOR ALUMI)

**WINDSHIELD DEICER**

WITHOUT



WINDSHIELD GLASS

LAMINATED GREEN 70% AC

WINDSHIELD WIPER CONTROL

AUTO (RAIN SENSOR)

WIRELESS CHARGER

WITH

WIRELESS DOOR LOCK

SMART ENTRY LESS

## Cronologie

S-au găsit 3 înregistrări

Cronologia înregistrărilor pentru acest vehicul

### Ultimele înregistrări

2019-01  Țară necunoscută



**A fost fabricat**

Țara (sau statul) indică fie locația centrului de producție, uzina de asamblare sau adresa de înregistrare a producătorului. Data poate fi aproximativă.

2019-12  România



**A fost înmatriculat**

Înregistrarea reprezintă un eveniment administrativ. Acest lucru ar putea fi legat de o schimbare de proprietar, documente etc

2023-02  România



**A fost verificat**

A fost înregistrat un eveniment de inspecție tehnică (cunoscut și sub denumirea de ITP, test tehnic sau test de control al emisiilor). Pot fi incluse atât instanțe reușite, cât și eșuate.



+31

## Surse de date

Am verificat 900+ de surse de date în **35 de țări**