

Toyota Corolla



VIN: SB1K93BE60E231159

Benzină

2021

Generat pe 04.02.2025, 09:13



Odometru

✓ Arată bine



Statut legal

✓ Arată bine



Daune

✓ Arată bine



+31

Surse de date

Am verificat 900+ de surse de date în 35 de țări

Furt

Vehiculul este în prezent marcat ca furat? A fost furat în trecut? A fost recuperat?



Nu s-au găsit probleme

Nu am găsit nicio înregistrare că vehiculul a fost furat.



Notă

Am încheiat verificarea bazelor de date ale poliției privind vehiculele furate din 8 țări: +2

Iată ce am verificat:



Căutat drept furat

✓ Nu s-a găsit nicio înregistrare



Furat în trecut

✓ Nu s-a găsit nicio înregistrare Starea actuală necunoscută



Furat în trecut

✓ Nu s-a găsit nicio înregistrare Vehiculul a fost recuperat

Baza de date aparținând poliției cu vehicule furate, **verificare finalizată în:**

România

Lituania

Slovacia

Statele Unite ale Americii

Italia

Cehia

Slovenia

Suedia


Odometru

Există semne conform cărora kilometrajul a fost dat înapoi sau discrepanțe ale kilometrajului?



Notă

Ultimul kilometraj cunoscut: 28.565 km



Disclaimer (declinarea responsabilității): acest grafic reprezintă o tendință estimată a kilometrajului. Deși se bazează pe înregistrări reale de kilometraj disponibile pentru acest vehicul, există lacune având în vedere că evoluția kilometrajului nu este înregistrată în mod constant. Pentru a lua în considerare aceste date lipsă, aplicăm un model patentat de analiză a datelor care prezice modul în care probabil s-a schimbat kilometrajul între evenimentele înregistrate. Acest lucru ajută la furnizarea unei imagini mai complete a utilizării vehiculului în timp.

Statut legal

A trecut vehiculul inspecțiile tehnice? A fost notat drept casat?



Notă

Inspecția tehnică a fost transmisă pe 09.2024 în România

Legal



Inspecție tehnică periodică (ITP)

A trecut

09.2024

România

A trecut cu succes inspecția tehnică

Valabil până la 09.2026



Casat

✓ Nu s-a găsit nicio înregistrare

Nu există nici o înregistrare că vehiculul a fost marcat drept casat

Daune

Acest vehicul a fost avariat în trecut ? Care a fost valoarea daunelor?

✓ Nu s-au găsit probleme

Înregistrări de daune



Ocazional pot apărea inexactități, mai ales la verificarea vehiculelor vechi. Atelierele clandestine de reparații pot deghiza ilegal defectele sau daunele vehiculelor, fără să declare nicăieri existența lor. Uneori până și plăcuțele VIN ale vehiculului pot fi înlocuite. Avem o varietate de metode de a detecta chiar și astfel de infracțiuni, dar este imposibil de oferit o garanție de 100%.

Dezastre naturale

Locația vehiculului a fost înregistrată în zona unui dezastru natural?

✓ Nu s-au găsit probleme

Locația vehiculului nu a fost înregistrată în zona unui dezastru natural

Valoarea de piață

Cu cât s-a vândut vehiculul în trecut? Care este în medie prețul vehiculelor din acest model și an?

i Notă

- Prețul mediu de pe piață pentru un astfel de vehicul: 91.859 RON
- Atenție la problemele ascunse dacă vehiculul a fost la vânzare la un preț semnificativ mai mic decât prețul actual!

Valoarea de piață azi pentru Toyota Corolla 2021

Valoarea de piață este determinată prin examinarea prețului unui anumit model de mașină (fabricat în același an) în țara în care a fost generat raportul. Analizăm datele din ultimele 6 luni.

Cel mai mic preț

88.201 RON

Prețul mediu

91.859 RON

Cel mai mare preț

100.210 RON

Emisii

Câte emisii de CO2 produc vehiculele din acest model/an?



Notă

Emisii CO2: A (102 g/km)

Emisii CO2

Emisiile CO2 ale
vehiculului tău

102 g/km Clasă **A**

Până la 120

120 - 140

140 - 155

155 - 165

165 - 190

190 - 225

225 și peste

Emisii CO₂ g/km

Specificații și echipare

Ce specificații și echipamente sunt înregistrate pentru acest vehicul?



Notă

Verificați dacă specificațiile și echipamentul acestui vehicul se potrivesc cu datele furnizate de vânzător.

Identificare și specificații tehnice



Producător

Toyota



Model

Corolla



Descriere

Corolla



Tip caroserie

Hatchback



An de fabricație

2021



Capacitate cilindrică

1,8 l



Putere motor

72 kW (97 cp)



Cuplu
142 Nm



Tip combustibil
Benzină



Cutie de viteze
Automată



Tip transmisie
Tracțiune față (FWD)



Culoare
Gri



Nr. uși
5



Amplasarea volanului
Volan pe stânga



Nr. cilindri
4

Echipare

Cum a fost primit de la producător

A/C

AUTO (DUAL MODE)

ACCELERATOR PEDAL

ELECTRIC TYPE

ACCESSORY CONNECTOR (NO 2)

WITHOUT

AIR BAG MANUAL ON-OFF SW

P SEAT WITH INDICATOR

ANTI-THEFT SYSTEM

IMMOBILIZER

AUDIO

T1 (8") DAB 6SP

AVS (TEMS)

WITHOUT

BACK MONITOR

CAMERA + W/H

ABS

WITH

ACCESSORY CONNECTOR (NO 1)

CONSOLE BOX

ADDITIONAL HEATER

WITHOUT

ANTENNA

SHARK + DAB

ASSIST GRIP

FR2, RR2

AUDIO JACK

WITH

BACK GLASS

SOLAR GREEN WITH AERO FIN

BLACK OUT

WITH (DOOR SASH + WHEEL HOUSE)

BRAKE CONT VALVE- EDB CONTROL

EBD

CATALYTIC CONVERTER

9R-08+11R-11 (GPF)

CHILD RESTRAINT SYSTEM

WITH (ISO FIX) *2

CLEARANCE & BACK SONAR

WITHOUT

COAT HOOK

WITH

CONSOLE BOX

RESIN

CRUISE CONTROL

WITH ACC, ALL SPEED

DATA COMMUNICATION MODULE

REG CMPL ECALL

DESTINATION PACKAGE

WITHOUT

DOOR ARM REST

FABRIC

DOOR INNER GARNISH

PLATING + RESIN

DOOR OUTSIDE HANDLE

BODYCOLOUR D: W/ KEY P:W/O

DOOR SCUFF PLATE

RESIN + RESIN

DOOR TRIM ORNAMENT

RESIN + SATIN PLATING

ECO PACKAGE

WITHOUT

EXHAUST EMISSION CONTROL

EURO 6C WITH OBD

FENDER LINER

FR (LOW) & RR (LOW)

FRONT DIFFERENTIAL

2.834

FRONT FOG LAMPS

WITH

BUMPER

PP PNT WITH PNT FOG CVR

CHILD PROTECTOR

WITH (REAR DOOR ONLY)

CLEAN AIR FILTER

POLLEN FILTER

CLOCK

AUDIO + METER

COLD AREA PACKAGE

WITHOUT

COOLER REAR DUCT

WITHOUT

CUP HOLDER

FR2/BLACK

DAYTIME RUNNING LIGHT SYSTEM

WITH (LED TYPE)

DESTINATION PACKAGE (EXC/ ERP)

WITHOUT

DOOR BELT MOULDING

BLACK

DOOR INSIDE HANDLE

PLATING

DOOR POCKET

FR&RR

DOOR TRIM

FR: SOFT RR: HARD W/O NV FELT

DOOR WINDOW FRAME

BLACK + RESIN

EMERGENCY BRAKE LIGHTS

WITH

EXHAUST TAIL PIPE & DIFFUSER

SINGLE WITHOUT DIFFUSER

FLOOR MAT ILA

TEXTILE HI LHD HV 830GR

FRONT FLOOR CARPET AND MAT

DILOUR

FRONT HEADRESTS

VERTICAL X2

FRONT PERSONAL LAMP

WITH (BULB)

FRONT SEAT

SPORTY

FRONT SEAT VERTICAL ADJUSTER

D&P: 2 WAY MANUAL

FRONT SUSPENSION

MACPHERSON STRUT (FF)

FUEL CAUTION LABEL

E5, E10 REG.

GLOVE BOX LAMP

WITH

GRILL SHUTTER

WITHOUT

HEADLAMP AIMING

RH AIMING (FOR LHD CAR)

HEADLAMP LEVELLING

MANUAL

HIGH MOUNT STOP LAMP

WITH (LED TYPE, SPOILER)

HILTI SPEC

WITHOUT

ILLUMINATED ENTRY SYSTEM

WITH (ROOM + MAP LAMP)

INSTRUMENT FINISH PANEL

ADP/MC: STAIN PLATING

INTERMITTENT WIPER

TIME ADJUSTMENT

KEY PLATE

SMART-MASTER 2

LANE KEEP ASSIST (LKA)

WITH (LTA)

LIGHT REMIND WARNING

WITH (BUZZER+AUTOCUT)

LUGGAGE AND BACK DOOR RELEASE

ELEC LOCK

LUGGAGE ROOM LAMP

WITH

FRONT PILLAR GARNISH

BASE

FRONT SEAT SLIDE

260MM D&P MANUAL

FRONT SIDE GLASS

GREEN 70%

FRONT WHEEL BRAKE

15" DISC (B)

GLOVE BOX

WITH DAMPER

GRADE PACKAGE

WITHOUT

HEAD UP DISPLAY

WITHOUT

HEADLAMP CLEANER

WITHOUT

HEADLAMPS

PARABOLA LED + AHB

HILL ASSIST CONTROL (HAC)

WITH (HAC3)

I/P CENTER CLUSTER

SATIN PLATING/PIANO BLACK

INSIDE REAR VIEW MIRROR

EC MIRROR

INSTRUMENT PANEL

SOFT W/ STITCH (P-PAD)

JACK

WITH

LANE CHANGE ASSIST

WITHOUT

LIGHT CONTROL SYSTEM

ALC + FMH 3 POSITION

LOWER BACK AND BACK DOOR GARNISH

WITH

LUGGAGE ROOM & DECK TRIM

SIDE + RR2 HOOK (UNI)

LUGGAGE ROOM SEPARATOR

WITHOUT

LUGGAGE TRAY

WITHOUT

MICROPHONE

WITH

MUD GUARDS

WITHOUT

OUTSIDE REAR VIEW MIRROR

ELECTRIC, HEATER

PACKAGE OPTION 1

WITHOUT

PACKAGE OPTION 5

WITHOUT

PACKAGE TRAY TRIM & TONNEAU COVER

NEEDLE PUNCH

PARKING BRAKE

EPB

POWER WINDOWS

FR & RR 4 ONE TOUCH UP/DOWN HI

RADIATOR LOWER GRILLE

PAINT WITH PAINT

REAR BUMPER

PP COLOUR WITH R/F

REAR CONSOLE BOX

FAB W/O STITCH W/ SLIDE P-BLK

REAR QUARTER GLASS

WITHOUT

REAR SEAT BELT

SIDE ELR PT FL CTR ELR

REAR SPOILER

ONE MOLD WITH BD + LOWERSIDE

REAR WINDOW DEFOGGER

WITH (HEAVY WITH TIMER)

REFRIGERANT CORRESPONDENT

HF01234F

REGULATION COMPLIANCY

WVTA LABEL

ROCKER & DOOR LOWER MOULDING

WITH (COLOR)

MALTA SPEC

WITHOUT

MODEL NAME MARK

COROLLA

MULTI INFO DISPLAY

WITH (7")

OWNER'S MANUAL

WITHOUT

PACKAGE OPTION 4

WITHOUT

PACKAGE OPTION 6

WITHOUT

PAINT PROTECTION WAX/FILM

WRAP GUARD

POWER DOOR LOCK

WITH

RADIATOR GRILLE

PAINT

REAR ARM REST

WITH

REAR COMBINATION LAMP

LED + LIGHT GUIDE

REAR HEADRESTS

VERTICAL X3

REAR SEAT

6:4 SPLIT FOLD

REAR SIDE GLASS

GREEN 70%

REAR SUSPENSION

DOUBLE WISHBONE (FF)

REAR WINDOW WIPER

WITH (INT + WASHER)

REGISTER

FR ONLY KNOB SATIN

REMOTE SERVICE PACKAGE

NOTIFICATION PACKAGE

ROOF RAILS

WITHOUT

ROOM LAMP

DOME TYPE (BULB)

SAFETY SENSE

TSS2

SEAT BELT WARNING

FR & RR (BUZZER + LAMP)

SEAT LUMBAR SUPPORT

WITH (POWER D)

SHIFT LEVER & KNOB

CVT SMOOTH LEATHER

SHIFT POSITION INDICATOR

WITH (METER)

SIDE TURN SIGNAL LAMP

WITH OUTER MIRROR

SPEED WARNING

WITH ASL

SRS AIRBAG

D&P SNGL HI+SD (FR) + CSA + KN

STARTING SYSTEM

PUSH (WITH SMART)

STEERING COLUMN

TILT & TELESCOPIC

STEERING WHEEL SWITCHES

DISP (H) + TEL + VOICE + AUDIO + ACC + ASL + LDA

SUN VISOR

PVC (D&P MIRROR + LIGHT)

TIRE & DISC WHEEL

205/55R16 SM AL-SPORT

TOOL (PLANT INSTALL)

WITH

TRAFFIC SIGN RECOGNITION

WITH

TYRE INFLATION PRESSURE WARNING

WITH 433MHZ

VEHICLE APPROACH NOTICE

WITH

WASHER FLUID

ETHANOL (FULL)

ROUGH ROAD PACKAGE

WITHOUT

SEAT BACK POCKET

WITH (PASSENGER ONLY)

SEAT HEATER

WITH (D+P CUSHION & BACK)

SEAT MATERIAL

FABRIC B MID

SHIFT LEVER BOOT

WITH SATIN PLATING + P-BLK BEZEL

SIDE PROTECTION MOULDING

WITHOUT

SPARE TYRE

TEMP 125/70D17

SPEEDOMETER

KM/H + SATIN

STABILIZER

FR & RR

STEERING

EPS (BRUSHLESS D-MOTOR)

STEERING WHEEL

3-SPOKE LEATHER

SUN ROOF & MOON ROOF

WITHOUT

SWITCH TRONICS

STRAIGHT W/O PADDLE

TIRE & DISC WHEEL 2

OTHER SPEC (010) IS TAKEN

TOWING PACKAGE

WITHOUT

TRUNK & DECK CARPET & MAT

NEEDLE PUNCH S FLOOR HI-POSI

TYRE PRESS CAUTION LABEL

ENGLISH

VSC

WITH (AHB-R)

WHEEL CAP

CENTRE ORNAMENT (FOR ALUMI)

WINDSHIELD DEICER

WITHOUT

WIRELESS CHARGER

WITHOUT

WINDSHIELD GLASS

LAMINATED GREEN 70% AC

WIRELESS DOOR LOCK

SMART (SMART ENTRY LESS)

Cronologie

S-au găsit 3 înregistrări

Cronologia înregistrărilor pentru acest vehicul

Ultimele înregistrări

01.2021 🌐 Țară necunoscută



A fost fabricat

Țara (sau statul) indică fie locația centrului de producție, uzina de asamblare sau adresa de înregistrare a producătorului. Data poate fi aproximativă.

07.2021 🇷🇴 România



A fost înmatriculat

Înregistrarea reprezintă un eveniment administrativ. Acest lucru ar putea fi legat de o schimbare de proprietar, documente etc

09.2024 🇷🇴 România



A fost verificat

A fost înregistrat un eveniment de inspecție tehnică (cunoscut și sub denumirea de ITP, test tehnic sau test de control al emisiilor). Pot fi incluse atât instanțe reușite, cât și eșuate.



+31

Surse de date

Am verificat 900+ de surse de date în **35 de țări**