

# Škoda Superb

VIN: TMBAH9NP6M7041060

Diesel

2020

Generat pe 2025-01-21 06:50



## Odometru

✓ Arată bine



## Statut legal

✓ Arată bine



## Daune

⚠ Necesită atenție



+31

## Surse de date

Am verificat 900+ de surse de date în 35 de țări

## Furt

Vehiculul este în prezent marcat ca furat? A fost furat în trecut? A fost recuperat?



### Nu s-au găsit probleme

Nu am găsit nicio înregistrare că vehiculul a fost furat.



### Notă

Verificarea bazei de date a poliției privind vehiculele furate finalizată în 8 țări:



+2

## Iată ce am verificat:



### Căutat drept furat

✓ Nu s-a găsit nici o înregistrare



### Furat în trecut

✓ Nu s-a găsit nici o înregistrare

Starea actuală necunoscută



### Furat în trecut

✓ Nu s-a găsit nici o înregistrare

Vehiculul a fost recuperat

Baza de date aparținând poliției cu vehicule furate, verificare finalizată în:



România



Statele Unite ale Americii



Danemarca



Lituania



Slovacia



Suedia



Slovenia




Cehia

# Odometru

Există semne conform cărora kilometrajul a fost dat înapoi sau discrepanțe ale kilometrajului?

## i Notă

Ultimul kilometraj cunoscut: 81.312 km



**Disclaimer (declinarea responsabilității):** acest grafic reprezintă o tendință estimată a kilometrajului. Deși se bazează pe înregistrări reale de kilometraj disponibile pentru acest vehicul, există lacune având în vedere că evoluția kilometrajului nu este înregistrată în mod constant. Pentru a lua în considerare aceste date lipsă, aplicăm un model patentat de analiză a datelor care prezice modul în care probabil s-a schimbat kilometrajul între evenimentele înregistrate. Acest lucru ajută la furnizarea unei imagini mai complete a utilizării vehiculului în timp.

## Statut legal

A trecut vehiculul inspecțiile tehnice? A fost notat drept casat?

## i Notă

Inspecția tehnică a fost transmisă pe 2024-02 în  România

Legal

✓= **Inspecție tehnică periodică (ITP)** **A trecut** 2024-02 🇷🇴 România

A trecut cu succes inspecția tehnică Valabil până la 2026-02

↺↻ **Casat** ✓ Nu s-a găsit nici o înregistrare Nu există nici o înregistrare că vehiculul a fost marcat drept casat

## Daune

Acest vehicul a fost avariat în trecut ? Care a fost valoarea daunelor?

⚠ **Ai grijă!**  
Vehiculul a fost avariat de 2 ori!

i **Notă**  
Daunele minore nu vor afecta în mod normal siguranța vehiculului și nu vor cauza probleme structurale

## Înregistrări de daune



Daune pe partea stângă:

Stânga / Portieră față

2022-07

🇷🇴 România

### Daune

Părți afectate

**Partea stângă**

Costul estimativ al reparațiilor

**0 RON – 2.000 RON**

Cauza posibilă

**Necunoscut**



Daune pe partea dreaptă:

Daune pe partea dreaptă:

Dreapta / Portieră față

Spate / Bară de protecție

Spate stânga / Bară de protecție

Spate dreapta / Bară de protecție

2024-03

România

## Daune

Părți afectate

Partea dreaptă

Spate

Costul estimativ al reparațiilor

**2.001 RON – 6.000 RON**

Cauza posibilă

**Necunoscut**

Categoriile de daune

Părți exterioare ale caroseriei

**Disclaimer (declinarea responsabilității):** Majoritatea înregistrărilor de daune sunt legate de accidente, dar uneori nu este acesta cazul. Unele înregistrări provin din alte surse cum ar fi serviciile specializate pe lucrări de caroserie, cereri de daune, licitații sau inspecții ale vehiculelor. Aceste înregistrări arată că starea vehiculului a fost evaluată, chiar dacă nu a fost din cauza unui accident.

## Dezastre naturale

Locația vehiculului a fost înregistrată în zona unui dezastru natural?

✓ Nu s-au găsit probleme

Locația vehiculului nu a fost înregistrată în zona unui dezastru natural

## Valoarea de piață

Cu cât s-a vândut vehiculul în trecut? Care este în medie prețul vehiculelor din acest model și an?

i Notă

- Prețul mediu de pe piață pentru un astfel de vehicul: 107.242 RON
- Atenție la problemele ascunse dacă vehiculul a fost la vânzare la un preț semnificativ mai mic decât prețul actual!

## Valoarea de piață azi pentru Škoda Superb 2020

Valoarea de piață este determinată prin examinarea prețului unui anumit model de mașină (fabricat în același an) în țara în care a fost generat raportul. Analizăm datele din ultimele 6 luni.

Cel mai mic preț

91.346 RON

Prețul mediu

107.242 RON

Cel mai mare preț

121.088 RON

## Emisii

Câte emisii de CO<sub>2</sub> produc vehiculele din acest model/an?

### *i* Notă

Emisii CO<sub>2</sub>: B (129 g/km)

## Emisii CO<sub>2</sub>

Emisiile CO<sub>2</sub> ale  
vehiculului tău

129 g/km Clasă **B**

Până la 120

120 - 140

140 - 155

155 - 165

165 - 190

190 - 225

225 și peste

Emisii CO<sub>2</sub> g/km

## Specificații și echipare

Ce specificații și echipamente sunt înregistrate pentru acest vehicul?

### *i* Notă

Verificați dacă specificațiile și echipamentul acestui vehicul se potrivesc cu datele furnizate de vânzător.

## Identificare și specificații tehnice



Producător

Škoda



Model

Superb



Tip caroserie

Sedan



An de fabricație

**2020**



Capacitate cilindrică

**2 l**



Putere motor

**110 kW (148 cp)**



Tip combustibil

**Diesel**



Cutie de viteze

**Automată**



Tip transmisie

**Tracțiune față (FWD)**



Culoare

**Negru**



Amplasarea volanului

**Volan pe stânga**



Nr. cilindri

**4**



Nr. angrenaje

**7**



Nr. locuri

**5**



Cod motor

**DTSB**

---

## Echipare

Cum a fost primit de la producător

---

**OB5**

WHEELBASE

**OF5**

FUEL SYSTEM FOR DIESEL ENGINE

**OFA**

STANDARD MANUFACTURING SEQUENCE

0IJ

INSTALLATION DIFFERENTIATION FOR TRANSMISSION "DQ381" -- VEHICLE COMPONENTS --

0K0

WITHOUT ALTERNATIVE DRIVE SYSTEM

0M4

FUEL TANK

0NB

NAMEPLATE SET IN BASIC STYLE

0P0

REAR EXHAUST TAILPIPE (STANDARD)

0RF

WITH ELECTRONIC STEERING COLUMN LOCK

0SC

LABELS/PLATES IN ENGLISH

0TD

FLOOR MATS IN FRONT AND REAR

0XH

INFORMATION KIT IN ROMANIAN

0Y1

STANDARD CLIMATIC ZONES

0YC

WEIGHT RANGE 3 INSTALLATION CONTROL ONLY, NO REQUIREMENT FORECAST

1AQ

BRS FOR VEHICLES WITHOUT ELECTRIC DRIVE (ESC AND ELECTRIC BRAKE BOOSTER)

1D0

WITHOUT TRAILER HITCH

1E9

WITHOUT ACTIVATED CARBON CANISTER WITH SCR

1EX

SPECIAL IDENTIFICATION PLATE FOR EC FOR M1 PASSENGER VEHICLE

1G4

SPACE-SAVING SPARE WHEEL

1JA

REAR SHOCK ABSORPTION, BASIC VERSION 1

1N3

SPEED-RELATED VARIABLE STEERING ASSIST (SERVOTRONIC)

1NL

TRIMS FOR ALLOY WHEELS

1PF

STANDARD WHEEL BOLTS

1Q3

MASS DAMPER FOR STEERING WHEEL, XX HZ

1S1

TOOL KIT AND JACK

1SA

WITHOUT ADDITIONAL FRONT UNDERBODY GUARD

1X0

FRONT WHEEL DRIVE

1Z0

INITIAL STANDARD FUEL FILLING

1ZK

DISK BRAKES IN FRONT

20A

WITHOUT ELECTRIC MOTOR ( HYBRID )

2A0

WITHOUT DELIVERY EQUIPMENT

2EM

DISK BRAKES IN REAR

2F0



WITHOUT LOCKING AND STARTING SYSTEMS

2H0

WITHOUT "DRIVE SELECT"

2JB

STANDARD BUMPERS

2WA

WITHOUT ADDITIONAL TIRES

2ZH

LEATHER-WRAPPED MULTIFUNCTION STEERING WHEEL

3B4

CHILD SEAT ANCHOR FOR CHILD SEAT SYSTEM ISOFIX

3C7

3-POINT SEAT BELT FOR CENTER REAR SEAT

3CA

WITHOUT PARTITION

3D2

CENTER CONSOLE

3FA

WITHOUT ROOF INSERT (STANDARD ROOF)

3G0

WITHOUT CHILD SEAT ANCHOR FRONT (ISOFIX)

3GA

WITHOUT CARGO AREA

3H0

WITHOUT BACKREST RELEASE FOR FRONT SEATS

3L3

MANUAL HEIGHT ADJUSTMENT FOR FRONT SEATS

3LE

DOOR AND SIDE TRIM PANEL

3N3

STORAGE COMPARTMENTS IN TRUNK

3NU

REAR SEAT BENCH UNSPLIT, BACKREST SPLIT FOLDING WITH CENTER ARMREST

3QT

3-POINT SEAT BELTS IN FRONT, WITH PRETENSIONER AND HEIGHT ADJUSTMENT

3S0

WITHOUT ROOF RAILS/ROOF LOAD RACK

3T2

THREE REAR HEAD RESTRAINTS

3U1

FOLDING TRUNK COVER

3W6

ADDITIONAL INTERIOR NOISE SUPPRESSION

3X0

WITHOUT LOAD-THROUGH HATCH

3Y0

WITHOUT ROLL-UP SUNSHADE

3ZU

3-POINT SEAT BELTS, OUTER REAR WITH ECE LABEL

4A3

SEAT HEATER FOR FRONT SEATS SEPARATELY CONTROLLED

4D0

WITHOUT SEAT VENTILATION/MASSAGE SEAT

4E7

TAILGATE/TRUNK LID POWER CLOSING

4GF

WINDSHIELD IN HEAT-INSULATING GLASS

4H5

POWER-OPERATED CHILD SAFETY LOCK

4I7

CENTRAL LOCKING SYSTEM "KEYLESS-GO" WITHOUT SAFELOCK

4KC

SIDE AND REAR WINDOWS IN HEAT-INSULATINGGLASS

4L1

DIMMING BREAKAWAY INTERIOR REARVIEW MIRROR

4UP

DRIVER AND FRONT PASSENGER AIRBAG WITH KNEE AIRBAG AND FRONT PASSENGER AIRBAG DEACTIVATION

4V0

WITHOUT FRONT PASSENGER SEAT CONTROL

4X4

SIDE AIRBAG IN FRONT AND REAR WITH CURTAIN AIRBAG

4ZB

BRIGHT MOLDINGS

5C0

WITHOUT SPECIAL BODY MEASURES

5D1

CARRIER FREQUENCY 433.92 MHZ-434.42 MHZ

5J0

WITHOUT REAR SPOILER

5K5

TRANSIT COATING FILM WITH ADDITIONAL TRANSPORT PROTECTION MEASURES

5MI

DECORATIVE INSERTS

5RQ

RIGHT EXTERIOR MIRROR, CONVEX

5SJ

LEFT EXTERIOR MIRROR, CONVEX

5XI

SUN VISORS WITH MIRROR, ILLUMINATED, AIRBAG LABEL ON SUN VISOR

5ZF

FRONT HEAD RESTRAINTS

6A0

WITHOUT FIRE EXTINGUISHER

6E3

CENTER ARMREST IN FRONT

6FF

BODY-COLORED EXTERIOR MIRROR HOUSINGS AND VARIOUS ADD-ON PARTS

6I0

WITHOUT LANE KEEPING SYSTEM

6K4

FORWARD COLLISION WARNING INCL. AUTONOMOUS EMERGENCY BRAKING, FOR ADAPTIVE CRUISE CONTROL "HIGH"

6KH

RADIATOR GRILLE

6M0

WITHOUT TIE DOWN STRAPS/NET/POCKET

6N0

WITHOUT MUD FLAP

6NA

UNSPLIT MOLDED HEADLINER

6Q2

LEATHER GEARSHIFT KNOB/HANDLE

6T1

INTERIOR LIGHT IN FOOTWELL

6XW

EXTERIOR MIRRORS, AUTO-DIMMING, POWER-FOLDING/ADJUSTABLE, SEPARATELY HEATED

7AA

ELECTRONIC ENGINE IMMOBILIZER

7B3

12-VOLT SOCKET(S)

7E0

WITHOUT HEAT ACCUMULATOR/AUXILIARY HEATER

7K1

DIRECT TIRE PRESSURE MONITORING SYSTEM

7L6

START/STOP SYSTEM WITH REGENERATIVE BRAKING

7M4

SCUFF PLATES IN DOOR APERTURES

7P4

MANUALLY ADJUSTABLE LUMBAR SUPPORT IN FRONT SEATS

7QA

WITHOUT CD/DVD FOR NAVIGATION

7U0

STANDARD ENGINE STARTER

7W2

WITH EXTENDED SAFETY SYSTEM (PROACTIVE PASSENGER PROTECTION SYSTEM, BASIC AND FRONT)

7X1

PARK DISTANCE CONTROL

7Y0

WITHOUT LANE CHANGE ASSIST

7ZU

VEHICLE CLASS DIFFERENTIATION 3V0

8AR

RADIO "GAMMA" WITH REMOVABLE OPERATING PANEL

8FA

WITHOUT SECOND BATTERY

8G4

MATRIX BEAM

8GU

ALTERNATOR 140 A

8IX

LED HEADLAMPS WITH CORNERING LIGHT (SEPARATE DAYTIME RUNNING LIGHTS WITH SPECIAL CLASS-A SURFACE)

8K3

SEPARATE DAYTIME RUNNING LIGHTS WITH AUTOMATIC HEADLAMP ACTIVATION AND COMING HOME FEATURE

8M0

WITHOUT REAR WINDOW WIPER AND WASHER SYSTEM

8N6

WINDSHIELD WIPER INTERMITTENT CONTROL WITH LIGHT/RAIN SENSOR

8Q5

HEADLIGHT RANGE ADJUSTMENT, AUTOMATIC/ DYNAMIC, WITH CORNERING LIGHT (AFS 1)

8QL

KEY FOR LOCKING SYSTEM WITH REMOTE CONTROL

8RM

8 SPEAKERS (PASSIVE)

8S1

READING LIGHT IN FRONT

8T8

ADAPTIVE CRUISE CONTROL (WITH "FOLLOW-TO-STOP") AND SPEED LIMITER

8TB

REAR FOG LAMP

8WB

FRONT FOG LAMPS

8X1

HEADLAMP WASHER SYSTEM

8Y1

TWO-TONE HORN

8Z5

NOT HOT COUNTRY

8ZQ

ANTENNA FOR FM RECEPTION ONLY, DIVERSITY

9AK

CLIMATRONIC WITH IMPACT PRESSURE CONTROL, CFC-FREE

9D0

WITHOUT PREPARATION FOR TWO-WAY RADIO INSTALLATION

9HA

WITHOUT ADDITIONAL MALFUNCTION DISPLAY

9JB

SMOKER'S PACKAGE, ASHTRAY IN FRONT AND REAR

9M9

FUEL-FIRED PARKING HEATER WITH RADIO REMOTE CONTROL

9P5

VISUAL AND ACOUSTIC SEAT BELT REMINDER, ELECTRIC CONTACT

9S6

MULTI-FUNCTION DISPLAY/ON-BOARD COMPUTER"COLOUR"

9T1

HEATED WASHER NOZZLES IN FRONT

9TC

ADDITIONAL REFLECTORS (DOOR AREA)

9WJ

POWER SUPPLY/TV SIGNAL FOR CUSTOMIZED INSTALLATION

9Z0

OPERATING VOLTAGE 12 V

9ZX

MOBILE PHONE INTERFACE

A8C

COMFORT EQUIPMENT

AV1

DRIVING ON THE RIGHT

B0A

COMPONENT PARTS SET WITHOUT COUNTRY-SPECIFIC BUILDING REGULATION

B43

TYPE APPROVAL COUNTRY ROMANIA

C6U

ALLOY WHEELS 7J X 17

DN4

4-CYL. TURBO DIESEL ENGINE 2.0 L/110 KW (4V) TDI COMMON RAIL; B.ENGINE T37/T6F  
TS1/TR1/T0P/T0N/T13/T29/TM4/TD1/TI9/T1I

E0A

NO SPECIAL EDITION

EA2

1 YEAR FOLLOW-ON WARRANTY, MAX. 60 000 KM

EF0

WITHOUT ECO FUNCTION

EL5

ONLINE SERVICE, WITH OCU, WITH HEAD UNITCODING, WITHOUT ENGINE IMMOBILIZER INTERCONNECTION

EM1

DRIVER ALERT SYSTEM

ER1

REGIONAL CODE " ECE " FOR RADIO

ES0

WITHOUT VEHICLE INLET

EVO

WITHOUT CHARGING CABLE

F0A

NO SPECIAL PURPOSE VEHICLE, STANDARD EQUIPMENT

FB0



STANDARD PAINT COATING

FM0

BASIC EQUIPMENT VARIANT

G01

SHOCK ABSORPTION IN FRONT

G1C

SEVEN-SPEED AUTOMATIC TRANSMISSION

GM1

STANDARD ELECTRONIC ENGINE SOUND

GP1

VEHICLES WITH SPECIAL UPGRADE MEASURES

IA0

WITHOUT BRACKET

IG1

CURB WEIGHT RANGE 1

J2D

BATTERY 380 A (68 AH)

J85

SUSPENSION RANGE 85

K8B

NOTCHBACK

KA0

WITHOUT CAMERA SYSTEMS/ACCIDENT SENSORS

KK3

REFRIGERANT R1234YF

KS0

WITHOUT HEAD-UP DISPLAY

L08

SUSPENSION RANGE 08 INSTALLATION CONTROL ONLY, NO REQUIREMENT FORECAST

LOL

LEFT-HAND DRIVE

N0H

SEAT TRIM COVERS IN FABRIC

ND0

WITHOUT ADAPTER

NZ2

PAN-EUROPEAN EMERGENCY CALL SERVICE

Q2J

COMFORT SEATS IN FRONT

QA0

WITHOUT CHILD SEAT

QG1

SERVICE INTERVAL PROLONGATION

QH1

VOICE CONTROL

QI6

SERVICE INDICATOR 30 000 KM OR 2 YEARS ( VARIABLE )

QJ1

CHROME PACKAGE

QK1

WITH MULTIFUNCTION CAMERA

QQ0

WITHOUT ADD. LIGHTS (INTERIOR LIGHTING)

QR0

WITHOUT COMPASS/ROAD SIGN DISPLAY/ DYNAMIC ROAD SIGN DISPLAY

QV3

DIGITAL RADIO RECEPTION

S4V

REGION

T3Y

4-CYLINDER DIESEL ENGINE 2.0 L UNIT 05L.D

U5A

INSTRUMENT CLUSTER, KM/H SPEEDOMETER

U9B

1 X USB TYPE C AND CD PLAYER

UG1

HILL START ASSIST

UH2

PARKING BRAKE

UK3

MECHANICAL REAR SEAT RELEASE

UP9

WITHOUT CLOCK

V0A

TIRES WITHOUT SPECIFICATION OF TIRE BRAND

VC0

WITHOUT REMOTE-CONTROLLED GARAGE DOOR OPENER

VF0

STANDARD PEDAL CLUSTER

VL3

EXTENDED AND PROACTIVE PEDESTRIAN PROTECTION

X4N

EQUIPMENT OPTIONS SUBSET FOR ROMANIA

## Cronologie

Cronologia înregistrărilor pentru acest vehicul

S-au găsit 5 înregistrări

Ultimele înregistrări

2020-01 🌐 Țară necunoscută



### A fost fabricat

Țara (sau statul) indică fie locația centrului de producție, uzina de asamblare sau adresa de înregistrare a producătorului. Data poate fi aproximativă.

2021-02 🇷🇴 România



### A fost înmatriculat

Înregistrarea reprezintă un eveniment administrativ. Acest lucru ar putea fi legat de o schimbare de proprietar, documente etc

2022-07 🇷🇴 România



### Daună detectată ⚠️

Avem indicii potrivit cărora acest vehicul a fost recunoscut ca avariat în această țară (sau stat). Pentru detalii, vă rugăm să consultați secțiunea „Daune”.

2024-02 🇷🇴 România



### A fost verificat

A fost înregistrat un eveniment de inspecție tehnică (cunoscut și sub denumirea de ITP, test tehnic sau test de control al emisiilor). Pot fi incluse atât instanțe reușite, cât și eșuate.

2024-03 🇷🇴 România



### Daună detectată ⚠️

Avem indicii potrivit cărora acest vehicul a fost recunoscut ca avariat în această țară (sau stat). Pentru detalii, vă rugăm să consultați secțiunea „Daune”.



+31

### Surse de date

Am verificat 900+ de surse de date în 35 de țări