

# Seat



VIN: VSSZZKLZNR008292

Diesel

Generat pe 2025-01-20 09:20



## Odometru

✓ Arată bine



## Statut legal

✓ Arată bine



## Daune

⚠ Necesită atenție



+31

## Surse de date

Am verificat 900+ de surse de date în 35 de țări

## Furt

Vehiculul este în prezent marcat ca furat? A fost furat în trecut? A fost recuperat?



### Nu s-au găsit probleme

Nu am găsit nicio înregistrare că vehiculul a fost furat.



### Notă

Verificarea bazei de date a poliției privind vehiculele furate finalizată în 8 țări: +2

## Iată ce am verificat:



### Căutat drept furat

✓ Nu s-a găsit nici o înregistrare



### Furat în trecut

✓ Nu s-a găsit nici o înregistrare

Starea actuală necunoscută



### Furat în trecut

✓ Nu s-a găsit nici o înregistrare

Vehiculul a fost recuperat

Baza de date aparținând poliției cu vehicule furate, **verificare finalizată în:**



România



Lituania



Slovacia




# Odometru

Există semne conform cărora kilometrajul a fost dat înapoi sau discrepanțe ale kilometrajului?

## Notă

Ultimul kilometraj cunoscut: 121.832 km



**Disclaimer (declinarea responsabilității):** acest grafic reprezintă o tendință estimată a kilometrajului. Deși se bazează pe înregistrări reale de kilometraj disponibile pentru acest vehicul, există lacune având în vedere că evoluția kilometrajului nu este înregistrată în mod constant. Pentru a lua în considerare aceste date lipsă, aplicăm un model patentat de analiză a datelor care prezice modul în care probabil s-a schimbat kilometrajul între evenimentele înregistrate. Acest lucru ajută la furnizarea unei imagini mai complete a utilizării vehiculului în timp.

## Statut legal

A trecut vehiculul inspecțiile tehnice? A fost notat drept casat?

## ✓ Nu s-au găsit probleme

Nu s-au găsit înregistrări despre statutul legal al acestui vehicul

## Legal



### Inspecție tehnică periodică (ITP)

✓ Nu s-a găsit nici o înregistrare

Nu au fost găsite înregistrări ale inspecției tehnice



### Casat

✓ Nu s-a găsit nici o înregistrare

Nu există nici o înregistrare că vehiculul a fost marcat drept casat

## Daune

Acest vehicul a fost avariat în trecut ? Care a fost valoarea daunelor?

### ⚠ Ai grijă!

Acest vehicul a fost avariat

### i Notă

Daunele minore nu vor afecta în mod normal siguranța vehiculului și nu vor cauza probleme structurale

## Înregistrări de daune



Daune frontale:

Față / Bară de protecție

Față dreapta / Bară de protecție

2023-05

 Germania

Daune

Costul estimativ al reparațiilor

**6.001 RON – 14.000 RON**


Cauza posibilă a daunelor

**Necunoscut**

**Disclaimer (declinarea responsabilității):** Majoritatea înregistrărilor de daune sunt legate de accidente, dar uneori nu este acesta cazul. Unele înregistrări provin din alte surse cum ar fi serviceurile specializate pe lucrări de caroserie, cereri de daune, licitații sau inspecții ale vehiculelor. Aceste înregistrări arată că starea vehiculului a fost evaluată, chiar dacă nu a fost din cauza unui accident.

## Dezastre naturale

Locația vehiculului a fost înregistrată în zona unui dezastru natural?

 **Nu s-au găsit probleme**

Locația vehiculului nu a fost înregistrată în zona unui dezastru natural

## Specificații și echipare

Ce specificații și echipamente sunt înregistrate pentru acest vehicul?

 **Notă**

Verificați dacă specificațiile și echipamentul acestui vehicul se potrivesc cu datele furnizate de vânzător.

## Identificare și specificații tehnice



Producător  
**Seat**



Tip caroserie

**Break**



Capacitate cilindrică

**2 l**



Putere motor

**110 kW (148 cp)**



Tip combustibil

**Diesel**



Cutie de viteze

**Automată**



Tip transmisie

**Tracțiune față (FWD)**



Amplasarea volanului

**Volan pe stânga**



Nr. cilindri

**4**



Cod motor

**DTTC**

---

## Echipare

Cum a fost primit de la producător

---

05Z

WITHOUT SPECIAL SPECIFICATIONS

0AE

FRONT STABILIZER

0B3

WHEELBASE

0BA

WITHOUT REAR STABILIZER

0F5

FUEL SYSTEM FOR DIESEL ENGINE

0FA

STANDARD MANUFACTURING SEQUENCE

0J

INSTALLATION DIFFERENTIATION FOR TRANSMISSION "DQ381" -- VEHICLE COMPONENTS --

0K0

WITHOUT ALTERNATIVE DRIVE SYSTEM

0N1

STANDARD REAR AXLE

0NA

WITHOUT NAMEPLATE SET (WITHOUT MODEL DESIGNATION)

0TA

WITHOUT FLOOR MATS

0VC

INFORMATION KIT IN GERMAN

0Y1

STANDARD CLIMATIC ZONES

0YL

WEIGHT RANGE 11 INSTALLATION CONTROL ONLY, NO REQUIREMENT FORECAST

1AQ

BRS FOR VEHICLES WITHOUT ELECTRIC DRIVE (ESC AND ELECTRIC BRAKE BOOSTER)

1E9

WITHOUT ACTIVATED CARBON CANISTER WITH SCR

1EX

SPECIAL IDENTIFICATION PLATE FOR EC FOR M1 PASSENGER VEHICLE

1G9

SPACE-SAVING SPARE WHEEL FOR TEMPORARY USE, RADIAL TIRE (5-HOLE)

1J2

SOUND DEADENING PACKAGE AND ADDITIONAL ENCLOSURES FOR SOME UNITS

1JA

REAR SHOCK ABSORPTION, BASIC VERSION 1

1KE

DISK BRAKES IN REAR

1M6

TRAILER HITCH MECHANICALLY SWIVELING AND POWER-DETACHABLE

1N3

SPEED-RELATED VARIABLE STEERING ASSIST (SERVOTRONIC)

1PE

WHEEL BOLTS WITH ANTI-THEFT PROTECTION (UNLOCKABLE)

1Q0

WITHOUT MASS DAMPER FOR STEERING WHEEL

1S1

TOOL KIT AND JACK

1SA

WITHOUT ADDITIONAL FRONT UNDERBODY GUARD

1T0

WITHOUT FIRST AID KIT AND WARNING TRIANGLE

1X0

FRONT WHEEL DRIVE

1Y3

ELECTRONIC DIFFERENTIAL LOCK XDS DYNAMIC TRACTION CONTROL

1Z0

INITIAL STANDARD FUEL FILLING

1ZK

DISK BRAKES IN FRONT

20A

WITHOUT ELECTRIC MOTOR ( HYBRID )

2A0

WITHOUT DELIVERY EQUIPMENT

2CN

VEHICLE CLASS DIFFERENTIATION 5FN

2F0

WITHOUT LOCKING AND STARTING SYSTEMS

2FT

SPORTS MULTIFUNCTION STEERING WHEEL WITH TIPTRONIC (LEATHER + WOOD)

2H0

WITHOUT "DRIVE SELECT"

2JD

SPORTS BUMPERS

2KW

LABELS/PLATES IN GERMAN, FRENCH, AND DUTCH

2WA

WITHOUT ADDITIONAL TIRES

2Z3

TYPE SIGN AND COMPANY LOGO

31F

FRONT LICENSE PLATE CARRIER (LARGE)

3C7

3-POINT SEAT BELT FOR CENTER REAR SEAT

3CX

NET PARTITION

3FU

BIG ROOF SYSTEM

3GH

VARIABLE CARGO AREA

3H0

WITHOUT BACKREST RELEASE FOR FRONT SEATS

3L3

MANUAL HEIGHT ADJUSTMENT FOR FRONT SEATS

3LD

DOOR AND SIDE TRIM PANEL



3NU

REAR SEAT BENCH UNSPLIT, BACKREST SPLIT FOLDING WITH CENTER ARMREST

3QC

3-POINT SEAT BELTS IN FRONT

3S2

BLACK ROOF RAILS

3T2

THREE REAR HEAD RESTRAINTS

3U2

SLIDING TRUNK COVER

3W0

WITHOUT ADDITIONAL NOISE SUPPRESSION MEASURES FOR PASSENGER COMPARTMENT

3ZU

3-POINT SEAT BELTS, OUTER REAR WITH ECE LABEL

4A3

SEAT HEATER FOR FRONT SEATS SEPARATELY CONTROLLED

4D0

WITHOUT SEAT VENTILATION/MASSAGE SEAT

4E6

SENSOR-CONTROLLED LUGGAGE COMPARTMENT OPENER

4G3

STORAGE COMPARTMENT, LEFT AND RIGHT 1ST ROW OF SEATS

4GW

HEAT INSULATING WINDSHIELD

4K5

CENTRAL LOCKING SYSTEM "KEYLESS ENTRY" WITH FINGERPRINT

4KF

SIDE WINDOWS IN HEAT-INSULATING GLASS, FROM B-PILLAR AND REAR WINDOW DARK TINTED

4L6

BREAKAWAY INTERIOR REARVIEW MIRROR, AUTO-DIMMING

4N0

STANDARD DASHBOARD

4P3

REAR FLOOR PANEL MODULE, TYPE 4

4R4

POWER WINDOWS WITH COMFORT OPERATION AND CIRCUIT BREAKER

4U5

LUGGAGE POCKETS ON BACKREST

4UP

DRIVER AND FRONT PASSENGER AIRBAG WITH KNEE AIRBAG AND FRONT PASSENGER AIRBAG DEACTIVATION

4ZA

STANDARD MOLDINGS

5A5

LUGGAGE COMPARTMENT LINING, WITH STORAGE COMPARTMENTS

5C0

WITHOUT SPECIAL BODY MEASURES

5F1

1 ARMREST FOR LEFT FRONT SEAT AND 2 ARMRESTS FOR RIGHT FRONT SEAT

5J1

REAR SPOILER

5JB

AMBULANCE SEAT FOR MEDICAL STAFF WITH HEAD BOLSTER ON PARTITION

5K7

TRANSPORT PROTECTION FILM (MINIMUM PROTECTION) WITH ADDITIONAL TRANSPORT PROTECTION MEASURES

5N4

FOLDING GRAB HANDLES, MULTI-PIECE

5XJ

SUN VISORS WITH MIRROR, ILLUMINATED, WITH AIRBAG LABEL ON SUN VISOR AND B-PILLAR

5ZF

FRONT HEAD RESTRAINTS

6A0

WITHOUT FIRE EXTINGUISHER

6C4

SIDE AIRBAG IN FRONT AND REAR, WITH CURTAIN AIRBAG AND INTERACTION AIRBAG IN FRONT

6E3

CENTER ARMREST IN FRONT

6EA

WITHOUT ADDITIONAL SIDE BODY COVERS (STONE GUARD)

6F0

WITHOUT DECORATIVE FILMS / EMBLEMS

6FH

EXTERIOR MIRROR HOUSINGS PAINTED

6I1

LANE KEEPING SYSTEM

6NA

UNSPLIT MOLDED HEADLINER

6Q0

WITHOUT GEARSHIFT KNOB/HANDLE

6YD

EXTERIOR MIRRORS, POWER-FOLDING/ POWER-ADJUSTABLE, HEATED, WITH FRONT PASSENGER EXTERIOR MIRROR LOWERING F.

76A

WITHOUT MODE 3 CHARGING CABLE

77G

DATA STORAGE DEVICE FOR EU, INTEGRATED

7AA

ELECTRONIC ENGINE IMMOBILIZER

7B2

12-VOLT SOCKET IN LUGGAGE BOOT

7E6

ELECTRIC AUXILIARY AIR HEATER

7G0

WITHOUT PREPARATION FOR VTS (VEHICLE TRACKING SYSTEM)

7K1

DIRECT TIRE PRESSURE MONITORING SYSTEM

7L6

START/STOP SYSTEM WITH REGENERATIVE BRAKING

7M0

PLASTIC SCUFF PLATES IN DOOR APERTURES

7P5

MANUALLY ADJUSTABLE LUMBAR SUPPORT FOR LEFT FRONT SEAT

7UG

NAVIGATION SYSTEM - HIGH

7W0

WITHOUT EXTENDED SAFETY SYSTEM

7X5

PARK ASSIST

7Y0

WITHOUT LANE CHANGE ASSIST

8AR

RADIO "GAMMA" WITH REMOVABLE OPERATING PANEL

8FA

WITHOUT SECOND BATTERY

8G1

HIGH-BEAM CONTROL

8GU

ALTERNATOR 140 A

8IY

LED HEADLAMPS WITH LENS

8J3

HAND BRAKE/LOW BRAKE FLUID LEVEL WARNINGLIGHT AND INSCRIPTION

8M1

REAR WINDOW WIPER AND WASHER SYSTEM WITH INTERMITTENT CONTROL

8N6

WINDSHIELD WIPER INTERMITTENT CONTROL WITH LIGHT/RAIN SENSOR

8Q3

AUTOMATIC HEADLIGHT RANGE ADJUSTMENT DYNAMIC (SELF-ADJUSTING WHILE DRIVING)

8S4

TWO READING LIGHTS IN FRONT, TWO IN REAR

8T8

ADAPTIVE CRUISE CONTROL (WITH "FOLLOW-TO-STOP") AND SPEED LIMITER

8TB

REAR FOG LAMP

8WB

FRONT FOG LAMPS

8X6

WITHOUT HEADLAMP WASHER SYSTEM, WITHOUT WASHER FLUID LEVEL INDICATOR

8Y0

SINGLE-TONE HORN

8Z5

NOT HOT COUNTRY

8ZQ

ANTENNA FOR FM RECEPTION ONLY, DIVERSITY

9I5

SEPARATE DAYTIME RUNNING LIGHTS WITH AUTOMATIC HEADLAMP ACTIVATION AND COMING HOME FEATURE (AUTOMATIC)

9J

COMFORT TELEPHONY WITH LTE AND WIRELESS CHARGING

9JA

NON-SMOKER'S PACKAGE

9M0

WITHOUT AUXILIARY HEATER/FUEL-FIRED PARKING HEATER

9P4

SEAT BELT REMINDER, ELECTRIC CONTACT IN FRONT AND REAR, VISUAL AND ACOUSTICAL

9T0

WITHOUT HEATED WASHER NOZZLES

9VG

SOUND SYSTEM WITH SUBWOOFER "BRANDED" DESIGN 2

9WY

MIRROR LINK AND WIRELESS "APP" AND RSE (PREPARATION)

9Z0

OPERATING VOLTAGE 12 V

A23

IN-PLANT CONTROL OF SELF-COLLECTION

A8M

EXECUTIVE COMFORT EQUIPMENT

AV1

DRIVING ON THE RIGHT

B01

TYPE APPROVAL COUNTRY GERMANY

B0A

COMPONENT PARTS SET WITHOUT COUNTRY-SPECIFIC BUILDING REGULATION

C12

OPERATING PERMIT, ALTERATION

C2F

ALLOY WHEELS 7J X 16

DN4

4-CYL. TURBO DIESEL ENGINE 2.0 L/110 KW (4V) TDI COMMON RAIL; B.ENGINE T37/T6F  
TS1/TR1/T0P/T0N/T13/T29/TM4/TD1/TI9/T1I

E0A

NO SPECIAL EDITION

EA0

WITHOUT FOLLOW-ON WARRANTY

EL5

ONLINE SERVICE, WITH OCU, WITH HEAD UNITCODING, WITHOUT ENGINE IMMOBILIZER INTERCONNECTION

EM1

DRIVER ALERT SYSTEM

ER1

REGIONAL CODE " ECE " FOR RADIO

EVO

WITHOUT CHARGING CABLE

EW0

WITHOUT MAINTENANCE CONTRACT

F0A

NO SPECIAL PURPOSE VEHICLE, STANDARD EQUIPMENT

FA0

CONTROL OF SERIES PRODUCTION

FC0

WITHOUT CUSTOMIZED INSTALLATION

FM0

BASIC EQUIPMENT VARIANT

G04

SHOCK ABSORPTION IN FRONT

G1C

SEVEN-SPEED AUTOMATIC TRANSMISSION

GB1

BOOSTER TYPE 1

GM1

STANDARD ELECTRONIC ENGINE SOUND

GP0

VEHICLES WITHOUT SPECIAL UPGRADE MEASURES

GW0

WITHOUT CAR2X

HH7

TIRES 205/55 R16 91V

IT0

WITHOUT AUDI CONNECT PACKAGE 1

J0V

BATTERY 420 A (70 AH)

K8D

WAGON/AVANT

KA2

WITH REAR VIEW CAMERA SYSTEM (TYPE 2)

KH7

CLIMATRONIC (3-ZONE) WITH REAR AIR CONDITIONING CONTROL PANEL

KK3

REFRIGERANT R1234YF

KS0

WITHOUT HEAD-UP DISPLAY

L08

SUSPENSION RANGE 08 INSTALLATION CONTROL ONLY, NO REQUIREMENT FORECAST

L0L

LEFT-HAND DRIVE

N7C

SEAT TRIM COVERS IN FABRIC



NY0

STANDARD BATTERY/ALTERNATOR CAPACITY

NZ4

PRIVATE EMERGENCY CALL SYSTEM

Q1A

STANDARD SEATS IN FRONT

Q9B

DECORATIVE INSERTS FOR CONSOLE

QG1

SERVICE INTERVAL PROLONGATION

QH1

VOICE CONTROL

QI6

SERVICE INDICATOR 30 000 KM OR 2 YEARS ( VARIABLE )

QJ1

CHROME PACKAGE

QK1

WITH MULTIFUNCTION CAMERA

QN3

DRAWERS UNDER FRONT SEATS

QQ3

INTERIOR AMBIENT LIGHTING AND SURROUND LIGHTING

QR9

WITH DYNAMIC ROAD SIGN DISPLAY

QV3

DIGITAL RADIO RECEPTION

T6M

4-CYLINDER DIESEL ENGINE 2.0 L UNIT 05L.C

U5A

INSTRUMENT CLUSTER, KM/H SPEEDOMETER

U9C

2 X USB TYPE C

UG0

WITHOUT HILL START ASSIST/HILL DESCENT CONTROL/COMFORT DRIVING ASSIST

UH2

PARKING BRAKE

UK3

MECHANICAL REAR SEAT RELEASE

V0A

TIRES WITHOUT SPECIFICATION OF TIRE BRAND

VF0

STANDARD PEDAL CLUSTER

VH0

STANDARD ELECTRIC

X0A

EQUIPMENT OPTIONS SUBSET FOR GERMANY

## Cronologie

S-a găsit 1 înregistrare

Cronologia înregistrărilor pentru acest vehicul

### Ultimele înregistrări

2023-05  Germania



**Daună detectată**



Avem indicii potrivit cărora acest vehicul a fost recunoscut ca avariat în această țară (sau stat). Pentru detalii, vă rugăm să consultați secțiunea „Daune”.



+31

#### Surse de date

Am verificat 900+ de surse de date în **35 de țări**