




Audi A3

VIN: WAUZZZGY7MA004671

Diesel

2020



Generat pe 14.04.2025, 09:31

Scanează ca să accesezi raportul complet



Odometru

✓ Arată bine



Statut legal

✓ Arată bine



Daune

✓ Arată bine



+31

Surse de date

Am verificat 900+ de surse de date în 35 de țări

Furt

Vehiculul este declarat furat în prezent? A fost furat în trecut? A fost recuperat?



Nu s-au găsit probleme

Nu am găsit nicio înregistrare că vehiculul a fost furat.



Notă

Am încheiat verificarea bazelor de date ale poliției privind vehiculele furate din 11 țări: +5

Iată ce am verificat:



Căutat drept furat

✓ Nu s-a găsit nicio înregistrare



Furat în trecut

✓ Nu s-a găsit nicio înregistrare

Nu au fost găsite înregistrări anterioare de furt pentru acest vehicul.

Bazele de date ale poliției cu vehicule furate **verificare finalizată în:**



România



Cehia



Italia



Slovenia



Slovacia



Ungaria



Canada



Danemarca



Lituania



Statele Unite ale Americii



Suedia


Odometru

Există semne conform cărora kilometrajul a fost dat înapoi sau sunt discrepanțe de kilometraj?



Notă

- Ultimul kilometraj cunoscut: 135.992 km
- Kilometraj mediu pentru modele similare: 104.489 km
- 8 înregistrări ale kilometrajului



Înregistrările odometrelui

01.2020	17 km
01.2021	5.429 km
10.2021	34.527 km
08.2022	63.309 km
05.2023	91.079 km

Înregistrările odometrelui

03.2024	121.952 km
04.2024	127.141 km
04.2025	135.992 km

Statut legal

A trecut vehiculul inspecțiile tehnice? A fost marcat drept casat?



Nu s-au găsit probleme

Nu s-au găsit înregistrări despre statutul legal al acestui vehicul

Legal



Inspecție tehnică periodică (ITP)

✓ Nu s-a găsit nicio înregistrare

Nu au fost găsite înregistrări ale inspecției tehnice



Casat

✓ Nu s-a găsit nicio înregistrare

Nu există nicio înregistrare că vehiculul a fost marcat drept casat

Daune

Acest vehicul a fost avariat în trecut ? Care a fost valoarea daunelor?

✓ Nu s-au găsit probleme

Înregistrări de daune



Ocazional pot apărea inexactități, mai ales la verificarea vehiculelor vechi. Atelierele clandestine de reparații pot deghiza ilegal defectele sau daunele vehiculelor, fără să declare nicăieri existența lor. Uneori până și plăcuțele VIN ale vehiculului pot fi înlocuite. Avem o varietate de metode de a detecta chiar și astfel de infracțiuni, dar este imposibil de oferit o garanție de 100%.

Dezastre naturale

Locația vehiculului a fost înregistrată în zona unui dezastru natural?

✓ Nu s-au găsit probleme
Locația vehiculului nu a fost înregistrată în zona unui dezastru natural

Valoare de piață

Cu cât s-a vândut vehiculul în trecut? Care este prețul mediu pentru un vehicul din același model și an?

i Notă

- Prețul mediu de pe piață pentru un astfel de vehicul: 117.464 RON
- Atenție la problemele ascunse dacă vehiculul a fost la vânzare la un preț semnificativ mai mic decât prețul actual!

Valoarea actuală de piață pentru Audi A3 2020

Valoarea de piață este determinată prin examinarea prețului unui anumit model de mașină (fabricat în același an) în țara în care a fost generat raportul. Analizăm datele din ultimele 6 luni.

Cel mai mic preț

Prețul mediu

Cel mai mare preț

106.811 RON

117.464 RON

128.977 RON

Emisii

Care este nivelul de emisii de CO₂ al vehiculele din acest model/an?



Sugestia carVertical

Acest vehicul are emisii medii. Probabil vor fi percepute taxe standard pentru emisii.

Emisii CO₂

Emisii CO₂ g/km

Până la
120

120 - 140

140 - 155

155 - 165

165 - 190

190 - 225

225 +

Emisiile de
CO₂ ale
vehiculului
tău

123 g/km

Clasă **B**

Specificații și echipare

Ce specificații și echipamente sunt înregistrate pentru acest vehicul?



Notă

Verifică dacă specificațiile și echipamentul acestui vehicul se potrivesc cu datele furnizate de vânzător.

Identificare și specificații tehnice



Producător

Audi



Model

A3



Variantă

Sportback



Tip caroserie

Hatchback



An de fabricație

2020



An model

2021



Capacitate cilindrică

2 l



Putere motor

110 kW (148 cp)



Tip combustibil

Diesel



Cutie de viteze

Automată



Tip transmisie

Tracțiune față (FWD)



Culoare

Albastru



Nr. locuri

5



Cod motor

DSRB



Categorie

m1

Echipare

Cum a fost primit de la producător

0AD

FRONT STABILIZER

0BD

REAR STABILIZER

0IJ

INSTALLATION DIFFERENTIATION FOR TRANSMISSION
"DQ381" -- VEHICLE COMPONENTS --

0LJ

WITH SPECIAL PLATES/LABELS/ SAFETY
CERTIFICATES FOR FRANCE

0P0

REAR EXHAUST TAILPIPE (STANDARD)

0B1

WHEELBASE

0F5

FUEL SYSTEM FOR DIESEL ENGINE

0K0

WITHOUT ALTERNATIVE DRIVE SYSTEM

0N4

4-LINK REAR SUSPENSION

0SS

LABELS/PLATES IN ENGLISH AND FRENCH

0TD

FLOOR MATS IN FRONT AND REAR

0Y1

STANDARD CLIMATIC ZONES

1AQ

BRS FOR VEHICLES WITHOUT ELECTRIC DRIVE (ESC AND ELECTRIC BRAKE BOOSTER)

1EX

SPECIAL IDENTIFICATION PLATE FOR EC FOR M1 PASSENGER VEHICLE

1JP

REAR SHOCK ABSORPTION

1M5

TRAILER HITCH PREPARATION

1PE

WHEEL BOLTS WITH ANTI-THEFT PROTECTION (UNLOCKABLE)

1SA

WITHOUT ADDITIONAL FRONT UNDERBODY GUARD

1X0

FRONT WHEEL DRIVE

1Z6

INCREASE IN INITIAL STANDARD FUEL FILLING

20A

WITHOUT ELECTRIC MOTOR (HYBRID)

2F0

WITHOUT LOCKING AND STARTING SYSTEMS

2JD

SPORTS BUMPERS

2Z8

TYPE SIGN AND COMPANY LOGO

3FA

WITHOUT ROOF INSERT (STANDARD ROOF)

3NT

REAR SEAT BENCH UNSPLIT, BACKREST SPLIT FOLDING (THREE PIECES) WITH CENTER ARMREST

3S0

0VB

INFORMATION KIT IN FRENCH

0YD

WEIGHT RANGE 4 INSTALLATION CONTROL ONLY, NO REQUIREMENT FORECAST

1E9

WITHOUT ACTIVATED CARBON CANISTER WITH SCR

1G8

BREAKDOWN KIT

1KE

DISK BRAKES IN REAR

1N3

SPEED-RELATED VARIABLE STEERING ASSIST (SERVOTRONIC)

1S1

TOOL KIT AND JACK

1T3

FIRST AID KIT WITH WARNING TRIANGLE

1XX

LEATHER-WRAPPED MULTIFUNCTION SPORTS STEERING WHEEL W/ TIPTRONIC

1ZK

DISK BRAKES IN FRONT

2CH

VEHICLE CLASS DIFFERENTIATION 8Y0/8YA/ 8YF

2I0

ADAPTIVE CHASSIS CONTROL WITH CONTINUOUS OPERATION

2WA

WITHOUT ADDITIONAL TIRES

31B

REAR LICENSE PLATE CARRIER (ECE)

3H0

WITHOUT BACKREST RELEASE FOR FRONT SEATS

3PB

POWER SEAT ADJUSTMENT FOR LEFT SEAT, RIGHT SEAT MANUALLY HEIGHT-ADJUSTABLE

3T2

WITHOUT ROOF RAILS/ROOF LOAD RACK

41R

ALLOY WHEELS 8J X 17

4E6

SENSOR-CONTROLLED LUGGAGE COMPARTMENT
OPENER

4GH

WINDSHIELD IN HEAT-INSULATING GLASS WITH
SUNSHIELD

4K5

CENTRAL LOCKING SYSTEM "KEYLESS ENTRY" WITH
FINGERPRINT

4P4

REAR FLOOR PANEL MODULE, TYPE 5

4X3

SIDE AIRBAG IN FRONT, WITH CURTAIN AIRBAG

5C0

WITHOUT SPECIAL BODY MEASURES

5J1

REAR SPOILER

5K5

TRANSIT COATING FILM WITH ADDITIONAL
TRANSPORT PROTECTION MEASURES

5TD

DECORATIVE ALUMINUM INSERTS

6A0

WITHOUT FIRE EXTINGUISHER

6F7

EMBLEMS

6I6

LANE KEEPING SYSTEM PLUS SEMI-AUTOMATIC
VEHICLE CONTROL IN A MEDICAL EMERGENCY AND
TRAFFIC JAM ASSIST

6SS

LUGGAGE COMPARTMENT FLOOR COVERING

6Y2

SPEED LIMITER

THREE REAR HEAD RESTRAINTS

4A3

SEAT HEATER FOR FRONT SEATS SEPARATELY
CONTROLLED

4G1

STORAGE COMPARTMENT, DIRECTION OF
TRAVEL LEFT, 1ST ROW OF SEATS

4H5

POWER-OPERATED CHILD SAFETY LOCK

4L2

DIMMING BREAKAWAY INTERIOR REARVIEW MIRROR

4UF

DRIVER AND FRONT PASSENGER AIRBAG WITH FRONT
PASSENGER AIRBAG DEACTIVATION

4ZD

BLACK MOLDINGS

5F1

1 ARMREST FOR LEFT FRONT SEAT AND 2 ARMRESTS
FOR RIGHT FRONT SEAT

5JA

WITHOUT AMBULANCE SEAT FOR MEDICAL STAFF

5L0

WITHOUT FRONT SPOILER

5ZF

FRONT HEAD RESTRAINTS

6E3

CENTER ARMREST IN FRONT

6FJ

BLACK EXTERIOR MIRROR HOUSINGS

6NQ

STANDARD MOLDED HEADLINER

6XN

EXTERIOR MIRRORS: POWER-ADJUSTABLE,
SEPARATELY HEATED

73A

WITHOUT CHARGING CABLE (INDUSTRIAL
CONNECTOR)

76A

WITHOUT MODE 3 CHARGING CABLE

7E6

ELECTRIC AUXILIARY AIR HEATER

7HF

LEATHER VARIANT 5

7L6

START/STOP SYSTEM WITH REGENERATIVE BRAKING

7UG

NAVIGATION SYSTEM - HIGH

7X5

PARK ASSIST

8G1

HIGH-BEAM CONTROL

8IT

LED HEADLAMPS

8K4

SEPARATE DAYTIME RUNNING LIGHTS -- NAR --

8N6

WINDSHIELD WIPER INTERMITTENT CONTROL WITH
LIGHT/RAIN SENSOR

8X7

WITHOUT HEADLAMP WASHER SYSTEM / WITH
WASHER FLUID LEVEL INDICATOR

8Z5

NOT HOT COUNTRY

9JD

SMOKER'S PACKAGE, ASHTRAY IN FRONT

9S9

.

9ZX

MOBILE PHONE INTERFACE

A51

AUDI AG

AQ0

7AA

ELECTRONIC ENGINE IMMOBILIZER

7F9

PLASTIC/LEATHER GEARSHIFT KNOB/HANDLE

7K1

DIRECT TIRE PRESSURE MONITORING SYSTEM

7P1

POWER-ADJUSTABLE LUMBAR SUPPORT IN
FRONTSEATS

7W0

WITHOUT EXTENDED SAFETY SYSTEM

8FA

WITHOUT SECOND BATTERY

8GU

ALTERNATOR 140 A

8J3

HAND BRAKE/LOW BRAKE FLUID LEVEL
WARNINGLIGHT AND INSCRIPTION

8M1

REAR WINDOW WIPER AND WASHER SYSTEM WITH
INTERMITTENT CONTROL

8T8

ADAPTIVE CRUISE CONTROL (WITH "FOLLOW-TO-
STOP") AND SPEED LIMITER

8Y1

TWO-TONE HORN

9AK

CLIMATRONIC WITH IMPACT PRESSURE CONTROL,
CFC-FREE

9M0

WITHOUT AUXILIARY HEATER/FUEL-FIRED PARKING
HEATER

9VD

SPEAKER (ACTIVE)

A00

NO SELF-COLLECTION

A9E

"AMBIENTE" EQUIPMENT

AV1

STANDARD-PRODUCTION QUALITY

B08

TYPE APPROVAL COUNTRY FRANCE

C01

OPERATING PERMIT, ALTERATION

E0A

NO SPECIAL EDITION

EF1

ECO FUNCTION

ES0

WITHOUT VEHICLE INLET

EW0

WITHOUT MAINTENANCE CONTRACT

FA0

CONTROL OF SERIES PRODUCTION

FQ0

PRODUCTION WHEELS

G04

SHOCK ABSORPTION IN FRONT

GB0

WITHOUT BOOSTER

GP0

VEHICLES WITHOUT SPECIAL UPGRADE MEASURES

IT4

WITH CONNECT PACKAGE 4

IW3

EMERGENCY CALL SERVICE AND ROADSIDE
ASSISTANCE CALL

J0V

BATTERY 420 A (70 AH)

KA2

WITH REAR VIEW CAMERA SYSTEM (TYPE 2)

KS0

WITHOUT HEAD-UP DISPLAY

L71

DRIVING ON THE RIGHT

B0A

COMPONENT PARTS SET WITHOUT COUNTRY-
SPECIFIC BUILDING REGULATION

DN4

4-CYL. TURBO DIESEL ENGINE 2.0 L/110 KW (4V) TDI
COMMON RAIL; B.ENGINE T37/T6F
TS1/TR1/T0P/T0N/T13/T29/TM4/TD1/TI9/T1I

EA2

1 YEAR FOLLOW-ON WARRANTY, MAX. 60 000 KM

ER1

REGIONAL CODE " ECE " FOR RADIO

EV0

WITHOUT CHARGING CABLE

FOA

NO SPECIAL PURPOSE VEHICLE, STANDARD
EQUIPMENT

FM0

BASIC EQUIPMENT VARIANT

FZ1

N.N.N. TYPE 1

G1C

SEVEN-SPEED AUTOMATIC TRANSMISSION

GM1

STANDARD ELECTRONIC ENGINE SOUND

H8V

TIRES 225/45 R17 91Y

IU1

WITH CONNECT PACKAGE 1

IX2

DIESEL ENGINE

K8R

SPORTSBACK

KK3

REFRIGERANT R1234YF

L0L

LEFT-HAND DRIVE

N2Y

SEAT TRIM COVERS IN FABRIC/LEATHERETTE

SUSPENSION RANGE 71 INSTALLATION CONTROL ONLY, NO REQUIREMENT FORECAST

NJ0

WITHOUT CHARGING DOCK

NT1

TRANSIT COATING (TYPE 2)

Q1D

SPORTS SEATS IN FRONT

QI6

SERVICE INDICATOR 30 000 KM OR 2 YEARS (VARIABLE)

QK1

WITH MULTIFUNCTION CAMERA

QQ2

WITH ADDITIONAL LIGHTS (INTERIOR LIGHTING)

QV3

DIGITAL RADIO RECEPTION

S3Y

2-DOOR GTI FOR HONG KONG

U5A

INSTRUMENT CLUSTER, KM/H SPEEDOMETER

V0A

TIRES WITHOUT SPECIFICATION OF TIRE BRAND

VF1

PEDAL CLUSTER

X3A

EQUIPMENT OPTIONS SUBSET FOR FRANCE

NM1

ENGINE COVER

NZ2

PAN-EUROPEAN EMERGENCY CALL SERVICE

QE1

STORAGE COMPARTMENT PACKAGE 1

QJ1

CHROME PACKAGE

QL5

DARK TINTED GLASS IN REAR SEAT AREA (VENUS 35/PRIVACY) HEAT-INSULATING GLASS (GREEN) IN FRONT

QR9

WITH DYNAMIC ROAD SIGN DISPLAY

S0C

INTRODUCTORY VOLUME

T3Y

4-CYLINDER DIESEL ENGINE 2.0 L UNIT 05L.D

UH2

PARKING BRAKE

VC0

WITHOUT REMOTE-CONTROLLED GARAGE DOOR OPENER

VT5

SCUFF PLATES IN DOOR APERTURES

Siguranță

Vehiculul are vreo rechemare pe motiv de siguranță? Care este ratingul său de siguranță?



Sugestia carVertical

Acest vehicul are un rating ridicat de siguranță. Întreținerea corespunzătoare și regulată va menține standardul ridicat de siguranță.

Rating de siguranță



Siguranță de 5 stele

Performanță generală excelentă la protecția împotriva accidentelor și bine echipat cu tehnologie amplă și robustă de evitare a accidentelor



89%

Ocupant adult



81%

Copil ocupant



68%

Utilizatori
vulnerabili ai
drumurilor



73%

Asistență de
siguranță

Cronologie

S-au găsit 5 înregistrări

Cronologia înregistrărilor pentru acest vehicul

Ultimele înregistrări

01.2020 🌐 Țară necunoscută



A fost fabricat

Țara (sau statul) indică fie locația centrului de producție, uzina de asamblare sau adresa de înregistrare a producătorului. Data poate fi aproximativă.

06.2020 🇫🇷 Franța



A fost înmatriculat

Înregistrarea reprezintă un eveniment administrativ. Acest lucru ar putea fi legat de o schimbare de proprietar, documente etc

02.2021 🇫🇷 Franța



A fost înmatriculat

Înregistrarea reprezintă un eveniment administrativ. Acest lucru ar putea fi legat de o schimbare de proprietar, documente etc

04.2024 🇷🇴 România



A fost înmatriculat

Înregistrarea reprezintă un eveniment administrativ. Acest lucru ar putea fi legat de o schimbare de proprietar, documente etc

04.2025  România

 A fost asigurat

Acest vehicul a fost asigurat în această țară (sau stat). Pot fi acoperite toate tipurile de asigurare (răspundere civilă față de terți, CASCO etc.), precum și reînnoirea polițelor.

Din: **09.04.2025** Până la: **08.04.2026**



Surse de date
Am verificat 900+ de surse de date în **35 de țări**