

# Volkswagen Caddy



VIN: WV1ZZZSKZNX040680

Diesel

2022

Generat pe 12.02.2025, 11:15



## Scop

⚠️ Necesită atenție



## Odometru

✓ Arată bine



## Statut legal

✓ Arată bine



## Daune

⚠️ Necesită atenție



+31

## Surse de date

Am verificat 900+ de surse de date în 35 de țări

## Scop

A fost folosit vehiculul drept taxi, pentru închiriere sau alt vehicul de serviciu? Notă: acest gen de vehicule pot fi într-o stare mai proastă decât ar fi normal!

### ⚠️ Ai grijă!

Vehiculul a fost folosit ca mașină utilitară!

## Iată ce am verificat:

Utilitar ⚠️ Înregistrare găsită 02.2025 România A fost folosit ca vehicul utilitar

Taxi ✓ Nu s-a găsit nici o înregistrare Nici o dovadă că a fost folosit pe post de taxi

Transport ✓ Nu s-a găsit nici o înregistrare Nici o dovadă că a fost folosit ca vehicul de transport

Închiriere ✓ Nu s-a găsit nici o înregistrare Nici o dovadă că a fost folosit ca vehicul de închiriat

Poliție ✓ Nu s-a găsit nici o înregistrare Nici o dovadă că a fost folosit de poliție

Demo ✓ Nu s-a găsit nici o înregistrare Nu există dovezi că a fost folosit pe post de vehicul demonstrativ


## Furt

Vehiculul este în prezent marcat ca furat? A fost furat în trecut? A fost recuperat?

✓ Nu s-au găsit probleme

Nu am găsit nicio înregistrare că vehiculul a fost furat.

i Notă

Verificarea bazei de date a poliției privind vehiculele furate finalizată în 9 țări:  +3

Iată ce am verificat:



Căutat drept furat

✓ Nu s-a găsit nici o înregistrare



Furat în trecut

✓ Nu s-a găsit nici o înregistrare

Starea actuală necunoscută



Furat în trecut

✓ Nu s-a găsit nici o înregistrare

Vehiculul a fost recuperat

Baza de date aparținând poliției cu vehicule furate, **verificare finalizată în:**



România



Danemarca



Statele Unite ale Americii



Lituania



Slovacia



Italia



Suedia



Slovenia




Cehia

## Odometru

Există semne conform cărora kilometrajul a fost dat înapoi sau discrepanțe ale kilometrajului?

i Notă

Ultimul kilometraj cunoscut: 43.317 km



**Disclaimer (declinarea responsabilității):** acest grafic reprezintă o tendință estimată a kilometrajului. Deși se bazează pe înregistrări reale de kilometraj disponibile pentru acest vehicul, există lacune având în vedere că evoluția kilometrajului nu este înregistrată în mod constant. Pentru a lua în considerare aceste date lipsă, aplicăm un model patentat de analiză a datelor care prezice modul în care probabil s-a schimbat kilometrajul între evenimentele înregistrate. Acest lucru ajută la furnizarea unei imagini mai complete a utilizării vehiculului în timp.

## Statut legal

A trecut vehiculul inspecțiile tehnice? A fost notat drept casat?

### i Notă

Inspecția tehnică a fost transmisă pe 09.2024 în România

## Legal

= Inspecție tehnică periodică (ITP) A trecut 09.2024 România

A trecut cu succes inspecția tehnică Valabil până la 12.2025

= Casat ✓ Nu s-a găsit nici o înregistrare Nu există nici o înregistrare că vehiculul a fost marcat drept casat

## Daune

Acest vehicul a fost avariat în trecut ? Care a fost valoarea daunelor?

## Ai grijă!

Acest vehicul a fost avariat

## Notă

Daunele minore nu vor afecta în mod normal siguranța vehiculului și nu vor cauza probleme structurale

## Înregistrări de daune



03.2023  România

### Evaluare

Părți afectate

**Partea dreaptă** Spate

Costul estimativ al reparațiilor

## 6.001 RON – 14.000 RON

Cauza posibilă

## Necunoscut

Daune pe partea dreaptă:

Dreapta / Portieră față

Daune pe partea dreaptă:

Spate dreapta / Bară de protecție

**Disclaimer (declinarea responsabilității):** Majoritatea înregistrărilor de daune sunt legate de accidente, dar uneori nu este acesta cazul. Unele înregistrări provin din alte surse cum ar fi serviciile specializate pe lucrări de caroserie, cereri de daune, licitații sau inspecții ale vehiculelor. Aceste înregistrări arată că starea vehiculului a fost evaluată, chiar dacă nu a fost din cauza unui accident.

## Dezastre naturale

Locația vehiculului a fost înregistrată în zona unui dezastru natural?

## Nu s-au găsit probleme

Locația vehiculului nu a fost înregistrată în zona unui dezastru natural

# Valoarea de piață

Cu cât s-a vândut vehiculul în trecut? Care este în medie prețul vehiculelor din acest model și an?

## i Notă

- Prețul mediu de pe piață pentru un astfel de vehicul: 119.903 RON
- Atenție la problemele ascunse dacă vehiculul a fost la vânzare la un preț semnificativ mai mic decât prețul actual!

## Valoarea de piață azi pentru Volkswagen Caddy 2022

Valoarea de piață este determinată prin examinarea prețului unui anumit model de mașină (fabricat în același an) în țara în care a fost generat raportul. Analizăm datele din ultimele 6 luni.

Cel mai mic preț

110.358 RON

Prețul mediu

119.903 RON

Cel mai mare preț

131.027 RON

## Emisii

Câte emisii de CO2 produc vehiculele din acest model/an?

## i Notă

Emisii CO2: B (134 g/km)

## Emisii CO<sub>2</sub>

Emisiile CO2 ale  
vehiculului tău

134 g/km Clasă **B**

Până la 120

120 - 140

140 - 155

155 - 165

165 - 190

190 - 225

225 și peste

Emisii CO<sub>2</sub> g/km

## Specificații și echipare

Ce specificații și echipamente sunt înregistrate pentru acest vehicul?

## i Notă

Verificați dacă specificațiile și echipamentul acestui vehicul se potrivesc cu datele furnizate de vânzător.

## Identificare și specificații tehnice



Producător

**Volkswagen**



Model

**Caddy**



Tip caroserie

**Dubă**



An de fabricație

**2022**



Capacitate cilindrică

**2 l**



Putere motor

**75 kW (101 cp)**



Tip combustibil

**Diesel**



Cutie de viteze

**Manuală**



Tip transmisie

**Tracțiune față (FWD)**



Culoare

**Alb**



Amplasarea volanului

**Volan pe stânga**



Nr. cilindri

**4**



Nr. locuri

**5**



Cod motor

**DTRE**



Categorie

**n1**

---

## Echipare

Cum a fost primit de la producător

02B

WHEELBASE

0ED

INSTALLATION DIFFERENTIATION FOR TRANSMISSION MQ 380 -- VEHICLE COMPONENTS --

0F5

FUEL SYSTEM FOR DIESEL ENGINE

0K0

WITHOUT ALTERNATIVE DRIVE SYSTEM

0NB

NAMEPLATE SET IN BASIC STYLE

0TA

WITHOUT FLOOR MATS

0WM

GROSS VEHICLE WEIGHT RATING

0XH

INFORMATION KIT IN ROMANIAN

0Y1

STANDARD CLIMATIC ZONES

0YC

WEIGHT RANGE 3 INSTALLATION CONTROL ONLY, NO REQUIREMENT FORECAST

0Z0

VW MARQUE-SPECIFIC/CLASS-SPECIFIC FEATURES

1AQ

BRS FOR VEHICLES WITHOUT ELECTRIC DRIVE (ESC AND ELECTRIC BRAKE BOOSTER)

1D0

WITHOUT TRAILER HITCH

1E9

WITHOUT ACTIVATED CARBON CANISTER WITH SCR

1EV

## SPECIAL IDENTIFICATION PLATE EC FOR COMMERCIAL VEHICLES

1G2

STEEL SPARE WHEEL WITH ORIGINAL EQUIPMENT TIRE

1HZ

LABELS WITHOUT COUNTRY GROUP

1KU

DISK BRAKES IN REAR

1N3

SPEED-RELATED VARIABLE STEERING ASSIST (SERVOTRONIC)

1NC

WHEEL TRIMS

1PA

STANDARD WHEEL BOLTS

1SA

WITHOUT ADDITIONAL FRONT UNDERBODY GUARD

1T0

WITHOUT FIRST AID KIT AND WARNING TRIANGLE

1U8

WITHOUT FOLDING TABLE ON FRONT SEAT BACKREST

1X0

FRONT WHEEL DRIVE

1Z0

INITIAL STANDARD FUEL FILLING

1ZK

DISK BRAKES IN FRONT

2FB

LEATHER-WRAPPED SPORTS STEERING WHEEL FOR AIRBAG SYSTEM WITH TIPTRONIC AND ALUMINUM LOOK

2H0

WITHOUT "DRIVE SELECT"



2J1

COMFORT BUMPERS

2P0

WITHOUT LOADING EDGE PROTECTION

2WA

WITHOUT ADDITIONAL TIRES

3A0

CHILD SEAT ANCHOR FOR CHILD SEAT SYSTEM I-SIZE, 2X TOP TETHER

3CA

WITHOUT PARTITION

3D7

CENTER CONSOLE

3FA

WITHOUT ROOF INSERT (STANDARD ROOF)

3H0

WITHOUT BACKREST RELEASE FOR FRONT SEATS

3JA

WITHOUT ROOF INSERT IN LOAD AND PASSENGER COMPARTMENT

3L1

MANUAL HEIGHT ADJUSTMENT FOR LEFT FRONT SEAT

3LX

DOOR AND SIDE TRIM PANEL

3NM

REAR SEAT BENCH/BACKREST, SPLIT FOLDING

3RE

REAR WING DOOR WITH WINDOW APERTURE

3S6

ROOF RAILS PREPARATION

3U1

FOLDING TRUNK COVER

3W4

ACOUSTICS PACKAGE "STANDARD"

3ZU

3-POINT SEAT BELTS, OUTER REAR WITH ECE LABEL

4A3

SEAT HEATER FOR FRONT SEATS SEPARATELY CONTROLLED

4BJ

MAN M-NUMBER

4DE

FIXED SIDE WINDOW IN PASSENGER COMPARTMENT FRONT LEFT

4EE

FIXED SIDE WINDOW IN PASSENGER COMPARTMENT, FRONT RIGHT

4FH

FIXED SIDE WINDOW IN LOAD/PASSENGER COMPARTMENT, LEFT

4G3

STORAGE COMPARTMENT, LEFT AND RIGHT 1ST ROW OF SEATS

4GF

WINDSHIELD IN HEAT-INSULATING GLASS

4H5

POWER-OPERATED CHILD SAFETY LOCK

4HH

HEATED REAR WINDOW

4I2

CENTRAL LOCKING WITH RADIO REMOTE CONTROL, INTERIOR RELEASE MECHANISM WITHOUT SAFELOCK

4JH

FIXED SIDE WINDOW IN LOAD/PASSENGER COMPARTMENT, RIGHT

4L2

DIMMING BREAKAWAY INTERIOR REARVIEW MIRROR

4QT

3-POINT SEAT BELTS IN FRONT, WITH PRETENSIONER AND HEIGHT ADJUSTMENT

4S0

WITHOUT ARMRESTS FOR FRONT SEATS

4U0

WITHOUT LUGGAGE NETS/POCKETS ON BACKRESTS

4UF

DRIVER AND FRONT PASSENGER AIRBAG WITH FRONT PASSENGER AIRBAG DEACTIVATION

4Z8

GLOVE COMPARTMENT COVER, WITH LIGHT (WITHOUT LOCK CYLINDER)

51A

WITHOUT ADHESIVE FILM

5AD

CARPET FLOOR COVERING IN CAB

5BF

CARPET FLOOR COVERING IN PASSENGER COMPARTMENT

5DD

COMFORT SIDE PANEL TRIM IN PASSENGER COMPARTMENT

5EV

REGISTRATION AS TRUCK

5F1

1 ARMREST FOR LEFT FRONT SEAT AND 2 ARMRESTS FOR RIGHT FRONT SEAT

5K7

TRANSPORT PROTECTION FILM (MINIMUM PROTECTION) WITH ADDITIONAL TRANSPORT PROTECTION MEASURES

5Q2

SLIDING DOOR LEFT IN LOAD/PASSENGER COMPARTMENT

5R2

SLIDING DOOR RIGHT IN LOAD/PASSENGER COMPARTMENT

5XR

SUN VISORS WITH MIRROR, AIRBAG LABEL ON FRONT PASSENGER SUN VISOR

6A0

WITHOUT FIRE EXTINGUISHER

6EA

WITHOUT ADDITIONAL SIDE BODY COVERS (STONE GUARD)

6FF

BODY-COLORED EXTERIOR MIRROR HOUSINGS AND VARIOUS ADD-ON PARTS

6I1

LANE KEEPING SYSTEM

6LG

STANDARD AIR OUTLET

6Q1

PLASTIC GEARSHIFT KNOB/HANDLE

6SF

STANDARD LUGGAGE COMPARTMENT FLOOR COVERING

6U1

ADDITIONAL DUST SEAL OUTSIDE

6XN

EXTERIOR MIRRORS: POWER-ADJUSTABLE, SEPARATELY HEATED

7AA

ELECTRONIC ENGINE IMMOBILIZER

7B6

12-VOLT SOCKET(S)

7E6

ELECTRIC AUXILIARY AIR HEATER

7K1

DIRECT TIRE PRESSURE MONITORING SYSTEM

7L6

START/STOP SYSTEM WITH REGENERATIVE BRAKING

7M5

WITHOUT PROTECTIVE FILM FOR SCUFF PLATE

7N1

OVERHEAD STORAGE COMPARTMENT

7P0

WITHOUT LUMBAR SUPPORT IN SEAT BACKRESTS

7Q0

WITHOUT NAVIGATION DEVICE

7TC

DECORATIVE INSERTS

7X1

PARK DISTANCE CONTROL

7Y0

WITHOUT LANE CHANGE ASSIST

8FA

WITHOUT SECOND BATTERY

8G0

WITHOUT LIGHT CONTROL

8GU

ALTERNATOR 140 A

8ID

HALOGEN TWIN HEADLAMPS

8J3

HAND BRAKE/LOW BRAKE FLUID LEVEL WARNINGLIGHT AND INSCRIPTION

8M1

REAR WINDOW WIPER AND WASHER SYSTEM WITH INTERMITTENT CONTROL

8N8

WINDSHIELD WIPER INTERMITTENT CONTROL WITH PHOTOSENSOR

8Q1

HEADLIGHT RANGE ADJUSTMENT

8QJ

KEY FOR LOCKING SYSTEM WITH REMOTE CONTROL

8RL

6 SPEAKERS (PASSIVE)

8SA

TAIL LAMP ASSEMBLIES, STANDARD DESIGN

8T6

CRUISE CONTROL SYSTEM AND SPEED LIMITER

8U0

WITHOUT ADDITIONAL INSTRUMENTS FOR DISTANCE MEASUREMENT

8WA

WITHOUT FRONT FOG LAMPS

8X7

WITHOUT HEADLAMP WASHER SYSTEM / WITH WASHER FLUID LEVEL INDICATOR

8Z5

NOT HOT COUNTRY

9A0

WITHOUT TAXI ALARM SYSTEM

9C7

SEPARATE DAYTIME RUNNING LIGHTS WITH AUTOMATIC HEADLAMP ACTIVATION

9CW

LED INTERIOR LIGHTS IN PASSENGER/LOAD COMPARTMENT

9D0

WITHOUT PREPARATION FOR TWO-WAY RADIO INSTALLATION

9JC

SMOKER'S VERSION

9KA

WITHOUT IDENTIFICATION LIGHTS

9M0

WITHOUT AUXILIARY HEATER/FUEL-FIRED PARKING HEATER

9P4

SEAT BELT REMINDER, ELECTRIC CONTACT IN FRONT AND REAR, VISUAL AND ACOUSTICAL

9S5

MULTI-FUNCTION DISPLAY/ON-BOARD COMPUTER"MEDIUM"

9T1

HEATED WASHER NOZZLES IN FRONT

9WT

MIRRORLINK

9Z0

OPERATING VOLTAGE 12 V

9ZX

MOBILE PHONE INTERFACE

A8C

COMFORT EQUIPMENT

AV1

DRIVING ON THE RIGHT

B0A

COMPONENT PARTS SET WITHOUT COUNTRY-SPECIFIC BUILDING REGULATION

B43

TYPE APPROVAL COUNTRY ROMANIA

C06

OPERATING PERMIT, ALTERATION

E0A

NO SPECIAL EDITION

EA0

WITHOUT FOLLOW-ON WARRANTY

EL2

ONLINE SERVICE, WITH OCU, WITHOUT HEAD UNIT CODING, WITHOUT ENGINE IMMOBILIZER INTERCONNECTION

EM1

DRIVER ALERT SYSTEM

ER1

REGIONAL CODE " ECE " FOR RADIO

**EWO**

WITHOUT MAINTENANCE CONTRACT

**F0A**

NO SPECIAL PURPOSE VEHICLE, STANDARD EQUIPMENT

**FM0**

BASIC EQUIPMENT VARIANT

**G04**

SHOCK ABSORPTION IN FRONT

**G0K**

6-SPEED MANUAL TRANSMISSION

**GW0**

WITHOUT CAR2X

**IA0**

WITHOUT BRACKET

**IG0**

STANDARD CURB WEIGHT RANGE

**IIO**

WITHOUT BUILT-IN CUPBOARD

**IM0**

FRONT AXLE WEIGHT, STANDARD

**IN1**

REAR AXLE WEIGHT, TYPE 1

**ISO**

WITHOUT INTERFACE FOR EXTERNAL USE

**J0V**

BATTERY 420 A (70 AH)

**J73**

SUSPENSION RANGE 73



K4B

WINDOW VAN

KA0

WITHOUT CAMERA SYSTEMS/ACCIDENT SENSORS

KH6

ELECTRONICALLY CONTROLLED AIR CONDITIONING SYSTEM

KK3

REFRIGERANT R1234YF

L0L

LEFT-HAND DRIVE

L32

SUSPENSION RANGE 32 INSTALLATION CONTROL ONLY, NO REQUIREMENT FORECAST

M0H

4-CYL. TURBO DIESEL ENGINE 2.0 L/75 KW TDI COMMON RAIL BASE ENGINE IS T29/TQ4/TOP

N0L

SEAT TRIM COVERS IN FABRIC

NY0

STANDARD BATTERY/ALTERNATOR CAPACITY

NZ2

PAN-EUROPEAN EMERGENCY CALL SERVICE

Q1A

STANDARD SEATS IN FRONT

QC1

DARK TINTED GLASS IN REAR SEAT AREA HEAT-INSULATING GLASS IN FRONT AREA

QE0

WITHOUT STORAGE COMPARTMENT PACKAGE/BOX

QG1

SERVICE INTERVAL PROLONGATION

QH0

WITHOUT VOICE CONTROL

Q16

SERVICE INDICATOR 30 000 KM OR 2 YEARS ( VARIABLE )

QK1

WITH MULTIFUNCTION CAMERA

QN0

WITHOUT DRAWERS UNDER FRONT SEATS

QR8

WITHOUT DYNAMIC ROAD SIGN DISPLAY

QV3

DIGITAL RADIO RECEPTION

T6M

4-CYLINDER DIESEL ENGINE 2.0 L UNIT 05L.C

U5A

INSTRUMENT CLUSTER, KM/H SPEEDOMETER

U9C

2 X USB TYPE C

UC7

REAR SHOCK ABSORPTION, SUSPENSION WITH INCREASED RIDE HEIGHT

V0A

TIRES WITHOUT SPECIFICATION OF TIRE BRAND

V36

STEEL WHEELS 6.5J X 17

VF0

STANDARD PEDAL CLUSTER

X7Y

EQUIPMENT OPTIONS SUBSET FOR EXPORT (OTHERS)

## Cronologie

Cronologia înregistrărilor pentru acest vehicul

S-au găsit 4 înregistrări

## Ultimele înregistrări

01.2022 🌐 Țară necunoscută

### A fost fabricat

Țara (sau statul) indică fie locația centrului de producție, uzina de asamblare sau adresa de înregistrare a producătorului. Data poate fi aproximativă.

02.2022 🇷🇴 România

### A fost înmatriculat

Înregistrarea reprezintă un eveniment administrativ. Acest lucru ar putea fi legat de o schimbare de proprietar, documente etc

03.2023 🇷🇴 România

### Evaluare de daune detectată

Avem indicii că acest vehicul a fost supus unei evaluări de daune în această țară (sau stat). Pentru informații detaliate, te rugăm să consulți secțiunea "Daune" .

09.2024 🇷🇴 România

### A fost verificat

A fost înregistrat un eveniment de inspecție tehnică (cunoscut și sub denumirea de ITP, test tehnic sau test de control al emisiilor). Pot fi incluse atât instanțe reușite, cât și eșuate.



+31

### Surse de date

Am verificat 900+ de surse de date în 35 de țări