



Volkswagen Tiguan

VIN: WVGZZZ5NZFW602143

Diesel

2015

Generat pe 10.02.2025, 06:15



Odometru

✓ Arată bine



Statut legal

✓ Arată bine



Daune

✓ Arată bine



+31

Surse de date

Am verificat 900+ de surse de date în 35 de țări

Furt

Vehiculul este declarat furat în prezent? A fost furat în trecut? A fost recuperat?




Nu s-au găsit probleme

Nu am găsit nicio înregistrare că vehiculul a fost furat.



Notă

Am încheiat verificarea bazelor de date ale poliției privind vehiculele furate din 9 țări:  +3

Iată ce am verificat:



Căutat drept furat

✓ Nu s-a găsit nicio înregistrare



Furat în trecut


✓ Nu s-a găsit nicio înregistrare Starea actuală necunoscută



Furat în trecut

✓ Nu s-a găsit nicio înregistrare Vehiculul a fost recuperat


Bazele de date ale poliției cu vehicule furate verificare finalizată în:


 România

 Lituania

 Statele Unite ale Americii

 Danemarca

 Slovacia

 Slovenia

 Suedia

 Cehia


 Italia

Odometru

Există semne conform cărora kilometrajul a fost dat înapoi sau sunt discrepanțe de kilometraj?

Notă

Ultimul kilometraj cunoscut: 205.978 km



Disclaimer (declinarea responsabilității): acest grafic reprezintă o tendință estimată a kilometrajului. Deși se bazează pe înregistrări reale de kilometraj disponibile pentru acest vehicul, există lacune având în vedere că evoluția kilometrajului nu este înregistrată în mod constant. Pentru a lua în considerare aceste date lipsă, aplicăm un model patentat de analiză a datelor care prezice modul în care probabil s-a schimbat kilometrajul între evenimentele înregistrate. Acest lucru ajută la furnizarea unei imagini mai complete a utilizării vehiculului în timp.

Statut legal

A trecut vehiculul inspecțiile tehnice? A fost marcat drept casat?

Notă

Inspecția tehnică a fost transmisă pe 02.2025 în România

Legal

✓= **Inspecție tehnică periodică (ITP)** **A trecut** 02.2025 România A trecut cu succes inspecția tehnică
○= Valabil până la 07.2027

↺↻ **Casat** ✓ Nu s-a găsit nicio înregistrare Nu există nicio înregistrare că vehiculul a fost marcat drept casat

Daune

Acest vehicul a fost avariat în trecut ? Care a fost valoarea daunelor?

✓ Nu s-au găsit probleme

Înregistrări de daune



Ocazional pot apărea inexactități, mai ales la verificarea vehiculelor vechi. Atelierele clandestine de reparații pot deghiza ilegal defectele sau daunele vehiculelor, fără să declare nicăieri existența lor. Uneori până și plăcuțele VIN ale vehiculului pot fi înlocuite. Avem o varietate de metode de a detecta chiar și astfel de infracțiuni, dar este imposibil de oferit o garanție de 100%.

Dezastre naturale

Locația vehiculului a fost înregistrată în zona unui dezastru natural?

✓ Nu s-au găsit probleme
Locația vehiculului nu a fost înregistrată în zona unui dezastru natural

Valoare de piață

Cu cât s-a vândut vehiculul în trecut? Care este prețul mediu pentru un vehicul din același model și an?

i Notă

- Prețul mediu de pe piață pentru un astfel de vehicul: 67.172 RON
- Atenție la problemele ascunse dacă vehiculul a fost la vânzare la un preț semnificativ mai mic decât prețul actual!

Valoarea actuală de piață pentru Volkswagen Tiguan 2015

Valoarea de piață este determinată prin examinarea prețului unui anumit model de mașină (fabricat în același an) în țara în care a fost generat raportul. Analizăm datele din ultimele 6 luni.

Cel mai mic preț

Prețul mediu

Cel mai mare preț

64.350 RON

67.172 RON

71.228 RON

Emisii

Care este nivelul de emisii de CO2 al vehiculele din acest model/an?



Notă

Emisii CO2: C (153 g/km)

Emisii CO₂

Emisiile de CO2 ale
vehiculului tău

153 g/km Clasă **C**

Până la 120

120 - 140

140 - 155

155 - 165

165 - 190

190 - 225

225 și peste

Emisii CO₂ g/km

Specificații și echipare

Ce specificații și echipamente sunt înregistrate pentru acest vehicul?



Notă

Verifică dacă specificațiile și echipamentul acestui vehicul se potrivesc cu datele furnizate de vânzător.

Identificare și specificații tehnice



Producător

Volkswagen



Model

Tiguan



Tip caroserie

Hatchback



An de fabricație

2015



Capacitate cilindrică

2 l



Putere motor


103 kW (138 cp)





Tip combustibil


Diesel


 Cutie de viteze
Automată

 Tip transmisie
Tracțiune integrală (AWD)

 Culoare
Gri

 Amplasarea volanului
Volan pe stânga

 Nr. cilindri
4

 Nr. locuri
5

 Cod motor
CFF

 Categorie
m1

Echipare

Cum a fost primit de la producător

0AK

FRONT STABILIZER

0EX

INSTALLATION DIFFERENTIATION FOR TRANSMISSION
DQ500 -- VEHICLE COMPONENTS --

0FW

WOLFSBURG MANUFACTURING SEQUENCE

0NA

WITHOUT NAMEPLATE SET (WITHOUT MODEL
DESIGNATION)

0VC

INFORMATION KIT IN GERMAN

0YF

WEIGHT RANGE 6 INSTALLATION CONTROL ONLY, NO
REQUIREMENT FORECAST

1D4

TRAILER HITCH, MANUALLY SWIVELING

0BE

REAR STABILIZER

0F9

COOLED FUEL SYSTEM FOR DIESEL ENGINE

0KZ

DECALS FOR SPECIAL EDITIONS

0TD

FLOOR MATS IN FRONT AND REAR

0Y1

STANDARD CLIMATIC ZONES

1AT

ELECTRONIC STABILITY CONTROL (ESC)

1E0

WITHOUT ACTIVATED CARBON CANISTER

1EX

SPECIAL IDENTIFICATION PLATE FOR EC FOR M1 PASSENGER VEHICLE

1JK

REAR SHOCK ABSORPTION, SPORTS VERSION

1LJ

DISK BRAKES IN FRONT

1NP

WHEEL CENTER TRIM

1Q1

MASS DAMPER FOR STEERING WHEEL, 26.5 HZ

1SA

WITHOUT ADDITIONAL FRONT UNDERBODY GUARD

1U9

FOLDING TABLE ON FRONT SEAT BACKRESTS

1X1

FOUR WHEEL DRIVE

1Z0

INITIAL STANDARD FUEL FILLING

2FQ

LEATHER-WRAPPED MULTIFUNCTION SPORTS STEERING WHEEL W/ TIPTRONIC

2H0

WITHOUT "DRIVE SELECT"

2KW

LABELS/PLATES IN GERMAN, FRENCH, AND DUTCH

2WA

WITHOUT ADDITIONAL TIRES

3C7

3-POINT SEAT BELT FOR CENTER REAR SEAT

3FA

WITHOUT ROOF INSERT (STANDARD ROOF)

3H2

BACKREST RELEASE FOR RIGHT FRONT SEAT

3L3

MANUAL HEIGHT ADJUSTMENT FOR FRONT SEATS

1G8

BREAKDOWN KIT

1KU

DISK BRAKES IN REAR

1N3

SPEED-RELATED VARIABLE STEERING ASSIST (SERVOTRONIC)

1PE

WHEEL BOLTS WITH ANTI-THEFT PROTECTION (UNLOCKABLE)

1S2

TOOL KIT

1T3

FIRST AID KIT WITH WARNING TRIANGLE

1VG

INSTALLATION PARTS FOR FOUR-CYLINDER ENGINE

1Y0

WITHOUT DIFFERENTIAL LOCK

2A0

WITHOUT DELIVERY EQUIPMENT

2G5

FILLER NECK MODULE 1 WITHOUT INSERT

2JD

SPORTS BUMPERS

2UC

SPORTS VERSION

3B4

CHILD SEAT ANCHOR FOR CHILD SEAT SYSTEM ISOFIX

3CX

NET PARTITION

3GN

VARIABLE CARGO AREA

3K0

WITHOUT SAFETY HEAD RESTRAINT SYSTEM

3M0

WITHOUT SPECIAL MEASURES

3Q6

THREE REAR HEAD RESTRAINTS

3S1

BRIGHT ROOF RAILS

3TF

COMFORT SEAT IN FRONT, LEFT

3ZB

3-POINT SEAT BELTS, OUTER REAR WITH ECE LABEL

4AF

DOOR AND SIDE TRIM PANEL IN FOAM FILM AND WOVEN FABRIC

4E0

TAILGATE/TRUNK LID UNLOCKING FROM OUTSIDE

4I2

CENTRAL LOCKING WITH RADIO REMOTE CONTROL, INTERIOR RELEASE MECHANISM WITHOUT SAFELOCK

4L6

BREAKAWAY INTERIOR REARVIEW MIRROR, AUTO-DIMMING

4U5

LUGGAGE POCKETS ON BACKREST

4X3

SIDE AIRBAG IN FRONT, WITH CURTAIN AIRBAG

5C0

WITHOUT SPECIAL BODY MEASURES

5J0

WITHOUT REAR SPOILER

5KN

REAR SEAT BENCH/BACKREST, SPLIT FOLDING

5RQ

RIGHT EXTERIOR MIRROR, CONVEX

5XI

SUN VISORS WITH MIRROR, ILLUMINATED, AIRBAG LABEL ON SUN VISOR

6A0

WITHOUT FIRE EXTINGUISHER

3QT

3-POINT SEAT BELTS IN FRONT, WITH PRETENSIONER AND HEIGHT ADJUSTMENT

3SF

COMFORT SEAT, FRONT RIGHT

3U1

FOLDING TRUNK COVER

4A3

SEAT HEATER FOR FRONT SEATS SEPARATELY CONTROLLED

4B3

PROTECTIVE SIDE MOLDING

4GF

WINDSHIELD IN HEAT-INSULATING GLASS

4KF

SIDE WINDOWS IN HEAT-INSULATING GLASS, FROM B-PILLAR AND REAR WINDOW DARK TINTED

4M6

BEVERAGE HOLDERS

4UF

DRIVER AND FRONT PASSENGER AIRBAG WITH FRONT PASSENGER AIRBAG DEACTIVATION

4ZB

BRIGHT MOLDINGS

5D1

CARRIER FREQUENCY 433.92 MHZ-434.42 MHZ

5K7

TRANSPORT PROTECTION FILM (MINIMUM PROTECTION) WITH ADDITIONAL TRANSPORT PROTECTION MEASURES

5MB

DECORATIVE INSERTS

5SL

LEFT EXTERIOR MIRROR: ASPHERICAL

5ZC

HEAD RESTRAINTS FOR FRONT SEATS (X-ADJUSTMENT)

6E3

CENTER ARMREST IN FRONT

6KL

RADIATOR GRILLE

6NT

MOLDED HEADLINER

6Q2

LEATHER GEARSHIFT KNOB/HANDLE

6T1

INTERIOR LIGHT IN FOOTWELL

6XQ

EXTERIOR MIRRORS: WITH MEMORY FEATURE,
POWER-FOLDING/ADJUSTABLE, SEPARATELY HEATED

7AA

ELECTRONIC ENGINE IMMOBILIZER

7E6

ELECTRIC AUXILIARY AIR HEATER

7JJ

VEHICLE CLASS DIFFERENTIATION 5N0-

7L6

START/STOP SYSTEM WITH REGENERATIVE BRAKING

7N1

OVERHEAD STORAGE COMPARTMENT

7QL

INTEGRATED DATA STORAGE DEVICE FOR WESTERN
EUROPE

7UC

NAVIGATION SYSTEM "RNS315" (INTEGRATED DATA
STORAGE DEVICE)

7Y0

WITHOUT LANE CHANGE ASSIST

8G0

WITHOUT LIGHT CONTROL

8IM

GAS-DISCHARGE HEADLAMPS WITH CORNERING
LIGHT

8N3

WINDSHIELD WIPER INTERMITTENT CONTROL WITH
RAIN SENSOR

6M0

WITHOUT TIE DOWN STRAPS/NET/POCKET

6P1

REAR LICENSE PLATE CARRIER (ECE)

6SJ

LUGGAGE COMPARTMENT FLOOR COVERING,
REVERSIBLE MAT (RUBBER/FABRIC)

6W1

FRONT LICENSE PLATE CARRIER (LARGE)

7A0

WITHOUT CD CHANGER/CD PLAYER

7B3

12-VOLT SOCKET(S)

7G0

WITHOUT PREPARATION FOR VTS (VEHICLE
TRACKING SYSTEM)

7K1

DIRECT TIRE PRESSURE MONITORING SYSTEM

7MJ

EMISSION STANDARD EU5 PLUS

7P4

MANUALLY ADJUSTABLE LUMBAR SUPPORT IN
FRONT SEATS

7R3

SIDE TURN SIGNALS (WHITE)

7X5

PARK ASSIST

8AY

RADIO NAVIGATION SYSTEM

8GU

ALTERNATOR 140 A

8K3

SEPARATE DAYTIME RUNNING LIGHTS WITH
AUTOMATIC HEADLAMP ACTIVATION AND COMING
HOME FEATURE

8Q5

HEADLIGHT RANGE ADJUSTMENT, AUTOMATIC/
DYNAMIC, WITH CORNERING LIGHT (AFS 1)

8RM

8 SPEAKERS (PASSIVE)

8SA

TAIL LAMP ASSEMBLIES, STANDARD DESIGN

8TC

REAR FOG LAMP FOR DRIVING ON THE RIGHT

8WH

FRONT FOG LAMP AND CORNERING LAMP

8Y1

TWO-TONE HORN

8ZH

ANTENNA FOR AM/FM RECEPTION, "DIVERSITY"

9AK

CLIMATRONIC WITH IMPACT PRESSURE CONTROL,
CFC-FREE

9M0

WITHOUT AUXILIARY HEATER/FUEL-FIRED PARKING
HEATER

9Q4

MULTI-FUNCTION DISPLAY/ON-BOARD
COMPUTERWITH CHECK CONTROL

9WC

WITHOUT "MULTIMEDIA" IN VEHICLE

9Z0

OPERATING VOLTAGE 12 V

A8F

SPORTS EQUIPMENT

B01

TYPE APPROVAL COUNTRY GERMANY

C0J

ALLOY WHEELS 8J X 18

D91

4-CYL.TURBO DIESEL ENG.2.0 L/103 KW (4V)TDI
COMMON RAIL; BASE ENGINE IS
TG3/TJ3/T5P/TU3/TU4/TL4/TP4/TM3/TW3/TR4/TS1/TN5

EA0

WITHOUT FOLLOW-ON WARRANTY

EM1

DRIVER ALERT SYSTEM

8S7

2 READING LIGHTS IN FRONT

8T2

CRUISE CONTROL SYSTEM (CCS) ELECTRONIC

8W1

WASHER FLUID LEVEL INDICATOR

8X1

HEADLAMP WASHER SYSTEM

8Z5

NOT HOT COUNTRY

9A0

WITHOUT TAXI ALARM SYSTEM

9JA

NON-SMOKER'S PACKAGE

9P3

BELT CONTROL, ELECTRIC CONTACT IN BUCKLE

9T1

HEATED WASHER NOZZLES IN FRONT

9Y1

OUTDOOR TEMPERATURE GAGE

9ZU

MOBILE PHONE INTERFACE

AV1

DRIVING ON THE RIGHT

B0A

COMPONENT PARTS SET WITHOUT COUNTRY-
SPECIFIC BUILDING REGULATION

C20

OPERATING PERMIT, ALTERATION

E15

CLUB & LOUNGE

ELO

WITHOUT ONLINE SERVICE

FOA

FB0

STANDARD PAINT COATING

G03

SHOCK ABSORPTION IN FRONT

GP1

VEHICLES WITH SPECIAL UPGRADE MEASURES

J2D

BATTERY 380 A (68 AH)

KA2

WITH REAR VIEW CAMERA SYSTEM (TYPE 2)

L0L

LEFT-HAND DRIVE

N2Z

SEAT TRIM COVERS FOR SPECIAL EDITIONS

QE0

WITHOUT STORAGE COMPARTMENT PACKAGE/BOX

QI6

SERVICE INDICATOR 30 000 KM OR 2 YEARS (VARIABLE)

QK0

WITHOUT MULTIFUNCTION CAMERA

QQ3

INTERIOR AMBIENT LIGHTING AND SURROUND LIGHTING

QV0

WITHOUT TV RECEPTION/DIGITAL RADIO RECEPTION

U5A

INSTRUMENT CLUSTER, KM/H SPEEDOMETER

UG6

HILL START ASSIST

V0A

TIRES WITHOUT SPECIFICATION OF TIRE BRAND

VL1

EXTENDED PEDESTRIAN PROTECTION MEASURES

X0A

EQUIPMENT OPTIONS SUBSET FOR GERMANY

NO SPECIAL PURPOSE VEHICLE, STANDARD EQUIPMENT

FC1

CUSTOMIZED INSTALLATION

G1D

7-SPEED AUTOMATIC TRANSMISSION FOR FOUR-WHEEL DRIVE

HV1

TIRES 235/50 R18 97V

K8G

HATCHBACK

KL1

LED LICENSE PLATE LIGHTING

L10

SUSPENSION RANGE 10 INSTALLATION CONTROL ONLY, NO REQUIREMENT FORECAST

NY0

STANDARD BATTERY/ALTERNATOR CAPACITY

QG1

SERVICE INTERVAL PROLONGATION

QJ1

CHROME PACKAGE

QN3

DRAWERS UNDER FRONT SEATS

QR0

WITHOUT COMPASS/ROAD SIGN DISPLAY/ DYNAMIC ROAD SIGN DISPLAY

TL4

4-CYLINDER DIESEL ENGINE 2.0 L UNIT 03L.L

UF6

ELECTRIC INTERFACE FOR EXTERNAL USE (MDI)

UH2

PARKING BRAKE

VF0

STANDARD PEDAL CLUSTER

VT9

SCUFF PLATES FOR SPECIAL EDITIONS

Cronologie

S-au găsit 5 înregistrări

Cronologia înregistrărilor pentru acest vehicul

Ultimele înregistrări

01.2015 🌐 Țară necunoscută



A fost fabricat

Țara (sau statul) indică fie locația centrului de producție, uzina de asamblare sau adresa de înregistrare a producătorului. Data poate fi aproximativă.

01.2019 🇷🇴 România



A fost înmatriculat

Înregistrarea reprezintă un eveniment administrativ. Acest lucru ar putea fi legat de o schimbare de proprietar, documente etc

01.2021 🇷🇴 România



A fost verificat

A fost înregistrat un eveniment de inspecție tehnică (cunoscut și sub denumirea de ITP, test tehnic sau test de control al emisiilor). Pot fi incluse atât instanțe reușite, cât și eșuate.

02.2023 🇷🇴 România



A fost verificat

A fost înregistrat un eveniment de inspecție tehnică (cunoscut și sub denumirea de ITP, test tehnic sau test de control al emisiilor). Pot fi incluse atât instanțe reușite, cât și eșuate.

02.2025 🇷🇴 România



A fost verificat

A fost înregistrat un eveniment de inspecție tehnică (cunoscut și sub denumirea de ITP, test tehnic sau test de control al emisiilor). Pot fi incluse atât instanțe reușite, cât și eșuate.



+31

Surse de date

Am verificat 900+ de surse de date în **35 de țări**