

Volkswagen Tiguan

VIN: WVGZZZ5NZHW842691

Diesel

2016

Generat pe 2025-01-17 06:55



Odometru

✓ Arată bine



Statut legal

✓ Arată bine



Daune

⚠ Necesită atenție



+31

Surse de date

Am verificat 900+ de surse de date în 35 de țări

Furt

Vehiculul este în prezent marcat ca furat? A fost furat în trecut? A fost recuperat?




Nu s-au găsit probleme

Nu am găsit nicio înregistrare că vehiculul a fost furat.



Notă

Verificarea bazei de date a poliției privind vehiculele furate finalizată în 8 țări:  +2

Iată ce am verificat:



Căutat drept furat

✓ Nu s-a găsit nici o înregistrare



Furat în trecut

✓ Nu s-a găsit nici o înregistrare

Starea actuală necunoscută



Furat în trecut

✓ Nu s-a găsit nici o înregistrare

Vehiculul a fost recuperat

Baza de date aparținând poliției cu vehicule furate, **verificare finalizată în:**



România



Lituania



Slovacia




Odometru

Există semne conform cărora kilometrajul a fost dat înapoi sau discrepanțe ale kilometrajului?

Notă

Ultimul kilometraj cunoscut: 157.944 km




Disclaimer (declinarea responsabilității): acest grafic reprezintă o tendință estimată a kilometrajului. Deși se bazează pe înregistrări reale de kilometraj disponibile pentru acest vehicul, există lacune având în vedere că evoluția kilometrajului nu este înregistrată în mod constant. Pentru a lua în considerare aceste date lipsă, aplicăm un model patentat de analiză a datelor care prezice modul în care probabil s-a schimbat kilometrajul între evenimentele înregistrate. Acest lucru ajută la furnizarea unei imagini mai complete a utilizării vehiculului în timp.

Statut legal

A trecut vehiculul inspecțiile tehnice? A fost notat drept casat?

i Notă

Inspecția tehnică a fost transmisă pe 2021-03 în  **România**

Legal



Inspecție tehnică periodică (ITP)

A trecut

2021-03  **România**

A trecut cu succes inspecția tehnică

Valabil până la 2025-04



Casat

✓ Nu s-a găsit nici o înregistrare

Nu există nici o înregistrare că vehiculul a fost marcat drept casat

Daune

Acest vehicul a fost avariat în trecut ? Care a fost valoarea daunelor?

 **Ai grijă!**

Vehiculul a fost avariat de 2 ori!

i Notă

Daunele minore nu vor afecta în mod normal siguranța vehiculului și nu vor cauza probleme structurale

Înregistrări de daune



Daune pe partea stângă **Stânga / Portieră față**

Daune frontale: **Față / Bară de protecție**

Față / Parbriz

Față stânga / Bară de protecție

Față dreapta / Bară de protecție

Daune pe partea dreaptă: **Dreapta / Portieră față**

Daune pe partea dreaptă: **Spate / Bară de protecție**

Spate stânga / Bară de protecție

Spate dreapta / Bară de protecție

Alte daune: **Acoperiș / Structură**

2019-09

România

Daune

Costul estimativ al reparațiilor

24.001 RON – 48.000 RON

Cauza posibilă a daunelor

Necunoscut

Categoriile de daune

Părți exterioare ale caroseriei

Sticlă

Elemente structurale ale caroseriei



Daune frontale: **Față / Bară de protecție**

Față stânga / Bară de protecție

Față dreapta / Bară de protecție

2020-08

România

Daune

Costul estimativ al reparațiilor

14.001 RON – 24.000 RON

Cauza posibilă a daunelor

Necunoscut

Categoriile de daune

Părți exterioare ale caroseriei

Iluminat exterior

Elemente structurale ale caroseriei

Disclaimer (declinarea responsabilității): Majoritatea înregistrărilor de daune sunt legate de accidente, dar uneori nu este acesta cazul. Unele înregistrări provin din alte surse cum ar fi serviciile specializate pe lucrări de caroserie, cereri de daune, licitații sau inspecții ale vehiculelor. Aceste înregistrări arată că starea vehiculului a fost evaluată, chiar dacă nu a fost din cauza unui accident.

Dezastre naturale

Locația vehiculului a fost înregistrată în zona unui dezastru natural?

✓ Nu s-au găsit probleme

Locația vehiculului nu a fost înregistrată în zona unui dezastru natural

Valoarea de piață

Cu cât s-a vândut vehiculul în trecut? Care este în medie prețul vehiculelor din acest model și an?

i Notă

- Prețul mediu de pe piață pentru un astfel de vehicul: 75.830 RON
- Atenție la problemele ascunse dacă vehiculul a fost la vânzare la un preț semnificativ mai mic decât prețul actual!

Valoarea de piață azi pentru Volkswagen Tiguan 2016

Valoarea de piață este determinată prin examinarea prețului unui anumit model de mașină (fabricat în același an) în țara în care a fost generat raportul. Analizăm datele din ultimele 6 luni.

Cel mai mic preț

73.188 RON

Prețul mediu

75.830 RON

Cel mai mare preț

79.671 RON

Emisii

Câte emisii de CO2 produc vehiculele din acest model/an?

i Notă

Emisii CO2: B (139 g/km)

Emisii CO₂

Emisiile CO₂ ale
vehiculului tău

139 g/km Clasă **B**

Până la 120

120 - 140

140 - 155

155 - 165

165 - 190

190 - 225

225 și peste

Emisii CO₂ g/km

Specificații și echipare

Ce specificații și echipamente sunt înregistrate pentru acest vehicul?

Notă

Verificați dacă specificațiile și echipamentul acestui vehicul se potrivesc cu datele furnizate de vânzător.

Identificare și specificații tehnice



Producător

Volkswagen



Model

Tiguan



Tip caroserie

Hatchback



An de fabricație

2016



Capacitate cilindrică

2 l



Putere motor

110 kW (148 cp)



Tip combustibil

Diesel



Cutie de viteze

Manuală



Tip transmisie

Tracțiune integrală (AWD)



Culoare

Gri



Amplasarea volanului

Volan pe stânga



Nr. cilindri

4



Nr. locuri

5



Cod motor

DFGA



Categorie

m1g

Echipare

Cum a fost primit de la producător

0AL

FRONT STABILIZER

0B3

WHEELBASE

0BG

REAR STABILIZER

0EN

INSTALLATION DIFFERENTIATION FOR TRANSMISSION MQ 350 -- VEHICLE COMPONENTS --

0F5

FUEL SYSTEM FOR DIESEL ENGINE

0FW

WOLFSBURG MANUFACTURING SEQUENCE

0K0

WITHOUT ALTERNATIVE DRIVE SYSTEM

0KA

WITHOUT DECALS AND EMBLEMS

0TD

FLOOR MATS IN FRONT AND REAR

0XH

INFORMATION KIT IN ROMANIAN

0Y1

STANDARD CLIMATIC ZONES

0YQ

WEIGHT RANGE 15 INSTALLATION CONTROL ONLY, NO REQUIREMENT FORECAST

1AT

ELECTRONIC STABILITY CONTROL (ESC)

1D0

WITHOUT TRAILER HITCH

1DG

NAMEPLATE SET "TDI"

1E9

WITHOUT ACTIVATED CARBON CANISTER WITH SCR

1EX

SPECIAL IDENTIFICATION PLATE FOR EC FOR M1 PASSENGER VEHICLE

1G9

SPACE-SAVING SPARE WHEEL FOR TEMPORARY USE, RADIAL TIRE (5-HOLE)

1JA

REAR SHOCK ABSORPTION, BASIC VERSION 1

1KU

DISK BRAKES IN REAR

1N3

SPEED-RELATED VARIABLE STEERING ASSIST (SERVOTRONIC)

1NL

TRIMS FOR ALLOY WHEELS

1PA

STANDARD WHEEL BOLTS

1S1

TOOL KIT AND JACK

1SA

WITHOUT ADDITIONAL FRONT UNDERBODY GUARD

1T2

WARNING TRIANGLE

1U9

FOLDING TABLE ON FRONT SEAT BACKRESTS

1X1

FOUR WHEEL DRIVE

1Z0

INITIAL STANDARD FUEL FILLING

1ZA

DISK BRAKES IN FRONT

2A0

WITHOUT DELIVERY EQUIPMENT

2H5

DRIVING PROFILE SELECTION AND CONVENTIONAL SHOCK ABSORBER

2JB

STANDARD BUMPERS

2KL

LABELS/PLATES IN ROMANIAN AND ENGLISH

2WA

WITHOUT ADDITIONAL TIRES

2ZH

LEATHER-WRAPPED MULTIFUNCTION STEERING WHEEL

31K

FRONT AND REAR LICENSE PLATE CARRIER (ECE)

3A0

CHILD SEAT ANCHOR FOR CHILD SEAT SYSTEM I-SIZE, 2X TOP TETHER

3C7

3-POINT SEAT BELT FOR CENTER REAR SEAT

3CA

WITHOUT PARTITION

3FA

WITHOUT ROOF INSERT (STANDARD ROOF)

3GB

CARGO AREA WITH SPLIT FUNCTION

3H2

BACKREST RELEASE FOR RIGHT FRONT SEAT

3L3

MANUAL HEIGHT ADJUSTMENT FOR FRONT SEATS

3M0

WITHOUT SPECIAL MEASURES

3P1

BRACKET FOR FIRST AID KIT AND WARNING TRIANGLE

3QT

3-POINT SEAT BELTS IN FRONT, WITH PRETENSIONER AND HEIGHT ADJUSTMENT

3S2

BLACK ROOF RAILS

3T2

THREE REAR HEAD RESTRAINTS

3U1

FOLDING TRUNK COVER

3ZU

3-POINT SEAT BELTS, OUTER REAR WITH ECE LABEL

4A3

SEAT HEATER FOR FRONT SEATS SEPARATELY CONTROLLED

4AF

DOOR AND SIDE TRIM PANEL IN FOAM FILM AND WOVEN FABRIC

4D0

WITHOUT SEAT VENTILATION/MASSAGE SEAT

4E0

TAILGATE/TRUNK LID UNLOCKING FROM OUTSIDE

4GF

WINDSHIELD IN HEAT-INSULATING GLASS

4I2

CENTRAL LOCKING WITH RADIO REMOTE CONTROL, INTERIOR RELEASE MECHANISM WITHOUT SAFELOCK

4KF

SIDE WINDOWS IN HEAT-INSULATING GLASS, FROM B-PILLAR AND REAR WINDOW DARK TINTED

4L6

BREAKAWAY INTERIOR REARVIEW MIRROR, AUTO-DIMMING

4U5

LUGGAGE POCKETS ON BACKREST

4UP

DRIVER AND FRONT PASSENGER AIRBAG WITH KNEE AIRBAG AND FRONT PASSENGER AIRBAG DEACTIVATION

4X3

SIDE AIRBAG IN FRONT, WITH CURTAIN AIRBAG

4ZB

BRIGHT MOLDINGS

5C0

WITHOUT SPECIAL BODY MEASURES

5D1

CARRIER FREQUENCY 433.92 MHZ-434.42 MHZ

5J0

WITHOUT REAR SPOILER

5K7

TRANSPORT PROTECTION FILM (MINIMUM PROTECTION) WITH ADDITIONAL TRANSPORT PROTECTION MEASURES

5KR

REAR SEAT BENCH/BACKREST, SPLIT FOLDING

5MB

DECORATIVE INSERTS

5RQ

RIGHT EXTERIOR MIRROR, CONVEX

5SL

LEFT EXTERIOR MIRROR: ASPHERICAL

5XI

SUN VISORS WITH MIRROR, ILLUMINATED, AIRBAG LABEL ON SUN VISOR

5ZC

HEAD RESTRAINTS FOR FRONT SEATS (X-ADJUSTMENT)

6A0

WITHOUT FIRE EXTINGUISHER

6E4

CENTER ARMREST IN FRONT

6K2

FORWARD COLLISION WARNING INCL. AUTONOMOUS EMERGENCY BRAKING, WITHOUT ADAPTIVE CRUISE CONTROL

6KL

RADIATOR GRILLE

6M0

WITHOUT TIE DOWN STRAPS/NET/POCKET

6NA

UNSPLIT MOLDED HEADLINER

6Q2

LEATHER GEARSHIFT KNOB/HANDLE

6SE

LUGGAGE COMPARTMENT FLOOR COVERING IN FLAT NEEDLE-PUNCHED NONWOVEN

6T1

INTERIOR LIGHT IN FOOTWELL

6XN

EXTERIOR MIRRORS: POWER-ADJUSTABLE, SEPARATELY HEATED

7AA

ELECTRONIC ENGINE IMMOBILIZER

7B3

12-VOLT SOCKET(S)

7E6

ELECTRIC AUXILIARY AIR HEATER

7IX

VEHICLE CLASS DIFFERENTIATION -550-

7K1

DIRECT TIRE PRESSURE MONITORING SYSTEM

7L6

START/STOP SYSTEM WITH REGENERATIVE BRAKING

7M5

WITHOUT PROTECTIVE FILM FOR SCUFF PLATE

7MM

EMISSION STANDARD EU6 PLUS

7N1

OVERHEAD STORAGE COMPARTMENT

7P4

MANUALLY ADJUSTABLE LUMBAR SUPPORT IN FRONT SEATS

7Q0

WITHOUT NAVIGATION DEVICE

7QA

WITHOUT CD/DVD FOR NAVIGATION

7W0

WITHOUT EXTENDED SAFETY SYSTEM

7X2

PARK DISTANCE CONTROL IN FRONT AND REAR

7Y4

LANE KEEPING SYSTEM

8FA

WITHOUT SECOND BATTERY

8G1

HIGH-BEAM CONTROL

8GU

ALTERNATOR 140 A

8IT

LED HEADLAMPS

8K3

SEPARATE DAYTIME RUNNING LIGHTS WITH AUTOMATIC HEADLAMP ACTIVATION AND COMING HOME FEATURE

8N6

WINDSHIELD WIPER INTERMITTENT CONTROL WITH LIGHT/RAIN SENSOR

8Q3

AUTOMATIC HEADLIGHT RANGE ADJUSTMENT DYNAMIC (SELF-ADJUSTING WHILE DRIVING)

8RM

8 SPEAKERS (PASSIVE)

8S4

TWO READING LIGHTS IN FRONT, TWO IN REAR

8SK

LED TAIL LAMP ASSEMBLY

8T6

CRUISE CONTROL SYSTEM AND SPEED LIMITER

8TB

REAR FOG LAMP

8W1

WASHER FLUID LEVEL INDICATOR

8WH

FRONT FOG LAMP AND CORNERING LAMP

8X1

HEADLAMP WASHER SYSTEM

8Y1

TWO-TONE HORN

8Z5

NOT HOT COUNTRY

8ZQ

ANTENNA FOR FM RECEPTION ONLY, DIVERSITY

9E5

LUGGAGE COMPARTMENT LAMP

9JC

SMOKER'S VERSION

9M0

WITHOUT AUXILIARY HEATER/FUEL-FIRED PARKING HEATER

9P9

SEAT BELT REMINDER, ELECTRIC CONTACT IN THE BUCKLE, ADVANCED SAFETY EQUIPMENT

9S6

MULTI-FUNCTION DISPLAY/ON-BOARD COMPUTER"COLOUR"

9T1

HEATED WASHER NOZZLES IN FRONT

9WC

WITHOUT "MULTIMEDIA" IN VEHICLE

9Z0

OPERATING VOLTAGE 12 V

9ZX

MOBILE PHONE INTERFACE

A62

CATEGORY 2

A8C

COMFORT EQUIPMENT

AV1

DRIVING ON THE RIGHT

B0A

COMPONENT PARTS SET WITHOUT COUNTRY-SPECIFIC BUILDING REGULATION

B43

TYPE APPROVAL COUNTRY ROMANIA

BG

ESC SPECIAL VEHICLE 14

C29

OPERATING PERMIT, ALTERATION

CQ9

ALLOY WHEELS 7J X 17

DN4

4-CYL. TURBO DIESEL ENGINE 2.0 L/110 KW (4V) TDI COMMON RAIL; B.ENGINE T37/T6F
TS1/TR1/T0P/T0N/T13/T29/TM4/TD1/TI9/T1I

E0A

NO SPECIAL EDITION

EA0

WITHOUT FOLLOW-ON WARRANTY

EF1

ECO FUNCTION

ELO

WITHOUT ONLINE SERVICE

EM1

DRIVER ALERT SYSTEM

ER1

REGIONAL CODE " ECE " FOR RADIO

ES0

WITHOUT VEHICLE INLET

FOA

NO SPECIAL PURPOSE VEHICLE, STANDARD EQUIPMENT

FB0

STANDARD PAINT COATING

FC0

WITHOUT CUSTOMIZED INSTALLATION

FM0

BASIC EQUIPMENT VARIANT

G01

SHOCK ABSORPTION IN FRONT

G0L

SIX-SPEED MANUAL TRANSMISSION FOR FOUR-WHEEL DRIVE VEHICLE

H82

TIRES 215/65 R17 99V SUPER-LOW ROLLING RESISTANCE

I8E

STANDARD RADIO (GEN2)

J2D

BATTERY 380 A (68 AH)

K8G

HATCHBACK

KA0

WITHOUT CAMERA SYSTEMS/ACCIDENT SENSORS

KH7

CLIMATRONIC (3-ZONE) WITH REAR AIR CONDITIONING CONTROL PANEL

KK3

REFRIGERANT R1234YF

KL1

LED LICENSE PLATE LIGHTING

KS0

WITHOUT HEAD-UP DISPLAY

L04

SUSPENSION RANGE 04 INSTALLATION CONTROL ONLY, NO REQUIREMENT FORECAST

L0L

LEFT-HAND DRIVE

N0U

SEAT TRIM COVERS IN VELOUR

NY0

STANDARD BATTERY/ALTERNATOR CAPACITY

NZ0

WITHOUT CALL FEATURE

Q2J

COMFORT SEATS IN FRONT

QE0

WITHOUT STORAGE COMPARTMENT PACKAGE/BOX

QG1

SERVICE INTERVAL PROLONGATION

QH0

WITHOUT VOICE CONTROL

QI6

SERVICE INDICATOR 30 000 KM OR 2 YEARS (VARIABLE)

QJ1

CHROME PACKAGE

QK1

WITH MULTIFUNCTION CAMERA

QN3

DRAWERS UNDER FRONT SEATS

QQ0

WITHOUT ADD. LIGHTS (INTERIOR LIGHTING)

QR8

WITHOUT DYNAMIC ROAD SIGN DISPLAY

QV0

WITHOUT TV RECEPTION/DIGITAL RADIO RECEPTION

TR1

4-CYLINDER DIESEL ENGINE 2.0 L UNIT 04L.A

U5A

INSTRUMENT CLUSTER, KM/H SPEEDOMETER

UG2

HILL DESCENT CONTROL

UH2

PARKING BRAKE

UI4

ELECTRIC INTERFACE FOR EXTERNAL USE, AUX-IN JACK, USB (IPOD-CAPABLE)

UK3

MECHANICAL REAR SEAT RELEASE

V0A

TIRES WITHOUT SPECIFICATION OF TIRE BRAND

VF0

STANDARD PEDAL CLUSTER

VL4

EXTENDED AND CRASH-ACTIVE AND PROACTIVE PEDESTRIAN PROTECTION

X4N

EQUIPMENT OPTIONS SUBSET FOR ROMANIA

Siguranță

Vehiculul are vreo rechemare pe motiv de siguranță? Care este ratingul său de siguranță?



Notă

Rating de siguranță Euro NCAP: ★★★★★

Rating de siguranță

★★★★★ Siguranță de 5 stele

Performanță generală excelentă la protecția împotriva accidentelor și bine echipat cu tehnologie amplă și robustă de evitare a accidentelor



96%

Ocupant adult



84%

Copil ocupant



72%

Utilizatori vulnerabili ai drumurilor



68%

Asistență de siguranță

Cronologie

S-au găsit 7 înregistrări

Cronologia înregistrărilor pentru acest vehicul

Ultimele înregistrări

2016-01  Țară necunoscută



A fost fabricat

Țara (sau statul) indică fie locația centrului de producție, uzina de asamblare sau adresa de înregistrare a producătorului. Data poate fi aproximativă.

2016-12  România



A fost înmatriculat

Înregistrarea reprezintă un eveniment administrativ. Acest lucru ar putea fi legat de o schimbare de proprietar, documente etc

2019-01  România



A fost verificat

A fost înregistrat un eveniment de inspecție tehnică (cunoscut și sub denumirea de ITP, test tehnic sau test de control al emisiilor). Pot fi incluse atât instanțe reușite, cât și eșuate.

2019-09  România

 **Daună detectată** 

Avem indicii potrivit cărora acest vehicul a fost recunoscut ca avariat în această țară (sau stat). Pentru detalii, vă rugăm să consultați secțiunea „Daune”.

2020-08  România

 **Daună detectată** 

Avem indicii potrivit cărora acest vehicul a fost recunoscut ca avariat în această țară (sau stat). Pentru detalii, vă rugăm să consultați secțiunea „Daune”.

2021-03  România

 **A fost verificat**

A fost înregistrat un eveniment de inspecție tehnică (cunoscut și sub denumirea de ITP, test tehnic sau test de control al emisiilor). Pot fi incluse atât instanțe reușite, cât și eșuate.

2023-04  România

 **A fost înmatriculat**

Înregistrarea reprezintă un eveniment administrativ. Acest lucru ar putea fi legat de o schimbare de proprietar, documente etc



+31

Surse de date

Am verificat 900+ de surse de date în **35 de țări**