



Volkswagen Tiguan

VIN: WVGZZZ5NZNW402222

Hibrid

2021

Generat pe 21.02.2025, 07:36



Odometru

✓ Arată bine



Statut legal

✓ Arată bine



Daune

✓ Arată bine



+31

Surse de date

Am verificat 900+ de surse de date în 35 de țări

Furt

Vehiculul este declarat furat în prezent? A fost furat în trecut? A fost recuperat?



Nu s-au găsit probleme

Nu am găsit nicio înregistrare că vehiculul a fost furat.



Notă

Am încheiat verificarea bazelor de date ale poliției privind vehiculele furate din 9 țări: +3

Iată ce am verificat:



Căutat drept furat

✓ Nu s-a găsit nicio înregistrare



Furat în trecut

✓ Nu s-a găsit nicio înregistrare Starea actuală necunoscută



Furat în trecut

✓ Nu s-a găsit nicio înregistrare Vehiculul a fost recuperat

Bazele de date ale poliției cu vehicule furate verificare finalizată în:



România



Statele Unite ale Americii



Danemarca



Lituania



Slovacia



Cehia



Italia



Suedia




Slovenia

Odometru

Există semne conform cărora kilometrajul a fost dat înapoi sau sunt discrepanțe de kilometraj?

Notă

Ultimul kilometraj cunoscut: 47.407 km



Disclaimer (declinarea responsabilității): acest grafic reprezintă o tendință estimată a kilometrajului. Deși se bazează pe înregistrări reale de kilometraj disponibile pentru acest vehicul, există lacune având în vedere că evoluția kilometrajului nu este înregistrată în mod constant. Pentru a lua în considerare aceste date lipsă, aplicăm un model patentat de analiză a datelor care prezice modul în care probabil s-a schimbat kilometrajul între evenimentele înregistrate. Acest lucru ajută la furnizarea unei imagini mai complete a utilizării vehiculului în timp.

Statut legal

A trecut vehiculul inspecțiile tehnice? A fost marcat drept casat?



Nu s-au găsit probleme

Nu s-au găsit înregistrări despre statutul legal al acestui vehicul

Legal



Inspecție tehnică periodică (ITP)

Nu s-a găsit nicio înregistrare

Nu au fost găsite înregistrări ale inspecției tehnice



Casat

Nu s-a găsit nicio înregistrare

Nu există nicio înregistrare că vehiculul a fost marcat drept casat

Daune

Acest vehicul a fost avariat în trecut ? Care a fost valoarea daunelor?

✓ Nu s-au găsit probleme

Înregistrări de daune



Ocazional pot apărea inexactități, mai ales la verificarea vehiculelor vechi. Atelierele clandestine de reparații pot deghiza ilegal defectele sau daunele vehiculelor, fără să declare nicăieri existența lor. Uneori până și plăcuțele VIN ale vehiculului pot fi înlocuite. Avem o varietate de metode de a detecta chiar și astfel de infracțiuni, dar este imposibil de oferit o garanție de 100%.

Dezastre naturale

Locația vehiculului a fost înregistrată în zona unui dezastru natural?

✓ Nu s-au găsit probleme
Locația vehiculului nu a fost înregistrată în zona unui dezastru natural

Valoare de piață

Cu cât s-a vândut vehiculul în trecut? Care este prețul mediu pentru un vehicul din același model și an?

i Notă

- Prețul mediu de pe piață pentru un astfel de vehicul: 135.307 RON
- Atenție la problemele ascunse dacă vehiculul a fost la vânzare la un preț semnificativ mai mic decât prețul actual!

Valoarea actuală de piață pentru Volkswagen Tiguan 2021

Valoarea de piață este determinată prin examinarea prețului unui anumit model de mașină (fabricat în același an) în țara în care a fost generat raportul. Analizăm datele din ultimele 6 luni.

Cel mai mic preț

124.545 RON

Prețul mediu

135.307 RON

Cel mai mare preț

158.717 RON

Emisii

Care este nivelul de emisii de CO₂ al vehiculele din acest model/an?



Notă

Emisii CO₂: A (39 g/km)

Emisii CO₂

Emisiile de CO₂ ale
vehiculului tău

39 g/km Clasă **A**

Până la 120

120 - 140

140 - 155

155 - 165

165 - 190

190 - 225

225 și peste

Emisii CO₂ g/km

Specificații și echipare

Ce specificații și echipamente sunt înregistrate pentru acest vehicul?



Notă

Verifică dacă specificațiile și echipamentul acestui vehicul se potrivesc cu datele furnizate de vânzător.

Identificare și specificații tehnice



Producător

Volkswagen



Model

Tiguan



Tip caroserie

Hatchback



An de fabricație

2021



Capacitate cilindrică

1,4 l






Putere motor

110 kW (148 cp)



Tip combustibil

Hibrid

-  Cutie de viteze
Automată
-  Tip transmisie
Tracțiune față (FWD)
-  Culoare
Gri
-  Amplasarea volanului
Volan pe stânga
-  Nr. locuri
5
-  Cod motor
DGEA
-  Categorie
m1
-  Omologare
e1*2001/116*0450*59

Echipare

Cum a fost primit de la producător

- 0AL**
FRONT STABILIZER
- 0BH**
REAR STABILIZER
- 0IC**
INSTALLATION DIFFERENTIATION FOR TRANSMISSION "DQ400" -- VEHICLE COMPONENTS --
- 0KA**
WITHOUT DECALS AND EMBLEMS
- 0P0**
REAR EXHAUST TAILPIPE (STANDARD)
- 0TD**
FLOOR MATS IN FRONT AND REAR
- 0Y1**
STANDARD CLIMATIC ZONES
- 0B3**
WHEELBASE
- 0FA**
STANDARD MANUFACTURING SEQUENCE
- 0K3**
HYBRID PROPULSION SYSTEM PHEV
- 0NB**
NAMEPLATE SET IN BASIC STYLE
- 0RE**
WITHOUT ELECTRONIC STEERING COLUMN LOCK
- 0XH**
INFORMATION KIT IN ROMANIAN
- 0YT**
WEIGHT RANGE 18 INSTALLATION CONTROL ONLY, NO REQUIREMENT FORECAST

1A5

FUEL SYSTEM FOR SI ENGINE

1E5

ACTIVATED CARBON CANISTER FOR INTENSIFIED
EVAPORATION SYSTEM WITH ON-BOARD
DIAGNOSTIC SYSTEM 2

1G8

BREAKDOWN KIT

1LA

DISK BRAKES IN FRONT

1N3

SPEED-RELATED VARIABLE STEERING ASSIST
(SERVOTRONIC)

1PA

STANDARD WHEEL BOLTS

1SA

WITHOUT ADDITIONAL FRONT UNDERBODY GUARD

1U8

WITHOUT FOLDING TABLE ON FRONT SEAT
BACKREST

1Z0

INITIAL STANDARD FUEL FILLING

2A0

WITHOUT DELIVERY EQUIPMENT

2H0

WITHOUT "DRIVE SELECT"

2KL

LABELS/PLATES IN ROMANIAN AND ENGLISH

31A

WITHOUT LICENSE PLATE CARRIER

3C7

3-POINT SEAT BELT FOR CENTER REAR SEAT

3FA

WITHOUT ROOF INSERT (STANDARD ROOF)

3H2

BACKREST RELEASE FOR RIGHT FRONT SEAT

1AE

BRS FOR VEHICLES WITH ELECTRIC DRIVE (ESC AND
ELECTRIC BRAKE BOOSTER)

1EX

SPECIAL IDENTIFICATION PLATE FOR EC FOR M1
PASSENGER VEHICLE

1JA

REAR SHOCK ABSORPTION, BASIC VERSION 1

1M6

TRAILER HITCH MECHANICALLY SWIVELING
ANDPOWER-DETACHABLE

1NL

TRIMS FOR ALLOY WHEELS

1S3

TOOL KIT

1T2

WARNING TRIANGLE

1X0

FRONT WHEEL DRIVE

20D

ELECTRIC MOTOR 100 KW /UNIT 0EC.B (HYBRID)

2FT

SPORTS MULTIFUNCTION STEERING WHEEL WITH
TIPTRONIC (LEATHER + WOOD)

2J4

COMFORT BUMPERS

2WA

WITHOUT ADDITIONAL TIRES

3A0

CHILD SEAT ANCHOR FOR CHILD SEAT SYSTEM I-
SIZE, 2X TOP TETHER

3CA

WITHOUT PARTITION

3GD

PLANE REAR CARGO AREA

3L3

MANUAL HEIGHT ADJUSTMENT FOR FRONT SEATS

3LM

DOOR AND SIDE TRIM PANEL

3S1

BRIGHT ROOF RAILS

3ZU

3-POINT SEAT BELTS, OUTER REAR WITH ECE LABEL

4D0

WITHOUT SEAT VENTILATION/MASSAGE SEAT

4I3

CENTRAL LOCKING SYSTEM "KEYLESS ENTRY"
WITHOUT SAFELOCK

4L6

BREAKAWAY INTERIOR REARVIEW MIRROR, AUTO-
DIMMING

4X3

SIDE AIRBAG IN FRONT, WITH CURTAIN AIRBAG

5C0

WITHOUT SPECIAL BODY MEASURES

5I6

SENSOR-CONTROLLED LUGGAGE COMPARTMENT
OPENER AND EASY CLOSE

5K7

TRANSPORT PROTECTION FILM (MINIMUM
PROTECTION) WITH ADDITIONAL TRANSPORT
PROTECTION MEASURES

5MJ

DECORATIVE INSERTS

5SL

LEFT EXTERIOR MIRROR: ASPHERICAL

5ZC

HEAD RESTRAINTS FOR FRONT SEATS (X-
ADJUSTMENT)

6E4

CENTER ARMREST IN FRONT

6I1

LANE KEEPING SYSTEM

3QT

3-POINT SEAT BELTS IN FRONT, WITH PRETENSIONER
AND HEIGHT ADJUSTMENT

3T2

THREE REAR HEAD RESTRAINTS

4A3

SEAT HEATER FOR FRONT SEATS SEPARATELY
CONTROLLED

4GF

WINDSHIELD IN HEAT-INSULATING GLASS

4KF

SIDE WINDOWS IN HEAT-INSULATING GLASS, FROM
B-PILLAR AND REAR WINDOW DARK TINTED

4UP

DRIVER AND FRONT PASSENGER AIRBAG WITH KNEE
AIRBAG AND FRONT PASSENGER AIRBAG
DEACTIVATION

4ZB

BRIGHT MOLDINGS

5D1

CARRIER FREQUENCY 433.92 MHZ-434.42 MHZ

5J0

WITHOUT REAR SPOILER

5KR

REAR SEAT BENCH/BACKREST, SPLIT FOLDING

5RQ

RIGHT EXTERIOR MIRROR, CONVEX

5XJ

SUN VISORS WITH MIRROR, ILLUMINATED, WITH
AIRBAG LABEL ON SUN VISOR AND B-PILLAR

6A0

WITHOUT FIRE EXTINGUISHER

6FF

BODY-COLORED EXTERIOR MIRROR HOUSINGS AND
VARIOUS ADD-ON PARTS

6K4

FORWARD COLLISION WARNING INCL. AUTONOMOUS
EMERGENCY BRAKING, FOR ADAPTIVE CRUISE

6M0

WITHOUT TIE DOWN STRAPS/NET/POCKET

6Q2

LEATHER GEARSHIFT KNOB/HANDLE

6XP

EXTERIOR MIRRORS, POWER-FOLDING, POWER-ADJUSTABLE, SEPARATELY HEATED

7AA

ELECTRONIC ENGINE IMMOBILIZER

7E0

WITHOUT HEAT ACCUMULATOR/AUXILIARY HEATER

7K1

DIRECT TIRE PRESSURE MONITORING SYSTEM

7N3

COMFORT OVERHEAD STORAGE COMPARTMENT

7W0

WITHOUT EXTENDED SAFETY SYSTEM

7Y0

WITHOUT LANE CHANGE ASSIST

8FC

INSTALLATION OF SLI BATTERY IN REAR, WITHOUT SECOND BATTERY

8GZ

WITHOUT ALTERNATOR

8N6

WINDSHIELD WIPER INTERMITTENT CONTROL WITH LIGHT/RAIN SENSOR

8RM

8 SPEAKERS (PASSIVE)

8SQ

LED TAIL LAMP ASSEMBLY

8TB

REAR FOG LAMP

8WP

CONTROL "HIGH"

6NA

UNSPLIT MOLDED HEADLINER

6T1

INTERIOR LIGHT IN FOOTWELL

76A

WITHOUT MODE 3 CHARGING CABLE

7B3

12-VOLT SOCKET(S)

7IX

VEHICLE CLASS DIFFERENTIATION -550-

7L6

START/STOP SYSTEM WITH REGENERATIVE BRAKING

7P4

MANUALLY ADJUSTABLE LUMBAR SUPPORT IN FRONT SEATS

7X5

PARK ASSIST

8AR

RADIO "GAMMA" WITH REMOVABLE OPERATING PANEL

8G5

MULTIPLE MATRIX BEAM

8IU

LED HEADLAMPS WITH VARIABLE LIGHT DISTRIBUTION

8Q5

HEADLIGHT RANGE ADJUSTMENT, AUTOMATIC/DYNAMIC, WITH CORNERING LIGHT (AFS 1)

8S6

2 READING LIGHTS IN FRONT

8T8

ADAPTIVE CRUISE CONTROL (WITH "FOLLOW-TO-STOP") AND SPEED LIMITER

8W1

WASHER FLUID LEVEL INDICATOR

8X0

WITHOUT HEADLAMP WASHER SYSTEM

FRONT FOG LAMP, CORNERING AND ALL-WEATHER LIGHT

8Y1

TWO-TONE HORN

8ZQ

ANTENNA FOR FM RECEPTION ONLY, DIVERSITY

9I5

SEPARATE DAYTIME RUNNING LIGHTS WITH AUTOMATIC HEADLAMP ACTIVATION AND COMING HOME FEATURE (AUTOMATIC)

9M0

WITHOUT AUXILIARY HEATER/FUEL-FIRED PARKING HEATER

9S0

MULTI-FUNCTION DISPLAY/TRIP COMPUTER ACTIVE INFO DISPLAY "ENTRY"

9WJ

POWER SUPPLY/TV SIGNAL FOR CUSTOMIZED INSTALLATION

9ZX

MOBILE PHONE INTERFACE

AV1

DRIVING ON THE RIGHT

B43

TYPE APPROVAL COUNTRY ROMANIA

C1K

STEEL WHEELS 5J X 13

DP2

4-CYLINDER SI ENGINE 1.4 L/110 KW TSI, HYBRID BASE ENGINE IS TH8

EA0

WITHOUT FOLLOW-ON WARRANTY

EL5

ONLINE SERVICE, WITH OCU, WITH HEAD UNITCODING, WITHOUT ENGINE IMMOBILIZER INTERCONNECTION

ER1

REGIONAL CODE " ECE " FOR RADIO

F0A

8Z5

NOT HOT COUNTRY

9E5

LUGGAGE COMPARTMENT LAMP

9JC

SMOKER'S VERSION

9P9

SEAT BELT REMINDER, ELECTRIC CONTACT IN THE BUCKLE, ADVANCED SAFETY EQUIPMENT

9T1

HEATED WASHER NOZZLES IN FRONT

9Z0

OPERATING VOLTAGE 12 V

A8F

SPORTS EQUIPMENT

B0A

COMPONENT PARTS SET WITHOUT COUNTRY-SPECIFIC BUILDING REGULATION

BG

ESC SPECIAL VEHICLE 14

C59

OPERATING PERMIT, ALTERATION

E0A

NO SPECIAL EDITION

EFO

WITHOUT ECO FUNCTION

EM1

DRIVER ALERT SYSTEM

EV3

CHARGING CABLE: MODE 2, TYPE 2/E+F (10 A)

FBO

STANDARD PAINT COATING

NO SPECIAL PURPOSE VEHICLE, STANDARD EQUIPMENT

FC0

WITHOUT CUSTOMIZED INSTALLATION

G16

SHOCK ABSORPTION IN FRONT

GM4

ELECTRONIC ENGINE SOUND, SOUND BOX WITHOUT DEACTIVATION (TYPE 1)

J0H

BATTERY 340 A (58 AH)

K8G

HATCHBACK

KH7

CLIMATRONIC (3-ZONE) WITH REAR AIR CONDITIONING CONTROL PANEL

KL1

LED LICENSE PLATE LIGHTING

L0L

LEFT-HAND DRIVE

N0R

SEAT TRIM COVERS IN

NZ4

PRIVATE EMERGENCY CALL SYSTEM

QG1

SERVICE INTERVAL PROLONGATION

QI4

SERVICE INDICATOR 15 000 KM OR 1 YEAR (FIX)

QK1

WITH MULTIFUNCTION CAMERA

QQ9

INTERIOR AMBIENT LIGHTING, TYPE 2

QV3

DIGITAL RADIO RECEPTION

U5A

INSTRUMENT CLUSTER, KM/H SPEEDOMETER

UG0

WITHOUT HILL START ASSIST/HILL DESCENT CONTROL/COMFORT DRIVING ASSIST

FM0

BASIC EQUIPMENT VARIANT

G1A

6-SPEED AUTOMATIC TRANSMISSION

GP1

VEHICLES WITH SPECIAL UPGRADE MEASURES

J94

SUSPENSION RANGE 94

KA2

WITH REAR VIEW CAMERA SYSTEM (TYPE 2)

KK3

REFRIGERANT R1234YF

KS2

COMBINER HEAD-UP DISPLAY

L25

SUSPENSION RANGE 25 INSTALLATION CONTROL ONLY, NO REQUIREMENT FORECAST

NY0

STANDARD BATTERY/ALTERNATOR CAPACITY

Q4H

SPORTS COMFORT SEATS IN FRONT

QH0

WITHOUT VOICE CONTROL

QJ3

CHROME PACKAGE (TYPE 2)

QN3

DRAWERS UNDER FRONT SEATS

QR9

WITH DYNAMIC ROAD SIGN DISPLAY

TH8

4-CYLINDER SI ENGINE 1.4 L UNIT 04E.C

U9B

1 X USB TYPE C AND CD PLAYER

UH2

PARKING BRAKE

UK3

MECHANICAL REAR SEAT RELEASE

VF0

STANDARD PEDAL CLUSTER

VT2

SCUFF PLATES IN DOOR APERTURES (ILLUMINATED)

V0A

TIRES WITHOUT SPECIFICATION OF TIRE BRAND

VL3

EXTENDED AND PROACTIVE PEDESTRIAN PROTECTION

X4N

EQUIPMENT OPTIONS SUBSET FOR ROMANIA

Cronologie

S-au găsit 2 înregistrări

Cronologia înregistrărilor pentru acest vehicul

Ultimele înregistrări

01.2021  Țară necunoscută



A fost fabricat

Țara (sau statul) indică fie locația centrului de producție, uzina de asamblare sau adresa de înregistrare a producătorului. Data poate fi aproximativă.

12.2021  România



A fost înmatriculat

Înregistrarea reprezintă un eveniment administrativ. Acest lucru ar putea fi legat de o schimbare de proprietar, documente etc



+31

Surse de date

Am verificat 900+ de surse de date în **35 de țări**