

# Volkswagen T-Cross

VIN: WVGZZC1ZLY046543

Diesel

2019

Generat pe 2025-01-20 13:58



## Odometru

✓ Arată bine



## Statut legal

✓ Arată bine



## Daune

⚠ Necesită atenție



+31

## Surse de date

Am verificat 900+ de surse de date în 35 de țări

## Furt

Vehiculul este în prezent marcat ca furat? A fost furat în trecut? A fost recuperat?



### Nu s-au găsit probleme

Nu am găsit nicio înregistrare că vehiculul a fost furat.



### Notă

Verificarea bazei de date a poliției privind vehiculele furate finalizată în 8 țări: +2

## Iată ce am verificat:



### Căutat drept furat

✓ Nu s-a găsit nici o înregistrare



### Furat în trecut

✓ Nu s-a găsit nici o înregistrare

Starea actuală necunoscută



### Furat în trecut

✓ Nu s-a găsit nici o înregistrare

Vehiculul a fost recuperat

Baza de date aparținând poliției cu vehicule furate, **verificare finalizată în:**

România

Lituania

Statele Unite ale Americii




# Odometru

Există semne conform cărora kilometrajul a fost dat înapoi sau discrepanțe ale kilometrajului?

## Notă

Ultimul kilometraj cunoscut: 99.194 km




**Disclaimer (declinarea responsabilității):** acest grafic reprezintă o tendință estimată a kilometrajului. Deși se bazează pe înregistrări reale de kilometraj disponibile pentru acest vehicul, există lacune având în vedere că evoluția kilometrajului nu este înregistrată în mod constant. Pentru a lua în considerare aceste date lipsă, aplicăm un model patentat de analiză a datelor care prezice modul în care probabil s-a schimbat kilometrajul între evenimentele înregistrate. Acest lucru ajută la furnizarea unei imagini mai complete a utilizării vehiculului în timp.

## Statut legal

A trecut vehiculul inspecțiile tehnice? A fost notat drept casat?

**i Notă**

Inspecția tehnică a fost transmisă pe 2024-11 în  **România**

## Legal



### Inspecție tehnică periodică (ITP)

**A trecut** 2024-11

 **România**

A trecut cu succes inspecția tehnică

Valabil până la 2026-11



### Casat

✓ Nu s-a găsit nici o înregistrare

Nu există nici o înregistrare că vehiculul a fost marcat drept casat

## Daune

Acest vehicul a fost avariat în trecut ? Care a fost valoarea daunelor?

**! Ai grijă!**

Acest vehicul a fost avariat

**i Notă**

Daunele minore nu vor afecta în mod normal siguranța vehiculului și nu vor cauza probleme structurale

## Înregistrări de daune



Daune frontale:

**Față / Bară de protecție**

**Față dreapta / Bară de protecție**

Daune pe partea dreaptă:

**Dreapta / Portieră față**

2024-08

 România

Daune

Costul estimativ al reparațiilor

**2.001 RON – 6.000 RON**

Cauza posibilă a daunelor

**Necunoscut**

Categoriile de daune

Părți exterioare ale caroseriei

**Disclaimer (declinarea responsabilității):** Majoritatea înregistrărilor de daune sunt legate de accidente, dar uneori nu este acesta cazul. Unele înregistrări provin din alte surse cum ar fi serviciile specializate pe lucrări de caroserie, cereri de daune, licitații sau inspecții ale vehiculelor. Aceste înregistrări arată că starea vehiculului a fost evaluată, chiar dacă nu a fost din cauza unui accident.

## Dezastre naturale

Locația vehiculului a fost înregistrată în zona unui dezastru natural?

**Nu s-au găsit probleme**

Locația vehiculului nu a fost înregistrată în zona unui dezastru natural

## Valoarea de piață

Cu cât s-a vândut vehiculul în trecut? Care este în medie prețul vehiculelor din acest model și an?

**i Notă**

- Prețul mediu de pe piață pentru un astfel de vehicul: 91.105 RON
- Atenție la problemele ascunse dacă vehiculul a fost la vânzare la un preț semnificativ mai mic decât prețul actual!

## Valoarea de piață azi pentru Volkswagen T-Cross 2019

Valoarea de piață este determinată prin examinarea prețului unui anumit model de mașină (fabricat în același an) în țara în care a fost generat raportul. Analizăm datele din ultimele 6 luni.

Cel mai mic preț

85.700 RON

Prețul mediu

91.105 RON

Cel mai mare preț

95.036 RON

## Emisii

Câte emisii de CO2 produc vehiculele din acest model/an?

### *i* Notă

Emisii CO2: B (140 g/km)

## Emisii CO<sub>2</sub>

Emisiile CO2 ale  
vehiculului tău

**140 g/km** Clasă **B**

Până la 120

120 - 140

140 - 155

155 - 165

165 - 190

190 - 225

225 și peste

Emisii CO<sub>2</sub> g/km

## Specificații și echipare

Ce specificații și echipamente sunt înregistrate pentru acest vehicul?

### *i* Notă

Verificați dacă specificațiile și echipamentul acestui vehicul se potrivesc cu datele furnizate de vânzător.

## Identificare și specificații tehnice



Producător

**Volkswagen**



Model

**T-Cross**



Tip caroserie  
**Hatchback**



An de fabricație  
**2019**



Capacitate cilindrică  
**1,6 l**



Putere motor  
**70 kW (94 cp)**



Tip combustibil  
**Diesel**



Cutie de viteze  
**Manuală**



Tip transmisie  
**Tracțiune față (FWD)**



Culoare  
**Gri**



Nr. uși  
**4**



Amplasarea volanului  
**Volan pe stânga**



Nr. cilindri  
**4**



Nr. locuri  
**5**



Cod motor  
**DGTD**

---

## Echipare

Cum a fost primit de la producător

---

00A

REAR OVERHANG, SHORT

0A2

4 DOORS

0AT

FRONT STABILIZER

0B1

WHEELBASE

0EJ

INSTALLATION DIFFERENTIATION FOR TRANSMISSION MQ 250 -- VEHICLE COMPONENTS --

0F5

FUEL SYSTEM FOR DIESEL ENGINE

0FB

PAMPLONA MANUFACTURING SEQUENCE

0K0

WITHOUT ALTERNATIVE DRIVE SYSTEM

0KA

WITHOUT DECALS AND EMBLEMS

0N6

STANDARD REAR AXLE

0NB

NAMEPLATE SET IN BASIC STYLE

0P0

REAR EXHAUST TAILPIPE (STANDARD)

0SS

LABELS/PLATES IN ENGLISH AND FRENCH

0TA

WITHOUT FLOOR MATS

0XH

INFORMATION KIT IN ROMANIAN

0Y1

STANDARD CLIMATIC ZONES

0YT

WEIGHT RANGE 18 INSTALLATION CONTROL ONLY, NO REQUIREMENT FORECAST

1AT

ELECTRONIC STABILITY CONTROL (ESC)

1D0

WITHOUT TRAILER HITCH

1E9

WITHOUT ACTIVATED CARBON CANISTER WITH SCR

1EX

SPECIAL IDENTIFICATION PLATE FOR EC FOR M1 PASSENGER VEHICLE

1G6

SPACE-SAVING SPARE WHEEL

1JB

REAR SHOCK ABSORPTION FOR ROUGH-ROAD VERSION

1KA

DRUM BRAKES IN REAR

1MM

STEERING WHEEL

1N1

POWER STEERING

1ND

WHEEL TRIMS

1PA

STANDARD WHEEL BOLTS

1S1

TOOL KIT AND JACK

1SA

WITHOUT ADDITIONAL FRONT UNDERBODY GUARD

1T2

WARNING TRIANGLE

1X0

FRONT WHEEL DRIVE



1Z0

INITIAL STANDARD FUEL FILLING

1ZS

DISK BRAKES IN FRONT (GEOMET D)

2A0

WITHOUT DELIVERY EQUIPMENT

2C2

AXIAL AND VERTICAL ADJUSTABLE STEERING COLUMN (REINFORCED)

2CC

VEHICLE CLASS DIFFERENTIATION -2GC-

2H0

WITHOUT "DRIVE SELECT"

2JF

PAINTED BUMPERS

2V1

DUST AND POLLEN FILTER

2WA

WITHOUT ADDITIONAL TIRES

31K

FRONT AND REAR LICENSE PLATE CARRIER (ECE)

3C7

3-POINT SEAT BELT FOR CENTER REAR SEAT

3FA

WITHOUT ROOF INSERT (STANDARD ROOF)

3GA

WITHOUT CARGO AREA

3H0

WITHOUT BACKREST RELEASE FOR FRONT SEATS

3L1

MANUAL HEIGHT ADJUSTMENT FOR LEFT FRONT SEAT

3NQ

UNSPLIT REAR SEAT BENCH, SPLIT FOLDING BACKREST

3Q6

THREE REAR HEAD RESTRAINTS

3S0

WITHOUT ROOF RAILS/ROOF LOAD RACK

3U1

FOLDING TRUNK COVER

3ZU

3-POINT SEAT BELTS, OUTER REAR WITH ECE LABEL

4A0

WITHOUT SEAT HEATER

4AP

DOOR AND SIDE TRIM PANEL

4GF

WINDSHIELD IN HEAT-INSULATING GLASS

4I2

CENTRAL LOCKING WITH RADIO REMOTE CONTROL, INTERIOR RELEASE MECHANISM WITHOUT SAFELOCK

4KC

SIDE AND REAR WINDOWS IN HEAT-INSULATING GLASS

4L6

BREAKAWAY INTERIOR REARVIEW MIRROR, AUTO-DIMMING

4P0

REAR FLOOR PANEL MODULE, TYPE 1

4QV

3-POINT SEAT BELTS IN FRONT, WITH ELECTRIC TENSIONER AND HEIGHT ADJUSTMENT

4R4

POWER WINDOWS WITH COMFORT OPERATION AND CIRCUIT BREAKER

4U0

WITHOUT LUGGAGE NETS/POCKETS ON BACKRESTS

4UF

DRIVER AND FRONT PASSENGER AIRBAG WITH FRONT PASSENGER AIRBAG DEACTIVATION

4X3

SIDE AIRBAG IN FRONT, WITH CURTAIN AIRBAG

4Z4

GLOVE COMPARTMENT DOOR WITHOUT LIGHT

4ZE

BLACK MOLDINGS

51A

WITHOUT ADHESIVE FILM

5D1

CARRIER FREQUENCY 433.92 MHZ-434.42 MHZ

5K7

TRANSPORT PROTECTION FILM (MINIMUM PROTECTION) WITH ADDITIONAL TRANSPORT PROTECTION MEASURES

5MA

DECORATIVE INSERTS

5RQ

RIGHT EXTERIOR MIRROR, CONVEX

5SL

LEFT EXTERIOR MIRROR: ASPHERICAL

5ZF

FRONT HEAD RESTRAINTS

6DF

SUN VISORS W/O MIRROR, W/ TICKET POCKET ON DRIVER SIDE, ON FRONT PASSENGER SIDE W/ AIRBAG LABEL ON SUN VISOR A. B-PILLAR

6E0

WITHOUT CENTER ARMREST IN FRONT

6FH

EXTERIOR MIRROR HOUSINGS PAINTED

6K2

FORWARD COLLISION WARNING INCL. AUTONOMOUS EMERGENCY BRAKING, WITHOUT ADAPTIVE CRUISE CONTROL

6NA

UNSPLIT MOLDED HEADLINER

6PA

PLASTIC HAND BRAKE LEVER HANDLE

6Q1

PLASTIC GEARSHIFT KNOB/HANDLE

6T0

WITHOUT INTERIOR LIGHT IN FOOTWELL

6U0

WITHOUT ADDITIONAL SEALS OUTSIDE

6XD

EXTERIOR MIRRORS, POWER-ADJUSTABLE/ HEATED

7AA

ELECTRONIC ENGINE IMMOBILIZER

7E6

ELECTRIC AUXILIARY AIR HEATER

7K1

DIRECT TIRE PRESSURE MONITORING SYSTEM

7L6

START/STOP SYSTEM WITH REGENERATIVE BRAKING

7M5

WITHOUT PROTECTIVE FILM FOR SCUFF PLATE

7P0

WITHOUT LUMBAR SUPPORT IN SEAT BACKRESTS

7Q0

WITHOUT NAVIGATION DEVICE

7W2

WITH EXTENDED SAFETY SYSTEM (PROACTIVE PASSENGER PROTECTION SYSTEM, BASIC AND FRONT)

7X0

WITHOUT PARK DISTANCE CONTROL

7Y9

BLIND SPOT MONITOR AND LANE KEEPING SYSTEM

8FA

WITHOUT SECOND BATTERY

8G0

WITHOUT LIGHT CONTROL

8GG

ALTERNATOR 110 A

8ID

HALOGEN TWIN HEADLAMPS

8K3

SEPARATE DAYTIME RUNNING LIGHTS WITH AUTOMATIC HEADLAMP ACTIVATION AND COMING HOME FEATURE

8M1

REAR WINDOW WIPER AND WASHER SYSTEM WITH INTERMITTENT CONTROL

8N6

WINDSHIELD WIPER INTERMITTENT CONTROL WITH LIGHT/RAIN SENSOR

8Q1

HEADLIGHT RANGE ADJUSTMENT

8RD

2 SPEAKERS (PASSIVE)

8S3

ADDITIONAL READING LIGHTS IN REAR

8T9

SPEED LIMITER WITHOUT CRUISE CONTROL SYSTEM AND WITHOUT ADAPTIVE CRUISE CONTROL

8W0

WITHOUT WASHER FLUID LEVEL INDICATOR

8WH

FRONT FOG LAMP AND CORNERING LAMP

8X0

WITHOUT HEADLAMP WASHER SYSTEM

8Y0

SINGLE-TONE HORN

8Z5

NOT HOT COUNTRY

8ZB

ANTENNA FOR FM RECEPTION ONLY

9AB

MANUALLY CONTROLLED AIR CONDITIONING SYSTEM

9E1

LUGGAGE COMPARTMENT LIGHTING

9JD

SMOKER'S PACKAGE, ASHTRAY IN FRONT

9P4

SEAT BELT REMINDER, ELECTRIC CONTACT IN FRONT AND REAR, VISUAL AND ACOUSTICAL

9S5

MULTI-FUNCTION DISPLAY/ON-BOARD COMPUTER"MEDIUM"

9T0

WITHOUT HEATED WASHER NOZZLES

9WC

WITHOUT "MULTIMEDIA" IN VEHICLE

9ZX

MOBILE PHONE INTERFACE

A60

CATEGORY 0

A9G

BASIC COMFORT EQUIPMENT

AV1

DRIVING ON THE RIGHT

AW5

STANDARD VERSION

B0A

COMPONENT PARTS SET WITHOUT COUNTRY-SPECIFIC BUILDING REGULATION

B43

TYPE APPROVAL COUNTRY ROMANIA

C04

OPERATING PERMIT, ALTERATION

CY0

STEEL WHEELS 6J X 16

DA9

4-CYL. TURBO DIES. ENG. 1.6 L/70 KW 4V TDI COMMON RAIL BASE ENGINE IS TJ1

E0A

NO SPECIAL EDITION

EA0

WITHOUT FOLLOW-ON WARRANTY

EFO

WITHOUT ECO FUNCTION

ELO

WITHOUT ONLINE SERVICE

EM0

WITHOUT DRIVER ALERT SYSTEM

ER1

REGIONAL CODE " ECE " FOR RADIO

F0A

NO SPECIAL PURPOSE VEHICLE, STANDARD EQUIPMENT

FC0

WITHOUT CUSTOMIZED INSTALLATION

G08

SHOCK ABSORPTION IN FRONT

G0C

5-SPEED MANUAL TRANSMISSION

GP0

VEHICLES WITHOUT SPECIAL UPGRADE MEASURES

H9D

TIRES 205/60 R16 92H

J0V

BATTERY 420 A (70 AH)

K8G

HATCHBACK

KA0

WITHOUT CAMERA SYSTEMS/ACCIDENT SENSORS

KK3

REFRIGERANT R1234YF

L0L

LEFT-HAND DRIVE

L28

SUSPENSION RANGE 28 INSTALLATION CONTROL ONLY, NO REQUIREMENT FORECAST

N4C

SEAT TRIM COVERS IN FABRIC

NY0

STANDARD BATTERY/ALTERNATOR CAPACITY

NZ2

PAN-EUROPEAN EMERGENCY CALL SERVICE

Q1A

STANDARD SEATS IN FRONT

QG1

SERVICE INTERVAL PROLONGATION



QH0

WITHOUT VOICE CONTROL

QI6

SERVICE INDICATOR 30 000 KM OR 2 YEARS ( VARIABLE )

QJ0

WITHOUT ALUMINUM/CHROME PACKAGE

QK2

WITH MULTIFUNCTION CAMERA FOR NCAP REQUIREMENTS

QN0

WITHOUT DRAWERS UNDER FRONT SEATS

QQ0

WITHOUT ADD. LIGHTS (INTERIOR LIGHTING)

QV0

WITHOUT TV RECEPTION/DIGITAL RADIO RECEPTION

S4F

DEVIATING INSTALLATION OF 19-INCH "SAVANNAH"

TJ1

4-CYLINDER DIESEL ENGINE 1.6 L UNIT 04L.1

U5A

INSTRUMENT CLUSTER, KM/H SPEEDOMETER

U9B

1 X USB TYPE C AND CD PLAYER

UG1

HILL START ASSIST

V0A

TIRES WITHOUT SPECIFICATION OF TIRE BRAND

VF0

STANDARD PEDAL CLUSTER

X4N

EQUIPMENT OPTIONS SUBSET FOR ROMANIA

# Siguranță

Vehiculul are vreo rechemare pe motiv de siguranță? Care este ratingul său de siguranță?

## Notă

Rating de siguranță Euro NCAP: ★★★★★

## Rating de siguranță

★★★★★ Siguranță de 5 stele

Performanță generală excelentă la protecția împotriva accidentelor și bine echipat cu tehnologie amplă și robustă de evitare a accidentelor



**97%**

Ocupant adult



**86%**

Copil ocupant



**81%**

Utilizatori  
vulnerabili ai  
drumurilor



**80%**

Asistență de  
siguranță

## Cronologie

S-au găsit 5 înregistrări

Cronologia înregistrărilor pentru acest vehicul

### Ultimele înregistrări

2019-01  Țară necunoscută



**A fost fabricat**

Țara (sau statul) indică fie locația centrului de producție, uzina de asamblare sau adresa de înregistrare a producătorului. Data poate fi aproximativă.

2019-11  România

 **A fost înmatriculat**

Înregistrarea reprezintă un eveniment administrativ. Acest lucru ar putea fi legat de o schimbare de proprietar, documente etc

2022-11  România

 **A fost verificat**

A fost înregistrat un eveniment de inspecție tehnică (cunoscut și sub denumirea de ITP, test tehnic sau test de control al emisiilor). Pot fi incluse atât instanțe reușite, cât și eșuate.

2024-08  România

 **Daună detectată** 

Avem indicii potrivit cărora acest vehicul a fost recunoscut ca avariat în această țară (sau stat). Pentru detalii, vă rugăm să consultați secțiunea „Daune”.

2024-11  România

 **A fost verificat**

A fost înregistrat un eveniment de inspecție tehnică (cunoscut și sub denumirea de ITP, test tehnic sau test de control al emisiilor). Pot fi incluse atât instanțe reușite, cât și eșuate.



**Surse de date**

Am verificat 900+ de surse de date în **35 de țări**