



Volkswagen Touareg

VIN: WVGZZZCR9RD013150 Diesel 2024

Generat pe 30.04.2025, 08:30

Odometru

✓ Arată bine

Statut legal

✓ Arată bine

Daune

⚠ Necesită atenție

+31 Surse de date
Am verificat 900+ de surse de date în 35 de țări

Furt

Vehiculul este declarat furat în prezent? A fost furat în trecut? A fost recuperat?

✓ Nu s-au găsit probleme
Nu am găsit nicio înregistrare că vehiculul a fost furat.

i Notă
Am încheiat verificarea bazelor de date ale poliției privind vehiculele furate din 11 țări: +5

Iată ce am verificat:

Căutat drept furat ✓ Nu s-a găsit nicio înregistrare

Furat în trecut ✓ Nu s-a găsit nicio înregistrare Nu au fost găsite înregistrări anterioare de furt pentru acest vehicul.

Bazele de date ale poliției cu vehicule furate verificare finalizată în:


- România
- Statele Unite ale Americii
- Lituania
- Ungaria
- Danemarca
- Slovacia
- Cehia
- Slovenia
- Italia
- Suedia
- Canada

Odometru

Există semne conform cărora kilometrajul a fost dat înapoi sau sunt discrepanțe de kilometraj?

i Notă

- Ultimul kilometraj cunoscut: 19 km
- Kilometraj mediu pentru modele similare: 19.678 km
- 1 înregistrare a kilometrajului



2024

— Kilometrajul tău — Kilometraj tipic pentru acest model

Înregistrările odometrului

01.2024 19 km

Statut legal

A trecut vehiculul inspecțiile tehnice? A fost marcat drept casat?



Notă

Inspecția tehnică a fost transmisă pe 04.2024 în  **România**

Legal



Inspecție tehnică periodică (ITP)

A trecut

04.2024

 **România**

A trecut cu succes inspecția tehnică

Valabil până la 05.2027



Casat

☒ Nu s-a găsit nicio înregistrare

Nu există nicio înregistrare că vehiculul a fost marcat drept casat

Daune

Acest vehicul a fost avariat în trecut ? Care a fost valoarea daunelor?



Ai grijă!

Am găsit 1 înregistrare pentru acest vehicul



Notă

Daunele minore nu vor afecta în mod normal siguranța vehiculului și nu vor cauza probleme structurale

Înregistrări de daune



Daune pe partea dreaptă:

Spate / Bară de protecție

Spate dreapta / Bară de protecție

08.2024

România

Evaluare

Părți afectate

Spate

Costul estimativ al reparațiilor

2.001 RON – 6.000 RON

Cauza posibilă

Necunoscut

Categorii de daune

Părți exterioare ale caroseriei

Disclaimer (declinarea responsabilității): Majoritatea înregistrărilor de daune sunt legate de accidente, dar uneori nu este acesta cazul. Unele înregistrări provin din alte surse cum ar fi serviceurile specializate pe lucrări de caroserie, cereri de daune, licitații sau inspecții ale vehiculelor. Aceste înregistrări arată că starea vehiculului a fost evaluată, chiar dacă nu a fost din cauza unui accident.

Termeni secțiunea Daune

Evaluare

Evaluarea este procesul prin care se determină gradul de deteriorare al unui vehicul. Aceasta implică inspectarea vehiculului pentru a determina ce reparații sunt necesare, pentru a estima costurile și pentru a decide dacă vehiculul este reparabil sau poate fi considerat daună totală.

Costul estimativ al reparațiilor

Odată ce un incident în care a fost implicat un vehicul este evaluat, furnizorii de date referitoare la daune calculează costul reparației și îl prezintă în moneda țării în care a fost evaluată dauna. Prin urmare, este posibil ca această estimare să nu coincidă cu așteptările tale. Motivele pot include:

- Țara în care au fost evaluate daunele vehiculului poate avea costuri de reparație mai mari/mai mici în comparație cu țara ta. (prețurile pieselor de schimb și costul forței de muncă diferă de la o țară la alta)
- Costul reparațiilor este calculat ca și cum reparațiile au fost făcute la un service oficial (care este de obicei ceva mai scump)

Dezastre naturale

Locația vehiculului a fost înregistrată în zona unui dezastru natural?




Nu s-au găsit probleme

Locația vehiculului nu a fost înregistrată în zona unui dezastru natural

Valoare de piață

Cu cât s-a vândut vehiculul în trecut? Care este prețul mediu pentru un vehicul din același model și an?

-  **Notă**
- Prețul mediu de pe piață pentru un astfel de vehicul: 384.408 RON
 - Atenție la problemele ascunse dacă vehiculul a fost la vânzare la un preț semnificativ mai mic decât prețul actual!




Emisii

Care este nivelul de emisii de CO2 al vehiculele din acest model/an?

-  **Sugestia carVertical**
- Acest vehicul are emisii ridicate. Acest lucru poate să însemne că vor fi aplicate taxe mai ridicate pentru emisii. Verifică reglementările locale ca să eviți surprizele neplăcute.

Emisii CO₂

Emisii CO₂ g/km



Specificații și echipare

Ce specificații și echipamente sunt înregistrate pentru acest vehicul?

-  **Notă**
- Verifică dacă specificațiile și echipamentul acestui vehicul se potrivesc cu datele furnizate de vânzător.

Identificare și specificații tehnice

	Producător Volkswagen
	Model Touareg
	Tip caroserie Break
	An de fabricație 2024
	An model 2024
	Capacitate cilindrică 3 l
	Putere motor 170 kW (228 cp)
	Tip combustibil Diesel
	Cutie de viteze Automată
	Tip transmisie Tracțiune integrală (AWD)
	Culoare Gri
	Nr. locuri 5
	Cod motor DPYC
	Categorie m1g
	Omologare e1*2007/46*1827*24

Echipare

Cum a fost primit de la producător

0E1

SHORT WHEELBASE

0FA

STANDARD MANUFACTURING SEQUENCE

0K0

WITHOUT ALTERNATIVE DRIVE SYSTEM

0M0

FUEL TANK

0NB

NAMEPLATE SET IN BASIC STYLE

0RC

STARTER SWITCH LOCKING SYSTEM

0XH

INFORMATION KIT IN ROMANIAN

0YG

WEIGHT RANGE 7 INSTALLATION CONTROL ONLY, NO
REQUIREMENT FORECAST

1D0

WITHOUT TRAILER HITCH

1G1

SPACE-SAVING SPARE WHEEL

1P0

STANDARD SUSPENSION

1S1

TOOL KIT AND JACK

1T2

WARNING TRIANGLE

1Y6

AUTOMATIC SLIP-CONTROL DIFFERENTIAL

1ZA

DISK BRAKES IN FRONT

2A0

WITHOUT DELIVERY EQUIPMENT

2ED

0F3

FUEL SYSTEM FOR DIESEL ENGINE

0JJ

WEIGHT CATEGORY FRONT AXLE WEIGHT RANGE 9

0LA

WITHOUT SPECIAL PLATES/LABELS/SAFETY
CERTIFICATES

0N1

STANDARD REAR AXLE

0P0

REAR EXHAUST TAILPIPE (STANDARD)

0TD

FLOOR MATS IN FRONT AND REAR

0Y1

STANDARD CLIMATIC ZONES

1BK

4-CORNER AIR SUSPENSION WITH ELECTRONIC
SHOCK ABSORPTION CONTROL

1EX

SPECIAL IDENTIFICATION PLATE FOR EC FOR M1
PASSENGER VEHICLE

1NE

WHEEL CENTER TRIM

1PD

WHEEL BOLTS WITH ANTI-THEFT PROTECTION
(UNLOCKABLE)

1SA

WITHOUT ADDITIONAL FRONT UNDERBODY GUARD

1VH

INSTALLATION PARTS FOR SIX-CYLINDER ENGINE

1Z0

INITIAL STANDARD FUEL FILLING

20A

WITHOUT ELECTRIC MOTOR (HYBRID)

2C5

AXIAL AND VERTICAL ADJUSTABLE STEERING
COLUMN

2FE

DISK BRAKES IN REAR

2G5

FILLER NECK MODULE 1 WITHOUT INSERT

2JB

STANDARD BUMPERS

2V5

FRESH AIR INTAKE SYSTEM WITH
COMBINATIONFILTER

31K

FRONT AND REAR LICENSE PLATE CARRIER (ECE)

3CA

WITHOUT PARTITION

3FU

BIG ROOF SYSTEM

3GD

PLANE REAR CARGO AREA

3M0

WITHOUT SPECIAL MEASURES

3QT

3-POINT SEAT BELTS IN FRONT, WITH PRETENSIONER
AND HEIGHT ADJUSTMENT

3U7

LUGGAGE COMPARTMENT COVER

3Y0

WITHOUT ROLL-UP SUNSHADE

4A3

SEAT HEATER FOR FRONT SEATS SEPARATELY
CONTROLLED

4D0

WITHOUT SEAT VENTILATION/MASSAGE SEAT

4I3

CENTRAL LOCKING SYSTEM "KEYLESS ENTRY"
WITHOUT SAFELOCK

4UF

WOODEN MULTIFUNCTION STEERING WHEEL FOR
TIPTRONIC

2H4

DRIVING PROFILE SELECTION AND HYDRAULIC
DAMPER CONTROL

2P1

PLASTIC LOADING EDGE PROTECTION

2WA

WITHOUT ADDITIONAL TIRES

3A0

CHILD SEAT ANCHOR FOR CHILD SEAT SYSTEM I-
SIZE, 2X TOP TETHER

3D3

CENTER CONSOLE

3G0

WITHOUT CHILD SEAT ANCHOR FRONT (ISOFIX)

3L3

MANUAL HEIGHT ADJUSTMENT FOR FRONT SEATS

3NS

SPLIT FOLDING REAR SEAT BENCH/BACKREST, WITH
CENTER ARMREST

3S5

BLACK ROOF RAILS

3W5

SPECIAL NOISE SUPPRESSION MEASURE FOR
PASSENGER COMPARTMENT, WITHOUT DEADENER
FOR ENCLOSURE

3ZU

3-POINT SEAT BELTS, OUTER REAR WITH ECE LABEL

4AP

DOOR AND SIDE TRIM PANEL

4GR

LAMINATED WINDSHIELD, HEATED

4KF

SIDE WINDOWS IN HEAT-INSULATING GLASS, FROM
B-PILLAR AND REAR WINDOW DARK TINTED

4X3

SIDE AIRBAG IN FRONT, WITH CURTAIN AIRBAG

DRIVER AND FRONT PASSENGER AIRBAG WITH
FRONT PASSENGER AIRBAG DEACTIVATION

4ZE

BLACK MOLDINGS

5D1

CARRIER FREQUENCY 433.92 MHZ-434.42 MHZ

5K7

TRANSPORT PROTECTION FILM (MINIMUM
PROTECTION) WITH ADDITIONAL TRANSPORT
PROTECTION MEASURES

5RQ

RIGHT EXTERIOR MIRROR, CONVEX

5ZF

FRONT HEAD RESTRAINTS

6D1

CENTER ARMREST IN REAR

6F0

WITHOUT DECORATIVE FILMS / EMBLEMS

6GA

WITHOUT ADD-ON KIT

6K8

PRE SENSE CITY WITHOUT PRE CARE

6M0

WITHOUT TIE DOWN STRAPS/NET/POCKET

6NJ

STANDARD MOLDED HEADLINER

6U0

WITHOUT ADDITIONAL SEALS OUTSIDE

73A

WITHOUT CHARGING CABLE (INDUSTRIAL
CONNECTOR)

7AA

ELECTRONIC ENGINE IMMOBILIZER

7G0

WITHOUT PREPARATION FOR VTS (VEHICLE
TRACKING SYSTEM)

5C0

WITHOUT SPECIAL BODY MEASURES

5I6

SENSOR-CONTROLLED LUGGAGE COMPARTMENT
OPENER AND EASY CLOSE

5MA

DECORATIVE INSERTS

5SL

LEFT EXTERIOR MIRROR: ASPHERICAL

6A0

WITHOUT FIRE EXTINGUISHER

6E3

CENTER ARMREST IN FRONT

6FG

EXTERIOR MIRROR HOUSINGS PAINTED

6I1

LANE KEEPING SYSTEM

6KE

RADIATOR GRILLE

6MB

DOUBLE SUN VISORS WITH MIRROR, ILLUMINATED,
AIRBAG LABEL ON SUN VISOR

6SF

STANDARD LUGGAGE COMPARTMENT FLOOR
COVERING

6XI

EXT. MIRR., AUTO-DIMMING, ELECTR.
FOLD./ADJUSTABLE, HEATED, W/ FRONT PASSENGER
EXTERIOR MIRROR LOWERING FUNCTION

76A

WITHOUT MODE 3 CHARGING CABLE

7E6

ELECTRIC AUXILIARY AIR HEATER

7IG

VEHICLE CLASS DIFFERENTIATION -760-

7K1

DIRECT TIRE PRESSURE MONITORING SYSTEM

7M0

PLASTIC SCUFF PLATES IN DOOR APERTURES

7US

PREMIUM NAVIGATION SYSTEM

7X5

PARK ASSIST

8G1

HIGH-BEAM CONTROL

8Q3

AUTOMATIC HEADLIGHT RANGE ADJUSTMENT
DYNAMIC (SELF-ADJUSTING WHILE DRIVING)

8T8

ADAPTIVE CRUISE CONTROL (WITH "FOLLOW-TO-STOP") AND SPEED LIMITER

8X0

WITHOUT HEADLAMP WASHER SYSTEM

8Z5

NOT HOT COUNTRY

9AD

CLIMATRONIC, CFC-FREE

9G6

ALTERNATOR 160-250 A

9IJ

COMFORT TELEPHONY WITH LTE AND WIRELESS CHARGING

9M0

WITHOUT AUXILIARY HEATER/FUEL-FIRED PARKING HEATER

9R0

WITHOUT NIGHT VISION

9T1

HEATED WASHER NOZZLES IN FRONT

9Z0

OPERATING VOLTAGE 12 V

7L8

START/STOP SYSTEM WITH REGENERATIVE BRAKING

7P0

WITHOUT LUMBAR SUPPORT IN SEAT BACKRESTS

7W0

WITHOUT EXTENDED SAFETY SYSTEM

7Y0

WITHOUT LANE CHANGE ASSIST

8IT

LED HEADLAMPS

8RM

8 SPEAKERS (PASSIVE)

8WP

FRONT FOG LAMP, CORNERING AND ALL-WEATHER LIGHT

8Y1

TWO-TONE HORN

8ZH

ANTENNA FOR AM/FM RECEPTION, "DIVERSITY"

9B0

WITHOUT TELEPAY DEVICE

9I5

SEPARATE DAYTIME RUNNING LIGHTS WITH AUTOMATIC HEADLAMP ACTIVATION AND COMING HOME FEATURE (AUTOMATIC)

9JB

SMOKER'S PACKAGE, ASHTRAY IN FRONT AND REAR

9P4

SEAT BELT REMINDER, ELECTRIC CONTACT IN FRONT AND REAR, VISUAL AND ACOUSTICAL

9S8

MULTI-FUNCTION DISPLAY/ON-BOARD COMPUTER"FPK" (ACTIVE INFO DISPLAY)

9WJ

POWER SUPPLY/TV SIGNAL FOR CUSTOMIZED INSTALLATION

A60

CATEGORY 0

A8B

BASIC EQUIPMENT

B0A

COMPONENT PARTS SET WITHOUT COUNTRY-SPECIFIC BUILDING REGULATION

C1J

ALLOY WHEELS 8J X 18

D4Z

6-CYL. TURBO DIES. ENG. 3.0 L/170 KW V6, TDI
COMMON RAIL BASE ENGINE IS T7V

EA0

WITHOUT FOLLOW-ON WARRANTY

ER1

REGIONAL CODE " ECE " FOR RADIO

EV0

WITHOUT CHARGING CABLE

FK2

WITH ADDITIONAL TANK FOR SCR (24 LITERS)

FT0

WITHOUT PARK ASSIST WITH REMOTE
CONTROL/GARAGE PARKING ASSIST

GH1

BASIC REAR DIFFERENTIAL

GM0

WITHOUT ELECTRONIC ENGINE SOUND MEASURES

GV1

SWITCH IN GEARSHIFT LEVER FOR REAR-AXLE
DIFFERENTIAL LOCK

GZ2

DOOR POWER LATCHING

I8Z

WITHOUT RADIO, BUT WITH PRODUCTION DISPLAY

IW0

WITHOUT EMERGENCY CALL SERVICE / ROADSIDE
ASSISTANCE CALL

JX0

WITHOUT FRONT CROSS TRAFFIC ASSIST

AV1

DRIVING ON THE RIGHT

B43

TYPE APPROVAL COUNTRY ROMANIA

C26

OPERATING PERMIT, ALTERATION

E0A

NO SPECIAL EDITION

EL5

ONLINE SERVICE, WITH OCU, WITH HEAD
UNITCODING, WITHOUT ENGINE IMMOBILIZER
INTERCONNECTION

ES0

WITHOUT VEHICLE INLET

F0A

NO SPECIAL PURPOSE VEHICLE, STANDARD
EQUIPMENT

FM0

BASIC EQUIPMENT VARIANT

G1G

8-SPEED AUTOMATIC TRANSMISSION FOR FOUR-
WHEEL DRIVE

GJ0

WITHOUT TRAFFIC JAM ASSIST/CO-PILOT IN HEAVY
TRAFFIC

GP1

VEHICLES WITH SPECIAL UPGRADE MEASURES

GY1

POWER LATCHING FOR TAILGATE

H0Q

TIRES 235/65 R18 106W

IT3

WITH CONNECT PACKAGE 3

J1N

BATTERY 420 A (75 AH)

K4H

CLOSED BODY

KA2

WITH REAR VIEW CAMERA SYSTEM (TYPE 2)

KK3

REFRIGERANT R1234YF

L0L

LEFT-HAND DRIVE

NT0

TRANSIT COATING (TYPE 1)

Q1A

STANDARD SEATS IN FRONT

QI6

SERVICE INDICATOR 30 000 KM OR 2 YEARS (VARIABLE)

QQ0

WITHOUT ADD. LIGHTS (INTERIOR LIGHTING)

QV3

DIGITAL RADIO RECEPTION

T2P

4-CYLINDER SI ENGINE 1.6 L UNIT 051.W

U9E

4 X USB TYPE C

UK3

MECHANICAL REAR SEAT RELEASE

VC0

WITHOUT REMOTE-CONTROLLED GARAGE DOOR OPENER

VH0

STANDARD ELECTRIC

X4N

EQUIPMENT OPTIONS SUBSET FOR ROMANIA

KB0

WITHOUT BATTERY CHARGER

KS0

WITHOUT HEAD-UP DISPLAY

N5M

SEAT TRIM COVERS IN LEATHER

NZ4

PRIVATE EMERGENCY CALL SYSTEM

QG1

SERVICE INTERVAL PROLONGATION

QK1

WITH MULTIFUNCTION CAMERA

QR9

WITH DYNAMIC ROAD SIGN DISPLAY

QZ7

POWER STEERING

U5A

INSTRUMENT CLUSTER, KM/H SPEEDOMETER

UH4

PARKING BRAKE

V0A

TIRES WITHOUT SPECIFICATION OF TIRE BRAND

VF0

STANDARD PEDAL CLUSTER

VL1

EXTENDED PEDESTRIAN PROTECTION MEASURES

Cronologie

S-au găsit 5 înregistrări

Cronologia înregistrărilor pentru acest vehicul

Ultimele înregistrări

01.2024 🌐 Țară necunoscută



A fost fabricat

Țara (sau statul) indică fie locația centrului de producție, uzina de asamblare sau adresa de înregistrare a producătorului. Data poate fi aproximativă.

03.2024 🇷🇴 România



Prima înmatriculare

Înregistrarea reprezintă un eveniment administrativ. Acest lucru ar putea fi legat de o schimbare de proprietar, documente etc

04.2024 🇷🇴 România



A fost verificat

A fost înregistrat un eveniment de inspecție tehnică (cunoscut și sub denumirea de ITP, test tehnic sau test de control al emisiilor). Pot fi incluse atât instanțe reușite, cât și eșuate.

08.2024 🇷🇴 România



Evaluare detectată



Avem indicii că acest vehicul a fost supus unei evaluări în această țară (sau stat). Te rugăm să consulți secțiunea "Daune" pentru informații detaliate.

03.2025 🇷🇴 România



A fost asigurat

Acest vehicul a fost asigurat în această țară (sau stat). Pot fi acoperite toate tipurile de asigurare (răspundere civilă față de terți, CASCO etc.), precum și reînnoirea polițelor.

Din: 07.03.2025

Până la: 06.03.2026



+31

Surse de date

Am verificat 900+ de surse de date în 35 de țări