




Volvo XC90

VIN: YV1LFBMUDK1499363 Benzină 2019



Generat pe 14.05.2025, 06:09

Scanează ca să accesezi raportul complet

Odometru

✓ Arată bine

Statut legal

✓ Arată bine

Daune

⚠ Necesită atenție

+31 Surse de date
Am verificat 900+ de surse de date în 35 de țări

Furt

Vehiculul este declarat furat în prezent? A fost furat în trecut? A fost recuperat?

Nu s-au găsit probleme

Nu am găsit nicio înregistrare că vehiculul a fost furat.

Notă

Am încheiat verificarea bazelor de date ale poliției privind vehiculele furate din 11 țări: +5

Iată ce am verificat:

Căutat drept furat

✓ Nu s-a găsit nicio înregistrare

Furat în trecut

✓ Nu s-a găsit nicio înregistrare

Nu au fost găsite înregistrări anterioare de furt pentru acest vehicul.

Bazele de date ale poliției cu vehicule furate **verificare finalizată în:**

- România
- Cehia
- Slovenia
- Slovacia
- Italia
- Ungaria
- Suedia
- Lituania
- Statele Unite ale Americii
- Danemarca
- Canada


Odometru

Există semne conform cărora kilometrajul a fost dat înapoi sau sunt discrepanțe de kilometraj?



Notă

- Ultimul kilometraj cunoscut: 83.884 km
- Kilometraj mediu pentru modele similare: 99.052 km
- 9 înregistrări ale kilometrajului



Înregistrările odometrelui

03.2019	11 km
07.2019	7.136 km
12.2019	14.000 km
02.2020	16.000 km
07.2020	22.000 km

Înregistrările odometrelui

07.2020	24.034 km
07.2021	42.646 km
04.2022	54.845 km
11.2024	83.884 km

Statut legal

A trecut vehiculul inspecțiile tehnice? A fost marcat drept casat?



Nu s-au găsit probleme

Nu s-au găsit înregistrări despre statutul legal al acestui vehicul

Legal



Inspecție tehnică periodică (ITP)

A trecut

11.2024



România

A trecut cu succes inspecția tehnică



Casat

✓ Nu s-a găsit nicio înregistrare

Nu există nicio înregistrare că vehiculul a fost marcat drept casat

Daune

Această secțiune te ajută să înțelegi dacă vehiculul a fost avariat sau inspectat pentru daune și prezintă estimările înregistrate ale costurilor (dacă sunt disponibile).



Ai grijă!

Am găsit 8 înregistrări pentru acest vehicul



Notă

Daunele minore nu vor afecta în mod normal siguranța vehiculului și nu vor cauza probleme structurale

Înregistrări de daune



Daune pe partea dreaptă:

Spate / Bară de protecție

Spate stânga / Bară de protecție

04.2019

România

Daune

Părți afectate

Spate

Costul estimativ al reparațiilor

0 RON – 2.000 RON

Cauza posibilă

Necunoscut

Categorii de daune

Părți exterioare ale caroseriei

Iluminat exterior



Daune frontale:

Față / Bară de protecție

Față stânga / Bară de protecție

11.2019

România

Evaluare

Părți afectate

Față

Costul estimativ al reparațiilor

2.001 RON – 6.000 RON

Cauza posibilă

Necunoscut

Categorii de daune

Părți exterioare ale caroseriei



Daune pe partea stângă:

Stânga / Portieră față

Daune pe partea dreaptă:

Spate / Bară de protecție

Spate stânga / Bară de protecție

12.2019

România

Evaluare

Părți afectate

Partea stângă

Spate

Costul estimativ al reparațiilor

2.001 RON – 6.000 RON

Cauza posibilă

Necunoscut

Categorii de daune

Părți exterioare ale caroseriei



Daune pe partea dreaptă:

Spate / Bară de protecție

06.2020

 România

Evaluare

Părți afectate

Spate

Costul estimativ al reparațiilor

0 RON – 2.000 RON

Cauza posibilă

Necunoscut

Categorii de daune

Părți exterioare ale caroseriei



Daune frontale:

Față / Bară de protecție

Față dreapta / Bară de protecție

1 înregistrare similară

06.2020

 România

Evaluare

Părți afectate

Față

Costul estimativ al reparațiilor

6.001 RON – 14.000 RON

Cauza posibilă

Necunoscut

Categorii de daune

Părți exterioare ale caroseriei

Iluminat exterior

Am grupat aceste înregistrări de evaluare a daunelor în acest raport în format PDF - par să descrie același eveniment deoarece conțin constant aceleași date, locații și detalii.

Ca să vezi toate detaliile disponibile și ca să te asiguri că vezi cele mai detaliate și curente informații, te rugăm să consulți raportul digital de pe site-ul nostru.



Daune frontale:

Față / Parbriz

1 înregistrare similară

02.2021

România

Evaluare

Părți afectate

Față

Costul estimativ al reparațiilor

2.001 RON – 6.000 RON

Cauza posibilă

Necunoscut

Categorii de daune

Sticlă

Am grupat aceste înregistrări de evaluare a daunelor în acest raport în format PDF - par să descrie același eveniment deoarece conțin constant aceleași date, locații și detalii.

Ca să vezi toate detaliile disponibile și ca să te asiguri că vezi cele mai detaliate și curente informații, te rugăm să consulți raportul digital de pe site-ul nostru.



Daune pe partea stângă:

Stânga / Portieră față

Daune pe partea dreaptă:

Dreapta / Portieră față

Daune pe partea dreaptă:

Spate stânga / Bară de protecție

3 înregistrări similare

01.2023

România

Evaluare

Părți afectate

Partea stângă

Partea dreaptă

Spate

Costul estimativ al reparațiilor

6.001 RON – 14.000 RON

Cauza posibilă

Necunoscut

Categorii de daune

Părți exterioare ale caroseriei

Am grupat aceste înregistrări de evaluare a daunelor în acest raport în format PDF - par să descrie același eveniment deoarece conțin constant aceleași date, locații și detalii.

Ca să vezi toate detaliile disponibile și ca să te asiguri că vezi cele mai detaliate și curente informații, te rugăm să consulți raportul digital de pe site-ul nostru.

11.2023

 România

Evaluare

Părți afectate

Față

Costul estimativ al reparațiilor

14.001 RON – 24.000 RON

Cauza posibilă

Necunoscut

Categorii de daune

Sisteme de siguranță active

Părți exterioare ale caroseriei

Iluminat exterior

Daune frontale:

Față / Bară de protecție

Față stânga / Bară de protecție

Disclaimer (declinarea responsabilității): Majoritatea înregistrărilor de daune sunt legate de accidente, dar uneori nu este acesta cazul. Unele înregistrări provin din alte surse cum ar fi serviceurile specializate pe lucrări de caroserie, cereri de daune, licitații sau inspecții ale vehiculelor. Aceste înregistrări arată că starea vehiculului a fost evaluată, chiar dacă nu a fost din cauza unui accident.

Termeni secțiunea Daune

Evaluare

Evaluarea este procesul prin care se determină gradul de deteriorare al unui vehicul. Aceasta implică inspectarea vehiculului pentru a determina ce reparații sunt necesare, pentru a estima costurile și pentru a decide dacă vehiculul este reparabil sau poate fi considerat daună totală.

Daune

Daunele se referă la orice deteriorare fizică sau pierdere suferite de un vehicul cum ar fi zgârieturi, lovituri sau piese defecte. Pot rezulta din cauza accidentelor, a vremii, a furtului sau a altui incident și pot afecta aspectul sau performanța mașinii.

Costul estimativ al reparațiilor

Odată ce un incident în care a fost implicat un vehicul este evaluat, furnizorii de date referitoare la daune calculează costul reparației și îl prezintă în moneda țării în care a fost evaluată dauna. Prin urmare, este posibil ca această estimare să nu coincidă cu așteptările tale. Motivele pot include:

- Țara în care au fost evaluate daunele vehiculului poate avea costuri de reparație mai mari/mai mici în comparație cu țara ta. (prețurile pieselor de schimb și costul forței de muncă diferă de la o țară la alta)
- Costul reparațiilor este calculat ca și cum reparațiile au fost făcute la un service oficial (care este de obicei ceva mai scump)

Dezastre naturale

Locația vehiculului a fost înregistrată în zona unui dezastru natural?

**Nu s-au găsit probleme**

Locația vehiculului nu a fost înregistrată în zona unui dezastru natural

Valoare de piață

Cu cât s-a vândut vehiculul în trecut? Care este prețul mediu pentru un vehicul din același model și an?



Notă

- Prețul mediu de pe piață pentru un astfel de vehicul: 181.784 RON
- Atenție la problemele ascunse dacă vehiculul a fost la vânzare la un preț semnificativ mai mic decât prețul actual!

Valoarea actuală de piață pentru Volvo XC90 2019

Valoarea de piață este determinată prin examinarea prețului unui anumit model de mașină (fabricat în același an) în țara în care a fost generat raportul. Analizăm datele din ultimele 6 luni.

Cel mai mic preț

172.481 RON

Prețul mediu

181.784 RON

Cel mai mare preț

200.864 RON

Emisii

Care este nivelul de emisii de CO₂ al vehiculele din acest model/an?



Sugestia carVertical

Acest vehicul are emisii scăzute. Poate se califica pentru taxe mai mici pentru emisii. Verifică reglementările locale ca să vezi dacă se aplică reduceri.

Emisii CO₂

Emisii CO₂ g/km

Până la
120

120 - 140

140 - 155

155 - 165

165 - 190

190 - 225

225 +

Emisiile de
CO₂ ale
vehiculului
tău

79 g/km

Clasă **A**

Specificații și echipare

Ce specificații și echipamente sunt înregistrate pentru acest vehicul?



Notă

Verifică dacă specificațiile și echipamentul acestui vehicul se potrivesc cu datele furnizate de vânzător.

Identificare și specificații tehnice



Producător

Volvo



Model
XC90



Descriere
XC90



Variantă
T8 Twin Engine



Tip caroserie
SUV



An de fabricație
2019



Capacitate cilindrică
2 l



Putere motor
64 kW (86 cp)



Tip combustibil
Benzină



Cutie de viteze
Automată



Tip transmisie
Tracțiune față (FWD)



Culoare
Albastru



Amplasarea volanului
Volan pe stânga



Nr. locuri
7



Cod motor
B4204T34

Echipare

Cum a fost primit de la producător

0

MAKEUP LAMP SUNVISOR 2 ILLUMINATED SUN
VISORS

1

PARKING TICKET HOLDER WITH TICKET HOLDER

10

TELEMATIC MODULE WITH TELEMATIC MODULE,
ROW LTE

101

VEHICLE INSPECTION NUMBER YV1

103

COMMON MATERIAL COMMON MATERIAL - ALL TYPE
42 CARS

105

COMMON MATERIAL SEAT NUMBER 5 AND 7 SEATS

107

PHONE AS KEY NO PHONEKEY

109

SHIELDED POT UNSHIELDED POWER OPERATED
TAILGATE

110

FRONT SEATS, RH EXTRA VARIANT

112

FOIL, EXTERIOR NO FOIL

114

AUTONOMOUS DRIVE KIT NO AUTONOMOUS DRIVE
KIT

116

MUDFLAPS FRONT NO MUDFLAPS FRONT

118

SKID PLATE REAR/DIFFUSER NO SKID PLATE
REAR/DIFFUSER

12

POWER RELEASE 2:D ROW MECHANICAL RELEASE
FOLD 2:D ROW REAR SEAT

121

LOCK CYLINDER GLOVEBOX NO LOCK CYLINDER
GLOVEBOX

123

PROTECTIVE PLATE ENGINE NO PROTECTIVE PLATE

125

TUNNEL BRACE FRONT TUNNEL BRACE B, 'NORMAL
SPEC'

127

100

MARKET PLATES/LABELS DECALS OUTSIDE JAPAN

102

COMMON 42 V526/V426

104

END STOP LENGTH LENGTH 2

106

COMMON MATERIAL SEAT NUMBER 4, 5, 6 AND 7
SEATS

108

CARPET X-VARIANT

11

KNEE AIRBAG KNEE AIRBAG DRIVER SIDE

111

SOC-LEVEL STANDARD SOC-LEVEL

113

AUTONOMOUS VEHICLE NO AUTONOMOUS VEHICLE

115

TOWBAR ACCESSORIES NO ACCESSORY TOWBAR

117

SKID PLATE FRONT NO SKID PLATE FRONT

119

FRONT DECOR FRAMES NO FRONT DECOR FRAMES

120

BODY KIT NO BODY KIT

122

POWER OUTLET TUNNEL NO 120/230 VOLT OUTLET
IN REAR/LOWER TUNNEL CONSOLE

124

TYRE CIRCUMFERENCE ROLLING CIRCUMFERENCE
2305MM

126

SCUFF PLATES NO SCUFF PLATES

128

MARKET PLATES/LABELS LABELS OUTSIDE KOREA

129

STEERING WHEEL POSITION LEFT HAND DRIVE

130

ACTIVE GRILLSHUTTER

132

REAR FOGLIGHT TOWFUNCTION FOGLIGHTS
RUNNING EVEN WHEN TRAILER IS CONNECTED

134

REAR WIEW MIRROR,LH SIDE LH SIDE REAR WIEW
MIRROR, WIDE ANGLE

136

HILL DESCENT CONTROL

138

TRANSMISSION 2 WHEEL DRIVE

14

WHEEL NUT PROTECTION CAP PLASTIC PROTECTION
CAP

141

END STOP QUANTITY, DRIVER SEAT ENDSTOP DRIVER
SEAT, 1PSC

143

INFOTAINMENT HEAD UNIT EXTRA VARIANT

145

DRIVE MODE WITH DRIVE MODE SWITCH

147

SRS CALIBRATION SRS CALIBRATION 1

149

HEADLIGHTS,SYMMETRY R ASYMMETRIC

150

HEADLIGHT CLEANING WITH HEADLIGHT CLEANING

152

VIDEO ALLOWED SPEED DEPENDENT

154

FOOT MOVEMENT DETECTION MODULE

156

INCLINATION SENSOR WITH INCLINATION SENSOR

USER EXCEPTIONS NOT FOR CHENGDU

13

LUGGAGE NET, TEXTILE LUGGAGE NET, BACKREST

131

GEARSHIFT INDICATOR

133

ALARM

135

HEATED REAR SEAT

137

HEATED STEERING WHEEL

139

ADJUSTABLE SPEED LIMITER

140

OPEN, REAR SIDE DOOR 1 PULL TO OPEN REAR SIDE
DOOR, FROM LOCKED

142

ALARM LOGIC ALARM LOGIC BASE

144

IHU LEVEL IHU HIGH

146

REFRIGERANT 1234YF

148

BASE COLOUR INTERIOR CHARCOAL BASE COLOUR
INTERIOR

15

DEVICE MIRRORING DEVICE MIRRORING, CARPLAY &
ANDROIDAUTO

151

TELEPHONE NETWORK TELEPHONE SYSTEM GSM

153

CENTRAL LOCK, TYPE BLOCKED LOCK MODE (BLL)

155

SELF OPENING BOOTLID/TAILGATE WITH
POWEROPERATED TAILGATE OR BOOTLID

157

KEYLESS ENTRY PASSIVE ENTRY, INCL. REMOTE TAG

158

AUDIBLE LOCKING FEEDBACK AUDIBLE LOCKING
FEEDBACK DISABLED

16

ELECTRIC FUEL LID OPENING WITH ELECTRIC FUEL
LID OPENING

161

INTERIOR MOTION SENSOR WITH INTERIOR MOTION
SENSOR

163

DIGITAL OWNERS MANUAL

165

NETPOCKET ON TUNNEL

167

END STOP MATERIAL END STOP IN PLASTIC

169

INTERIOR ILLUMINATION INTERIOR LIGHTNING HIGH
VERSION

170

SPARE WHEEL REPAIR KIT

172

TYREPRESSURE MONITORING SYSTEM INDIRECT
TPMS, EU ALGORITHM

174

COLLISION MITIGATION SUPPORT WITH COLLISION
MITIGATION SUPPORT FRONT, VER.1

176

VIBR. DAMPER STEERING WHEEL VIBRATION DAMPER,
VERSION 3

178

ROOF RAILS ROOF RAILS INTEGRATED
ALUMINIUM/SILVER

18

EMISSION VERSION 2 VEA GEN 2, EURO 6D

181

PARKING ASSISTANCE PARKING ASSISTANCE, FRONT
AND REAR

183

GEAR SHIFT PADDLES

159

UNLOCK SETTING TWO STEP UNLOCKING ENABLED,
DEFAULT OFF, SLAM LOCKING DISABLED

160

PRIVATE LOCKING LUGGAGE COMP. PRIVATE
LOCKING ENABLED

162

SPEECH

164

HEADRESTS FRONT 2 WAY HEADSRESTS FRONT,
MANUAL

166

HEADRESTS 2:ND ROW, FOLDING EL FOLDING REAR
HEADRESTS

168

LUMBAR SUPPORT 4 WAY LUMBAR SUPPORT

17

CENTRAL LOCK SWITCHES CENTRAL LOCK
SWITCHES IN BOTH FRONT DOORS AND LOCAL
LOCKING SWITCHES IN BOTH REAR DOORS

171

HILL START ASSIST

173

POST IMPACT BRAKING

175

ROAD FRICTION INDICATION

177

TAILPIPE DOUBLE PIPES, INTEGRATED

179

GLOBAL NAVIGATION SAT SYSTEM WITH GLOBAL
NAVIGATION SATELLITE SYSTEM

180

TPMS MENU FUNCTIONS IN IHU TPMS, RESET MENU

182

DARKENED REAR WINDOWS DARK GLASSES, REAR
SIDEDOOR AND CARGO AREA

184

COMPASS

185

GEARBOX/DRIVELINE 8-SPEED AUTOMATIC, 2WD AND 4WD

187

BLIND SPOT INFORMATION SYSTEM BLIND SPOT INFORMATION SYSTEM WITH CTA

189

ARMREST, MIDDLE REAR SEAT 2ROW CENTRE REAR ARMREST WITH CUPHOLDERS

190

RECESS

192

GEARBOX AWF22FWD, AUTOMATIC 8-SPEED FWD

194

PEDAL ARRANGEMENT PEDAL R-DESIGN

196

GRILL TYPE R-DESIGN GRILL

198

MEMORY, PASSENGER SEAT WITH MEMORY, PASSENGER SEAT

2

TOTAL WEIGHT CHECK CARWEIGHT IS OK

200

INTERIOR DECOR PANELS DECOR 'INNOVATION' / 'METAL MESH'

202

LAMINATED WINDOWS LAMINATED GLASS, SIDE & REAR WINDOWS

204

RIM, INCH 20' RIM

206

BOTTLEHOLDER IN CARGO AREA STRAP/BOTTLEHOLDER IN CARGO AREA

208

PTC HEATER (SUPL. AIR HEATER) POSITIVE THERMAL COFFICIENT

21

186

TELEMATIC MODULE WITH TELEMATIC MODULE

188

AIR QUALITY SYSTEM AIR QUALITY SYSTEM, MULTIFILTER

19

INTERIOR CODE CHARCOAL INTERIOR/LEAC/CHARCOAL SEAT/COMFORT

191

WINDSCREEN WIPER WET ARMS, HEATED

193

TRAFFIC INFORMATION WITH TRAFFIC MESSAGE CHANNEL PREMIUM

195

DIVERGENT COLOUR HEADLINING 'BLACK' COLOUR ON HEADLINING/CEILING

197

HEADLIGHTS, TYPE LED WITH BENDING LIGHT, TYPE B, TOP RANGE WITH HCM

199

SUBWOOFER

20

STOLEN VEHICLE/THEFT NOTIFY WITH STOLEN VEHICLE TRACKING / WITH THEFT NOTIFICATION

201

CUSHION EXTENSION

203

OVERHEAD CONSOLE ILLUMINATION OVERHEAD CONSOLE LIGHTNING HIGH VERSION

205

VEHICLE TYPE V526 XC90

207

WHEEL BRAKES TYPE REAR REAR BRAKE 18' REINFORCED 340X20 GG

209

LEVELLING SENSOR CONFIGURATION SUM, FRONT LEFT, FRONT RIGHT, REAR LEFT, REAR RIGHT

210

ASSISTANCE SERVICES WITH ASSISTANCE SERVICES

211

RADIO, AMP & SPEAKER SYSTEM PREMIUM SOUND AUDIO

213

WHEEL 20' 5-SPOKE MATT BLACK DIAMONDCUT ALLOY WHEEL - R-DESIGN

215

DECOR SIDE WINDOWS SILK METAL DECOR SIDE WINDOWS

217

SILLMOULDING SILLMOULDING 'R-DESIGN' ILLUMINATED

219

CIG. LIGHTER/ASHTRAYS CIGARETTE LIGHTER/ASHTRAY

220

HOMELINK TYPE HOMELINK 1

222

NUMBER PLATE ADAPTER FRONT NUMBER PLATE ADAPTER 1 'EU'

224

FRONT SEAT, RIGHT HAND SIDE RH SEAT, EXTRA VARIANT

226

ENGINE GENERATION VEA2 VEA GENERATION 2

228

AIRBAG, DRIVER/PASSENGER AIRBAG, TYPE B

23

PARKING CAMERA PARKING CAMERA 360

231

EXTERIOR LIGHT LOGIC DDRL NOT TOGETHER WITH POSITION LIGHT

233

SAFETY BELT REMINDER BELT MINDER ALL SEATS, EU LOGIC

235

CHILD LOCK.REAR DOORS ELECTRICAL CHILD LOCK, REAR SIDE DOORS

237

VAC, REAR WITH REAR VAC

212

KEY FOB KEY FOB R-DESIGN

214

WHEEL BRAKES TYPE FRONT BRAKE DISCS 19' FN+

216

STEERING WHEEL STEERING WHEEL, 3 SPOKE, PERFORATED LEATHER WITH UNIDECO INLAYS

218

HOMELINK WITH HOMELINK

22

CONNECTIVITY WITH CONNECTIVITY

221

TOWBAR NO TOWBAR

223

FRONT SEAT, LEFT HAND SIDE LH SEAT, EXTRA VARIANT

225

SEAT PADDING COMFORT SEAT PADDING

227

SAFETY BELT SAFETY BELT, TYPE B

229

PINCH PROTECTION LEVEL STANDARD PINCH PROTECTION

230

DIAGNOSIS SYSTEM EOBD

232

REAR WIEW MIRRORS,OUTER RETRACTABLE REAR VIEW MIRRORS

234

REGION IF DVD DVD REGION 2

236

FREQUENCY BAND & STEP,RADIO FREQUENCY BAND AND STEP FOR EU

238

LANGUAGE REGION LANGUAGE REGION FOR EUROPE

239

EMERGENCY BRAKE LIGHT EBL, FLASHING BRAKE LIGHT AND HAZARD WARNING

240

NAVI MAP REGIONS MAP REGION FOR EUROPE

242

MARKET PLATES/LABELS DECALS OUTSIDE LATIN AMERICA/MEXICO/RUSSIA

244

MARKET PLATES/LABELS DECALS OUTSIDE CHINA

246

MARKET PLATES/LABELS DECALS OUTSIDE INDIA

248

MARKET PLATES/LABELS LABELS FOR EUROPE

25

AC COMPRESSORS ELECTRIC AC

251

USER EXCEPTIONS NOT FOR MALAYSIA

253

EXTERIOR PAINT,TYPE METALLIC

255

REMOTE ENGINE START PRECOND REMOTE ENGINE START PRECOND FROM SMARTPHONE APP

257

SUNVISOR DECAL

259

FRONT SEATS, LH EXTRA VARIANT

260

COLOURED PROTECTION CARPETS CHARCOAL CARPET KIT, X-VARIANT

262

ENGINE FAMILY 2 VEP4 ENGINES

264

CUTOFF SWITCH PASSENGER AIRBAG CUT-OFF SWITCH PASSENGER AIRBAG

NETPOCKET IN CARGO AREA NO NETPOCKET IN CARGO AREA

24

END STOP QUANTITY, PASSENGER ENDSTOP PASSAGER SEAT, 1PSC

241

MARKET PLATES/LABELS DECALS OUTSIDE RUSSIA

243

MARKET PLATES/LABELS LABELS OUTSIDE USA

245

MARKET PLATES/LABELS DECALS OUTSIDE JAPAN/CHINA/KOREA

247

MARKET PLATES/LABELS DECALS OUTSIDE ARABIA

249

MAIN MARKET EUROPE AND OVERSEAS MARKETS

250

USER PACKAGES USER PACKAGE

252

HEATER TYPE FOH, FUEL OPERATED HEATER,WITH TIMER

254

SERVICE SOLUTION

256

LAMBDA SENSORS 2 LAMBDA PROBES

258

PARTS FOR SPECIAL PRODUCTS PARTS EXCLUDED FOR SPECIAL VEHICLE

26

TURBO CONFIGURATION HIGH PERFORMANCE

261

LEATHER/VINYL CARE KIT NO LEATHER CARE KIT

263

FUEL PETROL

265

COLOUR MATCHING, EXTERIOR

266

COLOUR MATCHING, EXTERIOR

268

LANE KEEPING AID

27

PROPULSION TYPE PLUGIN HYBRID VEHICLE

271

SERVICE DISTANCE SERVICE DISTANCE 30000 KM / ~18640 MILES

273

DRIVERS SEAT POWER ADJUSTABLE DRIVERS SEAT WITH MEMORY

275

12 VOLT OUTLET LUGGAGE 12V POWER OUTLET, LUGGAGE AREA

277

COLLISION MITIG. & WARN. REAR WITH REAR COLLISION WARNING AND MITIGATION

279

STEER. COLUMN LOCK/KEY WARNING WITH STEERING COLUMN LOCK, KEY WARNING DISABLED

280

IR REFLECTIVE GLASS WINDSCREEN STANDARD WINDSCREEN GLASS

282

WARNING TRIANGLE

284

MARKET PLATES/LABELS LABELS FOR MID EU

286

PLATES/DECALS LABELS FOR MFK19

288

TYRE PRESSURE HLLF HIGH SPEED, LIGHT LOAD, FRONT, 280 KPA

29

SHIFT BY WIRE WITH SHIFT BY WIRE

291

267

IF INSCRIPTION: LOGO HEAD REST NO INSCRIPTION LOGO ON HEADREST UPHOLSTERY

269

SURFACE TREATMENT TYPE GRILL STANDARD SURFACE TREATMENT GRILL

270

SHIELDED WIRE, IF POT NO SHIELDED WIRE

272

CHILD SEATS, REAR SEATS, 2ROW NO CHILD SEAT

274

HEATED FRONT SEATS

276

FIRST AID KIT AIDKIT TYPE 2

278

POWER STEERING PERSONALISATION WITH ELECTRO POWER STEERING PERSONALISATION

28

ELECTRIC VEHICLE INLET ELECTRIC VEHICLE INLET, TYPE 2

281

SCUFF PLATE BOOT REAR SCUFF PLATE, METAL

283

FENDER SEALING

285

MARKET PLATES/LABELS LABELS OUTSIDE AUSTRALIA

287

TYRE PRESSURE HLLR HIGH SPEED, LIGHT LOAD, REAR, 280 KPA

289

TYRE PRESSURE HHLR HIGH SPEED, HEAVY LOAD, REAR, 310 KPA

290

TYRE PRESSURE HHLF HIGH SPEED, HEAVY LOAD, FRONT, 310 KPA

292

NTA-CODE NO NTA NUMBERS

TYRE PRESSURE SPARE WHEEL - THE SIGN '-' TO BE PRINTED.

293

REMOTE BATTERY MANAGEMENT WITH REMOTE BATTERY MANAGEMENT FROM SMARTPHONE APP

295

SUNVISOR ILLUMINATED/DECAL SUNVISOR ILLUMINATED, KOMBINATION VARIANT

297

ENGINE GENERATION VEA VEP4 GENERATION 2

299

COLOUR MATCHING, INTERIOR COLOUR MATCHING INTERIOR

30

GEARBOX,TYPE AUTOMATIC GEARBOX

301

HEADLINING MATERIAL STANDARD MATERIAL IN HEADLINING

303

PASSENGERS SEAT POWER ADJUSTABLE PASSENGERS SEAT

305

PAC CALIBRATION PAC CALIBRATION STANDARD

307

BUMPERS/SILL MOULDING PAINTED BUMPER, R-DESIGN

309

POT VERSION STANDARD POT

310

MATERIAL/PADDING COMBINATION VARIANT: MATERIAL/PADDING

312

GEARLEVER,TYPE/KNOB GEARLEVER KNOB, CRYSTAL

314

MASSAGE FRONT SEAT MASSAGE, FRONT SEAT

316

POWER FOLD & RISE 3:D ROW MECANICAL FOLD & RISE 3:D ROW REAR SEAT

318

294

HATCH/RAILS EXTRA VARIANT HATCH/RAILS

296

CABLE HARNESS ENGINE EXTRA VARIANT

298

ROOF HATCH OPENABLE PANORAMA ROOF

3

LOADHOLDER LOADHOLDER,5-DOOR

300

CATALYST TYPE CATALYST PETROL 6C

302

LEATHER/DRESSED INTERIOR PARTS DRESSED INTERIOR PARTS

304

EXTRA EMBLEM PHEV AWD EMBLEM TAILGATE

306

OUTER REAR VIEW MIRRORS OUTER REAR VIEW MIRROR PACKAGE

308

INSULATION CARPETS STANDARD SPEC NVH-CARPETS

31

PARKING CLIMATE LEVEL FULL PARKING CLIMATE

311

ENGINE DENOMINATION ENGINE T8

313

CLIMATE CONTROL UNIT ELECTRONIC CLIMATE CONTROL, 4 ZONE

315

FRONT SEAT VENTILATION VENTILATED SEAT

317

POWER ADJUSTABLE SIDE SUPPORT

319

LOADCOVER LOAD COVER, AUTOMATIC

32

BYPASS VALVE HVAC WITH BYPASS VALVE

321

DEFAULT RIDE HEIGHT DEFAULT RIDE HEIGHT WITH AIR SUSPENSION

323

CHASSIS TYPE CCD WITH CCD HYBRID

325

DOOR MOULDING LOWER PAINTED DOOR MOULDING LOWER, NO CHROME

327

TYRE PRESSURE LLLR LOW SPEED, LIGHT LOAD, REAR, 260 KPA

329

TYRE PRESSURE LHLR LOW SPEED, HEAVY LOAD, REAR, 290 KPA

330

TYRE PRESSURE LHLF LOW SPEED, HEAVY LOAD, FRONT, 290 KPA

332

ENGINE COOLING FAN PERFORMANCE FAN HIGH PERFORMANCE

334

DOOR PANEL, FRONT DOORS DOOR PANEL FRONT DOOR

336

EMBLEM, SALES VERSION LEVEL R-DESIGN EMBLEM TAILGATE

338

ELECTRIC PROPULSION MOTOR ELECTRIC REAR AXLE DRIVE (87PS)

34

SIM CARD FOR CONNECTIVITY ONLY THROUGH PERSONAL SIM

341

REAR AXLE WEIGHT, ONLY CC REAR AXLE WEIGHT

343

TYRE BRAND MICHELIN V

CHASSIS TYPE CHASSIS, CCD

320

ACTIVE SUSPENSION CONTINUOUS CONTROLLED CHASSI

322

AIR SUSPENSION AIR SUSPENSION, 4 CORNER

324

ENGINE EMBLEM EMBLEM 'T8'

326

USER EXCEPTIONS ONLY FOR VOLVO CARS TORSLANDA

328

TYRE PRESSURE LLLF LOW SPEED, LIGHT LOAD, FRONT, 260 KPA

33

SEAT COLOUR INTERIOR CHARCOAL UPHOLSTERY COLOUR INTERIOR

331

SW MAJOR VERSION SW MAJOR 02

333

FRONT MESH PAINTED MESH FRONT, R-DESIGN

335

MUDFLAPS REAR NO MUDFLAPS REAR

337

HEAD REST TYPE STANDARD HEAD REST

339

EMISSION EVAPORATOR SYSTEM ELECT. ADJ. EVAP SYSTEM

340

SW PATCH VERSION SW PATCH 03

342

PROTECTION CARPETS, ROW 1 & 2 CARPET KIT, TEXTILE R-DESIGN

344

SILL MOULDING ACCESSORIES NO ACCESSORY SILL MOULDING/RUNNING BOARD

345

SEAL CARRIER NO SEAL CARRIER

347

CHARGE CORD LENGTH WITH CHARGE CORD, 4,5M

349

ENGINE/GENERATION B4204T34 GEN 2

350

ENGINE VEP4 HP 2.0L 303/400

352

HORN HORN, ELECTRONIC

354

HIGH VOLTAGE BATTERY HV LI-ION 346V 30AH

356

DECAL TRIMLEVEL R-DESIGN TRIMLEVEL DECAL

358

MAX FRONT AXLE WEIGHT, C3 1420 KG

36

VISIBLE LOCKING/UNLOCKING VISIBLE LOCKING AND
UNLOCKING FEEDBACK, DEFAULT ON

361

TRAIN WEIGHT, C2 5410 KG

363

DEM/TCM SW PS DEM/TCM SW

365

FRONT AXLE WEIGHT, ONLY CC FRONT AXLE WEIGHT

367

SYSTEM LANGUAGE ROMANIAN

369

DOOR PANEL, REAR DOORS DOOR PANEL 23, REAR
DOOR

38

AUTOMATIC LOCKING BY SPEED AUTOMATIC
LOCKING BY SPEED ENABLED, DEFAULT ON

4

ROAD SIGN INFORMATION WITH RSI

346

YEAR DESIGNATION LETTER YEAR DES K = MODEL
YEAR 2019

348

ENGINE VERSION ENGINE VERSION B

35

HEAD UP DISPLAY WITH HEAD UP DISPLAY, GRAPHIC

351

FUEL TANK, VOLUME VOLUME 70 LITRE

353

SW MINOR VERSION SW MINOR 13

355

REAR VIEW MIRROR CAP WITH DULL SILVER REAR
VIEW MIRROR CAP

357

BUMPER PROTECTION REAR NO BUMPER
PROTECTION, REAR

359

MAX REAR AXLE WEIGHT, C4 1630 KG

360

GROSS WEIGHT, C1 3010 KG

362

WVTA-NUMBER E4*2007/46*0929*10

364

POLESTAR PERFORMANCE SW OPTION POLESTAR
PERFORMANCE SOFTWARE (ACCESSORIES)

366

ENGINE OPTIMIZATION AFTERMARKE B4204T34
303/400 →

368

REAR AXLE CABLE HARNESS EXTRA VARIANT

37

PANIC FUNCTION PANIC FUNCTION WITH LIGHT &
SOUND

39

ACTIVE NOISE CONTROL ACTIVE NOISE CONTROL
(EOE & EOR)

40

INSTRUMENT CLUSTER CALIBR. PARAMETER FILE
FOR EUROPE

41

CHILD SEAT ATTCHM, LABEL REAR ISOFIX LABEL, B

43

SUN CURTAIN SIDEWINDOW REAR SUNBLIND,SIDE WINDOW

45

MODEL EMBLEM V526 EMBLEM

47

CAR/STEERING/SEAT EXTRA VARIANT

49

STOP LIGHT LED STOP LIGHT

50

RETRIGG ENABLING - IF ALARM RETRIGG 1 CYCLE

52

UPHOLSTERY TYPE PRODUCTION UPHOLSTERY

54

SIDE PANEL, LUGGAGE AREA SIDE PANEL 9, LUGGAGE AREA

56

BRAKE PADS STANDARD PAD

58

BUMPER FRONT EXTRA VARIANT

6

CRUISE CONTROL ADAPTIVE CRUISE CONTROL

61

WORKSHOP WIFI WITH WORKSHOP WIFI

63

HANDLE DOORS HANDLE SIDE DOOR BODY COLOR, WITH DAMPER, KEYLESS AND ILLUMINATION

65

INSTRUCTIONS OWNERS MANUAL ENGLISH, WITH WARRANTY BOOKLET

67

BATTERY H8 AGM EXIDE 95AH 850CCA

69

HEATED WINDSCREEN NO HEATED FRONTSCREEN

42

UPHOLSTERY MATERIAL LEATHER AGNES PERFORATED

44

COMFORT MODULE, SIDEPANEL COMFORT MODULE, SIDEPANEL LUGGAGE AREA

46

REMOTE MONITORING SYSTEM RMS DEACTIVATED

48

ERR SEAT BELTS WITH ELECTRICAL REVERSIBLE RETRACTORS

5

COMBINED INSTRUMENT DRIVERS INFORMATION MODULE WITH 12.3 INCH SCREEN

51

SEATS 7SEAT

53

WHEEL ARCH PAINTED LARGE WHEEL ARCH

55

ELECTRICAL REAR DRIVE TYPE ELECTRICAL REAR DRIVE 1

57

SCREEN THEMES/SKINS SCREEN SKINS 'R-DESIGN'

59

TRAFFIC JAM ASSIST WITH TRAFFIC JAM ASSIST 4

60

SPEED LIMITATION SPEED LIMIT 230 KM/H

62

INSULATED AIR DUCT B-PILLAR NO INSULATED AIR DUKT IN B-PILLAR

64

LEATHER IP X-VARIANT

66

CHROME STRIP BUMPER GLOSSY BLACK STRIPE AT REFLEX, REAR BUMPER

68

EXTERIOR CODE BURSTING BLUE

7

REAR VIEW MIRROR,TYPE AUTOMATIC DIMMING INNER AND OUTER

70

TYRE DIMENSION 275/45R20

72

CAR/GEARBOX/DRIVELINE V526 AUTO 2WD

74

CHARGE CORD CORD, PLUG F, TYPE 2, MODE 2,
LOWPWR, 1P-10A

76

THEFT PROTECTION COVER WITH THEFT
PROTECTION COVER

78

MFI FUEL FILLER MISFUELING INHIBITOR

8

ROOF COLOUR INTERIOR CHARCOAL ROOF COLOUR
INTERIOR

81

SERVICE ENGINE TIME SERVICE ENGINE TIME, 650
HOUR

83

OCCUPANTS NO OCCUPANTS

85

CSB - IF CONNECTIVITY CONNECTED SERVICE
BOOKING

87

THERMOSTAT THERMOSTAT MEK

89

PARKING CLIMATE LEVEL, OPTION NO PARKING
CLIMATE OPTION

90

FUEL ECONOMY LABEL NO FUEL ECONOMY LABEL

92

SPEECH LANGUAGE, NOT USED ENGLISH

94

STEERING COLUMN STEERING COLUMN TYPE B
MANUAL ADJ.

96

MARKET PLATES/LABELS DECALS OUTSIDE
JAPAN/CHINA

71

BUMPER REAR EXTRA VARIANT

73

REFRIGERANT AGENT QUANTITY REFRIGERATING
AGENT 975G

75

COLOURS,INT/EXT BURSTING BLUE

77

SECONDARY EXTERIOR CODE NO SECONDARY
EXTERIOR CODE

79

THEFT PROTECTION COVER HOOD THEFT
PROTECTION COVER FRONT (HOOD)

80

SERVICE TIME SERVICE TIME, 12 MONTHS.

82

UNIT SETTINGS TEMP:C, CLOCK:24, DISTANCE:KM,
FUEL:LITER/KM

84

TYRE DIMENSION FOR LABELS NONE

86

DOORS 5 DOOR

88

ENGINE FAMILY 4 MP/HP

9

USB CONNECTION WITH USB HUB, TYPE A

91

FREQUENCY - REMOTE CONTROLS FREQUENCY 434
MHZ

93

TYRE, INCH 20' TYRE

95

CEM HIGH SPEC CEM

97

MARKET PLATES/LABELS LABELS OUTSIDE CANADA

Cronologie

S-au găsit 12 înregistrări

Cronologia înregistrărilor pentru acest vehicul

Ultimele înregistrări

03.2019 🌐 Țară necunoscută



A fost fabricat

Țara (sau statul) indică fie locația centrului de producție, uzina de asamblare sau adresa de înregistrare a producătorului. Data poate fi aproximativă.

04.2019 🇷🇴 România



Daună detectată



Avem indicii potrivit cărora acest vehicul a fost recunoscut ca avariat în această țară (sau stat). Pentru detalii te rugăm să consulți secțiunea „Daune”.

04.2019 🇷🇴 România



A fost înmatriculat

Înregistrarea reprezintă un eveniment administrativ. Acest lucru ar putea fi legat de o schimbare de proprietar, documente etc

11.2019 🇷🇴 România



Evaluare detectată



Avem indicii că acest vehicul a fost supus unei evaluări în această țară (sau stat). Te rugăm să consulți secțiunea "Daune" pentru informații detaliate.

12.2019 🇷🇴 România



Evaluare detectată



Avem indicii că acest vehicul a fost supus unei evaluări în această țară (sau stat). Te rugăm să consulți secțiunea "Daune" pentru informații detaliate.

06.2020 🇷🇴 România



Evaluare detectată



Avem indicii că acest vehicul a fost supus unei evaluări în această țară (sau stat). Te rugăm să consulți secțiunea "Daune" pentru informații detaliate.

06.2020 🇷🇴 România



Evaluare detectată



Avem indicii că acest vehicul a fost supus unei evaluări în această țară (sau stat). Te rugăm să consulți secțiunea "Daune" pentru informații detaliate.

02.2021 🇷🇴 România



Evaluare detectată



Avem indicii că acest vehicul a fost supus unei evaluări în această țară (sau stat). Te rugăm să consulți secțiunea "Daune" pentru informații detaliate.

04.2022 🇷🇴 România



A fost verificat

A fost înregistrat un eveniment de inspecție tehnică (cunoscut și sub denumirea de ITP, test tehnic sau test de control al emisiilor). Pot fi incluse atât instanțe reușite, cât și eșuate.

01.2023 🇷🇴 România



Evaluare detectată



Avem indicii că acest vehicul a fost supus unei evaluări în această țară (sau stat). Te rugăm să consulți secțiunea "Daune" pentru informații detaliate.

11.2023 🇷🇴 România



Evaluare detectată



Avem indicii că acest vehicul a fost supus unei evaluări în această țară (sau stat). Te rugăm să consulți secțiunea "Daune" pentru informații detaliate.

11.2024 🇷🇴 România



A fost verificat

A fost înregistrat un eveniment de inspecție tehnică (cunoscut și sub denumirea de ITP, test tehnic sau test de control al emisiilor). Pot fi incluse atât instanțe reușite, cât și eșuate.



+31

Surse de date

Am verificat 900+ de surse de date în **35 de țări**