




Volvo XC40

VIN: YV1XZBBV6P2031836 Benzină 2022

Generat pe 19.05.2025, 05:33



Scanează ca să accesezi raportul complet

Odometru

✓ Arată bine

Statut legal

✓ Arată bine

Daune

⚠ Necesită atenție

+31 Surse de date
Am verificat 900+ de surse de date în 35 de țări

Furt

Vehiculul este declarat furat în prezent? A fost furat în trecut? A fost recuperat?

✓ Nu s-au găsit probleme

Nu am găsit nicio înregistrare că vehiculul a fost furat.

i Notă

Am încheiat verificarea bazelor de date ale poliției privind vehiculele furate din 10 țări: +4

Iată ce am verificat:

Căutat drept furat

✓ Nu s-a găsit nicio înregistrare

Furat în trecut

✓ Nu s-a găsit nicio înregistrare

Nu au fost găsite înregistrări anterioare de furt pentru acest vehicul.

Bazele de date ale poliției cu vehicule furate **verificare finalizată în:**

- România
- Statele Unite ale Americii
- Lituania
- Slovenia
- Cehia
- Ungaria
- Italia
- Slovacia
- Suedia
- Canada


Odometru

Există semne conform cărora kilometrajul a fost dat înapoi sau sunt discrepanțe de kilometraj?



Notă

- Ultimul kilometraj cunoscut: 12.912 km
- 2 înregistrări ale kilometrajului



Înregistrările odometrului

01.2023	11 km
12.2023	12.912 km

Statut legal

A trecut vehiculul inspecțiile tehnice? A fost marcat drept casat?



Nu s-au găsit probleme

Nu s-au găsit înregistrări despre statutul legal al acestui vehicul

Legal



Inspecție tehnică periodică (ITP)

✓ Nu s-a găsit nicio înregistrare

Nu au fost găsite înregistrări ale inspecției tehnice



Casat

✓ Nu s-a găsit nicio înregistrare

Nu există nicio înregistrare că vehiculul a fost marcat drept casat

Daune

Această secțiune te ajută să înțelegi dacă vehiculul a fost avariat sau inspectat pentru daune și prezintă estimările înregistrate ale costurilor (dacă sunt disponibile).



Ai grijă!

Am găsit 1 înregistrare pentru acest vehicul



Notă

Daunele minore nu vor afecta în mod normal siguranța vehiculului și nu vor cauza probleme structurale

Înregistrări de daune



Daune pe partea dreaptă:

Dreapta / Portieră față

Daune pe partea dreaptă:

Spate dreapta / Bară de protecție

11.2024

România

Evaluare

Părți afectate

Partea dreaptă

Spate

Costul estimativ al reparațiilor

6.001 RON – 14.000 RON

Cauza posibilă

Necunoscut

Categorii de daune

Părți exterioare ale caroseriei

Disclaimer (declinarea responsabilității): Majoritatea înregistrărilor de daune sunt legate de accidente, dar uneori nu este acesta cazul. Unele înregistrări provin din alte surse cum ar fi serviceurile specializate pe lucrări de caroserie, cereri de daune, licitații sau inspecții ale vehiculelor. Aceste înregistrări arată că starea vehiculului a fost evaluată, chiar dacă nu a fost din cauza unui accident.

Termeni secțiunea Daune

Evaluare

Evaluarea este procesul prin care se determină gradul de deteriorare al unui vehicul. Aceasta implică inspectarea vehiculului pentru a determina ce reparații sunt necesare, pentru a estima costurile și pentru a decide dacă vehiculul este reparabil sau poate fi considerat daună totală.

Costul estimativ al reparațiilor

Odată ce un incident în care a fost implicat un vehicul este evaluat, furnizorii de date referitoare la daune calculează costul reparației și îl prezintă în moneda țării în care a fost evaluată dauna. Prin urmare, este posibil ca această estimare să nu coincidă cu așteptările tale. Motivele pot include:

- Țara în care au fost evaluate daunele vehiculului poate avea costuri de reparație mai mari/mai mici în comparație cu țara ta. (prețurile pieselor de schimb și costul forței de muncă diferă de la o țară la alta)
- Costul reparațiilor este calculat ca și cum reparațiile au fost făcute la un service oficial (care este de obicei ceva mai scump)

Dezastre naturale

Locația vehiculului a fost înregistrată în zona unui dezastru natural?



Nu s-au găsit probleme

Locația vehiculului nu a fost înregistrată în zona unui dezastru natural

Valoare de piață

Cu cât s-a vândut vehiculul în trecut? Care este prețul mediu pentru un vehicul din același model și an?



Notă

- Prețul mediu de pe piață pentru un astfel de vehicul: 221.059 RON
- Atenție la problemele ascunse dacă vehiculul a fost la vânzare la un preț semnificativ mai mic decât prețul actual!

Valoarea actuală de piață pentru Volvo XC40 2022

Valoarea de piață este determinată prin examinarea prețului unui anumit model de mașină (fabricat în același an) în țara în care a fost generat raportul. Analizăm datele din ultimele 6 luni.

Cel mai mic preț

216.414 RON

Prețul mediu

221.059 RON

Cel mai mare preț

229.215 RON

Emisii

Care este nivelul de emisii de CO₂ al vehiculele din acest model/an?



Sugestia carVertical

Acest vehicul are emisii scăzute. Poate se califica pentru taxe mai mici pentru emisii. Verifică reglementările locale ca să vezi dacă se aplică reduceri.

Emisii CO₂

Emisii CO₂ g/km

Până la
120

120 - 140

140 - 155

155 - 165

165 - 190

190 - 225

225 +

Emisiile de
CO₂ ale
vehiculului
tău

18 g/km

Clasă **A**

Specificații și echipare

Ce specificații și echipamente sunt înregistrate pentru acest vehicul?



Notă

Verifică dacă specificațiile și echipamentul acestui vehicul se potrivesc cu datele furnizate de vânzător.

Identificare și specificații tehnice



Producător

Volvo



Model

XC40



Descriere

Ex40 / Xc40



Tip caroserie

Break



An de fabricație

2022



Capacitate cilindrică

1,5 l



Putere motor

55 kW (74 cp)



Tip combustibil

Benzină



Cutie de viteze

Automată



Tip transmisie

Tracțiune față (FWD)



Culoare

Gri



Nr. uși

5



Amplasarea volanului

Volan pe stânga



Nr. locuri

5



Cod motor

B3154T5

Echipare

Cum a fost primit de la producător

- 0
- MAKEUP LAMP SUNVISOR 2 ILLUMINATED SUN VISORS
- 10
- KNEE AIRBAG KNEE AIRBAG DRIVER SIDE
- 101
- HEADLIGHTS,SYMMETRY R ASYMMETRIC
- 103
- HEADLIGHT CLEANING WITH HEADLIGHT CLEANING
- 105
- TELEPHONE NETWORK TELEPHONE SYSTEM GSM
- 107
- SELF OPENING BOOTLID/TAILGATE WITH POWEROPERATED TAILGATE OR BOOTLID
- 109
- UNLOCK SETTING TWO STEP UNLOCKING ENABLED, DEFAULT OFF, SLAM LOCKING DISABLED
- 110
- SPEECH
- 112
- HEADRESTS 2:ND ROW, FOLDING EL FOLDING REAR HEADRESTS
- 114
- CUSHION EXTENSION, DRIVER CUSHION EXTENSION MECHANICAL, DRIVER
- 116
- CUSHION EXTENSION, PASSENGER CUSHION EXTENSION MECHANICAL, PASSENGER
- 118
- HILL START ASSIST
- 12
- LUGGAGE NET, TEXTILE LUGGAGE NET, BACKREST
- 121

- 1
- PARKING TICKET HOLDER WITH TICKET HOLDER
- 100
- BASE COLOUR INTERIOR CHARCOAL BASE COLOUR INTERIOR
- 102
- CORNERING LIGHTS WITH CORNERING LIGHT
- 104
- FOGLIGHTS IN SPOILER FOGLIGHT
- 106
- VIDEO ALLOWED SPEED DEPENDENT
- 108
- AUDIBLE LOCKING FEEDBACK AUDIBLE LOCKING FEEDBACK DISABLED
- 11
- POWER RELEASE 2:D ROW MECHANICAL RELEASE FOLD 2:D ROW REAR SEAT
- 111
- DIGITAL OWNERS MANUAL
- 113
- SEATS 5SEAT
- 115
- LUMBAR SUPPORT 4 WAY LUMBAR SUPPORT
- 117
- INTERIOR ILLUMINATION INTERIOR LIGHTNING HIGH VERSION
- 119
- TYREPRESSURE MONITORING SYSTEM INDIRECT TPMS, EU ALGORITHM
- 120
- POST IMPACT BRAKING
- 122
- ROAD FRICTION INDICATION

COLLISION MITIGATION SUPPORT WITH COLLISION
MITIGATION SUPPORT FRONT, VER.1

123

LAMINATED WINDOWS TEMPERED GLASS, SIDE &
REAR WINDOWS

125

ROOF RAILS ROOF RAILS INTEGRATED
ALUMINIUM/SILVER

127

TPMS MENU FUNCTIONS IN IHU TPMS, RESET MENU

129

DARKENED REAR WINDOWS DARK GLASSES, REAR
SIDEDOOR AND CARGO AREA

130

REAR FOGLIGHT TOWFUNCTION FOGLIGHTS SHUT
OFF WHEN TRAILER IS CONNECTED, ONLY TRAILERS
FOGLIGHTS ARE RUNNING

132

RIM, INCH 18' RIM

134

DIGITAL RADIO RECEIVER DAB RADIO SYSTEM

136

INTERIOR MOTION SENSOR WITH INTERIOR MOTION
SENSOR PREPARATION

138

HEATED WINDSCREEN HEATED FRONTSCREEN

14

WHEEL NUT PROTECTION CAP PLASTIC PROTECTION
CAP

141

LEVELLING SENSOR CONFIGURATION VDDM, FRONT
LEFT, REAR LEFT

143

VEHICLE TYPE V316 XC40

145

EXPANDING ABSORBER FRONT ABSORBER FIREWALL
TYPE A

147

AUTOMATIC LOCKING BY SPEED AUTOMATIC
LOCKING BY SPEED ALWAYS ON, DISABLED IN MENU

124

DECOR SIDE WINDOWS BRIGHT DECOR SIDE
WINDOWS

126

GLOBAL NAVIGATION SAT SYSTEM WITH GLOBAL
NAVIGATION SATELLITE SYSTEM

128

PARKING ASSISTANCE PARKING ASSISTANCE, FRONT
AND REAR

13

RAINSENSOR RAIN SENSOR

131

TELEMATIC MODULE WITH TELEMATIC MODULE

133

PRODUCT LABEL COUNTRY OF ORIGIN

135

SUBWOOFER

137

RADARTYPE WITH CADS 4

139

APMS AIR BORNE PARTICULATE MATTER SENSOR,
AKA PM2.5-SENSOR

140

HEATER TYPE HVCH, HIGH VOLTAGE COOLANT
HEATER

142

CAR/STEERING/GEARBOX EXTRA VARIANT

144

DRIVE FRONT WHEEL DRIVE

146

KEYLESS ENTRY PASSIVE ENTRY, PERSONAL CAR
COMMUNICATOR, INCL. REMOTE TAG

148

EXTERIOR SOUND UNIT WITH EXTERIOR SOUND UNIT
+ SPEAKER

149

HOOK FOR HANDBAG HOOK FOR HANDBAG IN GLOVEBOX

150

ESM CALIBRATION WITH ESM CALIBRATION C

152

GEARSHIFTER PANEL GEARSHIFT PANEL HIGH GLOSS BLACK

154

WHEEL BRAKES TYPE FRONT FRONT BRAKE DISCS 18'

156

VIBR. DAMPER STEERING WHEEL VIBRATION DAMPER, VERSION 4

158

CAR/GEARBOX/DRIVELINE V316 AUTO 2WD

16

STOLEN VEHICLE/THEFT NOTIFY WITH STOLEN VEHICLE TRACKING / WITH THEFT NOTIFICATION

161

INTERIOR DECOR PANELS ALU DECOR (URBAN GRID) ALUMINIUM DECOR INLAYS

163

TAILPIPE DOUBLE PIPES, HIDDEN

165

FRONT EL PROPULSION MOTOR FRONT ELECTRIC PROPULSION MOTOR (75PS)

167

WHEEL A 18' 7.5X18X50,5 18'DESIGNE

169

FOOT MOVEMENT DETECTION MODULE FOOT MOVEMENT DETECTION MODULE, GEN 2

170

AIR QUALITY SYSTEM AIR QUALITY SYSTEM, MULTIFILTER2

172

INTERIOR LIGHT INTENSITY EXTRA VARIANT

174

15

ELECTRIC FUEL LID OPENING WITH ELECTRIC FUEL LID OPENING

151

ARMREST, MIDDLE REAR SEAT 2ROW CENTRE ARMREST WITH CUPHOLDERS

153

REAR WIEW MIRROR,TYPE AUTOMATIC DIMMING INNER & OUTER

155

STEERING WHEEL STEERING WHEEL, 3 SPOKE, PU WITH UNIDECO INLAYS, SPORT

157

DEVICE MIRRORING WITH DEVICE MIRRORING, ACP & AA

159

INDUCTIVE CHARGING, SMARTPHONE INDUCTIVE CHARGING FOR SMARTPHONE

160

USB CONNECTION WITH USB HUB

162

WHEEL BRAKES TYPE REAR REAR BRAKE 16'

164

GEARBOX/DRIVELINE 7-SPEED DUAL CLUTCH, 2WD AND 4WD

166

GEARBOX 7DCTFWD, DUAL CLUTCH 7-SPEED FWD

168

INTERIOR CODE CHARCOAL INTERIOR/TEXTILE/GREY MELANGE SEAT/COMFORT

17

ASSISTANCE SERVICES WITH ASSISTANCE SERVICES

171

SPARE WHEEL TEMPORARY SPAREW T125/70R19 CMA

173

ADMIN. OPTION TYRES SUMMER TYRES

175

INSTRUCTIONS OWNERS MANUAL ROMANIA

176

COMMON MATERIAL COMMON MATERIAL - ALL TYPE
27 CARS

178

POLESTAR PERFORMANCE SW NO POLESTAR
PERFORMANCE SOFTWARE

18

CONNECTIVITY WITH CONNECTIVITY

181

INSULATION CARPETS HIGH SPEC NVH-CARPETS
WITH NETPOCKET

183

FRONT SEAT, LEFT HAND SIDE LH SEAT, EXTRA
VARIANT

185

SEAT PADDING COMFORT SEAT PADDING

187

PEDAL ARRANGEMENT PEDAL STANDARD

189

SAFETY BELT SAFETY BELT, TYPE B

190

PASSENGER AIRBAG TYPE PASS. AIRBAG WITH 1
STAGE INFLATOR AND ADAPTIVE VENT. PASS. SEAT
WITH SEAT TRACK SENSOR

192

ROOF HATCH NO ROOF HATCH/PANORAMA ROOF

194

EMERGENCY LANE KEEPING AID EMERGENCY LANE
KEEPING AID 3

196

EXTERIOR LIGHT LOGIC DDRL NOT TOGETHER WITH
POSITION LIGHT

198

SAFETY BELT REMINDER BELT MINDER ALL SEATS, EU
LOGIC

2

TOTAL WEIGHT CHECK CARWEIGHT IS OK

COMMON 27 V316/K316/V317

177

TOWBAR NO TOWBAR

179

SCREEN THEMES/SKINS SCREEN SKINS 'STANDARD 1'

180

NUMBER PLATE ADAPTER FRONT NUMBER PLATE
ADAPTER 1 'EU'

182

SPRING SETTING TYPE STANDARD SPRINGS

184

FRONT SEAT, RIGHT HAND SIDE RH SEAT, EXTRA
VARIANT

186

ENVIROMENT CLASS NO ECO

188

SEAT TRACK SENSORS WITH SEAT TRACK SENSOR
PASSENGER SEAT

19

PARKING CAMERA PARKING CAMERA 360

191

AIRBAG, DRIVER/PASSENGER AIRBAG, TYPE B

193

PINCH PROTECTION LEVEL STANDARD PINCH
PROTECTION

195

DIAGNOSIS SYSTEM EOBD

197

REAR WIEW MIRRORS, OUTER RETRACTABLE REAR
VIEW MIRRORS

199

REGION IF DVD DVD REGION 2

20

PROPULSION TYPE PLUGIN HYBRID VEHICLE

200

CHILD LOCK.REAR DOORS ELECTRICAL CHILD LOCK,
REAR SIDE DOORS

202

REAR VIEW MIRROR CAP WITH COLOUR MATCHED
REAR VIEW MIRROR CAP

204

FREQUENCY BAND & STEP,RADIO FREQUENCY BAND
AND STEP FOR EU

206

NETPOCKET IN CARGO AREA NO NETPOCKET IN
CARGO AREA

208

STORAGE TRAY TUNNEL CONSOL NO STORAGE TRAY
TUNNEL CONSOLE

21

ELECTRIC VEHICLE INLET ELECTRIC VEHICLE INLET,
TYPE 2

211

CHASSIS TYPE CHASSIS DYNAMIC

213

MODEL EMBLEM V316 EMBLEM

215

FRONT FENDER INSULATION FRONT FENER
INSULATION

217

MARKET PLATES/LABELS DECALS OUTSIDE RUSSIA

219

MARKET PLATES/LABELS LABELS OUTSIDE USA

220

MARKET PLATES/LABELS DECALS OUTSIDE CHINA

222

MARKET PLATES/LABELS DECALS OUTSIDE INDIA

224

MARKET PLATES/LABELS LABELS FOR EUROPE

226

MARKET PLATES/LABELS LABELS OUTSIDE
USA/CANADA

201

CENTRAL LOCK SWITCHES CENTRAL LOCK
SWITCHES IN BOTH FRONT DOORS

203

IONIZER OPTION NO IONIZER OPTION

205

LANGUAGE REGION LANGUAGE REGION FOR EUROPE

207

POWER FOLD & RISE 3:D ROW NO FOLD & RISE 3:D
ROW REAR SEAT

209

STORAGE BOX UNDER FRONT SEATS NO STORAGE
BOX UNDER DRIVER SEAT

210

TYRE CIRCUMFERENCE ROLLING CIRCUMFERENCE
2225MM

212

EMERGENCY BRAKE LIGHT EBL, FLASHING BRAKE
LIGHT AND HAZARD WARNING

214

WINDSCREEN WIPER WET ARMS, NOT HEATED

216

NAVI MAP REGIONS MAP REGION FOR EUROPE

218

MARKET PLATES/LABELS DECALS OUTSIDE LATIN
AMERICA/MEXICO/RUSSIA

22

SHIFT BY WIRE WITH SHIFT BY WIRE

221

MARKET PLATES/LABELS DECALS OUTSIDE
JAPAN/CHINA/KOREA

223

MARKET PLATES/LABELS DECALS OUTSIDE ARABIA

225

MARKET PLATES/LABELS LABELS FOR OUTSIDE
KOREA

227

MAIN MARKET EUROPE AND OVERSEAS MARKETS

228

USER PACKAGES USER PACKAGE

23

GEARBOX,TYPE AUTOMATIC GEARBOX

231

USER EXCEPTIONS NOT FOR LUQIAO

233

TYRE PRESSURE HHLF HIGH SPEED, HEAVY LOAD,
FRONT, 260 KPA

235

SERVICE SOLUTION

237

REMOTE ENGINE START PRECOND REMOTE ENGINE
START PRECOND FROM SMARTPHONE APP

239

MARKET CODE MARKET VARIANT, NOT FOR PART
STEERING

240

SW MAJOR VERSION SW MAJOR 03

242

REAR AXLE WEIGHT, ONLY CC REAR AXLE WEIGHT

244

ENGINE DENOMINATION ENGINE T5

246

BATTERY H7 AGM EXIDE 80AH 800CCA

248

CUTOFF SWITCH PASSENGER AIRBAG CUT-OFF
SWITCH PASSENGER AIRBAG

25

BYPASS VALVE HVAC WITH BYPASS VALVE

251

IF INSCRIPTION: LOGO HEAD REST NO INSCRIPTION
LOGO ON HEADREST UPHOLSTERY

253

EMISSION EVAPORATOR SYSTEM EVAPORATOR
SYSTEM, EU6

255

229

USER EXCEPTIONS ONLY FOR VOLVO CARS GENT

230

USER EXCEPTIONS NOT FOR MALAYSIA

232

TYRE PRESSURE HHLR HIGH SPEED, HEAVY LOAD,
REAR, 260 KPA

234

EXTERIOR PAINT,TYPE METALLIC

236

ENGINE OPTIMIZATION AFTERMARKE STANDARD
CALIBRATION ENGINE

238

SUNVISOR DECAL

24

PARKING CLIMATE LEVEL FULL PARKING CLIMATE

241

SPECIAL VEHICLE WEIGHT VERSION STANDARD
VEHICLE

243

FRONT SEATS, LH EXTRA VARIANT

245

FUEL PETROL

247

ENGINE COOLING FAN PERFORMANCE FAN MEDIUM
PERFORMANCE

249

COLOUR MATCHING, EXTERIOR

250

COLOUR MATCHING, EXTERIOR

252

LANE KEEPING AID

254

SPEED LIMITATION SPEED LIMIT 180 KM/H

256

SERVICE DISTANCE SERVICE DISTANCE 30000 KM /
~18640 MILES

257

HEATED FRONT SEATS

259

12 VOLT OUTLET LUGGAGE 12V POWER OUTLET,
LUGGAGE AREA

260

FIRST AID KIT AIDKIT TYPE 2

262

POWER STEERING PERSONALISATION WITH ELECTRO
POWER STEERING PERSONALISATION

264

IR REFLECTIVE GLASS WINDSCREEN STANDARD
WINDSCREEN GLASS

266

SCUFF PLATE BOOT REAR SCUFF PLATE, METAL

268

FENDER SEALING

27

VISIBLE LOCKING/UNLOCKING VISIBLE LOCKING AND
UNLOCKING FEEDBACK, DEFAULT ON

271

PLATES/DECALS LABELS FOR MFK19

273

TYRE PRESSURE LHLR LOW SPEED, HEAVY LOAD,
REAR, 260 KPA

275

NTA-CODE NO NTA NUMBERS

277

SW MINOR VERSION SW MINOR 03

279

SPECIAL VEHICLES SPEED LIMIT STANDARD SPEED
LIMITATION

280

HOOD ABSORBER NO HOOD ABSORBER ON CARS

282

DRIVERS SEAT POWER ADJUSTABLE DRIVERS SEAT
WITH MEMORY

258

TOLL ROAD TRANSPONDER NO TOLL ROAD
TRANSPONDER

26

SIM CARD FOR CONNECTIVITY ONLY THROUGH
PERSONAL SIM

261

TYRE, INCH 18' TYRE

263

STEER. COLUMN LOCK/KEY WARNING WITH
STEERING COLUMN LOCK, KEY WARNING DISABLED

265

HANDLE DOORS HANDLE SIDE DOOR BODY COLOR,
W/O DAMPER, KEYLESS AND ILLUMINATION

267

WARNING TRIANGLE

269

MARKET PLATES/LABELS LABELS FOR MID EU

270

MARKET PLATES/LABELS LABELS OUTSIDE
AUSTRALIA

272

TYRE PRESSURE LLLF LOW SPEED, LIGHT LOAD,
FRONT, 230 KPA

274

TYRE PRESSURE LHLF LOW SPEED, HEAVY LOAD,
FRONT, 260 KPA

276

REMOTE BATTERY MANAGEMENT WITH REMOTE
BATTERY MANAGEMENT FROM SMARTPHONE APP

278

SW PATCH VERSION SW PATCH 16

28

PANIC FUNCTION PANIC FUNCTION WITH LIGHT &
SOUND

281

PASSENGERS SEAT POWER ADJUSTABLE
PASSENGERS SEAT

283

MARKET PLATES/LABELS LABELS OUTSIDE CHINA
AND ARABIA

284

PAC CALIBRATION PAC CALIBRATION STANDARD

286

SALES VERSION - ADMINISTRATIVE ORDINARY SV

288

GEARLEVER,TYPE/KNOB GEARLEVER KNOB, PU WITH
UNIDECO

29

INSTRUMENT CLUSTER CALIBR. PARAMETER FILE
FOR EUROPE

291

PRIVATE LOCKING LUGGAGE COMP. PRIVATE
LOCKING NO EXIST

293

DOOR CASSETTE (F) NO DOOR CASSETTE

295

PROTECTION CARPETS CARPET KIT, TEXTILE

297

YEAR DESIGNATION LETTER YEAR DES P = MODEL
YEAR 2023

299

ELECTRIC ENGINE ONLY COMBUSTION ENGINE FOR
PROPULSION

30

CHILD SEAT ATTCHM, LABEL REAR ISOFIX LABEL, B

301

WHEEL REAR (IF FR RR DIFF) WILL NOT USE
STAGGERED WHEELS

303

STAGGERED WHEEL NO STAGGERED WHEELS

305

REAR SPRINGS-(WEIGHT) EXTRA VARIANT

307

FRONT SPRINGS-(WEIGHT) EXTRA VARIANT

CAR SHARING FUNCTIONALITY NO CAR SHARING
FUNCTIONALITY

285

LEATHER/VINYL CARE KIT NO LEATHER/VINYL CARE
KIT

287

EL CHARGE INLET BODY SIDE NO EL CHARGE INLET
BODY SIDE

289

CLIMATE CONTROL UNIT ELECTRONIC CLIMATE
CONTROL SMALL, 2 ZONE

290

STORAGE WITH COVER STORAGE WITH COVER IN
TUNNEL CONSOLE

292

POWER OUTLET TUNNEL 5 VOLT OUTLET (2 USB), IN
REAR/LOWER TUNNEL CONSOL

294

WVTA-NUMBER E9*2007/46*3146

296

AUTOMOTIVE SERVICE NO AUTOMOTIVE SERVICE
(NO ICUP)

298

FRONT SEATS, RH EXTRA VARIANT

3

ROAD SIGN INFORMATION WITH RSI

300

OIL LEVEL SENSOR

302

TYRE DIMENSION RR (IF DIFF FR) WILL NOT USE
STAGGERED WHEELS

304

TYRE PRESSURE HLLF HIGH SPEED , LIGHT LOAD,
FRONT, 230 KPA

306

OUTER REAR VIEW MIRRORS OUTER REAR VIEW
MIRROR PACKAGE

308

REAR AXLE CABLE HARNESS EXTRA VARIANT

309

ENGINE FAMILY 2 GEP3 ENGINES

310

ENGINE GENERATION VEA/GEA GEP3 GENERATION 1

312

ENGINE/GENERATION B3154T5 GEN 1

314

CYLINDERS ENGINE PETROL/DIESEL 3-CYLINDER
ENGINE

316

SUPPORT BATTERY SUPPORT BATTERY 4, SUPER CAP

318

EMISSION VERSION 2 GEN 1, EURO 6D

32

REMOTE MONITORING SYSTEM RMS DEACTIVATED

321

TREAD PLATE TREAD PLATE, RECHARGE

323

MAX REAR AXLE WEIGHT, C4 1150 KG

325

TRAIN WEIGHT, C2 4090 KG

327

TYRE PRESSURE HLLR HIGH SPEED, LIGHT LOAD,
REAR, 240 KPA

329

COLOUR HEADLINING OVER BELT 'BLACK' COLOUR
ON HEADLINING/CEILING

330

TYRE BRAND MICHELIN V

332

TYRE DIMENSION FOR LABELS T125/70R19

334

SYSTEM LANGUAGE ROMANIAN

35

INFOTAINMENT HEAD UNIT EXTRA VARIANT

37

DAB RADIO RECEIVER WITH DAB

39

31

BUMPERS/SILL MOULDING PAINTED BUMPER

311

ENGINE GENERATION VEA2 GEA GENERATION 1

313

ENGINE GEP3 MP 1.5L 180/265

315

HIGH VOLTAGE BATTERY HV LI-ION 326V 34AH CMA
P34 LG NEW CATHOD

317

FUEL TANK, VOLUME VOLUME 49 LITRE

319

CATALYST TYPE CATALYST PETROL 6B MONITORING

320

ENGINE EMBLEM EMBLEM 'T5'

322

MAX FRONT AXLE WEIGHT, C3 1200 KG

324

GROSS WEIGHT, C1 2290 KG

326

TYRE PRESSURE LLLR LOW SPEED, LIGHT LOAD,
REAR, 240 KPA

328

TYRE DIMENSION 235/55R18

33

RETRIGG ENABLING - IF ALARM RETRIGG 1 CYCLE

331

TYRE PRESSURE SPARE WHEEL 420 KPA/60 PSI

333

FRONT AXLE WEIGHT, ONLY CC FRONT AXLE WEIGHT

34

UPHOLSTERY TYPE PRODUCTION UPHOLSTERY

36

AC COMPRESSORS ELECTRIC AC

38

BRAKE PADS STANDARD PAD

4

AUDIO LEVEL AUDIO HIGH

40

TURBO CONFIGURATION MEDIUM PERFORMANCE

42

WORKSHOP WIFI WITH WORKSHOP WIFI

44

ALARM WITH ALARM PREPARATION

46

CAR/STEERING/SEAT2 EXTRA VARIANT

48

CAR/STEERING/SEAT3 EXTRA VARIANT

5

COMBINED INSTRUMENT DRIVERS INFORMATION
MODULE WITH 12.3 INCH SCREEN

51

PRE CLEANING WITH PRE-CLEANING GLOBAL

53

FRONT SHOCK ABSORBER FRONT SHOCK ABSORBER
6

55

EXTERIOR CODE THUNDER GREY

57

UPHOLSTERY MATERIAL TEXTILE RIVEL SHINE

59

CABLE HARNESS TAILGATE EXTRA VARIANT

60

BUMPER FRONT FRONT BUMPER WITH HOLES FOR
NUMBER PLATE HOLDER

62

SECONDARY EXTERIOR CODE NO SECONDARY
EXTERIOR CODE

64

SERVICE TIME SERVICE TIME, 12 MONTHS.

66

UNIT SETTINGS TEMP:C, CLOCK:24, DISTANCE:KM,
FUEL:LITER/KM

GRILL TYPE INSCRIPTION GRILL

41

RADIO, AMP & SPEAKER SYSTEM HIGH
PERFORMANCE AUDIO, PRO

43

INSERT COLOUR INTERIOR CHARCOAL INSERT
COLOUR INTERIOR

45

D-PILLAR TRIM RECHARGE

47

CAR/STEERING EXTRA VARIANT

49

HEADRESTS FRONT HEADSRESTS FRONT, FIXED

50

FRONT ANTI-ROLL BAR FRONT ANTI-ROLL BAR 2

52

REFRIGERANT AGENT QUANTITY REFRIGERATING
AGENT 520G

54

REAR SHOCK ABSORBER REAR SHOCK ABSORBER 6

56

COLOURS,INT/EXT THUNDER GREY

58

CHARGE CORD CORD, PLUG F, TYPE 2, MODE 2,
LOWPWR, 1P-10A

6

KEY FOB KEY FOB INSCRIPTION

61

SEAT COLOUR INTERIOR GREY MELANGE
UPHOLSTERY COLOUR INTERIOR

63

MFI FUEL FILLER MISFUELING INHIBITOR

65

SERVICE ENGINE TIME SERVICE ENGINE TIME, 650
HOUR

67

OCCUPANTS NO OCCUPANTS

68

CSB - IF CONNECTIVITY CONNECTED SERVICE
BOOKING

7

JACK

71

HORN HORN, STD.

73

STEERING COLUMN STEERING COLUMN TYPE B
MANUAL ADJ.

75

MARKET PLATES/LABELS DECALS OUTSIDE
JAPAN/CHINA

77

MARKET PLATES/LABELS DECALS OUTSIDE BRAZIL

79

MARKET PLATES/LABELS DECALS OUTSIDE JAPAN

80

VEHICLE INSPECTION NUMBER YV1

82

LOCK CYLINDER GLOVEBOX NO LOCK CYLINDER
GLOVEBOX

84

STEERING WHEEL POSITION LEFT HAND DRIVE

86

ACTIVE GRILLSHUTTER

88

REAR WIEW MIRROR,LH SIDE LH SIDE REAR WIEW
MIRROR, WIDE ANGLE

9

TELEMATIC MODULE WITH TELEMATIC MODULE,
ROW LTE

91

CRUISE CONTROL

93

ADJUSTABLE SPEED LIMITER

95

69

DOORS 5 DOOR

70

FUEL ECONOMY LABEL NO FUEL ECONOMY LABEL

72

FREQUENCY - REMOTE CONTROLS FREQUENCY 434
MHZ

74

CEM HIGH SPEC CEM

76

MARKET PLATES/LABELS LABELS OUTSIDE CANADA

78

MARKET PLATES/LABELS DECALS FOR OUTSIDE
TURKEY

8

ROOF COLOUR INTERIOR CHARCOAL ROOF COLOUR
INTERIOR

81

END STOP LENGTH LENGTH 2

83

TUNER WITH DAB TUNER, WITH FM TUNER (FOR DAB)

85

STOP/START

87

GEARSHIFT INDICATOR

89

HILL DESCENT CONTROL

90

HEATED STEERING WHEEL

92

TRANSMISSION 2 WHEEL DRIVE

94

OPEN, REAR SIDE DOOR 1 PULL TO OPEN REAR SIDE
DOOR, FROM LOCKED

96

ALARM LOGIC ALARM LOGIC BASE

97

DRIVE MODE WITH DRIVE MODE SWITCH

99

SRS CALIBRATION SRS CALIBRATION 1

IHU LEVEL IHU HIGH

98

REFRIGERANT 1234YF

Siguranță

Vehiculul are vreo rechemare pe motiv de siguranță? Care este ratingul său de siguranță?



Sugestia carVertical

Acest vehicul are un rating ridicat de siguranță. Întreținerea corespunzătoare și regulată va menține standardul ridicat de siguranță.

Rating de siguranță

★★★★★ Siguranță de 5 stele

Performanță generală excelentă la protecția împotriva accidentelor și bine echipat cu tehnologie amplă și robustă de evitare a accidentelor



92%

Ocupant adult



89%

Copil ocupant



70%

Utilizatori vulnerabili ai drumurilor



89%

Asistență de siguranță

Cronologie

S-au găsit 4 înregistrări

Cronologia înregistrărilor pentru acest vehicul

Ultimele înregistrări

01.2023 🌐 Țară necunoscută



A fost fabricat

Țara (sau statul) indică fie locația centrului de producție, uzina de asamblare sau adresa de înregistrare a producătorului. Data poate fi aproximativă.

01.2023  România



A fost înmatriculat

Înregistrarea reprezintă un eveniment administrativ. Acest lucru ar putea fi legat de o schimbare de proprietar, documente etc

11.2024  România



Evaluare detectată



Avem indicii că acest vehicul a fost supus unei evaluări în această țară (sau stat). Te rugăm să consulți secțiunea "Daune" pentru informații detaliate.

01.2025  România



A fost asigurat

Acest vehicul a fost asigurat în această țară (sau stat). Pot fi acoperite toate tipurile de asigurare (răspundere civilă față de terți, CASCO etc.), precum și reînnoirea polițelor.

Din: 27.01.2025

Până la: 26.07.2025



+31

Surse de date

Am verificat 900+ de surse de date în **35 de țări**